

Surveyor: Rasul REF: C33/AXA18005955/RISB^{SV}/1
ASSIGNMENT (Office)
 From (Person): Chen Xinyou of AXA Date/Time: 06072018
 Estimated Cost: _____ Bill to: _____

Special Instruction:
US: \$1200.00
 Third Parties:
 Claimant:
 Surveyor: Treasure Appraisal
 Workshop: Hendon Automotive

OD (TP Re-inspection) / Evaluation
 To Inspect Vehicle No: SLP 8803X Insured: SHC 5211P
 at Workshop m/s: Hendon Automotive Tel: 9459 2885
 of: 280 Woodlands Ind Park #01-25
 Policy No: _____ Claim No: (0147)689 mc/XY
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 24032018
 (Client's Record)

13.072018 (Friday) @ 11am

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT
 Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 8 days)
 Date/Time: 13/07/18 Submit Final Fig \$7,250/-, 7 days (Red \$ \$4,250/- 40%; Original 8 days)

Date/Time	Action/Instruction
	SLP 8803X - C33/AXA18005955/Sbs2
	SHC 5211P - C33/FCL17U20001/Ktb2
	DA: 24/3/18
	DA: 15/10/17
RECEIVED 10 SEP 2018	

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by: _____	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	<u>200</u>
Nett Value : _____		Transport	
		Photos	
		Others	
		Total	

- | | |
|---------------------------------------|---|
| 1) Date/Time _____ File Pass to _____ | 2) Date/Time _____ File Return to _____ |
| 3) Date/Time _____ File Pass to _____ | 4) Date/Time _____ File Return to _____ |
| 5) Date/Time _____ File Pass to _____ | 6) Date/Time _____ File Return to _____ |

REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 8803X Yr Regn: 23/4/2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Car
 Make: Peugeot 2008 c.c. 1560
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp Reading: 105001 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VF 5049 HPSKY 002689
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / **STD A/Rim** or
 Tyre Size: F: 105/155 R16 Yoko
 R: 11 Goodyear
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 24/3/18 D.O.I. 2/9/15
 Survey held at Handan
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/4 Submit PRS report.

RECEIVED 26 APR 2018

Case/Time. File Pass to?

: Preli. Report
 : Final Report

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee: _____
Transportation: _____

Date/Time. File Return to?

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

) \$ + PE \$
) Photos
) Others

Report Format: PRR

Lump Sum / I.B.f: (\$)

TOTAL

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Friday, 6 July, 2018 4:10 PM
To: assignments
Subject: FW: Your ref :C0472689 MC/XY Our ref : TKS/H600-ACC-40463.18/kc

Hi,

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHEN Xinyou [mailto:chen.xinyou@axa.com.sg]
Sent: Friday, 6 July, 2018 3:31 PM
To: Kelly Cheng <kelly.cheng@ksteoptr.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Your ref :C0472689 MC/XY Our ref : TKS/H600-ACC-40463.18/kc

WITHOUT PREJUDICE

Dear Kelly

We refer to your email of 06 Jul 2018.

We are writing to confirm our intention to re-inspect your client's vehicle on 13 Jul 2018.

Dear LKK

Please assist with re-inspection on 13 Jul 2018 at 11.00am.

Thank you.

Best Regards

Chen Xinyou | Senior Specialist, Claims (Litigation) Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: chen.xinyou@axa.com.sg
DID: 1800 880 4888



redefining / insurance

AXA's Values at Work:



Customer First



Integrity



Courage



ONE AXA

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kelly Cheng [mailto:kelly.cheng@ksteoptr.com]

Sent: Friday, July 06, 2018 3:15 PM

To: CHEN Xinyou <chen.xinyou@axa.com.sg>

Subject: Re: Your ref :C0472689 MC/XY Our ref : TKS/H600-ACC-40463.18/kc

REMINDER

WITHOUT PREJUDICE

Dear Xinyou,

We refer to your email dated 22 June 2018.

Please be informed that arrangements have been made for you to re-inspect our client's vehicle SLP 8803 X. The details of the re-inspection are as follows:-

Date/Time:	13 July 2018 (Friday) @11:00AM
Venue/Location:	280 WOODLANDS INDUSTRIAL PARK E5, #01-25, HARVEST @WOODLANDS (S) 757322
Person In-Charge:	Ms Lynn
Contact:	9459 2885
Remarks:	Please call our client upon reaching

Kindly confirm the same and arrange for your In-House-Surveyor to attend punctually.

Please let us have your proposed offer within 14 days from the date of re-inspection.

Thank you!

On Tue, Jul 3, 2018 at 5:40 PM, Kelly Cheng <kelly.cheng@ksteoptr.com> wrote:

WITHOUT PREJUDICE

Dear Xinyou,

We refer to your email dated 22 June 2018.

Please be informed that arrangements have been made for you to re-inspect our client's vehicle SLP 8803 X. The details of the re-inspection are as follows:-

Date/Time:	13 July 2018 (Friday) @11:00AM
Venue/Location:	280 WOODLANDS INDUSTRIAL PARK E5, #01-25, HARVEST @WOODLANDS (S) 757322
Person In-Charge:	Ms Lynn
Contact:	9459 2885
Remarks:	Please call our client upon reaching

Kindly confirm the same and arrange for your In-House-Surveyor to attend punctually.

Please let us have your proposed offer within 14 days from the date of re-inspection.

Thank you!

--

Best Regards,
Kelly Cheng
Tel: 6333 4222 ext 72
Fax: 6333 5675

Teo Keng Siang LLC
111 North Bridge Road
Peninsula Plaza, #29-07/08
Singapore 179098

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

...CLAIM SUBFOLDER...(Pending for Payment)

Reinspection

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2018		02 Apr 2018 11:46		22 Jun 2018 17:12 S\$0.00 (S\$107.00)		Pending for Payment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	LEE PANG KEE		
Vehicle Reg. No.:	SLP8803X	Date of Loss:	24/03/2018 00:00 - :59 [44 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0472689	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5211P	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Hendon Automotive (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-19 HARVEST @ WOODLANDS, 757322 Woodlands - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 11/04/2018]		
Adj Asg. Remarks:	Please seek mandate from Cynthia.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (06/07/2018): Reinspection - C0472689/P1680520
- AXA_SG (22/06/2018): Pls submit final report
- AXA_SG (02/04/2018): New TP Assignment - C0472689/P1680520

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

3019403587---



张景祥大律師樓
(律師公會及法官會)

TEO KENG SIANG LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098. Tel: 6333 4222 Fax: 6333 5676/5688
ROC: 201510228C GST Reg No.: 201510228C Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

61167263

Our Ref : TKS/H600-ACC-40463.18/kc
Your Ref : SHC 5211 P
Date : 19th June 2018

Secretary in charged: Kelly

Tel: 6333 4222 (ext 72)
Fax: 6333 5676 / 5688
Email: Kelly.cheng@ksteptr.com

WITHOUT PREJUDICE

BY PDX #8176

PDX Intercompany Exchange Pte Ltd



010808461421

FROM TEO KENG SIANG LLC
PDX Box No. 8902

BY CERTIFICATE OF POSTING
(For your information only)

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01/02, AXA Tower
Singapore 068811
Attn: Motor Claims Dept/

cc: ~~TRANS-CAB SERVICES PTE LTD~~
~~2 Ang Mo Kio Street 63~~
~~Singapore 569111~~

Dear Sirs,

ACCIDENT INVOLVING SLP 8803 X / SHC 5211 P ON 24th MARCH 2018 ALONG AIRPORT BOULEVARD HIGHWAY

We are instructed by GEORGE123 to claim damages against you in connection with a road accident ON 24th MARCH 2018 ALONG AIRPORT BOULEVARD HIGHWAY involving our client's motor vehicle registration number CLIENT'S SLP 8803 X and motor vehicle registration number DEFENDANT'S SHC 5211 P driven by you or your authorised driver at the material time.

We are instructed that your negligent driving and/or management of your vehicle caused the accident. As a result of the accident, our client's vehicle was damaged and our client was put to loss and expense, particulars of which are as follows:

• Cost of Repair	\$12,100.00
• Pre-repair loss of use (\$80 x 2 days)	\$ 160.00
• Loss of Use (\$80 x 19 days)	\$ 1,520.00
• LTA search fee	\$ 7.49
• GIA search and report fees	\$ 30.00
• Survey report fee	\$ 788.00
• Costs incl. GST	\$ 1,284.00
• Total	\$15,889.49



Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

1

1000

M/s Teo Keng Siang LLC

Our Ref : TKS/H600-ACC-40463.18/kc
Your Ref : **SHC 5211 P**
Date : 19th June 2018

WITHOUT PREJUDICE

A copy each of the following supporting documents is enclosed:

- GIA report of **CLIENT'S SLP 8803 X**
- Traffic Police Report of **CLIENT'S SLP 8803 X**
- LTA search on **DEFENDANT'S S SHC 5211 P**
- Certificate of Insurance / Vehicle Registration Card.
- Repairer's final repair bills.
- Surveyor's report.
- Original photographs of damage of **CLIENT'S SLP 8803 X - 93 copies.**

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Teo Keng Siang LLC
encs.
cc: client (by fax only: 6334 5178)

Teo Keng Siang
LL.M(Singapore).
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

Enquire Vehicle & Owner Information (Vehicle No. SHC5211P As At 24 Mar 2018 / 08:10:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LK2179-40271.18/KC

Current Owner Details

Owner ID Type: Company

Owner ID: 200303878K

Owner Name: TRANS-CA3 SERVICES PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 2

Registered Street Name: ANG MO KIO STREET 63

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 569111

Current Vehicle Details

Vehicle No.: SHC5211P

Make Description/Model: RENAULT / LATITUDE 2.0L DCI AUTO D/AB 4DR

Insurance Company Name: AXA INSURANCE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 10:50
Date Of Accident	24/03/2018 08:10
Exact Location Of Accident	AIRPORT BLVD HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP8803X
Insured/Policyholder	
Name Of Registered Owner	GEORGE123
Co Reg No	53370255X
Email Address	HUGOLEE2824Y@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-93808085
Vehicle Particulars	
Manufacturer	PEUGEOT
Model	2008 1.6 E-HDI EGC ACTIVE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094279834
Cover Note Number	
Driver	
Name of Driver	LEE PANG KEE
NRIC No	S1620590G
Date Of Birth	14/12/1963
Occupation	OUTDOOR
Date Of Driving Pass	19/03/1984
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91296443
Fax Number	
Contact Number	
Email Address	HUGOLEE2824Y@GMAIL.COM

Address BLK 257 BANGKIT ROAD
#05-53

Postcode 670257

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CLEMENTI N.P.C

Police Station Address ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC5211P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEE PANG KEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLP8803X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:





Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along Airport Blvd highway on 20/3/18 suddenly vehicle B (SHC 5211P) came from my right side and cut into my lane. Thus I realised vehicle B (SHC 5211P) hit onto my vehicle right side portion after the impact, I felt pain on my neck and hand.

DECLARATION

I/We declare the foregoing statements are true in every respect.


 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/PPN No.:



**SINGAPORE
POLICE FORCE**



T/20180324/2107

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20180324/2107

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/03/2018 16:59	Vide Report No.: P/20180324/0026	Station Diary No.: 134
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LEE PANG KEE		Address: APT BLK 257 BANGKIT ROAD #05-53 SINGAPORE 670257	
ID Type / ID No.: NRIC NO / S1620590G		Contact No.: Home/Office: Mobile: 91296443	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 54	Date of Birth: 14/12/1963	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/03/2018 08:10	Type of Location: Straight Road
Location: Along Road 1 AIRPORT BOULEVARD				
Towards PIE Direction				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5211P	Car	RENAULT	Latitude	Red	Slightly Damaged	0
SLP8803X	Car	PEUGEOT	2008	Grey	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20180324/2107

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180324/2107

CONTINUATION OF REPORT

Brief Details.

I was travelling along Airport Boulevard highway on 24/03/201. Suddenly the taxi bearing the said registration plate number, came from my right side and cut into my lane. Thus I realized the taxi had hit onto my vehicle right side portion. After the impact, I felt pain on my neck and hands.

I had seen the doctor and was given 3 days MC. This is the first time such incident happened to me.



**SINGAPORE
POLICE FORCE**



T/20180324/2107

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3
Report No. T/20180324/2107

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Staff Sgt CLEMENT CHEE WEI JUN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 24/03/2018 16:59
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAIZAL B'N YAHYA Contact No.: 65476202	Classification Of Case:

Authentication Stamp

	SINGAPORE POLICE FORCE	SN 37
--	---------------------------	-------

CERTIFICATE OF INSURANCE Pg. 1



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5094279334 Cover : drive CLASSIC

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SLP8803X |
| Chassis Number | : VF3CU9HP8EY002667 |
| 2. Name of Policyholder | : GEORGE123 |
| 3. Effective Date of Insurance | : 25 Sep 2017 |
| 4. Expiry Date of Insurance | : 24 Sep 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: YAP KWEE ENG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TAN WEI CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

[We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TAN WEI AUTO PTE. LTD. (00000572075)
 Date of Issue : 25 Sep 2017 10:41 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

HENDON AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands (S) 757322

Tel : 9459 2885

Fax: 6334 5178

Email: hendon.automotive@gmail.com

Date : 12/05/18

OUR REF : TP/SLP 8803X/18

M/S : GEORGE123

BLK 257 BANGKIT ROAD

#05-53

SINGAPORE 670257

Statement Of Claim On Veh No : SLP 8803X

MODEL : PEUGEOT 2008

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

\$12,100.00



Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



TAX INVOICE

Bill to : George123

C/O : Hendon Automotive Pte Ltd
280 Woodlands Industrial Park E5 #01-19
Harvest @ Woodlands
Singapore 757322
Tel: 9459 2885 Fax: 6334 5178
Contact: Lynn Sim HP:

Invoice No : TAS-1804-1137
Date : 20-Apr-18
Report No : T-HD-180327/8803X
Terms : COD

S/N	Descriptions	Amount (\$\$)
1	<p>Service Rendered In Respect of:</p> <p>Vehicle Number : SLP 8803 X Vehicle Make/Model : Peugeot 2008 Date of Inspection : 27-Mar-18 Date of Accident : 24-Mar-18</p> <p>Appraisal fees include transportation and follow-up inspection.</p> <p>Submission of appraisal report by hand.</p> <p>Photography services including storage of media and submission of color photograph copies by hand.</p> <p>SINGAPORE DOLLARS SEVEN HUNDRED AND EIGHTY-EIGHT ONLY</p>	\$ 788.00
Total		\$ 788.00

E. & O.E

All cheques should be crossed and made payable to "Treasure Appraisal Services".
All cheques should indicate our "Invoice No" on the reverse side of the cheque.

for Treasure Appraisal Services

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



VEHICLE ASSESSMENT REPORT

Report No : T-HD-180327/8803X
Date : 20-Apr-18

REFERENCE

Assigned By : George123
Name of Workshop : Hendon Automotive Pte Ltd
Place of Inspection : 280 Woodlands Industrial Park E5 #01-19 Harvest @ Woodlands Singapore 757322
Date of Assignment : 27-Mar-18
Date of Accident : 24-Mar-18
Date of Inspection : 27-Mar-18

PARTICULARS OF DAMAGED VEHICLE

Vehicle Reg No	: SLP 8803 X	Chassis No	: VF3CU9HP8EY002667
Year of Reg	: Jul-14	Odometer/km	: 108201
Make/Model	: Peugeot 2008	Engine No	: 10JBFN0023249
Vehicle Colour	: Grey	Engine Capacity	: 1560 cc
Vehicle Type	: Hatchback	Transmission Type	: Auto

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

General Condition	: Good		
Body Paint Work	: Good	Footbrake	: Serviceable
Steering	: Affected	Handbrake	: Serviceable
Front Undercarriage	: RHS Damaged	Rear Undercarriage	: Serviceable

TIRES CONDITION	Tire Brand	Size	Tread Balance
Front RH	: Yokohama	: 205/55 R16	: 80%
Rear RH	: Good Year	: 205/55 R16	: 80%
Front LH	: Yokohama	: 205/55 R16	: 80%
Rear LH	: Good Year	: 205/55 R16	: 80%

Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.
* Denotes damaged components.

SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the RHS multiple portions.

For further detail of the damages, please refer to our schedule and 93 pcs of surveyed photograph attached.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SLP 8803 X on 27-Mar-18 and in the accordance, we have carried out a physical assessment at your appointec workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for **SGD 16,401.10** as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to **SGD 15,067.10** and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of **SGD 12,100.00** nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our know.edge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,
Treasure Appraisal Services

Dixon-Yee T W
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage's should be notified to the company within **Fourteen (14) days** from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
 HP: (65) 9833 1618 Fax: (65) 6747 1017
 Email: treasureappraisal@gmail.com
 Reg No: 53218791A



APPRAISEMENT SCHEDULE

Vehicle Registration No: SLP 8803 X

Report No: T-HD-180327/8803X

S/N	Descriptions	Condition	Qty	Repairer's Estimate	Our Assessment
LIST ITEMS					
1	Front bumper cover	Damaged	1 pc	\$ 1,200.00	\$ 1,200.00
2	Front RH bumper retainer	Damaged	1 pc	\$ 80.00	\$ 80.00
3	Front RH fender panel	Damaged	1 pc	\$ 460.00	\$ 460.00
4	Front RH fender mud guard	Damaged	1 pc	\$ 190.00	\$ 190.00
5	Front RH fender mud guard clip	Necessary	1 set	\$ 35.00	\$ 35.00
6	Front RH shock absorber	Damaged	1 pc	\$ 450.00	\$ 450.00 XNH
7	Front RH shock absorber mounting	Damaged	1 pc	\$ 85.00	\$ 85.00 XNH
8	Front RH lower arm	Damaged	1 pc	\$ 380.00	\$ 380.00
9	Front RH knuckle arm	Damaged	1 pc	\$ 523.00	\$ 523.00
10	Front RH knuckle arm bearing	Necessary	1 pc	\$ 280.00	\$ 280.00
11	Front RH stabilizer link	Damaged	1 pc	\$ 180.00	\$ 180.00 XNH
12	Front RH side view mirror assy	Damaged	1 pc	\$ 358.00	\$ 358.00
13	Front RH door panel	Damaged	1 pc	\$ 1,350.00	\$ 1,350.00 repair
14	Front RH door black tape	Necessary	1 pc	\$ 125.00	\$ 125.00 XNH
15	Front RH door protector	Damaged	1 pc	\$ 145.00	\$ 145.00
16	RH side sill garnish assy	Damaged	1 pc	\$ 668.00	\$ 668.00
17	Rear RH door panel	Damaged	1 pc	\$ 1,250.00	\$ 1,250.00
18	Rear RH door black tape	Necessary	1 pc	\$ 115.00	\$ 115.00
19	Rear RH door protector	Damaged	1 pc	\$ 135.00	\$ 135.00
20	Rear RH door outer handle	Reusable	1 pc	\$ 75.00	\$. XNH
21	Rear RH door power window regulator assy	Damaged	1 pc	\$ 480.00	\$ 480.00
22	Rear RH door glass run	Damaged	1 pc	\$ 168.00	\$ 168.00 XNH
23	Rear RH door lock assy	Damaged	1 pc	\$ 365.00	\$ 365.00
24	Rear RH door striker	Reusable	1 pc	\$ 85.00	\$. XNH
25	Rear RH door checker	Damaged	1 pc	\$ 145.00	\$ 145.00 XNH
26	Rear RH quarter panel	Damaged	1 pc	\$ 1,500.00	\$ 1,500.00 repair
27	Rear RH quarter fixed glass moulding	Necessary	1 pc	\$ 152.00	\$ 152.00 XNH
				\$ 10,979.00	\$ 10,819.00
	Less Discount : 10%			\$ 1,097.90	\$ 1,081.90
	List Parts Sub-Total :			\$ 9,881.10	\$ 9,737.10
SPECIAL NETT ITEMS					
1	Windscreen sealant	Necessary	1 pc	\$ 150.00	\$ 120.00 XNH
2	Windscreen seal form	Necessary	1 pc	\$ 120.00	\$ 100.00 XNH
3	Sport wheel rim	Damaged	1 pc	\$ 550.00	\$ 550.00 300
4	Wheel tire (dep-20%)	Damaged	1 pc	\$ 300.00	\$ 240.00 168
	Special Nett Parts Total :			\$ 1,120.00	\$ 1,010.00
	Parts Total :			\$ 11,001.10	\$ 10,747.10

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
 HP: (65) 9833 1618 Fax: (65) 6747 1017
 Email: treasureappraisal@gmail.com
 Reg No: 53218791A



S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
1	To furnish towing service to workshop.	\$ 150.00	\$ 60.00
2	Re-focus headlamp assy set.	\$ 60.00	\$ 40.00 X
3	Diagnose, replace and/or repair to rectify front electrical system for proper functioning.	\$ 60.00	\$ 40.00 } 40
4	Diagnose, replace and/or repair to rectify rear electrical system for proper functioning.	\$ 60.00	\$ 40.00 }
5	Transfer front RHS door mechanism, door glass and wiring assy to facilitate body repairs.	\$ 150.00	\$ 120.00 X
6	Transfer rear RHS door mechanism, door glass and wiring assy to facilitate body repairs.	\$ 150.00	\$ 120.00 60
7	Dismantle replace and/or re-install rear RHS quarter glass assy to facilitate body repairs.	\$ 150.00	\$ 120.00 X
8	Dismantle, replace, repair and/or re-install front RHS undercarriage suspension and drive train system.	\$ 350.00	\$ 300.00 150
9	Conduct computerise wheel alignment, adjustments, measurement and rectification to specification.	\$ 150.00	\$ 120.00 60
10	Dismantle and re-install rear interior upholstery; trimming and garnish/es to facilitate body repairs.	\$ 200.00	\$ 180.00 X
11	To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,600.00	\$ 1,200.00 900
12	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.	\$ 1,800.00	\$ 1,600.00 1200
13	To furnish and apply under-sealing & rust proofing coats on accident affected area.	\$ 400.00	\$ 320.00 100
14	Conduct water leakage tests to ensure proper air and water sealing.	\$ 120.00	\$ 60.00 30
Labour Total :		<u>\$ 5,400.00</u>	<u>\$ 4,320.00</u>
Parts & Labour Total :		<u>\$ 16,401.10</u>	<u>\$ 15,067.10</u>

L/S

7 days

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



Note: The repairer has agreed to undertake the repairs at our adjusted amount of **SGD 12,100.00** on a ***Contractual Lump Sum Basis** corresponding to supply of all parts, labour and spray painting charges.

N.B: *Under Contractual Lump Sum Basis, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Eight (8)** working days. Pursuant to your instruction, we have **NOT AUTHORISED** the repairs on your behalf

Treasure Appraisal Services



Bixun Yeap W
Automobile Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS3/AXA18005955/R1sbs2-1	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 08-10-2018	
ATTN: XINYOU		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SHC 5211P	Veh. Inspected	SLP 8803X
Policy No.	P1680520	Coverage (\$)	0.00
Claim No.	C0472689	Excess (\$)	0.00
Assign From	CHEN XINYOU	Assign Date	06/07/2018
2. Vehicle Particulars & Condition			
Make & Model	PEUGEOT 2008 1.6	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF3CU9HP8EY002667	Colour	GREY
Odometer	125359	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	24/03/2018	Inspection Date	13/07/2018
Survey held at	HENDON AUTOMOTIVE 280 WOODLANDS IND PARK E5 #01-11 SINGAPORE 757322		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8803X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	REPLACED	1,200.00	1,200.00
1	FRONT RH BUMPER RETAINER	REPLACED	80.00	80.00
1	FRONT RH FENDER PANEL	REPLACED	460.00	460.00
1	FRONT RH FENDER MUD GUARD	REPLACED	190.00	190.00
1	SET FRONT RH FENDER MUD GUARD CLIP	REPLACED	35.00	35.00
1	FRONT RH SHOCK ABSORBER	NOT CHANGED	450.00	-
1	FRONT RH SHOCK ABSORBER MOUNTING	NOT CHANGED	85.00	-
1	FRONT RH LOWER ARM	REPLACED	380.00	380.00
1	FRONT RH KNUCKLE ARM	REPLACED	523.00	523.00
1	FRONT RH KNUCKLE ARM BEARING	REPLACED	280.00	280.00
1	FRONT RH STABILIZER LINK	NOT CHANGED	180.00	-
1	FRONT RH SIDE VIEW MIRROR ASSY	REPLACED	358.00	358.00
1	FRONT RH DOOR PANEL	REPAIRED SEE LABOUR	1,350.00	-
1	FRONT RH DOOR BLACK TAPE	NOT CHANGED	125.00	-
1	FRONT RH DOOR PROTECTOR	REPLACED	145.00	145.00
1	RH SIDE SILL GARNISH ASSY	REPLACED	668.00	668.00
1	REAR RH DOOR PANEL	REPLACED	1,250.00	1,250.00
1	REAR RH DOOR BLACK TAPE	REPLACED	115.00	115.00
1	REAR RH DOOR PROTECTOR	REPLACED	135.00	135.00
1	REAR RH DOOR OUTER HANDLE	NOT CHANGED	75.00	-
1	REAR RH DOOR POWER WINDOW REGULATOR ASSY	REPLACED	480.00	480.00
1	REAR RH DOOR GLASS RUN	NOT CHANGED	168.00	-
1	REAR RH DOOR LOCK ASSY	REPLACED	365.00	365.00
1	REAR RH DOOR STRIKER	NOT CHANGED	85.00	-
1	REAR RH DOOR CHECKER	NOT CHANGED	145.00	-
1	REAR RH QUARTER PANEL	REPAIRED SEE LABOUR	1,500.00	-
1	REAR RH QUARTER FIXED GLASS MOULDING	NOT CHANGED	152.00	-
	LESS 10% DISCOUNT		-1,097.90	-666.40
			9,881.10	5,997.60

Report Ref No. CS3/AXA18005955/R1sbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>SPECIAL NETT ITEMS</u>				
1	WINDSCREEN SEALANT (SN)	NOT CHANGED	150.00	-
1	WINDSCREEN SEAL FORM (SN)	NOT CHANGED	120.00	-
1	SPORT WHEEL RIM (SN)	REPLACED	550.00	300.00
1	WHEEL TIRE (@ \$240.00 DISC 70%) (SN)	REPLACED	300.00	168.00
			1,120.00	468.00
<u>LABOUR</u>				
	TO FURNISH TOWING SERVICE TO WORKSHOP.		150.00	60.00
	RE-FOCUS HEADLAMP ASSY SET.	NOT NECESSARY	60.00	-
	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. }		60.00	40.00
	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. }		60.00	-
	TRANSFER FRONT RHS DOOR MECHANISM, DOOR GLASS AND WIRING ASSY TO FACILITATE BODY REPAIRS.	NOT NECESSARY	150.00	-
	TRANSFER REAR RHS DOOR MECHANISM, DOOR GLASS AND WIRING ASSY TO FACILITATE BODY REPAIRS.		150.00	60.00
	DISMANTLE REPLACE AND/OR RE-INSTALL REAR RHS QUARTER GLASS ASSY TO FACILITATE BODY REPAIRS.	NOT NECESSARY	150.00	-
	DISMANTLE, REPLACE, REPAIR AND/OR RE-INSTALL FRONT RHS UNDERCARRIAGE SUSPENSION AND DRIVE TRAIN SYSTEM.		350.00	150.00
	CONDUCT COMPUTERISE WHEEL ALIGNMENT, ADJUSTMENTS, MEASUREMENT AND RECTIFICATION TO SPECIFICATION.		150.00	60.00
	DISMANTLE AND RE-INSTALL REAR INTERIOR UPHOLSTERY; TRIMMING AND GARNISH/ES TO FACILITATE BODY REPAIRS.	NOT NECESSARY	200.00	-
	TO CARRY OUT ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND/OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR PANEL AND REAR RH QUARTER PANEL.		1,600.00	900.00

Report Ref No. CS3/AXA18005955/R1sbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON AFFECTED AREAS.		1,800.00	1,200.00
	TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA.		400.00	100.00
	CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND WATER SEALING.		120.00	30.00
			5,400.00	2,600.00
	GRAND TOTAL		16,401.10	9,065.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,250.00

Report Ref No. CS3/AXA18005955/R1sbs2-1

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT NOT AGREED WITH OUR OFFER

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.