

22/03/2018

ASS. REC. BY:

REF: CS/FCI18012592/T1sd3ⁿ²

Special Instruction:

Surveyor:

Tiquah

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

11/7/18 @ 9:59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 4315P

Insured:

SHD 6918Y

at Workshop m/s

3A Automobile

Tel:

62231122

of

120 Lower Delta Rd # 02-15

Policy No:

Claim No:

D18005260 MFSA

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Sup

H.O.D. Endorsement:

Date/Time:

10:15am @ 11/7/18

Person Contacted:

Winnie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 4315P - CC3/AIG18012174/NWA3

DOA: 2/7/2018

SHD 6918Y - CC3/AIG18012174/NWA3

DOA: 2/7/2018

13/07/18

@ 13:24 p.m. revised PA to Glen via email.

Signature

Tanjin

REF:

FC1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SKD 4315P

Yr Regn: 2011 / Nov.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Citroen Grand C4

c.c 1598

Colour

Blue.

A/C Insured / Std / NI / NA

Sp. Reading

119771

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF 7445 FV 8B-37 62857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/7/18 01040

Survey held at

3A Auto

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5/14 00, 4 days

(\$ 5,074.40 Red - 78%)

RECEIVED 27 AUG 2010

Date/Time, File Pass to?

27/02/18
Typist

1)

Date/Time, File Return to?

2)



: Preli. Report

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

: S + RS: SI

: Photos

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 1,400/- 4/5)

145

50

50

41

286



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005260MFSH

Date: 13 July 2018

Our Ref: CS/FCI18012592/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKD 4315P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/07/2018 at the premises of M/s 3A Automobile Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,474.40</u>
Revised Estimate Amount	: S\$ <u>1,828.80</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-07-2018	Our Ref No. D18005260MFSH
Accident Date	02-07-2018	Claim Type. Third Party
Insured Vehicle	SHD6918Y	Third Party Vehicle. SKD4315P
Survey Location	120 LOWER DELTA ROAD #02-15 CENDEX CENTRE	
Contact Person.	WINNIE FAN	
Contact No.	62231122/ 0	Fax No. 67386666
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	3A AUTOMOBILE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242151)



PRI Documents



Close



PRI Header Details

Claim No	D18005260MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & 3A AUTOM
Workshop Name	3A AUTOMOBILE PTE LTD (Contact Person : WINNIE FAN)	Survey Location & Contact Details	120 LOWER DELTA ROAD #02-15 CENDEX CENTRE Mobile: 0 , Phone: 62231122 , Fax: 67386666 EmailId: WINNIE.FAN@BKW.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6918Y	TP Vehicle No	SKD4315P
PRI Recieved Date	06-07-2018 09:08:54 PM	Surveyor Appointed Date	11-07-2018 09:58:09 AM	Surveyor Accept Date	11-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shirley Hiew (LKK Auto)

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Thursday, 26 July 2018 9:37 AM
To: 'Winnie Fan'
Cc: 'Shirley Hiew (LKK Auto)'
Subject: RE: After repair photos for SKD 4315 P

Hi Winnie,

COR lumpsum \$1400 , 4 days.

Regards
Taufikh
Lkk Auto

From: Winnie Fan [mailto:winnie.fan@bkw.sg]
Sent: Tuesday, 24 July 2018 5:23 PM
To: Taufikh (LKKAuto); SUR
Subject: After repair photos for SKD 4315 P

Hi Taufikh,

Attached is the after repair photos for SKD 4315 P you surveyed on 11/07/2018.

Please let us have the finalise amount ASAP.

Thank you and have a wonderful day! ☺

Winnie Fan
3A Automobile Pte Ltd
120 Lower Delta Road
#02-15 Cendex Centre
Singapore 169208



Office : 6223 1122



Fax : 6738 6666



Email : winnie.fan@bkw.sg

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 13 July 2018 1:24 PM
To: EILEENLEE@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005260MFSH/1
Attachments: SKD 4315P - Preli Advise.pdf

Dear Eileen,

Enclosed preliminary revised for SKD 4315P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 11 July 2018 10:21 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005260MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 11 July 2018 9:59 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005260MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

Date: 9-Jul-2018

MS First Capital Insurance Ltd

36 Robinson Road

#16-01

Singapore 068877

Email: MotorClaims@msfirstcapital.com.sg

Attn: Claims Officer

Dept: Motor Claim Department

Vehicles Number: SKD 4315 P

Make and Model: Citroen Grand C4 Picasso 1.6

Date Of Accident: 2-Jul-2018

Tel: 65073848

Fax: 65073849

Unit	List Items	Units Price	Prices
1 pc	Front Left Door	\$ 1,545.00	\$ <i>Ry</i> 1,545.00
1 pc	Front Left Door Protector	\$ 148.00	\$ <i>at</i> 148.00
1 pc	Front Left Fender	\$ 482.00	\$ <i>Ry</i> 482.00
8 pcs	Front Inner Shield Clips	\$ 2.00	\$ <i>X n n</i> 16.00
1 pc	Rear Left Fender	\$ 1,528.00	\$ <i>Ry</i> 1,528.00
1 pc	Rear Left Door	\$ 1,345.00	\$ <i>Ry</i> 1,345.00
1 pc	Rear Left Door Protector	\$ 138.00	\$ <i>int</i> 138.00
8 pcs	Rear Inner Shield Clips	\$ 2.00	\$ <i>X n n</i> 16.00
S/Total			\$ 5,218.00
Less 20% 10%			(\$1,043.60)
			\$ 4,174.40

Labour Charges

To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint On All Affected Areas with Oven Spray Booth Facilities.	\$ 800 <i>900</i>	1,100.00
To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts.	\$ 700	1,200.00
Total	\$	6,474.40

Yours faithfully,

3A Automobile Pte Ltd

Person to contact: Johnny / Winnie

Mobilephone : 9786 8677 / 6223 1122

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey after repair
sur @ lkkauto.com
4 days

6996.20
Tauphin 274 15749
WP
11/7/18 @ 1040

1757.40

1/8/1400

16/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012592/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6918Y	Veh. Inspected	SKD 4315P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005260MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN GRAND C4	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	VF7UA5FV8BJ762857	Colour	BLUE	
Odometer	119771	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	NEXEN	6 mm	
L/H Front Tyre	215/50 R17	NEXEN	6 mm	
R/H Rear Tyre	215/50 R17	NEXEN	6 mm	
L/H Rear Tyre	215/50 R17	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2018	Inspection Date	11/07/2018	
Survey held at	3A AUTOMOBILE PTE LTD BLK 120 LOWER DELTA ROAD #02-15 SINGAPORE 169208			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 4315P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LEFT DOOR	TO REPAIR SEE LABOUR	1,545.00	-
1	FRONT LEFT DOOR PROTECTOR	CUT	148.00	148.00
1	FRONT LEFT FENDER	TO REPAIR SEE LABOUR	482.00	-
8	FRONT INNER SHIELD CLIPS @\$2.00	NOT NECESSARY	16.00	-
1	REAR LEFT FENDER	TO REPAIR SEE LABOUR	1,528.00	-
1	REAR LEFT DOOR	TO REPAIR SEE LABOUR	1,345.00	-
1	REAR LEFT DOOR PROTECTOR	CUT	138.00	138.00
8	REAR INNER SHIELD CLIPS @\$2.00	NOT NECESSARY	16.00	-
	LESS 10% DISCOUNT		-521.80	-28.60
			4,696.20	257.40
LABOUR				
	TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON ALL AFFECTED AREAS WITH OVEN SPRAY BOOTH FACILITIES.		1,100.00	800.00
	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE,INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS,JACK,PANEL BEAT & RESHAPE THE AFFECTED PARTS & CPMONENTS.CORRECT & REALIGN THE NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT LEFT DOOR,FRONT LEFT FENDER,REAR LEFT FENDER AND REAR LEFT DOOR.		1,200.00	700.00
			2,300.00	1,500.00
GRAND TOTAL			6,996.20	1,757.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/FCI18012592/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.