

ASS. REC. BY:

REF

CS3/MSG18012597/ Gz4d3⁵⁷

Special Instructions:

Surveyor
menimen

From (Person):

Guo Chany
Lionel fan

ASSIGNMENT (Office)

MSG

Date/Time: 10/7/18 @ 4:18pm

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

PC3006J

Insured:

SGC7771M

at Workshop m/s:

MSM Logistics

Tel:

9107 4212

of 160 Kin Ming Drive # 03-08

Policy No:

28861316 QMX

Claim No:

563835

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/07/2015

CA / REV / REP. / REV 24 HRS

Cup?

H.O.D. Endorsement:

Date/Time:

9:37am @ 11/7/18

Person Contacted:

Mr. Siew

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	PC 3006J - NA/INC150/5879/e	DOA: 18/09/2015
	SGC 7771M - X	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18012597/Gz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-07-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGC 7771M	Veh. Inspected	PC 3006J
Policy No.	28861316QMX	Coverage (\$)	0.00
Claim No.	563835	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	11/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/07/2018	Inspection Date	11/07/2018
Survey held at	160 SIN MING DRIVE # 03-08		
Repairer	MSM LOGISTICS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		10 Jul 2018 16:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHAN WAI MENG, ID: S7106690H, Tel: +6590181288		
Main Claimant:	ALBERT PANG TRANSPORT, Co. Reg. No.: 52922438X		
Vehicle Reg. No.:	PC3006J	Date of Loss:	07/07/2018 21:00 - :59 [40 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563835	Policy/Cover Note No.:	28861316QMX (Comprehensive) Coverage: 30/12/2017 - 29/12/2018
Vehicle Reg. No. (Insured):	SGC7771M	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/07/2018]		
Driver/Custodian (Insured):	CHAN WAI MENG (47 / Male), NRIC: S7106690H, Tel: +6590181288		
Adj Asg. Remarks:	SJE - DISAGREED Liability : NOT CLEAR Please appoint LKK AUTO to conduct the survey , Kindly contact MR SIEW @ 9849 6649 / 9107 4212 to arrange for survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2438X
Vehicle Details	
Vehicle No.:	PC3006J
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	ISUZU
Vehicle Model:	LT434P 7.8 SMT
Primary Colour:	Multi-Colour
Manufacturing Year:	2014
Engine No.:	6HK1662872
Chassis No.:	JALLT434PE7000075
Maximum Power Output:	-
Open Market Value:	\$96,164.00
Original Registration Date:	17 Feb 2015
First Registration Date:	17 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$4,809.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Feb 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,101.00
COE Rebate Amount:	\$34,295.00
Total Rebate Amount:	\$34,295.00

The information contained herein is correct as at 18 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		10 Jul 2018 16:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAN WAI MENG , ID: S7106690H, Tel: +6590181288		
Main Claimant:	ALBERT PANG TRANSPORT , Co. Reg. No.: 52922438X		
Vehicle Reg. No.:	PC3006J	Date of Loss:	07/07/2018 21:00 - :59 [40 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563835	Policy/Cover Note No.:	28861316QMX (Comprehensive) Coverage: 30/12/2017 - 29/12/2018
Vehicle Reg. No. (Insured):	SGC7771M	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 11/07/2018]		
Driver/Custodian (Insured):	CHAN WAI MENG (47 / Male), NRIC: S7106690H, Tel: +6590181288		
Adj Asg. Remarks:	SJE - DISAGREED Liability : NOT CLEAR Please appoint LKK AUTO to conduct the survey . Kindly contact MR SIEW @ 9849 6649 / 9107 4212 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***PC3006J (563835)**
[SGC7771M]
TP
ALBERT PANG TRANSPORT
Jul 7 2018 9:00PM
[CHAN WAI MENG]
Msm Logistics Pte Ltd- Sin Ming

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 10:05	General View	1 Load JPG	✓
2	18/07/18 10:05	General View	1 Load JPG	✓
3	18/07/18 10:05	General View	1 Load JPG	✓
4	18/07/18 10:05	General View	1 Load JPG	✓
5	18/07/18 10:05	General View	1 Load JPG	✓
6	18/07/18 10:05	General View	1 Load JPG	✓
7	18/07/18 10:05	General View	1 Load JPG	✓
8	18/07/18 10:05	General View	1 Load JPG	✓
9	18/07/18 10:05	General View	1 Load JPG	✓
10	18/07/18 10:05	General View	1 Load JPG	✓
11	18/07/18 10:05	General View	1 Load JPG	✓
12	18/07/18 10:05	General View	1 Load JPG	✓
13	18/07/18 10:05	General View	1 Load JPG	✓
14	18/07/18 10:05	General View	1 Load JPG	✓
15	18/07/18 10:05	General View	1 Load JPG	✓
16	18/07/18 10:05	General View	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 11:54	OI SGC7771M GIA REPORT	1 Load PDF	
2	10/07/18 11:54	TPD PC3006J GIA REPORT	1 Load PDF	
3	10/07/18 11:54	TPD PC3006J - PRI	1 Load PDF	
4	10/07/18 11:54	Reject email to TP Lawyer & appoint LKK AUTO - PC3006J	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012597/GZ4D3S2

Date: 18/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28861316QMX

Claimant Vehicle No : PC3006J

Insured Vehicle No : SGC7771M

Date of Loss: 07/07/2018

Nature of Claim: TP

Claim No: 563835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC3006J

Make & Model: ISUZU LT434P 7.8 SMT, 7.8 D (M)

Engine No: 6HK1662872

Reg. Date: 17/02/2015 (Man. Year: 2014)

Chassis No: JALLT434PE7000075

Colour: White

Odometer: 178035 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6/6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 11/07/2018 Inspected At:

Msm Logistics Pte Ltd- Sin Ming (HQ)
160 Sin Ming Drive #03-08 Sin Ming Auto City
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jul 2018)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3006J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >