(08/11/13) wef

ASS. REC. BY:

REF: LCR

ASSIGNMENT

From: Date: 17/07/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 5197A

at Workshop m/s BH Auto

of Blk 1, Sector C Sin Ming Ind. Est #01-111

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record) 10:30am @ owner waiting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wps

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLV 5197A Yr Regn: 12 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A) Wagon

Make: Toy Voxy c.c 1797

Colour M.D. Green A/C: Insured / Std / NI / NA

Sp.Reading 8368 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZWR80 · 0283845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.	9/7/18	D.O.I.	17/7/18

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/7	File pass to Catherine, parts prices not ready

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL