22/03/2002

ASS. REC. BY: | REF: CS3/CTI18012630/ G 24d3ck | Special Instruction:

Surveyor: Mennen Guocheng

ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 11/7/18 @ 3:16pm

Estimated Cost: Bill to:

~~OD~~ / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCL 251T Insured: PC2837J

at Workshop m/s King's Auto Tel: 6457 8629

of Blk 176, Sin Ming Drive #02-10

Policy No: DMBISN3088321700 Claim No: SNM18D03344C02

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 30/06/2018

12/07/2018

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 3:39pm @ 11/7/18 Person Contacted: Alex Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SCL 251T - X
	PC2837J - CC1/AXAH013765/T1yb33 2 DOA: 5/7/2017
	Dismantle: 16/7/2018

(08/11/13) wef YRS

ASS. REC. BY: XNL

REF: CTI

ASSIGNMENT

From: _____ Date: 12/07/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCL 251T

at Workshop m/s King's Auto

of BIK 176 Sin Ming Drive #02-10

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Alex @ 61578629

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCL251T Yr Regn: Feb 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Subaru c.c 2457

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 116833 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1BP9KV57G054905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/45 R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	12-07-18

Survey held at W/S 5:30pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range $3,000 – $4,000.

8/8/2018

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : PRS

Lump Sum / I.B.I: ($ _____)

Survey Fee:	150
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	150

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18012630/Gz4d3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 11-07-2018

Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	PC 2837J	**Veh. Inspected**	SCL 251T
	Policy No.	DMB1SN3088321700	**Coverage ($)**	0.00
	Claim No.	SNM18D03344C02	**Excess ($)**	0.00
	Assign From	MERIMEN (IRENE TAY)	**Assign Date**	11/07/2018

2. Vehicle Particulars & Condition

	Make & Model		**c.c**	0
	Engine No.	HIDDEN	**Year of Reg.**	
	Chassis No.		**Colour**	
	Odometer	-	**Steering**	
	Brakes		**Modification**	
	General			

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	30/06/2018	**Inspection Date**	12/07/2018
	Survey held at	KING'S AUTO AIR-CONDITIONING SERVICE BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2018		12 Jul 2018 10:11 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**JING MA PTE LTD,** Co. Reg. No.: 201603182M		
Main Claimant:	**THEVATHASAN IVOR GUNASEELAN**		
Vehicle Reg. No.:	**SCL251T**	Date of Loss:	28/06/2018 13:00 - :59
Claim Type:	**TP** / SNM18D03344C02	Policy/Cover Note No.:	DMB1SN3088321700 (Comprehensive)
Vehicle Reg. No. (Insured):	**PC2837J**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**King's Auto Air-Conditioning Service (HQ)** Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 23/07/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 11 July 2018 3:16 PM
To: Kuru & Co
Cc: Lucas Lee; assignments@lkkauto.com
Subject: RE: PRI of SCL251T (CTI REF: SNM18D03344C02) (YrRef:L18.1075.cj)

WITHOUT PREJUDICE

Dear Irene,

We refer to the above matter and telephonic conversation a moment ago.

We will appoint our surveyor, **LKK** to liasie with you.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com

Disclaimer :
This message is confidential: its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Wednesday, 11 July, 2018 2:10 PM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: PRI of SCL251T (CTI REF: SNM18D03344C02) (YrRef:L18.1075.cj)

WITHOUT PREJUDICE

Dear Lucas/Irene

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert **or** that you are objecting to our client's proposed list of surveyors.

If we do not hear from you **within 2 working days,** it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 11 July 2018, 12:07:33 PM SGT, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Tuesday, 10 July, 2018 4:30 PM
To: Claims Dept of CTI
Subject: PRI 1 - L18.1075.cj /ACCIDENT INVOLVING SCL 251T & PC 2837J ON 30/06/18 ALONG QUEEN ST LEFT TURN TO STAMFORD ROAD NOTIFCATION OF ACCIDENT AND PRE-REPAIR SURVEY

ACCIDENT INVOLVING SCL 251T & PC 2837J ON 30/06/18

ALONG QUEEN ST LEFT TURN TO STAMFORD ROAD

NOTIFCATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **THEVATHASAN IVOR GUNASEELAN,** whose vehicle registration number **SCL251T** was damaged in the above accident.

A copy of the Singapore Accident Statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

Nivitha (LKK Auto)

From: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Wednesday, 11 July 2018 3:33 PM
To: Irene Tay
Cc: Lucas Lee; assignments@lkkauto.com
Subject: Re: RE: PRI of SCL251T (CTI REF: SNM18D03344C02) (YrRef:L18.1075.cj)

WITHOUT PREJUDICE

Hi Irene

We refer to your email of 11.07.18.

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

KING'S AUTO AIR-CONDITIONING SERVICE

Blk 176 Sin Ming Drive #02-10 Sin Ming Autocare
Singapore 575721

Tel: Annie 64578629

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 11 July 2018, 3:16:00 PM SGT, Irene Tay <irene.tay@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Irene,

We refer to the above matter and telephonic conversation a moment ago.

We will appoint our surveyor, **LKK** to liasie with you.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192
Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Wednesday, 11 July, 2018 2:10 PM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: PRI of SCL251T (CTI REF: SNM18D03344C02) (YrRef:L18.1075.cj)

WITHOUT PREJUDICE

Dear Lucas/Irene

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert **or** that you are objecting to our client's proposed list of surveyors.

If we do not hear from you **within 2 working days,** it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 11 July 2018, 12:07:33 PM SGT, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG

KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Tuesday, 10 July, 2018 4:30 PM
To: Claims Dept of CTI
Subject: PRI 1 - L18.1075.cj /ACCIDENT INVOLVING SCL 251T & PC 2837J ON 30/06/18 ALONG QUEEN ST LEFT TURN TO STAMFORD ROAD NOTIFCATION OF ACCIDENT AND PRE-REPAIR SURVEY

ACCIDENT INVOLVING SCL 251T & PC 2837J ON 30/06/18

ALONG QUEEN ST LEFT TURN TO STAMFORD ROAD

NOTIFCATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **THEVATHASAN IVOR GUNASEELAN,** whose vehicle registration number **SCL251T** was damaged in the above accident.

A copy of the Singapore Accident Statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SCL251T
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	SUBARU
Vehicle Model :	LEGACY WAGON 2.5GT AWD 5AT ABS
Chassis No. :	JF1BP9KV57G054905
Propellant :	Petrol
Engine No. :	EJ25D074624
Engine Capacity :	2457 cc
Maximum Power Output :	184.0 kW (246 bhp)
Maximum Laden Weight :	1785 kg
Unladen Weight :	1510 kg
Year Of Manufacture :	2007
Original Registration Date :	01 Feb 2010
Lifespan Expiry Date :	-
COE Category :	E - Open Category
Quota Premium :	$19,000.00
COE Expiry Date :	31 Jan 2020
Road Tax Expiry Date :	31 Jul 2018
PARF Eligibility Expiry Date :	31 Jan 2020
Inspection Due Date :	31 Jan 2019
Intended Transfer Date :	26 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 31 Jul 2018. You may renew the road tax from 01 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 31 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 01 Aug 2018 to 31 Jan 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	875.00	-	875.00
Total Amount Payable :			**900.00**

Amount Payable (From 01 Aug 2018 to 31 Jul 2019)

	Amount Before GST (S$)	GST Amount (S$)	Amount After GST (S$)
Transfer Fee :	25.00	-	25.00
Sub Total :			**25.00**
Nett Road Tax Amount (After Offsetting Over Payment) :	1,750.00	-	1,750.00
Total Amount Payable :			**1,775.00**

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4627I
Vehicle Details	
Vehicle No.:	SCL251T
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	SUBARU
Vehicle Model:	LEGACY WAGON 2.5GT AWD 5AT ABS
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	EJ25D074624
Chassis No.:	JF1BP9KV57G054905
Maximum Power Output:	184.0 kW (246 bhp)
Open Market Value:	$30,902.00
Original Registration Date:	01 Feb 2010
First Registration Date:	01 Feb 2010
Transfer Count:	0
Actual ARF Paid:	$30,902.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jan 2020
PARF Rebate Amount:	$16,996.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	$19,000.00
COE Rebate Amount:	$2,718.00
Total Rebate Amount:	**$19,714.00**

The information contained herein is correct as at 08 Aug 2018

OK

Atta Ann Active. PRI King's Auto

To UCK

MOR118086767 / ETHOZ Protect Pte Ltd - Bukit Batok
ENTRY DATE & TIME: 05/07/2018 15:57
SUBMITTED BY: Haibullah Bin Maspot

Your NCD will be affected due to late reporting
Actual e-Filling Submission Date & Time: 05/07/2018 16:25

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/07/2018 15:57
Date Of Accident	30/06/2018 13:00
Exact Location Of Accident	ALONG QUEEN ST LEFT TURN TO STAMFORD RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCL251T
Insured/Policyholder	
Name Of Registered Owner	THEVATHASAN IVOR GUNASEELAN
NRIC No	S1114627I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96783458
Alternative Phone No	HOME-96783458
Vehicle Particulars	
Manufacturer	SUBARU
Model	LEGACY WAGON 2.5GT AWD 5AT ABS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	GA315824
Cover Note Number	
Driver	
Name of Driver	THEVATHASAN IVOR GUNASEELAN
NRIC No	S1114627I
Date Of Birth	18/08/1940
Occupation	INDOOR
Date Of Driving Pass	19/12/1960
Driving Experience	57 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96783458
Fax Number	
Contact Number	HOME-96783458
EMail Address	NOEMAIL

Address	1 GREENRIDGE CRESENT SINGAPORE 598889
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE POST
Police Station Address	**ROAD**: BLK 1 TOH YI DRIVE , **POSTCODE**: 590001 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: 1800-4689999 - **FAX NO**: 64623782
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC2837J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 4

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that.

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed.

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 5/7/18
1615hrs.

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Report Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT.

Important:		
You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.		- Reporting Only
		- Claim OD
		- Claim TP
	✓	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

5/7/18 1615 HRS

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

Sketch Plan Pg. 5

SINGAPORE POLICE FORCE

T/20180703/2090

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

Report No. T/20180703/2090

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
03/07/2018 15:41		30

Informant's Particulars

Name of Informant: THEVATHASAN IVOR GUNASEELAN			Address: 1 GREENRIDGE CRESCENT SINGAPORE 598889	
ID Type / ID No.: NRIC NO / S1114627I			Contact No.: Home/Office:	Mobile: 96783458
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 77	Date of Birth: 18/08/1940	Type of Informant: Driver	
Race: Sri Lankan-Indian			Language: English	Institution / School Name:
Occupation: MEDICAL DOCTOR			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 30/06/2018 13:00	Type of Location:
Location: Along Road 1 QUEEN STREET Left turn to Stamford Road				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
PC2837J	Bus/Coach/Minibus				Slightly Damaged	0
SCL251T	Car	SUBARU	LEGACY WAGON 2.5GT AWD 5AT ABS	Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date

Sketch Plan Pg. 6

SINGAPORE POLICE FORCE

T/20180703/2090

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

Report No. T/20180703/2090

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SCL251T	AXA INSURANCE SINGAPORE PTE LTD	GA315824	01/02/2018	31/01/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	THEVATHASAN IVOR GUNASEELAN		ID No.	S1114627I
Related Vehicle	SCL251T (Car)		Contact No.	96783458
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 30/06/2018 at about 1300hrs, I was driving on the right lane on Stamford Road towards Queen Street. There are 3 lanes on the road. After I completed the right turn to Queen St, I heard a bang and realized a private bus from the extreme left lane turned and hit onto the left rear of my car.

After which, we stopped along the bus stop and the bus driver said that I was in the wrong. Subsequently, a driver (witness) came over and talked to the bus driver and said that he was at fault for wrong judgement. The witness has a Car camera installed. My car left rear was damaged and nobody was injured.

I am lodging this report for insurance claims.

SINGAPORE POLICE FORCE

T/20180703/2090

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

Report No. T/20180703/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: D / Sgt 2 EUGENE TAN WEI JIE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/07/2018 15:41
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:

Authentication Stamp
SN 38

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2018		12 Jul 2018 10:11 Edit Adj Rpt	**S$0.00** Edit Estimates	**S$0.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	**JING MA PTE LTD**, Co. Reg. No.: 201603182M		
Main Claimant:	**THEVATHASAN IVOR GUNASEELAN**		
Vehicle Reg. No.:	**SCL251T**	Date of Loss:	28/06/2018 13:00 - :59 [**100** Months and **27** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / SNM18D03344C02	Policy/Cover Note No.:	DMB1SN3088321700 (Comprehensive)
Vehicle Reg. No. (Insured):	**PC2837J**	Policy No. (Claimant):	
		Excess:	S$0.00
Repairer:	**King's Auto Air-Conditioning Service (HQ)** Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629		
Handling Insurer:	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... [**Final Rpt** due 23/07/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SCL251T (SNM18D03344C02)**
[PC2837J]
TP
THEVATHASAN IVOR GUNASEELAN
Jun 28 2018 1:00PM
[JING MA PTE LTD]
King's Auto Air-Conditioning Service

Upload Documents | Upload Photos | Compose New Letter — View: View in Browser

Assessment Reports			1 per page		
No	Finalized On	**UCB Engineering Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	05/07/18 14:14	**Accident Statement**		Load HTM	
Photos/Images			3 per page		
No	Finalized On	**UCB Engineering Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	05/07/18 14:11	**Accident Photo** [Linked Accident Report Documents]		Load JPG	
2	05/07/18 14:11	**Accident Photo** [Linked Accident Report Documents]		Load JPG	
3	05/07/18 14:11	**Accident Photo** [Linked Accident Report Documents]		Load JPG	
4	05/07/18 14:11	**Accident Photo** [Linked Accident Report Documents]		Load JPG	
5	05/07/18 14:11	**Accident Photo** [Linked Accident Report Documents]		Load JPG	
6	05/07/18 14:11	**Driving License** [Linked Accident Report Documents]		Load JPG	
No	**Relabel/Reorder**	**LKK Auto Consultants Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	08/08/18 15:02	**General View**		Load PDF	
2	08/08/18 15:02	**Photographs of Damaged Parts**		Load PDF	
Documentation			1 per page		
No	Finalized On	**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**		**Thumbnail**	**Print**
1	12/07/18 10:10	**PRS**		Load PDF	
2	12/07/18 10:11	**OI GIA**		Load PDF	
No	Finalized On	**UCB Engineering Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	05/07/18 14:11	**Sketch Plan** [Linked Accident Report Documents]		Load JPG	
2	05/07/18 14:11	**Sketch Plan #2** [Linked Accident Report Documents]		Load JPG	

Linked Accident Report Documents

View: View in Browser

Assessment Reports			1 per page		
No	Finalized On	**UCB Engineering Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	05/07/18 14:14	**Accident Statement**		Load HTM	
Photos/Images			3 per page		
No	Finalized On	**UCB Engineering Pte Ltd (HQ)**		**Thumbnail**	**Print**
1	05/07/18 14:11	**Accident Photo**		Load JPG	
2	05/07/18 14:11	**Accident Photo**		Load JPG	
3	05/07/18 14:11	**Accident Photo**		Load JPG	
4	05/07/18 14:11	**Accident Photo**		Load JPG	
5	05/07/18 14:11	**Accident Photo**		Load JPG	
6	05/07/18 14:11	**Driving License**		Load JPG	

Assessment Reports			1 per page		☑
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
Documentation			1 per page		☑
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
1	05/07/18 14:11	**Sketch Plan**	1	Load JPG	☑
2	05/07/18 14:11	**Sketch Plan #2**	1	Load JPG	☑

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18012630/GZ4D3E2
Date: 10/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3088321700		
Claimant Vehicle No :	SCL251T	**Insured Vehicle No :**	PC2837J		
Date of Loss:	28/06/2018	Nature of Claim:	TP	Claim No:	SNM18D03344C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SCL251T**		
Make & Model:	SUBARU LEGACY, 2.5 GT WAGON TURBO (A)	Engine No:	EJ25D074624
Reg. Date:	01/02/2010 (Man. Year: 2007)	Chassis No:	JF1BP9KV57G054905
Colour:	Blue	Odometer:	116833 km
Engine Capacity:	2457 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S$)	**0.00**	**0.00**	**0.00**	

INSPECTION

Date of Assignment:	12/07/2018		
Date Inspected:	12/07/2018	Inspected At:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10 Singapore 575721
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG **Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $3,000.00 -$4,000.00

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 08 Aug 2018)
Parts:	N/A	SUBARU LEGACY 2.5 GT WAGON TURBO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCL251T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >