

INSURANCE

INS. CASE OWNER:

BERNARD

CC 6 /AIG1801

2638, 4663

LOK

IDAC

Surveyor:

MURKUS

DOI:

ASSIGNMENT

11/3/18

Date / Time:

11/3/18

Registered in Meritum:

11/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SL5 1847A

Name of Insured:

YIN PEMHUT

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SEL 92735



INSRS:
WSP:
Tel:
Liability:
RMKS:

tim chwee



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

12/3/18
✓

SEL 92735 - 4

SL5 1847A - 7

NO OI GIA, SENT OUT 1ST LETTER.

OI GIA REPORT IN: FINISHED. RECEIVED 08 NOV 2018
ORIGINAL TP LOD IN.

01/03/18
SPH

CALL OI. NO RESPONSE. THE REVIEWED.
OI INVOLVED IN 4 VEH. C.C.; OI LOST.
SEND LETTER 4 PAGES TO OI.
THEY REQUEST FOR HANDS
REPORT DONE

11/10/18

OBSC HANDS APPROVAL TO AIG BY
BURN/WHITEN.

07/11/18

AIG APPROVED HANDS.
95% 1ST OFFER TO TP.
TP ACCEPTED OFFER.
ALL DONE IN ORDER TO CLOSURE.

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	
After call Itr to OI:	01/03/18 - JC
Documentation Check List:	Handler Typist
Notification Itr (if non-pickup):	
After call Itr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	US \$8,000.00	8 days Reduction:	75%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Confirm by:	
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	28	If NO or B 28, Ass. Lia: 100%
Repair Cost (w/acc):	US \$8,560.00			(4 VEH. C.C.; OI LOST)
Loss of Rental (LOR):	US \$ () days			
Loss of Use (LOU):	US \$910.00 (10 x 9 days)			
Loss of Income (LOI):	US \$ (3 x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>				[Tick only one]
GIA/LTA Search:	US \$2.00			
Medical:	US \$ -			
Disbursement:	US \$ -	(e.g. Tow/ Independent)		
Legal Cost:	US \$ -			
Total:	US \$9,552.00	Global Sum US \$:	9,550.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Confirm by:	
Payee 1:	US \$9,550.00	Name 1:	KIM CHWEE AUTO PRT LOD	
Payee 2: (Strike if N.A.)	US \$ -	Name 2:	-	
Payee 3: (Strike if N.A.)	US \$ -	Name 3:	-	

(08/11/13) wef

ASS. REC. BY: MARCUS

REF:

A161

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL92335at Workshop m/s Knichuaof SL518471

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection

N/S	O/S

Bal. or Market Value: 24800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5350C

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKL92335 Yr Regn: 31/3/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAIMake: Mercedes-Benz C180 1796Colour: Black A/C: Insured / Std / NI / NASp. Reading: 140993 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB2037462E059960

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45 R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5- mm R/Bal. 5- mmL/Bal. 5- mm L/Bal. 5- mmD.O.A. 10/7/18 D.O.I. 11/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

knichua only 6k. 21A16763 Sub. net 803720/7/18 1/5 8000 confirmed with Alan. phv.?(GPD: \$21,077.62 / 76%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

(08/11/13) wet

ASS. REC. BY: MORIS

REF:

A161

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL92335at Workshop m/s Kmchee

of _____

Insured: SL518471

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 23800

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

S350C

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

achy 6k. 27A16763 Sub. netto 7037Veh No: SKL92335 Yr Regn: 31/3/09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: mercedes-benz 1796Colour: Black A/C: Insured / Std / NI / NASp. Reading: 140993 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WD32037462E059960Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5- mm R/Bal. 5- mmL/Bal. 5- mm L/Bal. 5- mmD.O.A. 10/7/18 D.O.I. 11/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18012638/Uhb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 11-07-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 1847A	Veh. Inspected	SKL 9233S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/07/2018	Inspection Date	11/07/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KIM CHWEE AUTO PTE LTD
 1 Kaki Bukit Ave 6
 #01-46,48,50 Autobay
 SINGAPORE 417883

VEHICLE NO: SKL 9233S

QTY	PARTICULAR
1 PCS	TAILGATE
1 PCS	REAR BUMPER <i>chrome 1458.32</i>
1 PCS	REAR BUMPER CHROME MOULDING <i>188.10</i>
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REINFORCEMENT <i>655</i>
2 PCS	REAR BUMPER SIDE HOLDERS @\$115.00
1 PCS	REAR BUMPER LOWER LIP <i>525.00</i>
1 PCS	REAR END PANEL <i>1206</i>
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$667.00
1 PCS	REAR BUMPER INNER RETAINER
1 PCS	REAR BUMPER SPONGE <i>166.05</i>
1 PCS	BONNET <i>1876.11</i>
1 PCS	BONNET LOGO <i>52.50</i>
1 PCS	BONNET LOCK LEVEL
2 PCS	BONNET LOCKS @\$245.00 <i>118 x 2 = 236.00</i>
2 PCS	BONNET LOCK CATCHES @\$150.00 <i>85 x 2 = 170</i>
1 PCS	FRONT GRILLE
1 PCS	FRONT GRILLE LOGO
1 PCS	FRONT BUMPER <i>1325</i>
2 PCS	FRONT BUMPER CHROME MOULDINGS @\$105.00
2 PCS	FRONT BUMPER SIDE REATAINERS @\$80.00
1 PCS	FRONT BUMPER SPONGE
1 PCS	FRONT BUMPER CENTRE GRILLE
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER CLIPS
1 PCS	FRONT TOP PANEL CENTRE
1 PCS	FRONT TOP PANEL CENTRE GARNISH
2 PCS	FRONT LOCK PANEL LH & RH @\$165.00
2 PCS	FRONT HEADLAMPS @\$2100 <i>1205 x 2 = 2410</i>
1 PCS	AIR CON CONDENSER <i>1475</i>
1 PCS	RADIATOR
2 PCS	FRONT REINFORCEMENT BRACKETS @\$252.00
1 PCS	AIR DUCT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
date
11/7/18
2/5/18 8000/2
8 day.

<i>n</i>	\$1,866.02	<i>X</i>
<i>n/re</i>	\$1,795.10	<i>—</i>
<i>ru</i>	\$211.40	<i>—</i>
<i>ru</i>	\$50.00	<i>—</i>
<i>Set</i>	\$798.00	<i>—</i>
<i>17</i>	\$230.00	<i>X</i>
<i>CU</i>	\$680.00	<i>—</i>
<i>DD</i>	\$1,415.00	<i>—</i>
<i>17</i>	\$126.00	<i>X</i>
<i>11</i>	\$1,334.00	<i>X</i>
<i>17</i>	\$168.00	<i>X</i>
<i>to/n</i>	\$210.00	<i>—</i>
<i>Bul</i>	\$2,450.10	<i>—</i>
<i>ru</i>	\$60.00	<i>—</i>
<i>twi</i>	\$118.00	<i>✓</i>
<i>twi</i>	\$490.00	<i>—</i>
<i>twi</i>	\$300.00	<i>—</i>
<i>CU</i>	\$695.00	<i>—</i>
<i>m-s</i>	\$80.00	<i>—</i>
<i>n/re</i>	\$1,815.00	<i>—</i>
<i>ru</i>	\$210.00	<i>—</i>
<i>Set</i>	\$160.00	<i>—</i>
<i>to/n</i>	\$98.00	<i>—</i>
<i>17</i>	\$105.00	<i>X</i>
<i>Set</i>	\$695.00	<i>—</i>
<i>ru</i>	\$50.00	<i>—</i>
<i>Bul</i>	\$145.00	<i>—</i>
<i>17</i>	\$172.00	<i>X</i>
<i>n</i>	\$330.00	<i>X</i>
<i>holder cu</i>	\$4,200.00	<i>—</i>
<i>Set/Am</i>	\$1,875.00	<i>—</i>
<i>Set/Am</i>	\$817.00	<i>—</i>
<i>Set</i>	\$504.00	<i>—</i>
<i>Set</i>	\$145.00	<i>X</i>

102

1 PCS

INTER COOLER / 250

(102)

1 SUR \$1,650.00
\$26,047.62

X

1 SET

REAR BUMPER REVERSE SENSOR

shut \$280.00 200

1 PCS

FRONT LICENCE PLATE W/HOLDER

shut \$50.00 40

1 BOT

RADIATOR COOLANT

shut \$50.00 ✓

S.NETT

TO CHECK WIRING

\$80.00 30

TO DISMENTLE & REPLACING REVERSE SENSOR

\$80.00 50

TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY

\$150.00 80

TO SPRAY RUST PROOFING

\$150.00 80

TO REFILL AIR CON GAS

\$150.00 100

TO MOUNT VEHICLE ON CAR O-LINER

11 \$380.00 X

TO RESET FAULT CODE

11 \$300.00 X

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED

\$1,800.00 1200

REPLACING PARTS

\$2,500.00 1500

TO PUTTY & SPRAY PAINTING

\$32,017.62

TOTAL

3330

15365.08
13828.57
17158.57
13726

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5350C

Vehicle Details

Vehicle No.:	SKL9233S
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLC 180 K
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	27194631124365
Chassis No.:	WDB2037462E059960
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$32,826.00
Original Registration Date:	31 Mar 2009
First Registration Date:	31 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$32,826.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2019
PARF Rebate Amount:	\$16,413.00

Intended COE Rebate Details

COE Expiry Date:	30 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$5,889.00
COE Rebate Amount:	\$350.00
Total Rebate Amount:	\$16,763.00

The information contained herein is correct as at 11 Jul 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Mercedes-Benz CLC

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Car Elegance > Mercedes-Benz CLC-Class CLC180K

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Commercial Vehicle

PARF

AMFAC

Service for people you trust

More than 1,000 fleet unit

Daily, Weekly, Monthly & Yearly Fleet Available

Mercedes-Benz CLC-Class CLC180K

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

CAT ON CAR

Price

\$22,800

Depreciation

\$8,910 /yr

View models with similar depreciation

Reg Date

31-Mar-2009

(8mths 19days COE left)

Manufactured

2008

Mileage

147,850 km (15.9k /yr)

Transmission

Auto

Engine Cap

1,796 cc

Road Tax

\$974 /yr

Power

105.0 kW (140 bhp)

View specs of the Mercedes-Benz CLC-Class (2008-2010)

Curb Weight

1,495 kg

Features

Airbags, ABS, Side Mirror Indicator, Multi Function Steering, Rear Aircon.

Accessories

Sports Rims, Leather Seats, CD Changer, Reverse Sensors And Camera, Fog Lamps.

Description

Red Hot Chilli CLC180K Is Up For Sale. Hurry, Call Me Now.

COE

\$5,889

OMV

\$32,812

ARF

\$32,812

Dereg Value

\$16,829 as of today (change)

No. of Owners

4

Type of Veh

Sports Car

Category

PARF Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 05-Jul-2018 | Last Updated on: 05-Jul-2018

Tags: Mercedes-Benz CLC180K, 2009 Mercedes-Benz CLC180K, Mercedes-Benz CLC180K, Used Mercedes-Benz

Upfront Payment

+ more Financial info

Transfer Fee

\$25

Down Payment

\$6,840 (change)

Maximum 70% Loan

1st Instalment

\$2,035

Car Photos

Location Map

Seller Information

Company

Car Elegance

• Dealer's prelist

• 1 vehs sold | 1 vehs available

Address

756 Upper Serangoon Road #03-22

Search cars nearby this location

Location

Upper Serangoon Shopping Centre

Contact Person(s)

Andy Ng

97934799

Useful Services

STA

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

http://www.sgcarmart.com/used_cars/info.php?ID=752161&DL=3417

11-Jul-18

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

McDonald's Har Jeong Gai burger

Do you still eat expired foods and drinks?

Durian Sellers - recommendations and to avoid

Post an Advertisement

Sell it yourself! Advertise it at just


\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling


Apr 12 Audi A5 Sportback 2.0A TFSI Quattro.



Facelifted Sporty White A5 Sportback With Sunroof,Reliable German Technology Shine Connect StarAd

ABWIN

ONE-STOP



Browse by Category

Sort by Date Posted

20 results/page

3 vehicles

Mercedes-Benz CLC

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz CLC		Any	Any	2009	Any	Any	Any	Available
	Mercedes-Benz CLC-Class	CLC180K (New 10-yr COE)	\$69,800	\$6,970 /yr	31-Mar-2009	1,796 cc	100,338 km	Sports	Available
Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming. Renew 10 Yrs COE! Depreciation At \$7000 Per Year! Low Monthly Installment.									
Yong Lee Seng Motor									
Posted: 06-Jul-2018 Tags: 2009 Mercedes-Benz CLC180K, Mercedes-Benz CLC180K, Mercedes-Benz, CLC180K, Used Mercedes-Benz									
	Mercedes-Benz CLC-Class	CLC180K	\$22,800	\$8,910 /yr	31-Mar-2009	1,796 cc	147,850 km	Sports	Available
Red Hot Chili CLC180K Is Up For Sale. Hurry, Call Me Now.									
Posted: 05-Jul-2018 Tags: 2009 Mercedes-Benz CLC180K, Mercedes-Benz CLC180K, Mercedes-Benz, CLC180K, Used Mercedes-Benz									
	Mercedes-Benz CLC-Class	CLC180K	\$28,800	\$11,090 /yr	03-Aug-2009	1,796 cc	134,600 km	Sports	Available
Consignment Unit. Lowest Depreciation In Market Only! Original Condition, Paintwork, Good Value For COE Renewal. Selling As It's Condition.									
Posted: 28-Jun-2018 Tags: 2009 Mercedes-Benz CLC180K, Mercedes-Benz CLC180K, Mercedes-Benz, CLC180K, Used Mercedes-Benz									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Vic (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Wednesday, 7 November, 2018 5:02 PM
To: Vic (LKKAUTO); 'Nancy Lam'
Cc: Admin A
Subject: RE: Your Ref: SKL 9233S_ACCIDENT INVOLVING VEHICLES SLS 1847A AND SKL 9233S ON 10/07/2018 LKK REF CC6/AIG18012638/Uhb3

Without Prejudice

Dear Vic,

We are pleased to accept your offer of global sum of \$9,550.00 all in (Property only).

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Wednesday, November 7, 2018 4:20 PM
To: jason@fastechauto.com.sg; Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: Your Ref: SKL 9233S_ACCIDENT INVOLVING VEHICLES SLS 1847A AND SKL 9233S ON 10/07/2018 LKK REF CC6/AIG18012638/Uhb3

WITHOUT PREJUDICE

Dear Nancy/Jason,

ACCIDENT INVOLVING VEHICLES SLS 1847A AND SKL 9233S ON 10/07/2018

We refer to the above matter and we confirmed in receipt of your LOD.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer settlement of global sum of \$9,550.00 (all in) to settle your client's claim.

For your acceptance please.

The above amount is to be made payable to **KIM CHWEE AUTO PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Print Received Message

This mail is associated with :

***SKL9233S (8591390075SG)
[SLS1847A]**

TP
SIM HWEE FERN
Jul 10 2018 7:00PM
[XIN PENGWEI]
Kim Chwee Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/11/2018 14:38 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9552.00) - SKL9233S - Claim Handler: Ler, Bernard-JQ

Approved:9552.00:Hi, pls try ur utmost to settle TP claim as follows: Cost of Repair : \$8,560.00 Loss of Use : \$990.00 9 days @ S\$ 110/day Search Fee : \$2.00 Total : \$9,552.00

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 27.07.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SKL9233S AND SLS1847A ON 10.07.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SKL9233S**, which was involved in the captioned accident with your insured vehicle no: **SLS1847A**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	8,560.00
2) Loss Of Use (8days + 1sun x \$150)	\$	1,350.00
3) GIA Search Fee	\$	2.00
	\$	9,912.00

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

01 AUGUST 2018

XIN PENGWEI
BLOCK 321 TAMPINES STREET 33
#07-124
SINGAPORE 520321

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18012638/Uhb3
YOUR REF : SLS 1847A
ACCIDENT INVOLVING SLS 1847A / SKL 9233S / OTHERS ALONG PIE NEAR
JALAN EUNOS EXIT ON 10.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKL 9233S against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKL 9233S. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

lvynxin36@msn.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 1 August, 2018 5:07 PM
To: Ivyxin36@msn.com
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SLS 1847A_ACCIDENT INVOLVING SLS 1847A / SKL 9233S / OTHERS ALONG PIE NEAR JALAN EUNOS EXIT ON 10.07.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

01 AUGUST 2018

XIN PENGWEI
BLOCK 321 TAMPINES STREET 33
#07-124
SINGAPORE 520321

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18012638/Uhb3
YOUR REF : SLS 1847A
ACCIDENT INVOLVING SLS 1847A / SKL 9233S / OTHERS ALONG PIE NEAR JALAN EUNOS EXIT ON 10.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKL 9233S against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SKL 9233S. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Sim Hwee Fern ("the third party claimant")
of 64 Springleaf Garden Singapore 788216 (address),
owner of SKL 9233S (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKL 9233S that was
damaged pursuant to the accident which occurred on 10-07-2018 (date) along
PIE (Changi) Before Jalan Eunos Exit (location)
involving vehicle no/s SLS 1847A ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 11 day of 07 (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I Kim chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 9,550.00 (repair costs), S\$ — (loss of use/rental) S\$ — (search fees) for vehicle no. SKL 92335 that was damaged pursuant to the accident which occurred on 10/7/18 (date) along PIE (Changi) Before Jalan Eunos Exit (location) involving vehicle no/s SL51847A.

This is pursuant to the inspection conducted on 11/07/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Sim Hwee Fern ("third party claimant") of vehicle no. SKL 92335 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKL 92335 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 day of 11 (month) 20 18 (year)



CMS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20411

Date: 27.07.2018

Vehicle No: SKL9233S

Make/Model: MERCEDES BENZ

Chassis/Eng# :

Accident Date: 10.07.2018

Claim No : 0718-20411

	Amount
To proceed on lump sum repair	S\$ 8,000.00

E. & O. E.	Total : S\$	8,000.00
	GST @ 7% : S\$	560.00
	Amount Due : S\$	8,560.00


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-105853

Date of Request: 11/07/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 11/07/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SLS1847A
Accident Date 10/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLS1847A	AIG Asia Pacific Insurance Pte. Ltd.	12/09/2017-11/09/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-105853

Date of Request: 11/07/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 11/07/2018
Enquiry By: Tang Kok Wee, Allan
TP Vehicle No: SLS1847A
Accident Date: 10/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2018 Edit Reg		11 Jul 2018 00:00 Edit Adj Rpt	\$58,000.00 Edit Estimates	\$58,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	XIN PENGWEI , ID: S8574448H								
Main Claimant:	SIM HWEE FERN , ID: S7835350C								
Vehicle Reg. No.:	SKL9233S	Date of Loss:	10/07/2018 19:00 - :59 [111 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8591390075SG	Policy/Cover Note No.:	1700049849 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS1847A	Policy No. (Claimant):	S118V04119/VPE/R04						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (07/11/2018): Alert - Adj Mandate Approved (\$59552.00) - SKL9233S - Claim Handler: Ler, Bernar... AIG_SG (12/07/2018): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















































Claim Documents

*SKL9233S (8591390075SG)
[SLS1847A]
TP
SIM HWEE FERN
Jul 10 2018 7:00PM
[XIN PENGWEI]
Kim Chwee Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼	
Letters/Correspondences						1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown			1	Edit	
Photos/Images						3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	11/07/18 18:04	Chassis Number			1	Load JPG	<input checked="" type="checkbox"/>
2	11/07/18 18:05	Odometer Reading			1	Load JPG	<input checked="" type="checkbox"/>
3	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
4	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
5	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
6	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
7	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
8	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
9	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
10	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
11	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
12	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
13	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
14	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
15	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
16	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
17	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
18	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
19	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
20	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
21	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
22	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
23	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
24	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
25	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
26	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
27	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
28	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
29	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
30	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
31	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
32	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
33	11/07/18 18:06	General View			1	Load JPG	<input checked="" type="checkbox"/>
34	11/07/18 18:06	General View			1	Load JPG	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
81	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
82	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
83	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
85	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
86	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
87	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
88	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
89	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
90	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
91	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
92	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
93	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
94	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
95	11/07/18 18:06	General View	 Load JPG	<input checked="" type="checkbox"/>
96	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	11/07/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	23/07/18 20:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 16:46	TP GIA REPORT	 Load PDF	
2	13/07/18 10:01	Non reporting letter	 Load PDF	
3	01/08/18 16:51	OI DRIVING LICENCE STATUS	 Load PDF	
4	01/08/18 16:54	TP ESTIMATE - MARKED	 Load PDF	
5	01/08/18 16:55	TP MARKET VALUE AND LTA REBATE	 Load PDF	
6	01/08/18 17:10	EMAIL TO OI	 Load PDF	
7	01/08/18 17:10	LETTER TO OI	 Load PDF	
8	24/09/18 15:35	GIA SEARCH	 Load PDF	
9	12/11/18 11:36	WORKSHOP INVOICE	 Load PDF	
10	12/11/18 11:36	AUTHORISATION TO ACT FORM	 Load PDF	
11	12/11/18 11:36	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Letters/Correspondences			1 per page	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 11:56	SLS 1847A GIA AMEND From:OO - Reg. No: SLS1847A, Claimant: XIN PENGWEI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS1847A (Insd veh)	Model:	MERCEDES-BENZ CLC180
	SKL9233S (TP veh)		1.8 KOMPRESSOR (A)
Date of Accident:	10/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		34,258.85
Final Repair Cost	:	\$		9,550.00
Loss of Use	:	\$		9.00 days at \$110.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		9,550.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 9,550.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

12 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18012638/UHB3Q2

Date: 12/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700049849
Claimant Vehicle No : SKL9233S **Insured Vehicle No :** SLS1847A
 Date of Loss: 10/07/2018 Nature of Claim: TP Claim No: 8591390075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL9233S**
 Make & Model: MERCEDES-BENZ CLC180, 1.8 Kompressor (A) Engine No: 27194631124365
 Reg. Date: 31/03/2009 (Man. Year: 2008) Chassis No: WDB2037462E059960
 Colour: Black Odometer: 140993 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18 Rear Tyre Size: 225/45Z R18
 Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
 Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,427.62	14,118.57	12,309.05	46.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	3,040.00	2,550.00	45.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,017.62	17,158.57	14,859.05	46.41
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	32,017.62	8,000.00	24,017.62	75.01
+ GST 7.00/7.00% (S\$)	2,241.23	560.00	1,681.23	75.01
Nett Amount (S\$)	34,258.85	8,560.00	25,698.85	75.01
+ Loss of Use (9.0 x S\$110.00/day) (S\$)		990.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,552.00		
Global Sum Settlement (S\$)		9,550.00		

INSPECTION

Date of Assignment: 11/07/2018
 Date Inspected: 11/07/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,866.02 F	*- FL
2	1		*REAR BUMPER	Dented / Deformed	1,795.10 F	*1,458.32 FL
3	1		*REAR BUMPER CHROME MOULDING	Necessary	211.40 F	*188.10 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	798.00 F	*655.00 FL
6	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	230.00 F	*- FL
7	1		*REAR BUMPER LOWER LIP	Cut	680.00 F	*525.00 FL
8	1		*REAR END PANEL	Dented	1,415.00 F	*1,206.00 FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	126.00 F	*- FL
10	2		*TAILLAMPS	Not Necessary	1,334.00 F	*- FL
11	1		*REAR BUMPER INNER RETAINER	Not Necessary	168.00 F	*- FL
12	1		*REAR BUMPER SPONGE	Torn	210.00 F	*166.05 FL
13	1		*BONNET	Buckled	2,450.10 F	*1,876.11 FL
14	1		*BONNET LOGO	Necessary	60.00 F	*52.50 FL
15	1		*BONNET LOCK LEVEL	Twisted	118.00 F	*118.00 FL
16	2		*BONNET LOCKS	Twisted	490.00 F	*236.00 FL
17	2		*BONNET LOCK CATCHES	Twisted	300.00 F	*170.00 FL
18	1		*FRONT GRILLE	Cracked	695.00 F	*695.00 FL
19	1		*FRONT GRILLE LOGO	Missing	80.00 F	*80.00 FL
20	1		*FRONT BUMPER	Dented / Deformed	1,815.00 F	*1,325.00 FL
21	2		*FRONT BUMPER CHROME MOULDINGS	Necessary	210.00 F	*210.00 FL
22	2		*FRONT BUMPER SIDE RETAINERS	Bent	160.00 F	*160.00 FL
23	1		*FRONT BUMPER SPONGE	Torn	98.00 F	*98.00 FL
24	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	105.00 F	*- FL
25	1		*FRONT BUMPER REINFORCEMENT	Bent	695.00 F	*695.00 FL
26	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
27	1		*FRONT TOP PANEL CENTRE	Buckled	145.00 F	*145.00 FL
28	1		*FRONT TOP PANEL CENTRE GARNISH	Not Necessary	172.00 F	*- FL
29	2		*FRONT LOCK PANEL LH & RH	Repair	330.00 F	*- FL
30	2		*FRONT HEADLAMPS	Holder Cracked	4,200.00 F	*2,410.00 FL
31	1		*AIR CON CONDENSER	Bent / Punctured	1,875.00 F	*1,475.00 FL
32	1		*RADIATOR	Bent / Cracked	817.00 F	*817.00 FL
33	2		*FRONT REINFORCEMENT BRACKETS	Bent	504.00 F	*504.00 FL
34	1		*AIR DUCT	Serviceable	145.00 F	*- FL
35	1		*INTER COOLER	Serviceable	1,650.00 F	*- FL
36	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
37	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
38	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	26,427.62	15,655.08
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,536.51

Total Parts (S\$)	26,427.62	14,118.57
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
4	TO SPRAY RUST PROOFING	New	150.00	80.00
5	TO REILL AIR CON GAS	New	150.00	100.00
6	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
7	TO RESET FAULT CODE	New	300.00	0.00
8	LABOUR FOR PANEL BEATING ,CUT WELD,STRAIGHTENED REPLACING PARTS	New	1,800.00	1,200.00
9	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,500.00
Gross Labour Cost (S\$)			5,590.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >