



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012689/Gga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 01-12-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 9905B	Veh. Inspected	GBH 2091H
Policy No.	P1963973	Coverage (\$)	0.00
Claim No.	S8M0002Q	Excess (\$)	0.00
Assign From		Assign Date	12/07/2018

2. Vehicle Particulars & Condition

Make & Model	PEUGEOT PARTNER	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF37FBHYMHJ750959	Colour	SILVER
Odometer	14313	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KLEBER	8 mm
L/H Front Tyre	195/65 R15	KLEBER	8 mm
R/H Rear Tyre	195/65 R15	KLEBER	8 mm
L/H Rear Tyre	195/65 R15	KLEBER	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/07/2018	Inspection Date	12/07/2018
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------