

15/5/2010

INS. CASE OWNER:

CC4/QBE1801

2705, A we abbsz

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

12/7/18

Date / Time :

12/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

GBB 2075L

Name of Insured :

WESTCH SYSTEMS P/L

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A.:

3/7/18

Is driver the owner?

(YES / NO)

Nature of Accident :

TUNNEL

If NO, Driver Name / Age : TIM LOCK 50YD 75%KEY.

Driver Tel No. :

(V/L-YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

8-0016002-MWA.

PENCART

FPE TMS LRY INSIDE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

GBB 2075L

SLJ 8013R

SLP 5225P



INSRS:

WSP:

Tel :

Liability :

RMKS:

01



INSRS:

WSP:

Tel :

Liability :

RMKS:

P10

66

TP



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

12/7/18
TIMSLJ 8013R ? NAR (M 401209/14) DATE: 3/7/18
GBB 2075L

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. :

38

If NO or B 28, Ass. Lia : 100%

Repair Cost:

S\$

3 VEN CC OLD LAST.

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP/OP

3) Survey fee:

3300

COPY SENT

Asst. Pcr. Br. Adrian King

REF:

ASSIGNMENT

12/07/08
2008 July

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No. _____
at Workshop no. _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report Consistent? Yes or No
GIA / PR Seen Consistent? Yes or No
Est. Repairs: _____ days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ8013R Yr Regn: 2008 July
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer of:
Make: Toyota Picnic cc 1888
Colour: Silver A/C Insured / Std / NI / NA
Sp Reading: 173053 T/Radio: Insured / Std / NI / NA
Eng No: _____
C/No: JTEGH13B200025803
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: 205/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook
Front _____ Rear _____
R/Bal: 06 mm R/Bal: 06 mm
L/Bal: 06 mm L/Bal: 06 mm
D.O.A _____ D.O.I: 12/07/08
Survey held at Pico 60
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP QBF

Total Loss

MV: + 13,000
LTA: + 12,350
Net: + 650

MV: 13.1K
PV: 12.3K
Net: 100

→ Please offer \$700.

File/Time: File Path to:

☐

Preli. Report

File

File/Time: File Return to:

☐

Final Report

Report Format

Group Sem / LRP (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐
☐
☐
☐

Site Insp (\$)
Interview (\$)
Tech. Insp (\$)
Workshop (\$)

Survey Fee

Transportation

File/Time: File Path to:

File/Time: File Return to:

File/Time: File Path to:

File/Time: File Return to:

File/Time: File Path to:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18012705/ub3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 12-07-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 2075L	Veh. Inspected	SLJ 8013R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/07/2018	Inspection Date		
Survey held at	RICO 66			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 12 July 2018 8:29 AM
To: assignments
Subject: FW: PRI Arrangement for SLJ 8013 R [VC011632]
Attachments: GBB2075L.pdf; SLJ8013R-TP2.pdf

9.02am @ 12/07/2018
Person @ John
Vehicle In

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [mailto:joyce.foo@qbe.com]
Sent: Thursday, 12 July 2018 8:25 AM
To: Admin A <admin-a@lkkauto.com>; claims-singapore@qbe.com
Subject: FW: PRI Arrangement for SLJ 8013 R [VC011632]

Our Ref. VC011632

Hi

Please assist to arrange for TP survey – Direct settlement.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg

From: Rico 60 [mailto:claims@rico60.com]
Sent: Wednesday, 11 July, 2018 6:17 PM
To: Joyce Foo <joyce.foo@qbe.com>; claims-singapore@qbe.com
Subject: RE: PRI Arrangement for SLJ 8013 R [VC011632]

Dear all,

Please have LKK survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Joyce Foo

Sent: Wednesday, 11 July 2018 4:15 PM

To: Rico 60; claims-singapore@qbe.com

Subject: RE: PRI Arrangement for SLJ 8013 R [VC011632]

Our ref : VC011632

Dear Sirs/Madam

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Infinite Appraisal Service
Priority Services
Quantum Risk Management (S) Pte Ltd


Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

We are agreeable to proceed with direct settlement subject to our surveyor's recommendation on COR, LOU/LOR per benchmark.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Rico 60 [mailto:claims@rico60.com]

Sent: Wednesday, 11 July, 2018 3:22 PM

To: Joyce Foo <joyce.foo@qbe.com>; Karen Poh <karen.poh@qbe.com>; Jenny Toh <jenny.toh@qbe.com>; Gwen Tan <gwen.tan@qbe.com>; Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>

Subject: PRI Arrangement for SLJ 8013 R

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLJ 8013 R

Your Insured – GBB 2075 L

DOA – 03/07/2018

Thank you.

Best Regards,

Cass Chua



RICO 60 AUTO SERVICES PTE. LTD.

Co. Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Asher Sng (LKKAuto)

From: Rico 60 <claims@rico60.com>
Sent: Monday, 25 November 2019 3:11 PM
To: Asher Sng (LKKAuto)
Subject: Withdrawal of Claim for SLJ 8013 R

Follow Up Flag: Follow up
Flag Status: Completed

Dear Miss Asher,

We would like to withdraw the claim for SLJ 8013 R.

Thank you.

Best Regards,

Elfphaine Tan



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 25 November 2019 6:24 PM
To: Jenny Toh; Syaheeda Nacah Binte Mohamed Othman
Subject: ACCIDENT INVOLVING GBB 2075L AND SLJ 8013R ON 03/07/2018
Attachments: Withdrawal of Claim for SLJ 8013 R

Your Ref: VC011632

Hi Sir,

We refer to the above matter.

ACCIDENT INVOLVING GBB 2075L AND SLJ 8013R ON 03/07/2018

We were informed by TP workshop that claimant withdraw third party claim from the workshop.

In view of the above, We will proceed to close file and submit our report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

1612G

Vehicle Details

Vehicle No:

SLJ8013R

Vehicle to be Exported:

Yes

Intended De-registration Date:

12 Jul 2018

Vehicle Make:

TOYOTA

Vehicle Model:

PICNIC AUTO W/O ROOF RACK

Primary Colour:

Silver

Manufacturing Year:

2008

Engine No:

1A25786470

Chassis No:

JTEGH23B200025803

Maximum Power Output:

110.0 kW (147 bhp)

Open Market Value:

\$24,659.00

Original Registration Date:

18 Jul 2008

First Registration Date:

18 Jul 2008

Transfer Count:

1

Actual ARF Paid:

\$24,659.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

17 Jul 2018

PARF Rebate Amount:

\$12,329.00

Intended COE Rebate Details

COE Expiry Date:

17 Jul 2018

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$16,500.00

COE Rebate Amount:

\$21.00

Total Rebate Amount:

\$12,350.00

The information contained herein is correct as at 12 Jul 2018

OK