

INS. CASE OWNER:

CC3/CT11801

2707, K2 job

LKK:
IDAC:

Surveyor:

KALVIN

DOE:

ASSIGNMENT

11/5/18

Date / Time:

11/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEP 6939M

Name of Insured:

LIM UHAN JERENY

Insured Tel No.:

HP: 81266852

Excess Sec II : \$5

D.O.A: 11/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SM11802044200

Policy No.:

DMP15W207058700

Make / Model:

TOYOTA

Place of Accident:

YELLOW BOX JUNE TANGJONG

PUBHE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

% Final ? Yes / No

SH 92810

INSRS:
WSP:
Tel:
Liability:
RMKS:CD6E
WINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

16/5/18

JOY

324PM (M2E-D-ND) WORK

330PM W/ OI CONFIRMED ACC.
AGREED & AWARE
NCU ISSUE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

JOY 1-8-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

11/5/18

Sent By:

DICE

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

1-8-18

Confirm with:

CATH

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27

Repair Cost:

\$5

1,162.10

days) X115

Loss of Rental (LOR):

\$5

230

days) X115

Loss of Use (LOU):

\$5

100

days) X115

Loss of Income (LOI):

\$5

100

days) X115

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

\$5

7.49

Medical:

\$5

-

Disbursement:

\$5

-

Legal Cost:

\$5

-

Total:

\$5

1,499.59

Global Sum \$5:

1,495

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5

1,495

Name 1:

COMFORT DELGRU ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

\$5

X

Name 2:

X

Payee 3: (Strike if N.A.)

\$5

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COMFORT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18012707/K1jb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 6939M	Veh. Inspected	SH 9281D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/07/2018	Inspection Date	11/07/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305186489

Date : 11.07.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Kalvin

Vehicle Reg No. : SH 9281D

Date of Accident : 11.07.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SKP6939M
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$706.08</u>
(b) Labour Charges	<u>\$380.00</u>
Total for Part-By-Part Repair Cost	<u>\$1,086.08</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$0.00</u>
Final Lumpsum Repair cost	<u>\$0.00</u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]

Signature : [Signature]

Name : FAUZY BIN MOKHTAR

Name : Kalvin

Tel : 62148319

Date : 12/7/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.07.2018

REPAIR ESTIMATE

Time: 14:54:42

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305186489
REGN NO : SH 9281D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 16.06.2016
DATE/TIME IN : 11.07.2018 09:35
ACCIDENT DATE : 11.07.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002 04-01-0101-0111-A	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0004 04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	32.00	20.00	25.60

SUB-TOTAL : 706.08

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 L	SPRAY PAINTING CHARGE	180.00

SUB-TOTAL : 380.00

TOTAL : 1,086.08

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9281D

MAKE :

MODEL : HYUNDAI i40

DATE 11/7/2018 11:52

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (RH)			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 2,101.48

Kalin LKK

11/7/2018

2 hrs

P18

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are based on "market" basis
- Third party survey is not "binding" basis
- No illegal modification
- Suppliers are not responsible for "warranty" and is subject to law approval from insurance company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 13 July 2018 11:53 AM
To: Shu Pei (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving SKP6939M (OI : CTI - SNM18D03442C02) AND SH9281D (TP : LKK REF - CC3/CTI18012707/K1jb3) on 11.07.2018
Attachments: leeSZ_SNM18D03442C01-SKP6939M-LKKDirectSettlementAccidentLtr_CLCR95.112.pdf; MSNH18090053-SKP6939M.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]
Sent: Thursday, 12 July, 2018 5:08 PM
To: Claims Dept of CTI
Cc: Sharon Han; Lucas Lee; Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SKP6939M (OI : CTI - TBA) AND SH9281D (TP : LKK REF - CC3/CTI18012707/K1jb3) on 11.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SH 9281D at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Jbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03442/C01/9**

Date : **13 JULY 2018**

via Ordinary & Registered Mail

**CHIN LIHAN JEREMY
BLK 310B ANG MO KIO AVENUE 1
#03-377 TECK GHEE VISTA
SINGAPORE 562310**

Dear Sir / Madam

**ACCIDENT INVOLVING SKP6939M AND SH9281D ON 11 JULY 2018
ALONG JUNCTION OF TANJONG PAGAR & KEPPEL ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SH9281D**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY
Ref : CC3/CTI18012707/K1JB3
Contact No : 68412409
via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0397A) - INDEX AGENCY PTE LTD

F01/LKKDS-2013

eam: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 3838866

JC NO.: 305186489

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO. SH 9281D MAKE: HYUNDAI MODEL I-40 YR OF MANU. 16.06.2016 CHASSIS CODE KMHLB41UMGU091361	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 11.07.2018 09:35 TARGET DATE COMPLETION DATE/TIME
--	---	---

UNT CARD NO.

JOB DESCRIPTION

Accident Date: 11.07.2018
NATURE: 3P 11.07.18

CHINA

3/NO LABOR CODE DESCRIPTION

CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

vedgement Slip

Exit Pass

No.: SH 9281D FZ

Vehicle No.: SH 9281D

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18012707/K1jb3

Date: 12.07.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SH9281D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.07.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,101.48
Revised Estimate Amount	: S\$	1,086.08
"Check" Items Amount	: S\$	845.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9281D

MAKE :

MODEL : HYUNDAI i40

DATE 11/7/2018 11:52

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (RH) ✓			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00 180
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 2,101.48
<p> <i>Kalvin LKK</i> <i>11/7/18 1400h</i> <i>2 bgs</i> <i>P18</i> <i>Before Paint photo</i> </p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer:</p> <p>Signature: _____</p> <p>Date: _____</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



e-Services (/content/policehubhome/homepage.html)

Log in

Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number	S8120132C
Status of Qualified Driving Licence	Valid
Class(es) of Qualified Driving Licence	3
Expiry Date	Valid for life unless revoked,suspended or disqualified

Provisional Driving Licence

Provisional Driving Licence Number	S8120132C
Status of Provisional Driving Licence	No Licence
Class(es) of Provisional Driving Licence	
Expiry Date	-

HOME (<https://www.police.gov.sg/>)
ABOUT US (<https://www.police.gov.sg/about-us>)
SGSECURE (<https://www.police.gov.sg/sgsecure>)
I-WITNESS (<https://www.police.gov.sg/iwitness>)
COMMUNITY PROGRAMMES (<https://www.police.gov.sg/community-programme>)
RESOURCES (<https://www.police.gov.sg/resources>)
NEWS & PUBLICATIONS (<https://www.police.gov.sg/news-and-publications>)
JOIN US (<https://www.police.gov.sg/join-us>)
FAQS (<https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx>)

Our Ref : T 0718 / SH 9281D /WT(st)

Your Ref :

Date : 23-Jul-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No. 10950648W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
Shun Industrial Park A
Singapore 768732

CHINA INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 9281D YOUR INSURED SKP6939M
AND OTHER _____ ON 11.07.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SH 9281D which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SKP6939M we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

- 1 Cost of Repair
- 2 2 days Loss of Rental @ \$ 115.00 per day
- 3 Survey Report Fees (Surveyed by M/s LKK)
- 4 LTA Search Fees
- 5 GIA / Police Report Fees
- 6 Towing / Medical / Transportation Fees

\$	1,162.10
\$	230.00
\$	-
\$	7.49
\$	-
\$	-
Sub Total :	\$ 1,399.59

HIRER'S CLAIM

- 7 2 days Loss of Income @ \$ 80.00 per days

\$	160.00
Total Claims :	\$ 1,559.59

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 6 pcs.
- b) LTA search slip/s of : SKP6939M
- c) GIA / Police report/s of : SH 9281D
- d) Letter of authority from owner / hirer / operator
 - () Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance
 - (X) Photograph/s of Accident Scen (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
William Tan

Deputy Manager
CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 1 August 2018 3:35 PM
To: jem.chin@gmail.com
Cc: Admin A
Subject: ACCIDENT INVOLVING SKP 6939M AND SH 9281D ON 11/07/2018

Our ref: CC3/CTI18012707/K1jb3

CHIN LIHAN JEREMY

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SKP 6939M AND SH 9281D ON 11/07/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGi 40 SH9281D , SKP6939M
KEPPEL RD TWDS ECP BEFORE SHENTON WAY

ON 11-Jul-18 09:00

I / We

PEH CHENG BEE

(Hirer) NRIC No.: S13201431

and/or

SEAH ENG SIONG

(Relief) NRIC No.: S0724184D

Taxi Number

SH9281D

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

11-Jul-2018

Name of Hirer
Hirer NRICPEH CHENG BEE
S13201431

Signature :



Address

235 COMPASSVALE WALK #13-504
540235

Contact No.

91896779

Name of Relief
Relief NRICSEAH ENG SIONG
S0724184D

Signature :



Address

534 HOUGANG ST 52 #08-38
530534

Contact No.

98188038



MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : 001 VSN3070581700

Claim No : SNM18D03442/C01/9

Claimant : COMFORT TRANSPORTATION PTE LTD

Amount : S\$1,495.00

SINGAPORE DOLLARS ONE THOUSAND FOUR HUNDRED NINETY FIVE ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SH 9281D

Insured Vehicle No. : SKP 6939M

Date of Loss : 11/07/2018

Place of Accident : KEPPEL ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : CHIN LIHAN JEREMY

Driver Name : CHIN LIHAN JEREMY

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 1,495.00
=====	
TOTAL	S\$ 1,495.00
=====	

CLAIMS DEPARTMENT
COMFORTDELORO ENGINEERING PTE LTD
50 LOYANG DRIVE
SINGAPORE 103994

Claimant Name : _____ NRIC No : _____

Signature :  Date : 11/8/18

The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

Printed Name and Position of Claimant and Date Issued
Chhin Li Han Jeremy 11/8/18

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SH 9281D

MAKE
HYUNDAI

MODEL
i-40

DATE OF REG
16.06.2016

CHASSIS CODE
KMHTB41UMGU091361

INV. NO/DATE
91384348 17.07.2018

JOB NO.
305186489

ODOMETER READING

DATE/TIME IN
11.07.2018 09:35

Description : 3P 11.07.18

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	04-01-0103-0579	140VC COVER ASSY-RR BUMPER	1	603.60	20.00	482.88
0002	04-01-0103-0738	140VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003	04-01-0103-0852	140VC REFLECTOR/REFLEX AS	1	32.00	20.00	25.60
SUB-TOTAL,				:		688.48

JOB NATURE

0001	20-05	RRAR BUMPER CLIPS	17.60		17.60
0002	L	PANEL BEATING	200.00		200.00
0003	L	SPRAY PAINTING CHARGE	180.00		180.00
SUB-TOTAL			:		397.60

ComfortDelGro Engineering Pte Ltd
member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ N
8010012	91384348	1,162.10	

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010012

CHINA TAIPING INSURANCE CO(S) PTE L
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE SG 079909

CONTACT NO: 62222366

VEHICLE NO
SH 9281D

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
16.06.2016

CHASSIS CODE
KMHLB41UMGU091361

INV. NO/DATE
91384348 17.07.2018

JOB NO.
305186489

ODIOMETER READING

DATE/TIME IN
11.07.2018 09:35

Items total		1,086.08
Add GST @	7.000 %	76.02
Invoice amount		1,162.10

Issued by : KATHERINETAN 17.07.2018 10:12:31
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO
8010012	91384348	1,162.10	

Our Ref: CT18070293

Date: 13 July 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 11/07/2018 @ 09:00 hrs
ALONG KEPPEL RD TWDS ECP BEFORE SHENTON WAY
INVOLVING SKP6939M

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH9281D** (the "Taxi"). The Taxi was hired to **PEH CHENG BEE IC NO S1320143I** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate \$115.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKP6939M	11 Jul 2018 / 09:00:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

[Previous](#) [OK](#)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18012707/K1jb3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 07-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKP 6939M	Veh. Inspected	SH 9281D
Policy No.	DMPCSN3070581700	Coverage (\$)	0.00
Claim No.	SNM18D03442/C01/9	Excess (\$)	0.00
Assign From		Assign Date	11/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091361	Colour	BLUE
Odometer	302001	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/07/2018	Inspection Date	11/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9281D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CUT	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (RH)	GRAZED	32.00	32.00
	LESS 20% DISCOUNT		-387.87	-176.52
			1,551.48	706.08
	<u>LABOUR</u>			
	PANEL BEATING .		350.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
			550.00	380.00
GRAND TOTAL			2,101.48	1,086.08

RECOMMENDED COST OF REPAIRS			1,086.08
------------------------------------	--	--	-----------------

Report Ref No. CC3/CT118012707/K1jb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.