

ASS. REC. BY:

REF: CS/MSG18 012711 / K9d362

Special Instruction:

Surveyor:

Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIG

Date/Time: 12/7/2018 @ 3:53pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 7806J

Insured:

FV 2780 G

at Workshop m/s

T & T Auto Services

Tel:

9145 9776

of

Blk 160, Sin Ming Drive # 08-14

Policy No:

MSD/VMT/17-368399-CA

Claim No:

MSC/v/18-000936

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/07/2018

CA / REV / REP. / REV 24 HRS

1up

16/07/18

H.O.D. Endorsement:

Date/Time:

4:04pm @ 12/7/18

Person Contacted:

Vincent

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKF 7806J - X

FV 2780 G - X

13/7/18 @ 2:21pm: vehicle not in yet Requirer arrange on 16/07/2018

17/7/18 @ 4:31pm revised to Elaine Ngu via Merimen.

24/7

@ 2514.80 ena1 & calim (red @ 5326.20, 68%) checked by

part prices

JL

(08/11/13) Wef

REF: MSIG

ASS. REC. BY:

ASSIGNMENT

From: Date: 16/7/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKF 7806J

at Workshop m/s

T & T Auto Services

of Blk 160 Sin Ming Drive # 08-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

13.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKF 7806J

Yr Regn:

06, 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i

c.c

1995

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

18929

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAKD 52060 E492606

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

255/35R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/7/18

D.O.I.

16/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17 Plc pass to Carbum

no lump sum.

J. M. P.

25/7/2018

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 25/7/18

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

150

Transportation:

S + RS, SI

Photos

10

Others

TOTAL

160

Report Format:

net-TP

Lump Sum / I.B.I. (\$

2514.80




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18012711/Kqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-07-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FV 2780G	Veh. Inspected	SKF 7806J
Policy No.	MSD/MT/17-368399-CA	Coverage (\$)	0.00
Claim No.	MSC/V/18-000936	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	12/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
General Information			
Accident Date	11/07/2018	Inspection Date	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		
Remarks			
THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2018		12 Jul 2018 15:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHD KHIR BIN ABDUL KADIR, ID: S1487577H		
Main Claimant:	TAY PEI HIAN (ZHENG PEIXIAN), ID: S7539538H		
Vehicle Reg. No.:	SKF7806J	Date of Loss:	11/07/2018 00:00 - :59 [72 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000936	Policy/Cover Note No.:	MSD/VMT/17-368399-CA (Third Party Only) Coverage: 25/07/2017 - 24/07/2018
Vehicle Reg. No. (Insured):	FV2780G	Policy No. (Claimant):	
		Excess:	
Repairer:	T & T Auto Services Pte Ltd (160 Sin Ming) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/07/2018]		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Insured non-reporting. TP agreed SJE & nominated LKK Contact : Mr Vincent Tan @ 9145 9776		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 17 Jul 2018

Preliminary Advice

Insured Vehicle No	: FV2780G		
TP Vehicle No	: SKF7806J	Accident Date	: 11/07/2018
Make	: BMW 320I	Assignment Date	: 12/07/2018
Date of Inspection	: 16/07/2018	Est. Duration of Repair	: 4.00
Inspection At	: T & T AUTO SERVICES PTE LTD (160 SIN MING) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,841.00
Revised Amount	:S\$	2,514.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,514.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9538H
Vehicle Details	
Vehicle No.:	SKF7806J
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320i AT ABS D/AB 2WD 2DR GAS/D SR
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	A409J117N46B20BD
Chassis No.:	WBAKD52060E492606
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,856.00
Original Registration Date:	29 Jun 2012
First Registration Date:	29 Jun 2012
Transfer Count:	2
Actual ARF Paid:	\$37,856.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2022
PARF Rebate Amount:	\$24,606.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$86,889.00
COE Rebate Amount:	\$33,636.00
Total Rebate Amount:	\$58,242.00

The information contained herein is correct as at 17 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2018 13:40
Date Of Accident	11/07/2018 15:40
Exact Location Of Accident	JUR WEST ST 52 BESIDE MS CARPARK BEF ZEBRACROSSING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF7806J
Insured/Policyholder	
Name Of Registered Owner	TAY PEI HIAN
NRIC No	S7539538H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93670304
Alternative Phone No	OFFICE-93670304

Vehicle Particulars

Manufacturer	BMW
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA339029/1
Cover Note Number	

Driver

Name of Driver	TAY PEI HIAN
NRIC No	S7539538H
Date Of Birth	31/12/1975
Occupation	INDOOR
Date Of Driving Pass	12/09/1995
Driving Experience	22 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93670304
Fax Number	
Contact Number	OFFICE-93670304
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FV2780G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 12/07/18 10:10am


Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/07/18 10:10am


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 11/07/2018, @ about 1540 hrs, I was travelling ^{along} Jurong West Street 52 beside the multi storey carpark before the zebra crossing. As I proceed towards the zebra crossing, I noticed there were pedestrian ~~cross~~ about to cross. I slow down and stop to allow them to proceed. Suddenly I felt an impact from behind and realised vehicle B had collided onto my rear left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 12/07/2018 10:10am


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 12/07/2018 12:10am


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

TAY PEI HIAN
3 TOH TUCK PLACE
SINGAPORE 596779

ESTIMATE

DATE : 16/07/2018
VEHICLE NO : SKF 7806 J
MAKE/MODEL : BMW 320I
ACC DATE : 11/07/2018

PARTICULAR AMOUNT S\$

LIST ITEMS:

1	1 REAR BUMPER	1,472.20	X
2	1 REAR BUMPER CENTER BRACKET	112.80	X
3	1 REAR BUMPER REINFORCEMENT	572.80	X
4	1 REAR BUMPER SIDE BRACKET - LH	83.00	X
5	1 REAR TAIL LAMP - LH	472.00	✓
6	1 REAR FENDER - LH	782.00	X
7	2 REAR REVERSE SENSOR	185.00	370.00 X
8	1 SIDE SKIRTING - LH	425.20	X

4,290.00

Less Discount: 10%

429.00

3,861.00

SPECIAL NETT ITEMS:

1	1 REAR TYRE RIM	580.00	✓
2	10 REAR BUMPER CLIPS	50.00	X

630.00

LABOUR CHARGES:

1	TO CHECK WIRING	50.00	200
2	TO TUFF KOTE	250.00	200
3	TO REMOVE/REFIX UPHOLSTERY, CUSSHION SEAT & ROOF LINING	150.00	1200
4	TO REMOVE/REFIX REVERSE SESNOR	100.00	X
5	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	1,400.00	600
6	TO SPRAY PAINTING ON AFFECTED AREA	1,400.00	750

3,350.00

GRAND TOTAL: 7,841.00

Singapore Dollars: Seven Thousand Eight Hundred And Forty One Only.

T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jul 2018		12 Jul 2018 15:53 Edit Adj Rpt	S\$2,514.80 Edit Estimates	S\$2,514.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MOHD KHIR BIN ABDUL KADIR , ID: S1487577H									
Main Claimant: TAY PEI HIAN (ZHENG PEIXIAN) , ID: S7539538H									
Vehicle Reg. No.: SKF7806J		Date of Loss: 11/07/2018 00:00 - :59 [72 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000936		Policy/Cover Note No.: MSD/VMT/17-368399-CA (Third Party Only) Coverage: 25/07/2017 - 24/07/2018							
Vehicle Reg. No. (Insured): FV2780G		Policy No. (Claimant):							
		Excess:							
Repairer: T & T Auto Services Pte Ltd (160 Sin Ming) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/08/2018]									
Adj Asg. Remarks: Third Party Pre-Repair Survey. Insured non-reporting. TP agreed SJE & nominated LKK Contact : Mr Vincent Tan @ 9145 9776									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKF7806J (MSC/V/18-000936)**
[FV2780G]
TP
TAY PEI HIAN (ZHENG PEIXIAN)
Jul 11 2018 12:00AM
[MOHD KHIR BIN ABDUL KADIR]
T & T Auto Services Pte Ltd (160 Sin Ming)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/07/18 14:31	Adjuster Immediate Advice	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
2	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
3	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
4	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
5	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
6	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
7	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
8	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
9	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
10	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
11	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
12	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
13	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
14	25/07/18 08:51	General View	Load JPG	<input checked="" type="checkbox"/>	
15	25/07/18 08:51	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>	
16	25/07/18 08:51	Chassis Number	Load JPG	<input checked="" type="checkbox"/>	
17	25/07/18 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
18	25/07/18 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
19	25/07/18 08:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	12/07/18 14:31	TP PRI	Load PDF		
2	12/07/18 14:53	REPLY TP ON OUR AGREED COMMON NOMINATED SJE - LKK	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012711/KQD3E2

Date: 02/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/17-368399-CA
Claimant Vehicle No :	SKF7806J	Insured Vehicle No :	FV2780G
Date of Loss:	11/07/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000936

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7806J		
Make & Model:	BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A)	Engine No:	A409J117N46B20BD
Reg. Date:	29/06/2012 (Man. Year: 2011)	Chassis No:	WBAKD52060E492606
Colour:	Metallic Silver	Odometer:	18929 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	255/35 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,491.00	1,004.80	3,486.20	77.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,510.00	1,840.00	54.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,841.00	2,514.80	5,326.20	67.93
+ GST 7.00/7.00% (S\$)	548.87	176.04	372.83	67.93
Nett Amount (S\$)	8,389.87	2,690.84	5,699.03	67.93

INSPECTION

Date of Assignment:	12/07/2018	
Date Inspected:	16/07/2018 Inspected At:	T & T Auto Services Pte Ltd (160 Sin Ming) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2018)
Parts:	M1-COUPE	BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF7806J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,472.20 FL	*- FL
2	1		*REAR BUMPER CENTER BRACKET	Serviceable	112.80 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	572.80 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET - LH	Serviceable	83.00 FL	*- FL
5	1		*REAR TAIL LAMP - LH	Cracked	472.00 FL	*472.00 FL
6	1		*REAR FENDER - LH	Repair	782.00 FL	*- FL
7	2		*REAR REVERSE SENSOR	Serviceable	370.00 FL	*- FL
8	1		*SIDE SKIRTING - LH	Serviceable	425.20 FL	*- FL
9	1		*REAR TYRE RIM	Dented	580.00 FS	*580.00 FS
10	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,920.00	1,052.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	429.00	47.20
Total Parts (\$\$)	4,491.00	1,004.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO TUFF KOTE	New	250.00	20.00
3	TO REMOVE / REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING	New	150.00	120.00
4	TO REMOVE / REFIX REVERSE SENSOR	New	100.00	0.00
5	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	New	1,400.00	600.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,400.00	750.00
Gross Labour Cost (S\$)			3,350.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >