

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18012713/Ked302

Special Instruction:

Surveyor  
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

msig

Date/Time:

12/7/18 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81X 295Y

Insured:

SKT 9130 M

at Workshop m/s

Cheng Hoe Motor

Tel:

6765 6142

of

38 woodlands Ind. park EI # 05-04

Policy No:

A29072524 AVW

Claim No:

564079

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/07/2018

CA / REV / REP. / REV 24 HRS

Cup)

Insp: Blk 1019, Yishun Ind. park A # 01-374

H.O.D. Endorsement:

Date/Time:

3:57pm 12/7/18

Person Contacted:

June

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

81X 295Y - X

SKT 9130 M - X.

16/07/18

@ 14:39 p.m. revised IA to Elaine Ngu via merimen.

ASS. REC. BY:

REF: MSG/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLX 2954 Yr Regn: 11, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Proton Exora c.c. 1597

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 125258 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: PL 1F88YRRAFC017952

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / Rim or

Tyre Size: F: 1P5/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/7/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 13/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/7 File pass to Catherine

31/12 11 Pm @ 31001 Carbm / Efuels

31/12/18 Confirmed HS @ 3,100/- @ 6 days with Kenneth.  
(\$ 1,307.04 Red - 30%)

RECEIVED 3 DEC 2018

Date/Time, File Pass to?

31/12/18

☐ : Prell. Report☒ : Final Report

1) Type 34

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$1

Fixes

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$ 3,100/- HS

|     |
|-----|
| 150 |
| 10  |
| 160 |

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |  |         |               |             |  |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case                     | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status   |
| Main                     | 11 Jul 2018 |               | 12 Jul 2018<br>15:49<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

### CLAIM SUBFOLDER DETAILS [Created by insurer]

|                             |   |                        |  |  |
|-----------------------------|---|------------------------|--|--|
| Insured:                    | PAUL JEYA SAMUEL, ID: S1500881D   |                        |  |  |
| Main Claimant:              | MOHAMED NUR MUBBIN BIN ABDUL KADIR, ID: S7341792I   |                        |  |  |
| Vehicle Reg. No.:           | SLX295Y   | Date of Loss:          | 11/07/2018 06:00 - :59<br>[104 Months and 8 Days From LTA Reg Date (Man Yr)] |  |
| Claim Type:                 | TP / 564079   | Policy/Cover Note No.: | A29072524AVW (Comprehensive)<br>Coverage: 09/02/2018 - 24/06/2019            |  |
| Vehicle Reg. No. (Insured): | SKT9130M  | Policy No. (Claimant): |  |  |
|                             |   | Excess:                | S\$2,000.00  |  |
| Repairer:                   | Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05, 757700 Woodlands - Tel: 6765 6142 |                        |  |  |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]   |                        |  |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/07/2018]                                |                        |  |  |
| Driver/Custodian (Insured): | MICHAEL JAMES SAMUEL (25 / Male), NRIC: S9318030E   |                        |  |  |
| Adj Asg. Remarks:           | SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (KENNETH KONG) LIABILITY: 100% CONTACT: JUNE PHUA 6755 6142           |                        |  |  |

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18012713/Ksd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-07-2018



Code : MSG

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SKT 9130M            | Veh. Inspected | SLX 295Y   |
| Policy No.   | A29072524AVW         | Coverage (\$)  | 0.00       |
| Claim No.    | 564079               | Excess (\$)    | 0.00       |
| Assign From  | MERIMEN (ELAINE NGU) | Assign Date    | 12/07/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 11/07/2018                                    | Inspection Date | 12/07/2018 |
| Survey held at | CHENG HOE- BLK 1019 YISHUN IND PARK A #01-374 |                 |            |
| Repairer       | CHENG HOE MOTOR PL                            |                 |            |

### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 1792I

### Vehicle Details

Vehicle No.: SLX295Y  
Vehicle to be Exported: No  
Intended De-registration Date: 11 Jul 2018  
Vehicle Make: PROTON  
Vehicle Model: EXORA 1.6L AT (M-LINE) ABS D/AB 2WD 5DR  
  
Primary Colour: Silver  
Manufacturing Year: 2009  
Engine No.: S4PHQB2575  
Chassis No.: PL1FZ6YRRAF017952  
Maximum Power Output: 93.0 kW (124 bhp)  
Open Market Value: \$14,115.00  
Original Registration Date: 03 Nov 2009  
First Registration Date: 03 Nov 2009  
Transfer Count: 1  
Actual ARF Paid: \$14,115.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 02 Nov 2019  
PARF Rebate Amount: \$7,763.00

### Intended COE Rebate Details

COE Expiry Date: 02 Nov 2019  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$16,201.00  
COE Rebate Amount: \$2,121.00  
**Total Rebate Amount: \$9,884.00**

The information contained herein is correct as at 11 Jul 2018

OK

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 16 Jul 2018

**Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SKT9130M  |                         |              |
| TP Vehicle No      | : SLX295Y   | Accident Date           | : 11/07/2018 |
| Make               | : PROTON EXORA  | Assignment Date         | : 12/07/2018 |
| Date of Inspection | : 13/07/2018  | Est. Duration of Repair | : 6 days     |
| Inspection At      | : Cheng Hoe Motor Pte Ltd (Woodlands)<br>38 Woodlands Industrial Park E1, #05-04/05<br>Singapore 757700 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,407.04 |
| Revised Amount              | :S\$ | 2,756.04 |
| Check Items (Estimated)     | :S\$ | 1,251.00 |
| Total                       | :S\$ | 4007.04  |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

**Michelle (LKKAUTO)**

---

**From:** "Patrick CHUA" <Patrick\_CHUA@spf.gov.sg>  
**To:** "Michelle Toh" <michelletoh@lkkauto.com>  
**Cc:** "SPF Feedback TP" <SPF\_Feedback\_TP@spf.gov.sg>; <SPF\_Feedback\_MAYCI@spf.gov.sg>  
**Sent:** Monday, April 11, 2011 3:47 PM  
**Attach:** IMG.pdf  
**Subject:** Fw: (SR#: SR/2011/0308/1-FKMEM) - Activity # - 1-FKRY4:Re: Your Ref: T/20100807/9036 \*Our Ref:CC6/AIG10015709/Ujf2 ; 15711Ujf2 ; 15712/Ujf2

Our Ref: TP/IP/45847/2010

Dear Sir/Mdm

ACCIDENT INVOLVING SJU 7092J / SBW 1909C / GBB 5344R /JKA 7766 AND SFQ 5196A ON 07/08//2010

Please be informed that no action is being taken against any one in this accident. This not preclude further prosecution should new evidence emerge opateer. Our finding do not affect insurance and civil claim.  
Regards

Patrick Chua

Supervisor Admin & Processing/Investigation & Violations Reports

Branch/Traffic Police Department/Tel: 65476237/Fax: 65474749

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error.

----- Forwarded by Patrick CHUA/SPF/SINGOV on 11/04/2011 03:50 PM -----

SPF Feedback  
TP/SPF/SINGOV

08 Mar, 2011  
04:21 PM

To  
[michelletoh@lkkauto.com](mailto:michelletoh@lkkauto.com)

cc

[SPF\\_Feedback\\_MAYCI@spf.gov.sg](mailto:SPF_Feedback_MAYCI@spf.gov.sg)

Subject  
(SR#: SR/2011/0308/1-FKMEM) -  
Activity # - 1-FKRY4:Re: Your Ref:  
T/20100807/9036 \*Our  
Ref:CC6/AIG10015709/Ujf2 ;  
15711Ujf2 ; 15712/Ujf2

10/05/2011

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 11/07/2018 13:12 |
| Date Of Accident           | 11/07/2018 06:55 |
| Exact Location Of Accident | SLE TWDS BKE     |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |         |
|-----------------------------|---------|
| Vehicle Registration Number | SLX295Y |
|-----------------------------|---------|

#### Insured/Policyholder

|                          |                                    |
|--------------------------|------------------------------------|
| Name Of Registered Owner | MOHAMED NUR MUBBIN BIN ABDUL KADIR |
| NRIC No                  | S7341792I                          |
| Email Address            | MVBIN73@HOTMAIL.COM                |
| Mobile Phone No          | (LOCAL) +65-92763402               |
| Alternative Phone No     | OTHERS-92763402                    |

#### Vehicle Particulars

|  |  |
|--|--|
| Manufacturer   | PROTON                                     |
| Model  | EXORA-1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) |
| Exact Purpose for which vehicle was being used at time of accident           | PTE USE                                    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO   |
| If No, Please state action to be taken                                       | THIRD PARTY                                |
| Vehicle Category   | PRIVATE CAR                                |

#### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5099730627                             |
| Cover Note Number         | 11/04/18 - 02/05/19                    |

#### Driver

|                      |                                    |
|----------------------|------------------------------------|
| Name of Driver       | MOHAMED NUR MUBBIN BIN ABDUL KADIR |
| NRIC No              | S7341792I                          |
| Date Of Birth        | 16/11/1973                         |
| Occupation           | INDOOR                             |
| Date Of Driving Pass | 29/05/2009                         |
| Driving Experience   | 9 YEARS AND 1 MONTH                |
| Gender               | MALE                               |
| Mobile Number        | (LOCAL) +65-92763402               |
| Fax Number           |                                    |
| Contact Number       |                                    |
| EMail Address        | MVBIN73@HOTMAIL.COM                |



Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number                      SLQ7763D  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category                                      PRIVATE CAR  
Name of Driver                                         ME. NG  
NRIC/Passport Number  
Contact Number                                        97629046  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

|   |                               |
|---|-------------------------------|
| Address   | BLK 26 WOODLANDS DR.16 #04-15 |
| Postcode  | 737882                        |
| Was driver an employee of the Insured's Company     | NO                            |
| If No, Relationship of the Driver with the Insured  | OWNER                         |
| Vehicle Registration Number of Driver's Own Vehicle | -                             |
|   | -                             |
|   | -                             |
| Insurance Company of Driver's Own Vehicle           | -                             |
|   | -                             |
|   | -                             |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | QUITE DARK      |
| Road Surface       | DRY             |

#### Other Information

|   |                                      |
|---|--------------------------------------|
| Was any foreign vehicle involved in this accident?  | NO                                   |
| Number of vehicles involved in the accident   |                                      |
| Was any body injured in the Accident?   | NO                                   |
| Was any injured conveyed to hospital by ambulance?  |                                      |
| Was any other material or property damaged?   | YES                                  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                   |
| Number of Passengers (Including Driver)   | 3                                    |
| Passenger 1   | NAME: : WIFE<br>GENDER: : FEMALE     |
| Passenger 2   | NAME: : DAUGHTER<br>GENDER: : FEMALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

On 11 July 2018, around 06:55 hrs, I was driving along SLE towards BKE. I saw the car in front of mine came to a stop. I immediately brake and stop my car. Suddenly I heard a 'thud' sound from behind and my car jolt forward and hit the front car. I use my hand brake to station my car. I came out and realised my car was hit from behind and hit the front car. No one was injured in all parties.

#### Attachment(s)


|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKT9130M             |
| Vehicle Make/Model/Colour   |                      |
| Details Of Properties       |                      |
| Vehicle Category            | PRIVATE CAR          |
| Name of Driver              | MICHAEL JAMES SAMUEL |
| NRIC/Passport Number        | S9318030E            |
| Contact Number              | 90677428             |
| Address                     |                      |

# SKETCH PLAN

SLE TOWARDS BKE



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11 July 2018, around 0655 hrs, I was driving along SLE towards BKE. I saw the car in front of mine came to a stop. I immediately brake and stop my car. Suddenly I heard a 'thud' sound from behind and my car jolt forward and hit the front car. I use my handbrake to station my car. I came ~~out~~ out and realised my car was hit from behind and hit the front car. No one was injured in all parties.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )

MT/1002608-001

**SKETCH PLAN**

VEHICLE NO.: SLX295Y

INSURER: NTUC

DATE & TIME: 11/7/18 6:55 AM

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Wibid 11 July 18  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

h 11/7/18  
Reporting Centre Personnel's Signature  
Name: (WL)  
NRIC/FIN No.:







# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chumotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SLX295Y  
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)  
16 RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581

TEL: 68277660 FAX: 62257402  
ATTN: Motor Claim Department

Estimate No: ES1890771 /WL  
Date: 12 Jul 2018  
Policy No: 5099730627  
Veh Reg No: SLX295Y  
Make/Model: PROTON EXORA 1.6L  
AT (M-LINE) ABS D/AB  
2WD  
Chassis No: PL1FZ6YRRAF017952  
Engine No: S4PHQB2575  
Reg. Date: 03/11/2009

WS Ref: TP/MSIG/WL  
Claim Type: Third Party  
Accident Date: 11/07/2018  
TP Veh Reg No: SKT9130M

Not Attached  
1/ Aug 8?  
Resurvey After Paint  
6 days

## Estimate Repair Cost to Vehicle No :SLX295Y

| Description   | U/Price | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|---|---------|----------|-------------------|---------------|
| <b>List Price</b>   |         |          |                   |               |
| 1 REAR BUMPER   | 612.00  | 1 PC     | 612.00            | ✓             |
| 2 REAR BUMPER REINFORCEMENT   | 385.00  | 1 PC     | 385.00            | ✓             |
| 3 REAR BUMPER CLIPS   | 2.80    | 6 PCS    | 16.80             | ✓             |
| 4 TAILGATE EMBLEM (CPS)   | 35.00   | 1 PC     | 35.00             | ✓             |
| 5 TAILGATE EMBLEM (EXTRA)   | 38.00   | 1 PC     | 38.00             | ✓             |
| 6 REAR PANEL  | 390.00  | 1 PC     | 390.00            | ✓             |
| 7 FRONT BUMPER  | 590.00  | 1 PC     | 590.00            | ✓             |
| 8 FRONT NUMBER PLATE GARNISH  | 52.00   | 1 PC     | 52.00             | ✓             |
| 9 FRONT BUMPER CLIPS  | 2.80    | 6 PCS    | 16.80             | ✓             |
|   |         |          | 2,135.60          |               |
|   |         | Less 10% | 213.56            | 1,922.04      |
| <b>Special Net</b>  |         |          |                   |               |
| 10 FRONT NUMBER PLATE   | 35.00   | 1 PC     | 35.00             | ✓             |
| 11 REVERSE SENSOR   | 200.00  | 1 SET    | 200.00            | ✓             |
|   |         |          | 235.00            | 235.00        |
| <b>Labour</b>   |         |          |                   |               |
| 12 REMOVE & REFIX REAR BUMPER<br>ASSY, REINFORCEMENT, KNOCK & REPAIR PANEL, BOOT &<br>REALIGN THE SAME      | 700.00  | 1 LA     | 700.00            | 600           |
| 13 PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, BOOT<br>& REAR AFFECTED AREAS                                | 700.00  | 1 LA     | 700.00            | 600           |
| 14 REMOVE & REFIX FRT BUMPER ASSY, GRILLE, KNOCK &<br>REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE<br>SAME | 400.00  | 1 LA     | 400.00            | 300           |
| 15 PUTTY & RESPRAY ON FRT BUMPER, GRILLE &<br>REINFORCEMENT   | 450.00  | 1 LA     | 450.00            | 250           |
|   |         |          | 2,250.00          | 2,250.00      |

Total S\$ 4,407.04  
Add GST @ 7% 308.49  
Total Amount Payable S\$ 4,715.53

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 11 Jul 2018 |               | 12 Jul 2018<br>15:49<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,100.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,100.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>  |   |                        |  |          |         |             |              |            |       |
| Insured:  | PAUL JEYA SAMUEL, ID: S1500881D   |                        |  |          |         |             |              |            |       |
| Main Claimant:  | MOHAMED NUR MUBBIN BIN ABDUL KADIR, ID: S7341792I   |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | SLX295Y   | Date of Loss:          | 11/07/2018 06:00 - :59<br>[104 Months and 8 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | TP / 564079   | Policy/Cover Note No.: | A29072524AVW (Comprehensive)<br>Coverage: 09/02/2018 - 24/06/2019            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | SKT9130M  | Policy No. (Claimant): |  |          |         |             |              |            |       |
|   |   | Excess:                | S\$2,000.00  |          |         |             |              |            |       |
| Repairer:   | Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05, 757700 Woodlands - Tel: 6765 6142 |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]   |                        |  |          |         |             |              |            |       |
| Adjuster:   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/08/2018]   |                        |  |          |         |             |              |            |       |
| Driver/Custodian (Insured):   | MICHAEL JAMES SAMUEL (25 / Male), NRIC: S9318030E   |                        |  |          |         |             |              |            |       |
| Adj Asg. Remarks:   | SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (KENNETH KONG) LIABILITY: 100% CONTACT: JUNE PHUA 6755 6142           |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |   |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |  |          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |  |          |         |             |              |            |       |



## Claim Documents

**\*SLX295Y (564079)**  
**[SKT9130M]**  
**TP**  
**MOHAMED NUR MUBBIN BIN ABDUL KADIR**  
**Jul 11 2018 6:00AM**  
**[PAUL JEYA SAMUEL]**  
**Cheng Hoe Motor Pte Ltd**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

**View** View in Browser

| Assessment Reports |                |                                   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                  | 16/07/18 14:39 | Adjuster Immediate Advice         | Load HTM   |                                     |

| Photos/Images |                 |                                   | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 2             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 3             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 4             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 5             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 6             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 7             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 8             | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 9             | 31/12/18 10:07  | Odometer Reading                  | Load JPG   | <input checked="" type="checkbox"/> |
| 10            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 11            | 31/12/18 10:07  | Chassis Number                    | Load JPG   | <input checked="" type="checkbox"/> |
| 12            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 13            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 14            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 15            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 16            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 17            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 18            | 31/12/18 10:07  | General View                      | Load JPG   | <input checked="" type="checkbox"/> |
| 19            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 20            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 21            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 22            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 23            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 24            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 25            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 26            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 27            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |
| 28            | 31/12/18 10:10  | Reinspection Photo                | Load JPG   | <input checked="" type="checkbox"/> |

| Documentation |                |   | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|---|------------|-------------------------------------|
| No            | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1             | 12/07/18 09:51 | OI SKT9130M E-FILE REPORT                 | Load PDF   |                                     |
| 2             | 12/07/18 09:51 | SLX295Y TP E-FILE REPORT                  | Load PDF   |                                     |
| 3             | 12/07/18 09:51 | EMAIL FROM TP TO ASSIGN SURVEY            | Load PDF   |                                     |
| 4             | 12/07/18 10:06 | SURVEY AGREE ON SJE - LKK (KENNTH KONG).  | Load PDF   |                                     |

Documents Checklist

|   |                       |                      |                       |
|---|-----------------------|----------------------|-----------------------|
| <b>DOCUMENTS CHECKLIST</b>  | <a href="#">Reset</a> | <a href="#">Save</a> | <a href="#">Print</a> |
| There are no document checklists configured.                                  |                       |                      |                       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |                       |                      |                       |
| <div></div>   |                       |                      |                       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |                       |                      |                       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |                       |                      |                       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012713/KSD3E2

Date: 03/01/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29072524AVW

Claimant Vehicle No : SLX295Y

Insured Vehicle No : SKT9130M

Date of Loss: 11/07/2018

Nature of Claim: TP

Claim No: 564079

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLX295Y

Make &amp; Model: PROTON EXORA, 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A)

Engine No: S4PHQB2575

Reg. Date: 03/11/2009 (Man. Year: 2009)

Chassis No: PL1FZ6YRRAF017952

Colour: Metallic Silver

Odometer: 125258 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 2,157.04   | 2,157.04   | 0.00       | 0.00   |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 2,250.00   | 1,750.00   | 500.00     | 22.22  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 4,407.04   | 3,907.04   | 500.00     | 11.35  |
| Approved Total (Overridden) (S\$) |            | 3,100.00   |            |        |
| (S\$)                             | 4,407.04   | 3,100.00   | 1,307.04   | 29.66  |
| + GST 7.00/7.00% (S\$)            | 308.49     | 217.00     | 91.49      | 29.66  |
| Nett Amount (S\$)                 | 4,715.53   | 3,317.00   | 1,398.53   | 29.66  |

## INSPECTION

Date of Assignment: 12/07/2018

Date Inspected: 13/07/2018 Inspected At:

BLK 1019 YISHUN IND PARK A #01-374

Repairer : Cheng Hoe Motor Pte Ltd

(Woodlands)

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|                      |  |   |
|----------------------|--|---|
| <b>Reference</b>     |  |   |
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 03 Jan 2019)                                       |
| <b>Parts:</b>        | M1-MPV   | PROTON EXORA 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)   |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLX295Y)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

## Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition        | Repairer's | Amount     |
|-----|-----|----------|-----------------------------|------------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                | Buckled          | 612.00 FL  | *612.00 FL |
| 2   | 1   |          | *REAR BUMPER REINFORCEMENT  | Bent             | 385.00 FL  | *385.00 FL |
| 3   | 6   |          | *REAR BUMPER CLIPS          | Necessary        | 16.80 FL   | *16.80 FL  |
| 4   | 1   |          | *TAILGATE EMBLEM (CPS)      | Necessary        | 35.00 FL   | *35.00 FL  |
| 5   | 1   |          | *TAILGATE EMBLEM (EXTRA)    | Necessary        | 38.00 FL   | *38.00 FL  |
| 6   | 1   |          | *REAR PANEL                 | Bent             | 390.00 FL  | *390.00 FL |
| 7   | 1   |          | *FRONT BUMPER               | Buckled / Dented | 590.00 FL  | *590.00 FL |
| 8   | 1   |          | *FRONT NUMBER PLATE GARNISH | Dented / Cut     | 52.00 FL   | *52.00 FL  |
| 9   | 6   |          | *FRONT BUMPER CLIPS         | Necessary        | 16.80 FL   | *16.80 FL  |
| 10  | 1   |          | *FRONT NUMBER PLATE         | Cracked          | 35.00 FS   | *35.00 FS  |
| 11  | 1   |          | *SET REVERSE SENSOR         | Shorted          | 200.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>2,370.60</b> | <b>2,370.60</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | <b>213.56</b>   | <b>213.56</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>2,157.04</b> | <b>2,157.04</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's      | Amount          |
|-------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>     |  |          |                 |                 |
| 1                       | REMOVE & REFIX REAR BUMPER ASSY, REINFORCEMENT, KNOCK & REPAIR PANEL, BOOT & REALIGN THE SAME      | New      | 700.00          | 600.00          |
| 2                       | PUTTY & RESPRAY ON REAR PANEL, REAR BUMPER, BOOT & REAR AFFECTED AREAS                             | New      | 700.00          | 600.00          |
| 3                       | REMOVE & REFIX FRT BUMPER ASSY, GRILLE, KNOCK & REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE SAME | New      | 400.00          | 300.00          |
| 4                       | PUTTY & RESPRAY ON FRT BUMPER, GRILLE & REINFORCEMENT  | New      | 450.00          | 250.00          |
| Gross Labour Cost (S\$) |  |          | <b>2,250.00</b> | <b>1,750.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >