



Your Ref: C0447003

Date: 24th July 2018

Our Ref: CS3/AXA17015306/Bqbe2-1

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKW 4802A
INSURED VEHICLE: SGB 2498R
ACCIDENT DATE: 04/08/2017

We thank you for your instruction on 12/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKW 4802A from M/s Par Automotive Consultancy.
- b) Final Repair Bill of SKW 4802A from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SKW 4802A.
- d) Colour damaged vehicle photographs of SKW 4802A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SKW 4802A
Make & Model : Nissan Sylphy 1.6 CVT
Year of Registration : 2015
Chassis Number : MNTBBAB17Z0024984
Engine Capacity : 1598 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.