

ASS. REC. BY:

REF:

CS/EG18012742/Kvd3/72

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG1

Date/Time:

13/07/2018 @ 9:46am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EZ 4428C

Insured:

GBG 8186J

at Workshop m/s

Lai Huet (Meng Kee)

Tel:

6453 8110

of

Blk 160 Sin Ming Drive #04-01

Policy No:

Claim No:

DSMcv1801347 / SL / P

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/07/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 13/7/18 @ 9:50am

Person Contacted:

Jenny

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	EZ 4428C-X
	GBG 8186J-X
16/7/18 @ 10:30am	vehicle still not in yet. called jenny.
25/7/18	Revert thru email
10/8/18	@ 4:44pm Jenny will email us finalised

Lum Sum:

10 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/7	File pass to Catherine
30/8	11Lp @ 835d confirmed by email (Red 4641.60, 36%)

RECEIVED 30 AUG 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

30/8 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

350

Report Format:

TP

Lump Sum / I.B.I. (\$) 8350/2