

ASS. REC. BY:

REF:

CS3/CTI18012749/Dead32

Special Instruction:

Surveyor  
meinenBryen  
wendy

ASSIGNMENT (Office)

From (Person):

of CTI

Date/Time 13/7/18 @ 9.28am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 3308J

Insured:

SJN 2226K

at Workshop n/s

My Car Consultant

Tel: 9888 8885

of

53 Ubi Ave 1 # 01-24

Policy No

DMPCSN/1102581807

Claim No:

8NM18D03365C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/07/2018

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time: 10:03am @ 13/7/18

Person Contacted:

Jeremy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	
	GX 3308J-NA/INC18012367/24	DOA: 05/07/2018
	SJN 2226K-NA/INC18012367/24	DOA: 05/07/2018
17/7/18	After Repair	


## ASSIGNMENT

COE 2019 March

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GX 33085 Yr Regn: 2004, March  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Litae C.C. 2184  
 Colour: White. A/C: Insured / Std / NI / NA  
 Sp. Reading: 267911 T/Radio: Insured / Std / NI / NA  
 Eng/No: 3C3 990620  
 C/No: CR425008707  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil S/Rim / STD A/Rim or  
 Tyre Size: F: 165 R13C  
 R: — — —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Yokohama

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. <u>05/07/2018</u>		D.O.I. <u>13/07/2018</u>

Survey held at My Car Page 101

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Teiping SSN 2226K PRS</u>
<u>8/9/8</u>	<u>submit PRS Report</u>
	<u>MV MV 36K</u> <u>vehicle balance 8 months at time of loss.</u>
	<u>LTA 3.1K</u> <u>dep abt 5.5K / year.</u>
	<u>HL 500</u>
	<u>If vehicle car lost of car is about 2K to 2.5K with 5 dy.</u>
	<u>grv.</u>

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

S \* RS. \$

Photos

Others

TOTAL

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2018		13 Jul 2018 09:28 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MR STEVE HO WAI SHING, ID: S7597018H		
Main Claimant:	FENG SHAN WEI TRADING, Co. Reg. No.: 53128148E		
Vehicle Reg. No.:	GX3308J	Date of Loss:	05/07/2018 16:00 - :59
Claim Type:	TP / SNM18D03365C02	Policy/Cover Note No.:	DMPCSN1102581807 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN2226K	Policy No. (Claimant):	5053771971-06
		Excess:	S\$0.00
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/07/2018]		
Driver/Custodian (Insured):	STEVE HO WAI SHING (STEVE HE WEICHENG) (42 / Male), NRIC: S7597018H, Tel: +6593837926		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Our Ref: 2018.1333.PD.MCC (GX3308J)  
Your Ref: SJN2226K

11 July 2018

**China Taiping Insurance (Singapore) Pte Ltd**  
(Motor Claims Dept)  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909  
Attn: Motor Claims Department

**BY EMAIL ONLY**  
[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
**CLAIMANT: FENG SHAN WEI TRADING**  
**TRAFFIC ACCIDENT ON 5 JULY 2018 AT 16:00 HRS ALONG THOMSON ROAD**  
**TOWARDS BALESTIER ROAD INVOLVING VEHICLES NO. GX3308J &**  
**SJN2226K**

We are instructed by **FENG SHAN WEI TRADING** to notify you of a road accident on 5 July 2018 at about 16:00 hrs along Thomson Road towards Balestier Road involving our clients' vehicle registration number GX3308J and vehicle registration number SJN2226K driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: **My Car Consultant Pte Ltd**  
Address: 53 Ubi Avenue 1  
#01-24, Paya Ubi Industrial Park  
Singapore 408934  
Contact: Jeremy @ 9888 8885 /  
Carmen @ 8321 0988 /  
Yvonne @ 9129 6469

Please liaise with the above workshop directly.

Yours faithfully

  
Esther Moey  
Email: [claims@esthermoey.com](mailto:claims@esthermoey.com)  
encs

**PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION**

.....

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/07/2018 18:35
Date Of Accident	05/07/2018 16:00
Exact Location Of Accident	THOMSON RD TWDS BALESTIER RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX3308J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FENG SHAN WEI TRADING
Co Reg No	53128148E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

### Vehicle Particulars

Manufacturer	TOYOTA
Model	LITEACE 2.2M
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5053771971-06
Cover Note Number	

### Driver

Name of Driver	GOH BOON HONG
NRIC No	S1561676H
Date Of Birth	19/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	30/11/2001
Driving Experience	16 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90033381
Fax Number	
Contact Number	OFFICE-90033381
Email Address	NOEMAIL

Address	4 CHENG SOON GARDEN
Postcode	599784
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN2226K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA5759L
Vehicle Make/Model/Colour	

#### Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name GOH BOON HONG

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? GX3308J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection<sup>1</sup>, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle A was travelling along Thomas Road towards Belvoir Int,  
I was at my own lane 4, in front of me the vehicle slow down  
and came to a stop, so I also follow to slow down and came to  
a stop, suddenly the vehicle B from behind bang on to my rear  
portion of my vehicle A. I felt a impact, when I came down of  
my vehicle A then I realise that there are 3 vehicle involved.

## DECLARATION

I hereby declare that the above particulars are true in every respect.

PENG SHAN JIE

Policyholder's Signature  
Date & Time:

GABAR, Street 1, Kuching, VI

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/VIN No.:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CT118012749/Dz4d3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-07-2018



Code : CTI

## Policy Particulars :- (THIRD PARTY CLAIM)

1.	Insured Veh.	SJN 2226K	Veh. Inspected	GX 3308J
	Policy No.	DMPCSN1102581807	Coverage (\$)	0.00
	Claim No.	SNM18D03365C02	Excess (\$)	0.00
	Assign From	MERIMEN (IRENE TAY)	Assign Date	13/07/2018

## Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

## Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

## Description of Damages

4.	
----	--

## General Information

5.	Accident Date	05/07/2018	Inspection Date	13/07/2018
	Survey held at	UNITED SG AUTOMOBILE - 53 UBI AVE 1 #01-56		
	Repairer	MY CAR 1		

## Remarks

5a.	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
-----	--

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2018		13 Jul 2018 09:28 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	MR STEVE HO WAI SHING, ID: S7597018H		
Main Claimant:	FENG SHAN WEI TRADING, Co. Reg. No.: S3128148E		
Vehicle Reg. No.:	GX3308J	Date of Loss:	05/07/2018 16:00 - :59 [171 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03365C02	Policy/Cover Note No.:	DMPCSN1102581807 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN2226K	Policy No. (Claimant):	5053771971-06
		Excess:	\$0.00
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 24/07/2018]		
Driver/Custodian (Insured):	STEVE HO WAI SHING (STEVE HE WEICHENG) (42 / Male), NRIC: S7597018H, Tel: +6593837926		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

























There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents




















\*GX3308J (SNM18D03365C02)  
[SJN2226K]  
TP  
FENG SHAN WEI TRADING  
Jul 5 2018 4:00PM  
[MR STEVE HO WAI SHING]  
My Car Consultant Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)				Thumbnail		Print	
1	06/07/18 18:45	Accident Statement				 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)				Thumbnail		Print	
1	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
2	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
3	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
4	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
5	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
6	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
7	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
8	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
9	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
10	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
11	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
12	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
13	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
14	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
15	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
16	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
17	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
18	06/07/18 18:42	Accident Photo [Linked Accident Report Documents]				 Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	17/08/18 13:38	Rear View Left				 Load JPG		<input checked="" type="checkbox"/>	
2	17/08/18 13:38	Rear View Right				 Load JPG		<input checked="" type="checkbox"/>	
3	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	17/08/18 13:38	General View				 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
10	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/08/18 13:38	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/08/18 13:38	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
20	17/08/18 13:38	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
21	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
22	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
23	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
24	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
25	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
26	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
27	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
28	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
29	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
30	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
31	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
32	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
33	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
34	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
35	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
36	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
37	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
38	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
39	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
40	17/08/18 13:39	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/07/18 09:28	PRI WITH TP GIA	Load PDF	
2	13/07/18 09:28	OI GIA	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/07/18 18:41	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 18:41	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/07/18 18:45	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/07/18 18:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
2	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	06/07/18 18:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/07/18 18:41	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 18:41	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div></div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18012749/DZ4D3E2

Date: 20/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN1102581807

Claimant Vehicle  
No : GX3308JInsured Vehicle  
No : SJN2226K

Date of Loss: 05/07/2018

Nature of Claim: TP

Claim  
No: SNM18D03365C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GX3308J

Make &amp; Model: TOYOTA LITEACE, 2.2 D (A)

Engine No: 3C3990620

Reg. Date: 31/03/2004 (Man. Year: 2004)

Chassis No: CR425008707

Colour: White

Odometer: 267911 km

Engine Capacity: 2184 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 165 R13C

Rear Tyre Size: 165 R13C

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 13/07/2018

Date Inspected: 13/07/2018 Inspected At:

My Car Consultant Pte Ltd (Ubi)  
53 Ubi Ave 1, #01-24, Paya Ubi Industrial  
Park  
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: Ho Zhao Tian



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,500.00

## REPAIR DETAILS

### Reference

Part Source:	(Last Synchronised: 20 Aug 2018)	
Parts:	N/A	TOYOTA LITEACE 2.2 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX3308J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >