(08/11/13) wef

ASS. REC. BY: Rasu

REF: AXA

0043K

ASSIGNMENT

From: _____ Date: 13/07/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 2207C

at Workshop m/s Lex Build International

of 2 Woodlands Sec. 1 # 05-12

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) 3pm @ owner waiting

Make of Veh: Shirley @ 96158280

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PC 2207C Yr Regn: 2013 / DKL

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Sunlong SLK6770B c.c 3760

Colour MULTI A/C: Insured / Std / NI / NA

Sp.Reading 175573 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LJM1DAGCXCAS01223

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/75R17.5

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front		Rear	
R/Bal.	7 mm	R/Bal.	7/7 mm
L/Bal.	7 mm	L/Bal.	7/7 mm
D.O.A.	19/06/18	D.O.I.	13/07/18

Survey held at LEXBUILD

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) _____ ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee:	
Transportation: ___S + RS, ___SI	
Photos	
Others	
TOTAL	