

22/03/2002

ASS. REC. BY:

REF: CS3 / ASM18012776 / GZ4462 Special Instruction:

Survivor:

GQ

ASSIGNMENT (Office)

Smart claim

From (Person):

Stacy Ng

of

ASM

Date/Time:

13072018 1035am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 724T

Insured:

SCW 10P

at Workshop m/s

Motor Intel

Tel:

of

13 Kaki Bukit Rd 4 #01-20

Policy No:

Claim No:

SSM000CO

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

13072018 278pm

Person Contacted:

Time

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJK 724T - X

SCW 10P - CS/ATG08006182 / Rc

DA: 17012008

Dismantle: 28/7/2018



Service Request Details

Claim

S8M00OC0

Reference

None 

Loss Date

July 11, 2018

Request Date

July 13, 2018

Due Date

July 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJK724T

Make

TPVD

Model

TBC

Service Address

...

Primary Contact/Insured

KUOK KHONG HONG @ KUOK KHOON HONG
6 QUEEN ASTRID GARDENS, 266865, Singapore

pl@anika.sg

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions
NON REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)