

ASS. REC. BY:

REF: CS3/SM017024471/Urd3-1

Special Instructions

SURVIVOR: Marcus

ASSIGNMENT (Office)

From (Person): Agnes Chan of SMO

Date/Time: 13/07/2018

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLV 57D

Insured: PC 2228S

at Workshop no: Imperium Automotive

Tel: 9748 9940

of 25 kaki Bkt Rd 4 #01-49

Policy No: _____

Claim No: CM7D1704672/AGC

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 26/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

Date/Time: 12.25pm 27/12/17 Person Contacted: Shawn

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time Action/Instruction ☒ Estimating

SLV 57D - X

PC 2228S - X

* Change v/c to V2 Auto

63295170

Dismantle: 3/1/2018

After repair: 30/1/2018

LTA Rebate as of 29-12-17 \$100990

note MV 129

LTA 100990

20 days

Submit L/S \$39K

net 28010

Submit L/S \$39,200.00 @ 20 days

Red: \$10,570.00, 21%

* Please note MV: \$129K (Est), LTA Rebate: \$100,990.00

Net value: \$28,010.00

→ (Include in Report)

1150 - 270 = 230

Signature: Marcu

REF:

SMD

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: 6
OD / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLV5-7D
at Workshop this: Merium
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: 129k.
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 18 days Res: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV5-7D Regn: 29/8/2012
Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA

Make: Audi A8L cc: 2995
Colour: Black A.C. Insured / Std / NI / NA
Sp. Reading: 54840 T.Radio: Insured / Std / NI / NA

Eng No: _____
C.No: WAUZZZ4H5DN005962

Gen. Cond: Good / Fair / Poor / Burnt
Steering: In Order / Jammed / Leaked / Burnt or
Brake: In Order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: _____ R: 255/45-19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /
TOYO / YOKO or

Front: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. 27/1/17

Survey held at: U2A @ 10.01pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & R/L
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction L7A 100990
501 4yrs 8mth. 2y 18mo Nett 28010
maybe 123k. maybe TOTAL 1055
22-28

RECEIVED 16 MAY 2018

Date/Time: File Pass to? ☐ : Prelim. Report
☐ : Final Report

Date/Time: File Return to? _____

Report Format: PRG
Lump Sum / I.B.I: \$ _____

Days Of Repair: 18
Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ Tech Invs \$
☐ Weekend \$

Survey Fee
Transportation
Photost
Other

100
60+60
220

Nivitha (LKK Auto)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Sent: Friday, 13 July 2018 2:51 PM
To: 'assignments' (assignments@lkkauto.com); 'sur@lkkauto.com'
Subject: PAPER RE-INSPECTION OF SV57D; OUR REF: CMTD1704672; YOUR REF: CS3/SMO17024471/Ud3e2
Attachments: 1437_001.pdf; SAS2330967.PDF; SAS2330949.PDF; SAS2331299.PDF; 1438_001.pdf; 1439_001.pdf

Dear LKK

We refer to the above matter.

We herewith enclosed GIA reports, the repair bill the photographs and the survey report for your attention.

Please prepare the paper resurvey of SLV57D.

Please forward the report with the market value status within 5 days.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

VZ AUTOMOTIVE PTE LTD

1 Kaki Bukit Avenue 6 #02-02 Autobay Singapore 417883

Tel: 6555 7272 Fax: 6741 1019

E-Mail: vzauto@iova.com.sg

Final Repair Bill

Date: 20/03/2018

Vehicle No : SLV 57 D
Make/Model : Audi A8 3.0 TFSI QU
Name : Chin Kin Leong Terence
Address : 57 Chislehurst Grove
Singapore 558640

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Third Party Accident Claim for Motor Vehicle No. SLV 57 D
Date of Accident: 26/12/2017

.....
S\$49,770.00
(Lump Sum)

Singapore Dollars: Forty-Nine Thousand Seven Hundred and Seventy Only





PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 2014044340

INVOICE

Mr Chin Kin Leong Terence
57 Chiselhurst Grove
Singapore 558640

Invoice No. : HA/1803-37

Date : 22/03/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 1,874.00
SGD Dollar : One Thousand Eight Hundred Seventy Four Dollars Only.	
Our Reference : PAS/TP/0501217	
Vehicle No. : SLV57D	
Make & Model : Audi A8L 3.0 TFSI QU	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".
Please indicate our "INVOICE NO." on the reverse side of the cheque.
Should you have any enquiries, please do not hesitate to contact us.

For PROMINENT APPRAISER SERVICES PTE LTD



VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0501217

Date of Report : 22/03/2018

To: Mr Chin Kin Leong Terence
57 Chiselhurst Grove
Singapore 558640

Date of Assignment : 29/12/2017
Report requested by : Mr Chin Kin Leong Terence
Date of Accident : 26/12/2017
Date of Inspection : 29/12/2017
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLV57D
Make & Model : Audi A8L 3.0 TFSI QU
Date of Registration : 29/08/2012
Colour : Black

Engine Capacity (cc) : 2995cc
Mileage (km) : 54841km
Chassis / Frame No. : WAUZZZ4H5DN005962
Engine No. : CGW051645

TYRE CONDITION

Front LH : 6 mm
Make : Pirelli

Front RH : 6 mm
Make : Pirelli

Rear LH : 6 mm
Make : Pirelli

Rear RH : 6 mm
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. VZ Automotive Pte Ltd
1, Kaki Bukit Ave 6, Autobay @ Kaki Bukit, #02-02, Singapore 417883

ASSESSMENT

Repairer's Estimate : \$ 69,066.81
Revised Amount : \$ 62,215.82
Less Excess : \$ -
Recommended Reserve : \$ 49,770.00 (Lump Sum)

Estimated Normal Period of Repairs : 25 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No. : SLV57D

S/No. Labour Descriptions

Report No. : PAS/TP/0501217

Repairer's	Our
Estimate (S\$)	Assessment (S\$)

Total (Parts & Labour) :	\$ 69,066.81	\$ 62,215.82
--------------------------	--------------	--------------

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 49,770.00

Under normal circumstances, the repairs should be completed within a reasonable period
of 25 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

284 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



Vehicle No : SLV57D

Report No. : PAS/TP/0501217

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. VZ Automotive Pte Ltd, 1, Kaki Bukit Ave 6, Autobay @ Kaki Bukit, #02-02, Singapore 417883.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, radiator assy, a/c condenser, intercooler, cooling fans, headlamps, front grilles, boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, rear exhaust silencer, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$62,215.82.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$49,770.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Report No.: PAS/TP/0501217

Vehicle No.: SLV57D

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Bonnet	Dented/Buckled 5814	\$ 5,878.40	\$ 5,878.40 ✓
2	1 pc	Bonnet top seal	Torn/Necessary	\$ 145.20	\$ 145.20 ✓
3	1 pc	Bonnet bottom seal	Torn	\$ 50.60	\$ 50.60 ✓
4	1 pc	Bonnet insulator	Refit	\$ 277.20	\$ 475.20 X
5	2 pcs	Bonnet hinge R/L	Bent	\$ 237.60	\$ 475.20 X
6	2 pcs	Bonnet hinge absorber R/L	Refit	\$ 103.40	\$ 202.40 ✓
7	1 pc	Bonnet lock hook	Dented/Bent	\$ 202.40	\$ 136.40 ✓
8	1 pc	Bonnet top lock striker	Dented/Bent	\$ 136.40	\$ 211.20 ✓
9	2 pcs	Bonnet bottom lock assy R/L	Dented/Jammed	\$ 105.60	\$ 211.20 ✓
10	2 pcs	Bonnet bottom lock bracket R/L	Bent	\$ 136.40	\$ 272.80 ✓
11	1 pc	Bonnet lock cable assy	Torn	\$ 66.00	\$ 66.00 ✓
12	2 pcs	Headlamp R/L 3809x2-7018	Broken/Cracked	\$ 3,546.40	\$ 7,092.80 ✓
13	1 pc	Frt grille assy	Broken	\$ 1,661.00	\$ 1,661.00 ✓
14	1 pc	Frt grille emblem	Dented/Cracked	\$ 107.80	\$ 107.80 ✓
15	1 pc	Frt grille emblem bracket	Dented/Cracked	\$ 83.60	\$ 83.60 ✓
16	1 pc	Frt bumper	Dented	\$ 2,932.60	\$ 2,932.60 ✓
17	2 pcs	Frt bumper washer nozzle R/L	RH Cracked	\$ 231.00	\$ 462.00 ✓
18	2 pcs	Frt bumper washer noz. cover R/L	RH Missing	\$ 112.20	\$ 112.20 ✓
19	2 pcs	Frt bumper park sensor	Dented/Damaged	\$ 217.80	\$ 435.60 ✓
20	2 pcs	Frt bumper side grille R/L	RH Dented/Cracked	\$ 369.60	\$ 369.60 ✓
21	1 pc	Frt bumper absorber	Cracked/Broken	\$ 110.00	\$ 110.00 ✓
22	1 pc	Frt bumper reinforcement	Dented	\$ 957.00	\$ 957.00 ✓
23	2 pcs	Frt bumper bracket R/L	Dented/Bent	\$ 44.00	\$ 88.00 ✓
24	2 pcs	Frt bumper side guide R/L	Cracked/Necessary	\$ 50.60	\$ 101.20 ✓
25	1 pc	Frt support top cover	Dented/Cracked	\$ 110.00	\$ 110.00 ✓
26	1 pc	Frt support panel assy	Dented/Cracked	\$ 981.20	\$ 981.20 ✓
27	2 pcs	Frt support top side member R/L	Dented/Bent	\$ 171.60	\$ 343.20 ✓
28	1 pc	Intercooler	Dented/Bent	\$ 1,010.00	\$ 1,010.00 ✓
29	1 pc	Radiator assy	Dented/Bent	\$ 1,206.00	\$ 1,206.00 ✓
30	1 pc	Radiator support air duct	Broken	\$ 48.40	\$ 48.40 ✓
31	2 pcs	Radiator deflector (air guide) R/L	Cracked/Deformed	\$ 61.60	\$ 123.20 ✓
32	1 pc	Radiator fan cowl	Dented/Cracked	\$ 536.80	\$ 536.80 X
33	1 pc	Radiator fan assy	Dented/Damaged	\$ 2,632.00	\$ 2,632.00 X
34	1 pc	A/c condenser fan assy	Dented/Damaged	\$ 2,632.00	\$ 2,632.00 X
35	1 pc	A/c condenser	Dented/Bent	\$ 867.00	\$ 867.00 ✓
36	1 pc	A/c discharge pipe	Refit	\$ 365.20	\$ - X
37	1 pc	A/c suction pipe	Refit	\$ 499.40	\$ - X
38	1 pc	A/c liquid pipe	Dented/Bent	\$ 132.00	\$ 132.00 ✓
39	1 pc	A/c ambient sensor	Broken/Dislodged/Mission	\$ 165.00	\$ 165.00 ✓
40	2 pcs	Horn R/L	Dented/Damaged	\$ 508.00	\$ 508.00 ✓
41	1 pc	P/steering cooling pipe	Dented	\$ 869.00	\$ 869.00 ✓
42	1 pc	Air cleaner assy	Broken	\$ 655.60	\$ 655.60 ✓
43	1 pc	Boot lid	Dented	\$ 4,070.00	\$ 4,070.00 ✓
44	1 pc	Boot emblem Logo	Cracked/Necessary	\$ 107.80	\$ 107.80 ✓
45	1 pc	Boot emblem A8L	Necessary	\$ 83.60	\$ 83.60 ✓
				\$ 40,862.80	\$ 38,801.40



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Report No. : PAS/TP/0501217

Vehicle No. : SLV57D

S/No. Labour Descriptions

Repairer's Estimate (\$\$) Our Assessment (\$\$)

\$ 40,862.80 \$ 38,801.40

46	1 pc	Boot emblem 3.0	Necessary		\$ 83.60	\$ 83.60	✓
47	1 pc	Boot emblem Quattro	Necessary		\$ 83.60	\$ 83.60	✓
48	2 pcs	Boot reflector lamp R/L	Cracked/Broken	\$ 1,270.60	\$ 2,541.20	\$ 2,541.20	✓
49	2 pcs	Boot reflector lamp side cover R/L	Cracked	\$ 52.80	\$ 105.60	\$ 105.60	✓
50	1 pc	Boot reverse camera	Damaged		\$ 1,183.60	\$ 1,183.60	X
51	1 pc	Boot no.plate garnish (w/lamp)	Dented/Cracked		\$ 364.00	\$ 364.00	✓
52	1 pc	Boot inner trim	Torn/Deformed		\$ 796.00	\$ 796.00	✓
53	1 pc	Boot lock assy	Bent/Jammed		\$ 121.00	\$ 121.00	✓
54	1 pc	Boot lock striker	Bent		\$ 11.00	\$ 11.00	✓
55	1 pc	Boot lock motor assy	Dented/Damaged		\$ 1,496.00	\$ 1,496.00	✓
56	2 pcs	Boot hinge R/L	Bent	\$ 337.00	\$ 674.00	\$ 674.00	✓
57	1 pc	Boot weatherstrip	Torn		\$ 356.40	\$ 356.40	✓
58	2 pcs	Taillamp R/L	Broken	\$ 1,353.00	\$ 2,706.00	\$ 2,706.00	✓
59	2 pcs	Taillamp side cover R/L	Broken	\$ 26.40	\$ 52.80	\$ 52.80	✓
60	1 pc	Rr bumper top	Dented		\$ 3,245.00	\$ 3,245.00	X
61	1 pc	Rr bumper bottom	Dented		\$ 594.00	\$ 594.00	✓
62	1 pc	Rr bumper chrome moulding	Dented/Cracked		\$ 792.00	\$ 792.00	✓
63	2 pcs	Rr bumper reverse sensor	Dented/Damaged	\$ 215.60	\$ 431.20	\$ 431.20	✓
64	2 pcs	Rr bumper side guide	Cracked/Necessary	\$ 28.60	\$ 57.20	\$ 57.20	✓
65	1 pc	Rr bumper center guide	Dented/Cracked		\$ 55.00	\$ 55.00	✓
66	1 pc	Rr bumper center bracket	Dented/Broken		\$ 61.60	\$ 61.60	✓
67	1 pc	Rr bumper reinforcement	Dented		\$ 1,328.80	\$ 1,328.80	✓
68	1 pc	Taillamp panel R/L	Dented/Distorted		\$ 132.00	\$ 132.00	✓
69	2 pcs	Rr fender inner trim R/L	Serviceable	\$ 1,160.00	\$ 2,320.00	\$ -	α
70	1 pc	Rr end panel outer	Dented		\$ 497.20	\$ 497.20	✓
71	1 pc	Rr end panel filler plate	Dented		\$ 451.00	\$ 451.00	✓
72	1 pc	Rr end panel inner	Dented		\$ 239.80	\$ 239.80	✓
73	1 pc	Rr end panel garnish	Cracked/Deformed		\$ 435.60	\$ 435.60	✓
74	1 pc	Rr floor panel compartment	Dented/Repair		\$ 906.40	\$ -	α
75	1 pc	Rr floor trim	Serviceable		\$ 576.40	\$ -	α
76	1 pc	Rr floor compartment cover	Dented/Deformed		\$ 899.00	\$ 899.00	α
77	1 pc	Frt fender R/L	Dented/Repair			(Refer to labour no.7)	α
78	1 pc	Frt chassis member R/L	Dented/Repair			(Refer to labour no.7)	X
79	1 pc	Rr fender R/L	Dented/Repair			(Refer to labour no.15)	α
80	1 pc	Rr floor panel	Dented/Repair			(Refer to labour no.15)	α
81	1 pc	Rr chassis member R/L	Dented/Repair			(Refer to labour no.15)	α

\$ 64,459.80 \$ 58,595.60

Less Discount : 5% \$ 3,222.99 5% \$ 2,929.78

List Parts Sub-Total : \$ 61,236.81 \$ 55,665.82

1	1 set	Frt no.plate (w/bracket)	Broken	\$ 50.00	\$ 50.00	✓
2	1 bot	Radiator coolant	Necessary	\$ 60.00	\$ 60.00	✓
3	1 set	Rr no.plate (w/bracket)	Cracked	\$ 50.00	\$ 50.00	✓
4	1 pc	Rr end panel sealant	Necessary	\$ 40.00	\$ 40.00	✓

Special Nett Sub-Total : \$ 200.00 \$ 200.00

Parts Total : \$ 61,436.81 \$ 55,865.82



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Address 1 Simei St 3 #02-24 S(529890)
Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No. : SLV57D

Report No. : PAS/TP/0501217

S/No. Labour Descriptions

Repairer's Estimate (S\$) Our Assessment (S\$)

1	Towing.	\$ 100.00	\$ 80.00 ✓
2	To check front electrical system, repair wire harness and calibrate/focus headlamp.	\$ 80.00	\$ 60.00 30
3	To remove, replace and reinstall intercooler assy & pipings. (Include pressure test air intake system)	\$ 100.00 11	\$ 80.00 X
4	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$ 120.00	\$ 120.00 1100
5	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$ 100.00	\$ 100.00
6	To remove, replace and/or transfer front parking sensors to new bumper.	\$ 60.00	\$ 40.00 ✓
7	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 1,200.00	\$ 990.00 700
8	To spray painting, blending on front affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 700
9	To conduct chassis alignments (Frt/Rr).	\$ 350.00 11	\$ 300.00 X
10	To check rear electrical wiring system and repair wire harness.	\$ 80.00	\$ 50.00 30
11	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$ 180.00	\$ 150.00 80
12	To transfer boot component parts to new boot.	\$ 150.00	\$ 120.00 80
13	To remove, replace and/or transfer rear reverse sensors to new bumper.	\$ 60.00	\$ 40.00 ✓
14	To straighten, repair and realign rear exhaust muffler.	\$ 100.00 11	\$ 80.00 X
15	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 1,500.00	\$ 1,320.00 800
16	To spray painting, blending on rear affected and adjacent area.	\$ 1,500.00	\$ 1,200.00 1100
17	To spray anti-rust coating on new and affected panels.	\$ 150.00	\$ 120.00 ✓
18	To inspection, diagnose, reset and perform coding programming on:-		
	18.1) Parking sensor control system.		
	18.2) Boot lock control system.		
	18.3) Comfort access system.		
	18.4) Stabilisation control system.		
	18.5) Hill hold assist control system.		
	18.6) Engine Start-Stop control system.		
	18.7) Parking brake control system.		
	18.8) Tyre pressure control system.		
	18.9) Air suspension control system.		
		\$ 600.00	\$ 500.00 300

Labour Total :

\$ 7,630.00

\$ 6,350.00

69066-81

4200

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/12/2017 16:55
Date Of Accident 26/12/2017 11:40
Exact Location Of Accident CTE TWDS AYE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV57D
Insured/Policyholder
Name Of Registered Owner CHIN KIN LEONG TERENCE
NRIC No S8031881B
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98571275
Alternative Phone No OFFICE-98571275

Vehicle Particulars

Manufacturer AUDI
Model A8
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA294043/1
Cover Note Number

Driver

Name of Driver CHIN KIN LEONG TERENCE
NRIC No S8031881B
Date Of Birth 12/10/1980
Occupation INDOOR
Date Of Driving Pass 30/11/2000
Driving Experience 17 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98571275
Fax Number
Contact Number OFFICE-98571275
Email Address NOEMAIL

Address	57 CHISELHURST GROVE
Postcode	558640
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG CTE (AYE). I WAS IN THE SECOND LANE. SUDDENLY, THE LORRY IN FRONT OF ME BRAKED TO STOP. I WAS ABLE TO STOP IN TIME BEHIND IT. HOWEVER, I WAS HIT IN THE BACK BY A BUS. THE IMPACT FORCED MY CAR FORWARD CASUING IT TO HIT THE LORRY IN FRONT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC2228S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YP3878J
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE C

COMMERCIAL VEHICLE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26/12/17

Driver's Signature

(If driver is not the policyholder)


Date & Time: 26/12/17

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along CTE(AYE). I was in the second lane. Suddenly, the lorry in front of me braked to a stop. I was able to stop in time behind it. However, I was hit in the back by a bus. The impact forced my car forward, causing it to hit the lorry in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 26/12/17

Driver's Signature

(If driver is not the policyholder)

Date & Time: 26/12/17

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, CHIN KIN LEONG TORRES, the owner of vehicle no. SLV57D

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, IMPERIUM AUTO

Signed and Acknowledge by:

S8031881B
Nric no. and signature of policyholder

.....
Company Stamp

26/12/2019
Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2017 10:43
Date Of Accident	26/12/2017 11:40
Exact Location Of Accident	CTE(CITY) NEAR TO BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2228S
Insured/Policyholder	
Name Of Registered Owner	STEADFAST TRANSPORT SERVICE
Co Reg No	53004741A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-84232871

Vehicle Particulars

Manufacturer	ANKAI
Model	HFF6107K05-6.7 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	BUS
------------------	-----

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	FANG ZHONGMING
NRIC No	G8043644R
Date Of Birth	09/05/1978
Occupation	OUTDOOR
Date Of Driving Pass	01/10/2007
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84232871
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 20

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLV57D
 Vehicle Make/Model/Colour AUDI - BLACK
 Details Of Properties FRONT & REAR
 Vehicle Category PRIVATE CAR
 Name of Driver CHIN KIN LEONG
 NRIC/Passport Number S8031881B
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YP3878J
 Vehicle Make/Model/Colour FUSO - WHITE

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

REAR

GOODS VEHICLE

SUTRADHAR ARADHON

G8402920W

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Anikka Lai
CSO

SKETCH PLAN



A: PC33285

B: SLV 57D

C: YP3878J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2017 @ about 11:40 hrs, my vehicle (A) was travelling along CTE (City) with about 20 passengers on board. While approaching near to Braddell exit, my vehicle was queuing along the lane heading to PIE and all of the vehicles were moving on & off. Suddenly veh C jam brake, and my vehicle (A) ~~was~~ could not stop in time and hit onto veh B rear portion. then veh B surged forward to hit veh C. rear portion. Veh A and B had moderate damage and veh C had minor damage. No injury involved in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time:

Anikka Lai
CSOReporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SOMPO

Sompo Insurance Singapore Pte. Ltd.
90 Raffles Place, #05-01/02 Singapore Land Tower, Singapore 041622
Tel: 6461 6655 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M20003116

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D17MTSCBU000727
1. Registration No. : PC2228S
2. Insured Name : STEADFAST TRANSPORT SERVICE
3. Commencement Date : 20 DECEMBER 2017 00:00
4. Expiry Date : 19 DECEMBER 2018 23:59
5. Coverage : Market value at time of loss - Comprehensive
6. Excess : \$3000 - Section I
 : \$1000 - Section II

7. Persons or Classes of Persons entitled to drive*
b) Any person provided he is in the Insured's employ and is driving on their order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

8. Limitations as to use*
a) Use only for the carriage of passengers or goods in connection with the Insured's business.
b) Use only in the Republic of Singapore.

The Policy does not cover

- 1) Use for racing, pacemaking, reliability trial or speed-testing.
- 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

9. ExcelDrive Workshops & Accident Reporting
It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, otherwise claim is not payable.

In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency Hotline : (65) 6226 3323

Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers

Hire Purchase : MERCEDES BENZ FINANCIAL SERVICES SINGAPORE LIMITED



I/We HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Sompo Insurance Singapore Pte. Ltd.

Stella

Date/Time of Issue : 22 NOVEMBER 2017 11:22

*Limitation rendered inoperative by section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189 and section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

IMPORTANT NOTICE

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).
3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle.
4. Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.
5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy.

Intermediary Code & Name : 11913002 & SSTA INSURANCE AGENCY PTE LTD CI Code: Z3H F6DZMY2NKNYMEAJ

REPUBLIC OF SINGAPORE DRIVING LICENCE

FANG ZHONGMING

09 May 1978

01 Oct 2015

Valid Till 26 Jun 2018

002351438K

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
STEADFAST TRANSPORT SERVICE

Sector: SERVICE

Name:
FANG ZHONGMING

Occupation:
BUS DRIVER

Work Permit No.:
0 57639121

Date of Application:
01-09-2015

Date of Issue:
31-08-2017

Date of Expiry:
11-08-2019

L8269805

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3: Motor cars <= 2000 kg with <= 7 passengers, exclusive of the driver, and motor tractors/vehicles <= 2500 kg

Class 4: Heavy motor cars and motor tractors > 2500 kg

01 Oct 2017

11 Mar 2015

S / No. 9000217818

C8043644R

NP 428A

Licence No: C8043644R

VISIT PASS
Immigration Regulations

Name:
FANG ZHONGMING

Date of Birth:
09-05-1978

Sex:
M

Nationality:
CHINESE

Fin:
08043844R

Date of Issue:
31-08-2017

Date of Expiry:
11-08-2019

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 16:46
Date Of Accident	26/12/2017 11:50
Exact Location Of Accident	CTE>AYE NEAR TP BRADELL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP3878J
Insured/Policyholder	
Name Of Registered Owner	SHUNXUE BUILDERS PTE. LTD.
Co Reg No	201224592C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082507645-01
Cover Note Number	

Driver

Name of Driver	SUTRADHAR ARADHON
Passport No/FIN	G8402920W
Date Of Birth	15/03/1980
Occupation	INDOOR
Date Of Driving Pass	28/11/2014
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93839575
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 7030 AMK AE 5 #08-36
NORTH STAR BUILDING
Postcode 569880
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLV57D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number PC2228S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SUTRADHAR ARADHON

Approximate Age

Injuries Sustain

WHISPLASH BACKACHE

Injured person in which vehicle?

YP3878J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

7030 AMK AE 5 #08-36 NORTH START BUILDING

Postcode

569880

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415922
Reporting Centre Person's Signature
Name: Fax: 67492305
NRIC/ID No: Email: vacb@singnet.com.sg

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2017 at about 11:50am I was traveling along CTE Towards AYE near Braddell Exit.

Suddenly I was stationary due to front traffic. Suddenly later I felt an impact. I was involved with a three vehicles chain collision.

Vehicle A: no passengers.

Vehicle B: 1 passenger.

Vehicle C: unknown number of passengers.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature
Date & Time:

Araden

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:
Fax: 67492305
Email: vac@singnet.com.sg

Denise Tay (LKKAUTO)

From:
Sent:
To:
Subject:

Nora Khai <nora.khai@premiumauto.com.sg>
Thursday, 11 January 2018 2:34 PM
Denise Tay (LKKAUTO)
RE: HELP ME CHECK PART PRICE

Hi Denise,

Please refer to the pricing below,

Audi A8 2012 Model

C/no. WAUZZZ4H5DN0105962

Boot lid - \$4023
Boot lid inner lock - \$170
Boot lid Reflector LH - \$1339 (LED)
Boot lid inner trim - \$400
Rear Bumper - \$3211
Rear Bumper Reverse sensor - \$211 (1pc)
Rear Bumper reinforcement - \$1315
Tail lamp LH - \$1339 (LED)
Rear end panel - inner \$494 / outer \$448 / lower \$237
Bonnet - \$5814
Headlamps LH & RH - \$3509 (1pc)
Front grille - \$1645
Front Bumper - \$2902
Front bumper Reinforcement - \$948
Condenser - \$867
Radiator - \$1206
Radiator for assy - \$1010 (additional radiator)
Front lock carrier - \$972

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Now is calling
The all-new Audi Q5



Find out more



27/12/2017

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1881B

Vehicle Details

Vehicle No.: SLV57D
Vehicle to be Exported: No
Intended De-registration Date: 29 Dec 2017
Vehicle Make: AUDI
Vehicle Model: A8L 3.0 TFSI QU (SR+HID)
Primary Colour: Black
Manufacturing Year: 2012
Engine No.: CGW051645
Chassis No.: WAUZZZ4H5DN005962
Maximum Power Output: 213.0 kW (285 bhp)
Open Market Value: \$89,445.00
Original Registration Date: 29 Aug 2012
First Registration Date: 29 Aug 2012
Transfer Count: 2
Actual ARF Paid: \$89,445.00 4722
Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Aug 2022
PARF Rebate Amount: \$62,611.00
Intended COE Rebate Details
COE Expiry Date: 28 Aug 2022
COE Category: B - Car (1601cc & above)

27/12/2017

PARF/COE Rebate Enquiry

10

COE Period(Years):

\$82,289.00

QP Paid:

\$38,379.00

COE Rebate Amount:

\$100,990.00

Total Rebate Amount:

The information contained herein is correct as at 27 Dec 2017

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO17024471/Urd3e2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 21-08-2018



Code : SMO

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	PC 2228S	Veh. Inspected	SLV 57D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704672/AGC	Excess (\$)	0.00
Assign From	AGNES CHAN	Assign Date	13/07/2018

Vehicle Particulars & Condition

2.

Make & Model	AUDI A8L (A)	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WAUZZZ4H5DN005962	Colour	BLACK
Odometer	54840	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre	255/45 R19	PIRELLI	6 mm
L/H Front Tyre	255/45 R19	PIRELLI	6 mm
R/H Rear Tyre	255/45 R19	PIRELLI	6 mm
L/H Rear Tyre	255/45 R19	PIRELLI	6 mm

Description of Damages

4.

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

General Information

5.

Accident Date	26/12/2017	Inspection Date	27/12/2017
Survey held at	25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB S (417800)		
Repairer	V Z AUTOMOTIVE PTE. LTD.		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Estimate Days of Repair

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 20 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 57D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
		NECESSARY	83.60	83.60
1	BOOT EMBLEM A8L	BUCKLED	5,878.40	5,814.00
1	BONNET	TORN	145.20	145.20
1	BONNET TOP SEAL	TORN	50.60	50.60
1	BONNET BOTTOM SEAL	NOT NECESSARY	277.20	-
1	BONNET INSULATOR	NOT NECESSARY	475.20	-
2	BONNET HINGE R/L @\$237.60	NOT NECESSARY	206.80	-
2	BONNET HINGE ABSORBER R/L @\$103.40	TWISTED	202.40	202.40
1	BONNET LOCK HOOK	TWISTED	136.40	136.40
1	BONNET TOP LOCK STRIKER	BENT	211.20	211.20
2	BONNET BOTTOM LOCK ASSY R/L @\$105.60	BENT	272.80	272.80
2	BONNET BOTTOM LOCK BRACKET R/L @\$136.40	TORN	66.00	66.00
1	BONNET LOCK CABLE ASSY	CRACKED	7,092.80	7,018.00
2	HEADLAMP R/L @\$3546.40	BROKEN	1,661.00	1,661.00
1	FRT GRILLE ASSY	CRACKED	107.80	107.80
1	FRT GRILLE EMBLEM	CRACKED	83.60	83.60
1	FRT GRILLE EMBLEM BRACKET	DENTED	2,932.60	2,932.60
1	FRT BUMPER	O/S CRACKED	462.00	231.00
2	FRT BUMPER WASHER NOZZLE R/L @\$231.00	O/S TORN	224.40	112.20
2	FRT BUMPER WASHER NOZ. COVER R/L @\$112.20	SHORTED	435.60	435.60
2	FRT BUMPER PARK SENSOR @\$217.80	N/S CRACKED	739.20	369.60
2	FRT BUMPER SIDE GRILLE R/L @\$369.60	TORN	110.00	110.00
1	FRT BUMPER ABSORBER	TO REPAIR SEE LABOUR	957.00	-
1	FRT BUMPER REINFORCEMENT	BENT	88.00	88.00
2	FRT BUMPER BRACKET R/L @\$44.00	CRACKED	101.20	101.20
2	FRT BUMPER SIDE GUIDE R/L @\$50.60	CRACKED	110.00	110.00
1	FRT SUPPORT TOP COVER	DENTED / CRACKED	981.20	981.20
1	FRT SUPPORT PANEL ASSY	BENT	343.20	343.20
2	FRT SUPPORT TOP SIDE MEMBER R/L @\$171.60	CAN'T SEE DAMAGE	1,010.00	-
1	INTERCOOLER	BENT / PUNCTURE	1,206.00	1,206.00
1	RADIATOR ASSY	BROKEN	48.40	48.40
1	RADIATOR SUPPORT AIR DUCT	DEFORMED	123.20	123.20
2	RADIATOR DEFLECTOR (AIR GUIDE) R/L @\$61.60			

Report Ref No. CS3/SMO17024471/Urd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN COWLING	NOT CHANGED	536.80	-
1	RADIATOR FAN ASSY	NOT CHANGED	2,632.00	-
1	A/C CONDENSER FAN ASSY	NOT CHANGED	2,632.00	-
1	A/C CONDENSER	BENT / PUNCTURE	867.00	867.00
1	A/C DISCHARGE PIPE	NOT NECESSARY	365.20	-
1	A/C SUCTION PIPE	NOT CHANGED	499.40	-
1	A/C LIQUID PIPE	BENT	132.00	132.00
1	A/C AMBIENT SENSOR	BROKEN	165.00	165.00
2	HORN R/L @\$254.00	CAN'T SEE DAMAGE	508.00	-
1	P/STEERING COOLING PIPE	BENT	869.00	869.00
1	AIR CLEANER ASSY	BROKEN	655.60	655.60
1	BOOT LID	BUCKLED	4,070.00	4,070.00
1	BOOT EMBLEM LOGO	NECESSARY	107.80	107.80
1	BOOT EMBLEM 3.0	NECESSARY	83.60	83.60
1	BOOT EMBLEM QUATTRO	NECESSARY	83.60	83.60
2	BOOT REFLECTOR LAMP R/L @\$1270.60	BROKEN	2,541.20	2,541.20
2	BOOT REFLECTOR LAMP SIDE COVER R/L @\$52.80	CRACKED	105.60	105.60
1	BOOT REVERSE CAMERA	NO PHOTO SHOW DAMAGE	1,183.60	-
1	BOOT NO. PLATE GARNISH (W/LAMP)	CRACKED	364.00	364.00
1	BOOT INNER TRIM	TORN	796.00	796.00
1	BOOT LOCK ASSY	BENT	121.00	121.00
1	BOOT LOCK STRIKER	BENT	11.00	11.00
1	BOOT LOCK MOTOR ASSY	DAMAGED	1,496.00	1,496.00
2	BOOT HINGE R/L @\$337.00	BENT	674.00	674.00
1	BOOT WEATHERSTRIP	TORN	356.40	356.40
2	TAILLAMP R/L @\$1353.00	BROKEN	2,706.00	2,678.00
2	TAILLAMP SIDE COVER R/L @\$26.40	CUT	52.80	52.80
1	RR BUMPER TOP	DENTED	3,245.00	3,211.00
1	RR BUMPER BOTTOM	NO PHOTO SHOW DAMAGE	594.00	-
1	RR BUMPER CHROME MOULDING	BENT	792.00	792.00
2	RR BUMPER REVERSE SENSOR @\$215.60	SHORTED	431.20	431.20
2	RR BUMPER SIDE GUIDE @\$28.60	NECESSARY	57.20	57.20
1	RR BUMPER CENTER GUIDE	CRACKED	55.00	55.00
1	RR BUMPER CENTER BRACKET	BROKEN	61.60	61.60

Report Ref No. CS3/SMO17024471/Urd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR BUMPER REINFORCEMENT	BENT	1,328.80	1,315.00
1	TAILLAMP PANEL R/L	DENTED	132.00	132.00
2	RR FENDER INNER TRIM R/L @\$1160.00	SERVICEABLE	2,320.00	-
1	RR END PANEL OUTER	BADLY DENTED	497.20	497.20
1	RR END PANEL FILLER PLATE	BADLY DENTED	451.00	451.00
1	RR END PANEL INNER	BADLY DENTED	239.80	239.80
1	RR END PANEL GARNISH	CRACKED	435.60	435.60
1	RR FLOOR PANEL COMPARTMENT	TO REPAIR SEE LABOUR	906.40	-
1	RR FLOOR TRIM	SERVICEABLE	576.40	-
1	RR FLOOR COMPARTMENT COVER	NOT CHANGED	899.00	-
1	FRT FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT CHASSIS MEMBER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR CHASSIS MEMBER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-3,222.99	-2,347.65
			61,236.81	44,605.35
	SPECIAL NETT ITEMS			
1	SET FRT NO. PLATE (W/BRACKET) (SN)	BROKEN	50.00	50.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	60.00	60.00
1	SET RR NO. PLATE (W/BRACKET) (SN)	CRACKED	50.00	50.00
1	RR END PANEL SEALANT (SN)	NECESSARY	40.00	40.00
			200.00	200.00
	LABOUR			
	TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON :-		600.00	300.00
	18.1)PARKING SENSOR CONTROL SYSTEM.			
	18.2)BOOT LOCK CONTROL SYSTEM.			
	18.3)COMFORT ACCESS SYSTEM.			
	18.4)STABILISATION CONTROL SYSTEM.			
	18.5)HILL HOLD ASSIST CONTROL SYSTEM.			
	18.6)ENGINE START-STOP CONTROL SYSTEM.			
	18.7)PARKING BRAKE CONTROL SYSTEM.			
	18.8)TYRE PRESSURE CONTROL SYSTEM.			
	18.9)AIR SUSPENSION CONTROL SYSTEM.			

Report Ref No. CS3/SMO17024471/Urd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING.		100.00	80.00
	TO CHECK FRONT ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND CALIBRATE / FOCUS HEADLAMP.		80.00	30.00
	TO REMOVE, REPLACE AND REINSTALL INTERCOOLER ASSY & PIPINGS. (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM)	NOT NECESSARY	100.00	-
	TO REMOVE, REPLACE AND REINSTALL A/C CONDENSER & A/C PIPINGS. (INCLUDE VACUUM & RECHARGE A/C GAS) }		120.00	100.00
	TO REMOVE, REPLACE AND REINSTALL RADIATOR & COOLING SYSTEM. (INCLUDE PRESSURE TEST COOLING SYSTEM) }		100.00	-
	TO REMOVE, REPLACE AND / OR TRANSFER FRONT PARKING SENSORS TO NEW BUMPER.		60.00	40.00
	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS.		1,200.00	700.00
	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA.		1,200.00	700.00
	TO CONDUCT CHASSIS ALIGNMENTS (FRT/RR)	NOT NECESSARY	350.00	-
	TO CHECK REAR ELECTRICAL WIRING SYSTEM AND REPAIR WIRE HARNESS.		80.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.		180.00	80.00
	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT.		150.00	80.00
	TO REMOVE, REPLACE AND / OR TRANSFER REAR REVERSE SENSORS TO NEW BUMPER.		60.00	40.00
	TO STRAIGHTEN, REPAIR AND REALIGN REAR EXHAUST MUFFLER.	NOT NECESSARY	100.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT BUMPER REINFORCEMENT, RR FLOOR PANEL COMPARTMENT, FRT FENDER R/L, FRT CHASSIS MEMBER R/L, RR FENDER R/L, RR FLOOR PANEL AND RR CHASSIS MEMBER R/L.		1,500.00	800.00
	TO SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,500.00	1,100.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		150.00	120.00
			7,630.00	4,200.00
	GRAND TOTAL		69,066.81	49,005.35

Report Ref No. CS3/SMO17024471/Urd3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			39,200.00
---	--	--	-----------

Report Ref No. CS3/SMO17024471/Urd3e2-1

MARKET VALUE: \$129,000.00(EST)-LTA REIMBURSEMENT VALUE: \$100,990.00=NETT VALUE: \$28,010.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.