

ASS. REC. BY:

REF

CS3/MSG18012788/Gzad302

Special Instruction:

Surveyor
Meinen

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Elaine Ng

of

MSIG

Date/Time:

13/07/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 9304E

Insured:

FBM 9920T

at Workshop m/s

Reliable Carz

Tel:

8166 9797

of

8 Kaki Bukit Ave 4 #05-50

Policy No:

MSD/VMW/18-384892-CA

Claim No:

MSC/v/18-000945

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/07/2018

CA / REV / REP. / REV 24 HRS

lap

H.O.D. Endorsement:

Date/Time:

4:55pm @ 13/7/18

Person Contacted:

Jason

Vehicle IN

OUT

Date/Time	Action/Instruction	Estimate
	GX 9304E -X	
	FBM 9920 T-X	
18/7/18	Dismantled	

(08/11/13) wef

ASS. REC. BY:

REF: MSIG

C8180R

ASSIGNMENT

(-2019)

From: Date: 17/07/18

Estimated Cost:

OP: TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GX 9304E

at Workshop m/s Reliable Carz

of 8 Kelki Bkt Ave 4 # 05-50 premier

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Jusun @ 8166 9797

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$10k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 6X9304E

Yr Regn: 03 Nov 2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan URVAN c.c 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 397115 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN/MG4E 2580712037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or OHTSU

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 17-07-18

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

24/7/18 Submit PRS Report.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018		13 Jul 2018 17:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD IRSADI BIN MUNARIS, ID: S8319358A		
Main Claimant:	BENJI PET SERVICES PTE LTD, Co. Reg. No.: 20143180R		
Vehicle Reg. No.:	GX9304E	Date of Loss:	10/07/2018 22:00 - :59 [164 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000945	Policy/Cover Note No.:	MSD/VMW/18-384892-CA (Comprehensive) Coverage: 13/06/2018 - 12/06/2019
Vehicle Reg. No. (Insured):	FBM9920T	Policy No. (Claimant):	
		Excess:	
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/07/2018]		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (ADRIAN LING) OI NOT REPORTED CONTACT: JASON LEE 8166 9797		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18012788/Gz4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-07-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBM 9920T	Veh. Inspected	GX 9304E	
Policy No.	MSD/VMW/18-384892-CA	Coverage (\$)	0.00	
Claim No.	MSC/V/18-000945	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/07/2018	Inspection Date	17/07/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2018 11:29
Date Of Accident	10/07/2018 22:45
Exact Location Of Accident	WEST COAST PARK TWDS JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX9304E
Insured/Policyholder	
Name Of Registered Owner	BENJI PET SERVICES PTE LTD
Co Reg No	20143180R
Email Address	RELIABLECARZPL@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63423383

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	GA292041/1
Cover Note Number	19/12/2017-18/12/2018

Driver

Name of Driver	CHEN YANTI
NRIC No	S7889866F
Date Of Birth	25/03/1978
Occupation	INDOOR
Date Of Driving Pass	17/02/2011
Driving Experience	7 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98284921
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 212/214 JOO CHIAT PLACE SINGAPORE 427922

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM9920T

Vehicle Make/Model/Colour HONDA

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver MUHAMMAD IRSADI

NRIC/Passport Number S8319358A

Contact Number 96488684

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Insured Person's
Date & Time

Authorised Driver's
Date & Time

Reporting Centre Personnel's Signature
Date & Time

SKETCH PLAN

A: Gx9304E B: FBM9920T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

10-7-2018 晚上 10:45pm 行经在 West Coast Park 的
17301 巴士站时 突然听到我的车后面传来一声巨响
下车查看 - 一辆摩托车 (车牌: FBM9920T) 撞到我
前后左右都没有其它车辆。我问摩托车手
他说没看见我的车。

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

AXA FORM



redefining PROTECTION

Date: 12/04/18

To: Owner of Vehicle Number: 67893046



The following has been advised to you via your workshop, through their staff:

Please tick the applicable box if you had been advised on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☒ The estimated waiting time for the spare parts to arrive is _____ The estimated arrival time does not include the repair period.
- ☒ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- ☒ For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for **Own Damage** repairs or workmanship related to the accident.
- ☒ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others: Noted Sat. policy at other workshop



Signature and acknowledge by

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1801R

Vehicle Details

Vehicle No.:	GX9304E
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	ZD30044415
Chassis No.:	JN1MG4E25Z0712037
Maximum Power Output:	-
Open Market Value:	\$21,779.00
Original Registration Date:	03 Nov 2004
First Registration Date:	03 Nov 2004
Transfer Count:	6
Actual ARF Paid:	\$1,089.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,133.00
COE Rebate Amount:	\$7,053.00
Total Rebate Amount:	\$7,053.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 23 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jul 2018		13 Jul 2018 17:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MUHAMMAD IRSADI BIN MUNARIS , ID: S8319358A									
Main Claimant: BENJI PET SERVICES PTE LTD , Co. Reg. No.: 20143180R									
Vehicle Reg. No.: GX9304E		Date of Loss: 10/07/2018 22:00 - :59 [164 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000945		Policy/Cover Note No.: MSD/VMW/18-384892-CA (Comprehensive) Coverage: 13/06/2018 - 12/06/2019							
Vehicle Reg. No. (Insured): FBM9920T		Policy No. (Claimant):							
		Excess:							
Repairer: Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 14/07/2018]									
Adj Asg. Remarks: SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK (ADRIAN LING) OI NOT REPORTED CONTACT: JASON LEE 8166 9797									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GX9304E (MSC/V/18-000945)**
[FBM9920T]
TP
BENJI PET SERVICES PTE LTD
Jul 10 2018 10:00PM
[MUHAMMAD IRSADI BIN MUNARIS]
Reliable Carz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
2	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
3	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
4	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
5	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
6	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
7	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
8	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
9	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
10	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
11	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
12	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
13	24/07/18 10:46	General View						Load JPG	<input checked="" type="checkbox"/>	
14	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
15	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
16	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
17	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
18	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
19	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
20	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
21	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
22	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
23	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
24	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
25	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
26	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
27	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
28	24/07/18 10:47	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
							1 per page		<input checked="" type="checkbox"/>	
Documentation										
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	13/07/18 14:40	PRI - CROSSBORDERS LLC						Load PDF		
2	13/07/18 15:11	SURVEY AGREE ON SJE - LKK (ADRIAN LING).						Load PDF		
3	13/07/18 15:13	GX9304E TP E-FILE REPORT						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012788/GZ4D3E2

Date: 24/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMW/18-384892-CA
Claimant Vehicle No :	GX9304E	Insured Vehicle No :	FBM9920T
Date of Loss:	10/07/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000945

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX9304E		
Make & Model:	NISSAN URVAN, 3.0 D (M)	Engine No:	ZD30044415
Reg. Date:	03/11/2004 (Man. Year: 2004)	Chassis No:	JN1MG4E25Z0712037
Colour:	Silver	Odometer:	397115 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 5 mm	Rear Left Side:	OHTSU 5 mm
Front Right Side:	OHTSU 5 mm	Rear Right Side:	OHTSU 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/07/2018		
Date Inspected:	17/07/2018	Inspected At:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50 Singapore 415875
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jul 2018)

Parts: N/A NISSAN URVAN 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GX9304E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >