

Surveyor

Rasu

ASSIGNMENT (Office)

aws

From (Person):

May Chua

of

FCI

Date/Time: 13/7/18 @ 5.15pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJW 617G

Insured:

SHC 8330J

at Workshop m/s:

GMA Auto Enterprise

Tel:

64587716 / 96729559

of

GD Mandai Estate #03-03

Policy No:

Claim No:

D18005327MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

08/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

16/7/18 @

Person Contacted:

Gibson

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SJW 617G - x

SHC 8330J - NA / FCI 16024622 / ST

DOA: 23/12/2016

Revert 1A via email

Confirm L/S \$1400 @ 4 days with Gibson (Red: \$1717.12, 55%.)

108/11/13) WBS
ASS. REC. BY: *Rama*

REF: FCI

5447K

EXP. 2020/1/16

ASSIGNMENT

From: Date: 16/07/2018

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW 617G
at Workshop m/s GMA Automotive
of GD Mandei Estate # 03-03

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Gibson @ 96729551

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$9k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW 617G Yr Regn: 2008 / 8P

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit C.C. 1339

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 17675 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GE61125994

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ OK or

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 08/07/18 D.O.I: 16/07/18

Survey held at GMA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

6/8 FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: \$9k, LTA: \$2805.00, NV: \$6195.00

RECEIVED 21 NOV 2013

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / 1st: (\$ 1400)

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

130

50

30

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012818/R1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8330J	Veh. Inspected	SJW 617G
Policy No.		Coverage (\$)	0.00
Claim No.	D18005327MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	16/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Chassis No.	HIDDEN	Year of Reg.	
Colour		Colour	
Steering		Steering	
Modification		Modification	
3. Conditions of Tyres			
	Size	Make	Balance
Front Left Tyre			mm
Front Right Tyre			mm
Rear Left Tyre			mm
Rear Right Tyre			mm
4. Description of Damages			
5. General Information			
Inspection Date	08/07/2018	Inspection Date	16/07/2018
Inspected at GMA AUTO ENTERPRISE LLP 6D MANDAI ESTATE #03-03 M-SPACE SINGAPORE 729938			
Remarks			
INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005327MFSH

Date: 21 November 2018

Our Ref: CS/FCI18012818/R1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 617G.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/07/2018 at the premises of M/s GMA AUTO ENTERPRISE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,117.12</u> .
Revised Estimate Amount	: S\$ <u>1,792.83</u> .
"Check" Items Amount	: S\$ <u>163.25</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s front portion.



Yours faithfully

RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-07-2018	Our Ref No. D18005327MFSH
Accident Date	08-07-2018	Claim Type. Third Party
Insured Vehicle	SHC8330J	Third Party Vehicle. SJW617G
Survey Location	6D MANDAI ESTATE #03-03 M-SPACE	
Contact Person.	GIBSON SOH	
Contact No.	64587716/ 96729559	Fax No. 64573091
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GMA AUTO ENTERPRISE LLP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242247)

PRI Documents

Close

PRI Header Details

Claim No	D18005327MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & GMA AUTI
Workshop Name	GMA AUTO ENTERPRISE LLP (Contact Person : GIBSON SOH)	Survey Location & Contact Details	6D MANDAI ESTATE #03-03 M-SPACE Mobile: 96729559 , Phone: 64587716 , Fax: 6457309 EmailId: GMAAUTO.RENTAL@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8330J	TP Vehicle No	SJW617G
PRI Recieved Date	13-07-2018 02:18:29 PM	Surveyor Appointed Date	13-07-2018 05:14:14 PM	Surveyor Accept Date	16-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-07-2018	Upload Survey Report *:	Choose File
-----------------------------	---	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, November 21, 2018 9:52 AM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18005327MFSH/1
Attachments: SJW 617G.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SJW 617G

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, July 16, 2018 9:02 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005327MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 13 July 2018 5:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005327MFSH/1

Dear Sir/Mdm,


We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Janice Lee (LKKAuto)

From: GMA AUTO ENTERPRISE <gmaauto.rental@gmail.com>
Sent: Wednesday, November 21, 2018 2:44 PM
To: Janice Lee (LKKAuto)
Subject: Re: SJW 617G FCI TP

Dear Jannice

Offer confirmed.
Please proceed accordingly.

Thank you

Gibson Soh
96729559

On Wed, Nov 21, 2018 at 9:38 AM Janice Lee (LKKAuto) <JaniceLee@lkkauto.com> wrote:

Dear Gibson,

Kindly confirm L/S \$1400 @ 4 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5447K
Vehicle Details	
Vehicle No.:	SJW617G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4139384
Chassis No.:	GE61125994
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$6,035.00
Original Registration Date:	17 Sep 2008
First Registration Date:	01 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$6,035.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,340.00
COE Rebate Amount:	\$2,805.00
Total Rebate Amount:	\$2,805.00

The information contained herein is correct as at 13 Oct 2018

OK

GMA Auto Enterprise LLP

6D Mandai Estate #03-03 M-Space, Singapore 729938

Tel: 6458 7716 (5 lines). Fax: 6457 3091

T12111035F

M/s First Capital Insurance Ltd
6 Raffles Quay
Singapore 048580

Date : 16-Jul-18

Line: 6222 2311

Attn: Motor Claim Dept

Re: Accident on 08/07/2018. Between SJW617G. AND SHC8330J (Your Insured)

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim**.

Parts

- 1pc Front door rh
- 1pc Front door glass retainer rh
- 1pc Front door protector rh
- 1pc Front door protector(chrome) rh
- 1pc Front door hinge rh
- 1pc Front door stopper rh
- 1pc Side mirror rh

Repair
Hp 90010068

4 days

4/8

16/07/18 @ 1645

Resurvey after repair

\$841.20 BT-
\$128.40 ? X h n
\$77.49 scx-
\$54.20 scx-
\$75.66 ? X pve
\$80.65 ne-
\$501.30 repair

Total: \$1,758.90

Less 20% \$351.78

Sub Total Parts: \$1,407.12

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.

To putty & respray paint on the relevant repaired areas.

To rust proof affected areas where necessary.

To remove, refix & check wiring in order to facilitate repairs.

To transfer front door components to new door to facilitate repair.

~~\$800.00~~ 400
~~\$600.00~~ 450
~~\$200.00~~ 40
~~\$40.00~~ X
~~\$180.00~~ 60

Parts & Labour Total: \$3,117.12

Your Faithfully,

GMA Auto Enterprise LLP



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012818/R1rd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8330J	Veh. Inspected	SJW 617G
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18005327MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	13/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61125994	Colour	RED
Odometer	176175	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/07/2018	Inspection Date	16/07/2018
Survey held at	GMA AUTO ENTERPRISE LLP 6D MANDAI ESTATE #03-03 M-SPACE SINGAPORE 729938		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 617G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH	BENT	841.20	841.20
1	FRONT DOOR GLASS RETAINER RH	NOT NECESSARY	128.40	-
1	FRONT DOOR PROTECTOR RH	SCRATCHED	77.49	77.49
1	FRONT DOOR PROTECTOR (CHROME) RH	SCRATCHED	54.20	54.20
1	FRONT DOOR HINGE RH	SERVICEABLE	75.66	-
1	FRONT DOOR STOPPER RH	NECESSARY	80.65	80.65
1	SIDE MIRROR RH	TO REPAIR SEE LABOUR	501.30	-
	LESS 20% DISCOUNT		-351.78	-210.71
			1,407.12	842.83
	LABOUR			
	TO REMOVE THE AFFECTED PARTS,ALL RELEVANT ATTACHMENTS,FITTINGS TO COMMENCE REPAIRS,REPLACE THE DAMAGED PARTS,REINSTALL & REALIGN ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF SIDE MIRROR RH.		800.00	400.00
	TO PUTTY & RESPRAY PAINT ON THE RELEVANT REPAIRED AREAS.		600.00	450.00
	TO RUST PROOF AFFECTED AREAS WHERE NECESSARY.		90.00	40.00
	TO REMOVE,REFIX & CHECK WIRING IN ORDER TO FACILITATE REPAIRS.	NOT NECESSARY	40.00	-
	TO TRANSFER FRONT DOOR COMPONENTS TO NEW DOOR TO FACILITATE REPAIR.		180.00	60.00
			1,710.00	950.00
	GRAND TOTAL		3,117.12	1,792.83
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FCI18012818/R1rd3n2

MARKET VALUE: \$9,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,805.00=NETT VALUE: \$6,195.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.