

22/03/2007

ASS. REC. BY:

REF: CS3/MSG18012821/G24d36 Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Catherine Chia

of

MSIG

Date/Time:

16/7/18 @ 9:39am

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 1068 M

Insured:

SKM 46 U

at Workshop m/s

JD Motorsports

Tel:

9237 3644

of

25 Kaki Bkt Rd 4 #06-38

Policy No:

A28786683 MCY

Claim No:

564214

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/07/2018

CA / REV / REP. / REV 24 HRS

lwp)

H.O.D. Endorsement:

Date/Time:

10:17am @ 16/7/18

Person Contacted:

Ronnie

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (x) Estimate
	SKA 1068 M-X
	SKM 46U-X
17/7/18	Dismantled.

10811/13
Surveyor


MS
xpl.

REF:

MSG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s JD Motor sports
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt.: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 1068M Yr Regn: 24 Apr 2015
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Vezel c.c. 1496
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 127697 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RU11018540
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60 R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Ling long

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 17-07-18
Survey held at w/s 9AM
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$4000 - \$5000</u>

24/7/18 submit PRS Report.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

120
50
10
180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		16 Jul 2018 09:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	AIK KOON TYRE & BATTERY CO PTE LTD, Co. Reg. No.: 199804700Z			
Main Claimant:	TAN TECK HIN (CHEN DEXING), ID: S7536350H			
Vehicle Reg. No.:	SKA1068M	Date of Loss:	07/07/2018 18:00 - :59 [38 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 564214	Policy/Cover Note No.:	A28786683MCY (Comprehensive) Coverage: 05/07/2018 - 04/07/2019	
Vehicle Reg. No. (Insured):	SKM46U	Policy No. (Claimant):		
		Excess:		
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/07/2018]			
Driver/Custodian (Insured):	KHOR GUO XIONG (), NRIC: S8932559E, Tel: +6596553607			
Adj Asg. Remarks:	liability: 100%. TP reject SJE - Assign LKK Auto consultants Pte Ltd. contact: Mr Ronnie Tay @ 9237 3644.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18012821/Gz4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 16-07-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKM 46U	Veh. Inspected	SKA 1068M	
Policy No.	A28786683MCY	Coverage (\$)	0.00	
Claim No.	564214	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	16/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/07/2018	Inspection Date	16/07/2018	
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2018 15:44
Date Of Accident	07/07/2018 18:00
Exact Location Of Accident	JURONG WEST AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1068M
Insured/Policyholder	
Name Of Registered Owner	TAN TECK HIN (CHEN DEXING)
NRIC No	S7536350H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90689075
Alternative Phone No	OFFICE-90689075

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098813574 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	TAN TECK HIN (CHEN DEXING)
NRIC No	S7536350H
Date Of Birth	28/11/1975
Occupation	OUTDOOR
Date Of Driving Pass	18/09/1992
Driving Experience	25 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90689075
Fax Number	
Contact Number	OFFICE-90689075
Email Address	NOEMAIL

Address	181A BOON LAY DRIVE #10-600
Postcode	S641181
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM46U
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

- 8 JUL 2019


IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6565 0722
Email: vacbb@singnet.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was braking due to my front vehicle brake the car behind me hit my car back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

- 8 JUL 2013

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659575
Tel: 6569 2112 Fax: 6569 0722
Email: vacb@singnet.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6350H
Vehicle Details	
Vehicle No.:	SKA1068M
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B3518554
Chassis No.:	RU11018540
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,860.00
Original Registration Date:	24 Apr 2015
First Registration Date:	24 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$8,860.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2025
PARF Rebate Amount:	\$6,645.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,199.00
COE Rebate Amount:	\$38,609.00
Total Rebate Amount:	\$45,254.00

The information contained herein is correct as at 23 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018		16 Jul 2018 09:39 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------



































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	AIK KOON TYRE & BATTERY CO PTE LTD, Co. Reg. No.: 199804700Z	
Main Claimant:	TAN TECK HIN (CHEN DEXING), ID: S7536350H	
Vehicle Reg. No.:	SKA1068M	Date of Loss: 07/07/2018 18:00 - :59 [38 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564214	Policy/Cover Note No.: A28786683MCY (Comprehensive) Coverage: 05/07/2018 - 04/07/2019
Vehicle Reg. No. (Insured):	SKM46U	Policy No. (Claimant):
		Excess:
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 17/07/2018]	
Driver/Custodian (Insured):	KHOR GUO XIONG (), NRIC: S8932559E, Tel: +6596553607	
Adj Asg. Remarks:	liability: 100%. TP reject SJE - Assign LKK Auto consultants Pte Ltd. contact: Mr Ronnie Tay @ 9237 3644.	








































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKA1068M (564214)**
[SKM46U]
TP
TAN TECK HIN (CHEN DEXING)
Jul 7 2018 6:00PM
[AIK KOON TYRE & BATTERY CO PTE LTD]
Jd Motorsports Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/07/18 10:06	Accident Statement <small>From: SC - Reg. No: SKM46U, Claimant: AIK KOON TYRE & BATTERY CO PTE LTD</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/07/18 11:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/07/18 10:06	SKA1068M e-file report From: SC - Reg. No: SKM46U, Claimant: AIK KOON TYRE & BATTERY CO PTE LTD	 Load PDF	
2	13/07/18 10:06	tp pri request	 Load PDF	
3	13/07/18 17:06	tp reject sje - assign lkk	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012821/GZ4D3E2

Date: 24/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28786683MCY

Claimant Vehicle No : SKA1068M

Insured Vehicle No : SKM46U

Date of Loss: 07/07/2018

Nature of Claim: TP

Claim No: 564214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA1068M

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B3518554

Reg. Date: 24/04/2015 (Man. Year: 2015)

Chassis No: RU11018540

Colour: Blue

Odometer: 127697 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Linglong 6 mm

Rear Left Side:

Linglong 6 mm

Front Right Side: Linglong 6 mm

Rear Right Side:

Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 17/07/2018 Inspected At:

Jd Motorsports Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4, #06-38
SYNERGY@KB
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA1068M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >