Trans-cab Auto Services Pte Ltd

AAD1807-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

Vehicle No.: SHD 9759U

Chassis No.: VF1ABL15AUC276883

Vehicle Make:RENAULTVehicle Model:LATITUDEDate of Accident:8.7.2018

Third Party Insurer:

	-	PART	LIST
1	1	BUMPER COVER REAR	\$ 1,108.46
2	1	BUMPER LOWER REAR	\$ 768.84
3	1	BUMPER BRACKET CTR REAR	\$ 113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$ 135.97
5	1	BUMEPR RETAINER RH REAR	\$ 44.99
6	1	BUMPER REFLECTOR RH	\$ 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$ 135.97
8	1	BUMEPR RETAINER LH REAR	\$ 44.99
9	1	BUMPER REFLECTOR LH	\$ 43.61
10	1	BUMPER BEAM REAR	\$ 777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$ 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$ 225.95
13	1	BOOT REAR	\$ 2,872.68
14	1	BOOT FINISHER	\$ 470.06
15	1	BOOT WHEATERSTRIP	\$ 323.05
16	1	BOOT REFLECTOR LAMP LH	\$ 493.35
17		BOOT REFLECTOR LAMP RH	\$ 493.35
18		BOOT BADGE 'RENAULT'	\$ 225.36
19		BOOT BADGE	\$ 225.36
20	1	BOOT STRUT LH	\$ 276.08
21		BOOT STRUT RH	\$ 276.08
22		BOOT HINGE LH	\$ 367.84
23		BOOT HINGE RH	\$ 367.84
24		BOOT INNER TRIM	\$ 586.45
25		BOOT SWITCH	\$ 168.13
26		BOOT LOCK	\$ 202.67
27		BOOT LOCK CATCH	\$ 74.40
28		LICENCE PLATE LAMP	\$ 50.52
29	2	BOOT RUBBER PLUG	\$ 221.81

	s-cab Auto Services Pte Ltd Ang Mo Kio Street 63 Singapore 569111		AAD1807-0	
	o. : 6287 6666 Fax No. : 6257 1330			
CO./G	ST Reg. No. 201019626G			
	9759U			
30	1 DOOR PANEL REAR RH		\$	2,844.6
30	1 FENDER PANEL INNER TRIM REAR RH		\$	671.4
30	1 FENDER PANEL REAR RH		\$	3,299.1
31	1 WHEELARCH REAR RH		\$	543.4
32	1 TAILLAMP RH		\$	552.5
33	1 TAILLAMP PANEL RH		\$	986.7
34	1 TAILLAMP LH		\$	552.5
35	1 TAILLAMP PANEL LH		\$	986.7
36	1 OUTER PANEL REAR (End Panel)		\$	1,471.7
37	1 OUTER PANEL REAR (End Panel)TRIM		\$	404.5
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)		\$	2,189.8
39	1 SPARE WHEEL PANEL TRIM		\$	612.2
40	1 EXHAUST REAR		\$	7,489.0
41	1 EXHAUST CAP REAR		\$	230.4
		TOTAL	\$	24 100 5
		JUIAL		54.199.5
			•	
		101AL 10%	•	3,419.9
	Specical Nott		\$	3,419.9
	Specical Nett		\$	3,419.9
1 15	Specical Nett SET PARKING AID		\$	3,419.9 30,779.5
	·		\$	3,419.9 30,779.5 700.0
2 13	SET PARKING AID		\$ \$	3,419.9 30,779.5 700.0 66.0
2 15 3 15	SET PARKING AID SET REAR BUMPER CLIP		\$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0
2 15 3 15 4 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP		\$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0
2 15 3 15 4 15 5 15 6 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR		\$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0
2 15 3 15 4 15 5 15 6 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR		\$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 10.0
2 15 3 15 4 15 5 15 6 15 7 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR		\$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0
2 15 3 15 4 15 5 15 6 15 7 15 8 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP		\$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 22.0
2 13 3 13 4 13 5 13 6 13 7 13 8 13 9 13	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 22.0 66.0
2 13 3 13 4 13 5 13 6 13 7 13 8 13 9 13	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 22.0 66.0 17.8
2 15 3 15 4 15 5 15 6 15 7 15 8 15 9 15 10	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 22.0 66.0 17.8 24.2
2 15 3 15 4 15 5 15 6 15 7 15 8 15 9 15 10 11 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR SET BOOT FINISHER CLIP		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 22.0 66.0 17.8 24.2 30.0
2 15 3 15 4 15 5 15 6 15 7 15 8 15 9 15 10 11 15	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR SET BOOT FINISHER CLIP 1 BOOT STICKER "Frans-cab" 1 BOOT STICKER "6555-3333"		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 22.0 66.0 17.8 24.2 30.0 30.0
2 15 3 15 4 15 5 15 6 15 7 15 8 15 10 11 15 12 13	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR SET BOOT FINISHER CLIP 1 BOOT STICKER "Trans-cab" 1 BOOT STICKER "6555-3333"		\$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 66.0 17.8 24.2 30.0 30.0 45.0
2 15 3 15 4 15 5 15 6 15 7 15 8 15 9 15 10 11 15 12 13 14	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR SET BOOT FINISHER CLIP 1 BOOT STICKER "Trans-cab" 1 BOOT STICKER "6555-3333" 1 BOOT INNER TRIM CLIP		\$	3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 20.0 66.0 17.8 24.2 30.0 30.0 45.0 35.0
2 15 3 15 4 15 5 15 6 15 7 15 8 15 9 15 10 11 15 12 13 14	SET PARKING AID SET REAR BUMPER CLIP SET BUMPER BRACKET CTR CLIP SET BUMPER BRACKET SIDE CLIP RH RR SET BUMEPR RETAINER RH CLIP RR SET BUMEPR BRACKET SIDE CLIP LH RR SET BUMEPR RETAINER CLIP LH RR SET BUMPER LOWER REAR RIVET SET BUMPER LOWER REAR CLIP 1 EXHAUST MOUNTING REAR SET BOOT FINISHER CLIP 1 BOOT STICKER "Trans-cab" 1 BOOT STICKER "6555-3333" 1 BOOT INNER TRIM CLIP SET FENDER WHEELARCH REAR RH CLIP SET FENDER WHEELARCH REAR LH CLIP		\$	34,199.5 3,419.9 30,779.5 700.0 66.0 33.0 10.0 20.0 22.0 66.0 17.8 24.2 30.0 35.0 35.0 28.0

	As-cab Auto Services Pte Ltd Ang Mo Kio Street 63 Singapore 569111		AAD1807-070
	o. : 6287 6666 Fax No. : 6257 1330		
	GST Reg. No. 201019626G		
	9759U		
" •-			
19	1 TAILLAMP CLIP RH	\$	5.00
20	1 TAILLAMP CLIP LH	\$	5.00
21	2 REAR WINDSCREEN SELANT	\$	80.00
22	1 WINDSCREEN MOULDING	\$	100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00
25	1 SPARE TYRE	\$	330.00
	ТОТА	L \$	2,225.02
	TOTAL PART	\$	33,004.61
	LABOUR	-	
	Putty And Spray Painting Of The Affected Portion.	\$	3,750.00
	Panel Beating, Knocking And Straightening The		
	Necessary Portion, Remove And Renewal Of Parts,		
	Adjust And Realign The Same	\$	3,200.00
	To Rust-Proofing Of The Affected Areas.	\$	170.00
	To reinstall rear bumper parking sensor.	\$	170.00
	To transfer of bootlid fittings, attachments and		
	perform water seepage test.	\$	170.00
	To repair and realign rear exhaust pipe.	\$	170.00
	To drop rear exhaust box, renew the same, to repair		
	and realign centre exhaust pipe.	\$	170.00
	To transfer of rear end panel fittings, attachment and		
	perform water seepage test.	\$	170.00
	To transfer of rear luggage floor panel fittings,		
	attachment and perform water seepage test.	\$	170.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

(LUMP SUM) Repair Days	15 days
Over All Total	\$ 42,294.61
TOTAL	\$ 9,290.00
To transfer of rear door fittings, attachment and perform water seepage test.	\$ 380.00
To check steering geometry and computer wheel alignment To transfer of roar door fittings attachment and	\$ 220.00
To transfer of rear windscreen fittings and conduct water seepage test.	\$ 170.00
To transfer of rear fender fittings, attachment and perform water seepage test.	\$ 380.00
To supply and re-do rear luggage floor panel insulation padding.	\$ 380.00

AAD1807-070

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 10/07/2018 16:04

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

	ACCIDENT STATEMENT
Date Of Report	09/07/2018 13:45
Date Of Accident	08/07/2018 20:45
Exact Location Of Accident	NEWTON CIRCUS
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD9759U
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	CHARAN SINGH
NRIC No	\$1683260Z
Date Of Birth	03/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	25/08/1981
Driving Experience	36 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86065495
Fax Number	
Contact Number	

NOEMAIL

BLK 111 WHAMPOA RD Address

#03-33

 Postcode 321111

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

2 Number of vehicles involved in the accident Was any body injured in the Accident? YES

Was any injured conveyed to hospital by NO

ambulance?

Was any other material or property damaged? YES NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

Passenger 2

NAME:

: UNKNOWN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

YES

3

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact Was notice of intended Prosecution given? TEL NO: - FAX NO:

If Yes, against whom?

NO

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT: T/20180710/7009

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT8112K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

No. Of Passenger (including Driver)		
	DETAILS OF INJURED PERSON 1	
Name	CHARAN SINGH	
Approximate Age	•	
Injuries Sustain	•	
Injured person in which vehicle?	SHD9759U	
Were seat belts worn?	YES	
Was this injured conveyed to hospital by ambulance?	NO	
Address	•	
Postcode		

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal Information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Smil

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

GIARMC SketchPlanForm_V3

Sketch Plan #2 Pg. 1

SKETCH PLAN DESCRIBE CIRCUMSTANCES OF THE ACCIDENT police DVS ottach DECLARATION I/We declare the foregoing particulars are true in every respect. Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature Date & Time: (If driver is not the policyholder) Name:

Date & Time:

GIARIMC SketchPlanForm_V3

NRIC/FIN No.:

2

POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20180710/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/07/2018 15:37			Vide Report No.:	Station Diary No.:	
ilio o manti	el artieu	i su alugura			
Name of In	formant:		Address: APT BLK 111 WHAMPOA ROAD #03-33 SINGAPORE 321111		
ID Type / ID No.: NRIC NO / S1683260Z			Contact No.: Home/Office: Mobile: 86065495		
Nationality: SINGAPORE CITIZEN			Email: s.charan@yahoo.com	•	
Sex: Age: Date of Birth: Male 53 03/03/1965			Type of Informant: Driver		
Race: Sikh			Language: Institution / School Name: English		
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,2,3,4	Date of Expiry: 11/07/2028	

Gere all informati	on/oi/the Accident					
Type of Accident:	Injury Hit and Run		Drink Drive: No	Date/Time of Accident: 08/07/2018 20:45	i	Type of Location: Roundabout
Location:						
NEWTON CIRCU	IS					
NEWTON CIRCU	S TOWARDS ROCHO	R ROA	AD			
Weather:		Road §	Burface:		Road	Speed Limit:
Clear		Dry			50 K	m/h
Traffic Flow:		Traffic	Control:		Traff	ic Volume:
One Way		Not Co	ontrolled .		Mode	erat e
Type of Collision: Between Moving Vehicles - Head To Side Anyone conveyed by ambulance: No						

Pair lib (c) V	nicielinvolvec					
Walaiidt Rigi	htypes and finds	Maka	(Jegolý)	Coloi	Condition	Modification
SHD9759U	Car	RENAULT	LATTITUDE		Slightly	2
	` .				Damaged	
SLT8112K	Car	NISSAN		Brown		4

IpatellatedPersontlityalyada (1994)	
Any Pedestrian Involved: No .	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



T/20180710/7009

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20180710/7009

CONTINUATION OF REPORT

Diverse						
Name	CHARAN SINGH			ID No		S1683260Z
Related Vehicle	SHD9759U (Car)			Conta	ct No.	86065495
Hospital/Clinic	SINGAPORE GENER	RAL HOSPIT	AL	Class Drivin Licend Expiry	g	Class: 2B,2,3,4 Date of Expiry: 11/07/2028
Date Treatment	09/07/2018	Date Disc	narge	09/07	7/2018	
No. of Days gran	03	Degree of	Injury	Sligh	t	

Brief Details.

On 8 July 2018 at 845pm, whilst I was driving around Newton Circus towards Clemenceau Avenue North, my vehicle SHD9759U met with an accident. Right next to the exit of Newton Circus into Bukit Timah Road towards Rochor Road, my motor car SHD9759U was in the centre lane of 3 lanes. I had intended to exit at Clemenceau Avenue North when I stopped and swerve slight to the left as there was a black car ahead which used the extreme right lane to turn into Bukit Timah Road towards Rochor. When I stopped to give way to the black vehicle in front of me, there was another vehicle SLT8112K on my right which also used the extreme right lane to turn into Bukit Timah Road towards Rochor Road. When I stopped in the centre lane to give way to the black vehicle in front, the front of motor car SLT8112K hit the rear back of my motorcar SHD9759U. As a result the right back portion of my motorcar was damaged. I stopped my vehicle there and was about to alight to exchange particulars, however, the motorcar SLT8112K overtook me from the right side and used the extreme right lane to turn into Bukit Timah Road towards Rochor Road. I went after the motorcar SLT8112K but the driver did not stop. He carried on driving and exited towards the Central Expressway. I have a video footage of the incident.

POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20180710/7009

CONTINUATION OF REPORT

9	keto	h	D1	an
2	кеп	313	М,	an

Authentication Stamp

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2018 15:37
Officer In Charge Of Case: TP / TPIB / KALESWARI PALANI Contact No.: 65476902	Classification Of Case: