

ASS. REC. BY:

REF: CS/CTI 18012839/TI sd312

Special Instruction:

Survivor
Mennen

Taufik

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

16/7/18 @ 1:00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 7793K

Insured:

GBG 2565M

at Workshop m/s

Borneo Motor

Tel:

9336 6875

of

2 pandan Crescent

Policy No:

DMCVSN3045851800

Claim No:

SNM18 D03469C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

13/07/2018

CA / REV / REP. / REV 24 HRS

lwp

01-08-2018 (Wednesday) @ 11am

H.O.D. Endorsement:

Date/Time:

2:33pm @ 16/7/18

Person Contacted:

Sushi

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKK 7793K - X

GBG 2565M - X

17/7/18 @ 3:17pm - called sushi vehicle is still not in yet.

(08/11/13)

Surveyor:

Tang

REF:

CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Sashi

Veh No: SKK 7793K Yr Regn: 2016 NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wish c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 14218 T/Radio: Insured / Std / NI / NAEng/No: STD6620W.205006242

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 1/8/180/1anSurvey held at Banua PaderDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/1/17	e-mail Sashi \$7514, 7 days
15/01/15	Confirmed PP \$7,514.00 @ 7 days with Tautel. (\$ 8,774.40 Red - 54%)

RECEIVED 16 JAN 2019

Date/Time, File Pass to?

14/1/15

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) S + RS _____ SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ 7,514/- P/P)Survey Fee: 220

Transportation: _____

TOTAL

220

Lucas Lee

From: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>
Sent: Monday, 16 July, 2018 9:21 AM
To: Claims Dept of CTI
Cc: Siti Nabilah PTCBC
Subject: Direct Settlement (ST) - Accident Involving SKK7793K & GBG2565M DOA 13.07.2018
Attachments: SKK7793K_GIA Rpt_Damaged Photos.pdf; SKK7793K_Est Inv.pdf

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured GBG2565M thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Shashi @ 9336 6875 / 6631 1864** located at **2 Pandan Crescent – Level 4** for an appointment to inspect our client's vehicle soonest as vehicle is in our premises.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg


Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg





This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18012839/T1sd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 2565M	Veh. Inspected	SKK 7793K	
Policy No.	DMCVSN3045851800	Coverage (\$)	0.00	
Claim No.	SNM18D03469C02	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	16/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/07/2018	Inspection Date	01/08/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Tuesday, 15 January 2019 5:00 PM
To: 'Shashi PTCBC'
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SKK7793 PHOTO BEFORE PAint

Hi Sashi,

COR \$7514 , 7 days.

Regards
Taufikh
Lkk Auto

-----Original Message-----

From: Shashi PTCBC [mailto:Shashitharan@borneomotors.com.sg]
Sent: Friday, 5 October 2018 3:48 PM
To: 'SUR'; taufikh@lkkauto.com
Subject: SKK7793 PHOTO BEFORE PAint

Your message is ready to be sent with the following file or link attachments:

20180802_113428
20180802_113433
20180803_103324
20180803_103328
20180803_103332
20180802_113416
20180802_113424

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/07/2018 09:34
Date Of Accident	13/07/2018 16:20
Exact Location Of Accident	BLK 9 JOO SENG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK7793K
Insured/Policyholder	
Name Of Registered Owner	TAN JIAN LI
NRIC No	S8703603J
Email Address	TANJIANLI87@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92979951
Alternative Phone No	OFFICE-92979951

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100491076
Cover Note Number	

Driver

Name of Driver	TAN JIAN LI
NRIC No	S8703603J
Date Of Birth	16/02/1987
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92979951
Fax Number	
Contact Number	OFFICE-92979951
EEmail Address	TANJIANLI87@GMAIL.COM

Address	BLK 9 JOO SENG ROAD #18-16
Postcode	360009
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2565M
Vehicle Make/Model/Colour	TOYOTA, SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAN HENG CHIN, ALBIN
NRIC/Passport Number	S8309720E
Contact Number	90092437
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: :
	GENDER: :

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM


(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SKK 7793 K
Name (as shown in NRIC) : Tan Jian Li NRIC/FIN/Passport No : _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 13.07.18 Time of Accident : 1620
Place of Accident : _____
Insurance Company: AIG


(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend insured vehicle number.



Policyholder / Driver's Signature
Date: _____



Reporting Centre Personnel's Signature
Name: Surendah
NRIC/FIN No.: _____
Date: 16/7/18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/07/2018 09:34
Date Of Accident	13/07/2018 16:20
Exact Location Of Accident	BLK 9 JOO SENG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKKK7793K
Insured/Policyholder	
Name Of Registered Owner	TAN JIAN LI
NRIC No	S8703603J
Email Address	TANJIANLI87@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92979951
Alternative Phone No	OFFICE-92979951

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100491076
Cover Note Number	

Driver

Name of Driver	TAN JIAN LI
NRIC No	S8703603J
Date Of Birth	16/02/1987
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92979951
Fax Number	
Contact Number	OFFICE-92979951
Email Address	TANJIANLI87@GMAIL.COM

Address	BLK 9 JOO SENG ROAD #18-16
Postcode	360009
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2565M
Vehicle Make/Model/Colour	TOYOTA, SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAN HENG CHIN, ALBIN
NRIC/Passport Number	S8309720E
Contact Number	90092437
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: :
	GENDER: :

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: Shashi

MOTOR ACCIDENT REPORT

Date Of Report: 14/17/2018 Time: 0800 Date Of Accident: 13/7/2018 Time: 1620

Exact Location Of Accident: Blk 9, Joo Seng Road

Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKK7793K

Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No:

Name Of Registered Owner: Tan Jian Li

Mobile Number: 92979951

Alternative No:

Email Address: tanjianli87@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model:Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: AIG

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒

Policy / Cover Note No: 2106491076

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: TAN JIAN LI

NRIC/ Passport / FIN No: S87036033

Date Of Birth: 16/2/1987

Occupation: Indoor ☐ Outdoor ☒

Date Of Driving Pass: 20/3/2008

Gender: Male ☒ Female ☐

Mobile Number: 92979951

Fax No:

Alternative No:

Address: Blk 9, Joo Seng Road, #18-16

Postal Code: 536009

Email Address: tanjianli87@gmail.com

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Stationary collision

Number of Passengers in the above vehicle (Including Driver): 1 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:

Number of vehicles involved in the accident:

Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name: | Contact No.: | Email:

Was there any other vehicle or property damaged? No ☒ Yes ☐Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: GBG 2565 M

Vehicle Make/Model/Colour: Toyota, Silver

Details Of Properties Damage in Accident: Nil

Vehicle Category: Lorry

Name of Driver: CHAN HENG CHIN ALBIN

NRIC/Passport/FIN Number: S8309720E

Contact Number: 9009 2437

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver): 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


14/7/2018 0550

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Blk 9 Joo Seng Rd

Describe Circumstances of the Accident

My vehicle (SKH793W) was stationary and waiting for a passenger.
Alleged vehicle (GBG2565M) reversed into my vehicle while trying to
unload materials.
My vehicle mounted the kerb slightly after the accident.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

14/7/18 0800

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : TAN JIAN LI
VEHICLE NUMBER : SKK 7793K
DATE/TIME OF ACCIDENT : 13/7/2018 1620'
PLACE OF ACCIDENT : Blk 9, Joo Sang Road
THIRD PARTY VEHICLE (IF ANY) : GBG 2565 M

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

Heading to 56 Kallang Pudding Road from Blk 9, Joo Sang Road

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

NO

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Lorry reversed into my car. Superficial damages to body.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO

Name: Tan Jian Li

I Affirmed The Above Information Is Given To My Best Knowledge.



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

COVER NOTE

Cover Note No. 2100491076

Date 21 Nov 2016

The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.

SCHEDULE

Policyholder	Tan Jian Li (Chen Jianli)		
Age Condition	All Age Condition	Registration No.	
Policy Type	TOYOTA AUTO PROTECTOR (2-YEAR)	Make/Model	TOYOTA New Wish
Effective Date	21 Nov 2016	CC/Tonnage	1,798.00
Expiry Date	20 Nov 2018	Engine No	2ZR1874783
Excess	S\$600.00	Chassis No	JTDGG20W20J006242
		Year of Registration	2016
		Hire Purchase Company	DBS BANK LTD

This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.

In addition to the Policy Excess, a Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00 (before GST) will apply to You or Your Authorised Driver who is below the age of 23 (in case of All Age Condition policies) and/or has less than 2 years' driving experience. The YIDR Excess is not applicable to Named Driver policies.

Usage of vehicle only for the following purposes:

1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.
2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.

Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.

The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE OF INSURANCE

I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in SINGAPORE

AIG Asia Pacific Insurance Pte. Ltd.

IMPORTANT NOTICE

THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD. APPLICABLE
TO CORPORATE POLICIES ONLY.


AUTHORISED REPRESENTATIVE

ORIGINAL

IASHEC

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

PASS DATE

20 Mar 2008

NP 428A



Licence No: S8703603J

5754511



NRIC No S8703603J



Date of issue
25-04-2017

Address

APT BLK 9 JOO SENG ROAD
#18-16
SINGAPORE 360009

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8703603J
Name:

TAN JIAN LI
(CHEN JIANLI)

Birth Date: 16 Feb 1987
Issue Date: 20 Mar 2008



001583609G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8703603J



Name

TAN JIAN LI
(CHEN JIANLI)
陈 建 利

Race

CHINESE

Date of birth

16-02-1987

Country/Place of birth

SINGAPORE

Sex

M

S8703603J



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Jian Li
	Document No	9 Joo Seng Road
	0	#18-16
	Document Date	Singapore 360009
	14/07/2018	Mobile: 92979951

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	28/11/2016	SKK7793K	0	33410	6TP/SKK7793K/14071:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W20J006242	22R1874783	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.:GBG2565M ACC DATE:13/07/18 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP				✓ 169.50
3	B	BP-MECH R/I AIR PIPE, VACCUM AND REGAS				an X 339.00
4	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				✓ 169.50
5	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				60 120.00
6	B	BP-LAB REPL ACC AFF PARTS AND PANEL				2034 4068.00
		STRAIGHTEN AND REALIGN ACC AFF AREA				20 1668.
7	B	BP-RES RESPRAY ACC AFF AREA				1875.20
8	L	BP-LPO SUPPLY REGN PLATE (PO#)				X 80.00
9	1	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	61.60		X 61.60
10	2	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	61.60		X 61.60
11	3	T52119-68909 FRONT BUMPER COVER,	1.00	581.20		de 581.20
12	4	T52611-68030 FRT BUMPER ABSORBER,	1.00	90.60		cr 90.60
13	5	T52021-68020 F/BPR REINFORCEMENT,	1.00	299.40		an X 299.40
14	6	T53101-68010 GRILLE SUB-ASSY,	1.00	407.00		cr 407.00
15	7	T53301-68020 FRONT BONNET ASSY,	1.00	958.10		bf 958.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tan Jian 9744549
			01/8/18 cllan
			Resurvey before paint
			07 days
			Amount Due sur@1kanto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE TEAR ALONG PERFORATED LINE

3723416

TO SECURITY GUARD

3723416PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 14/07/2018
TIME 09:21
Acknowledged by Repairer
Signature:
Date:

VEHICLE NO

SKK7793K

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

CUSTOMER



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Jian Li 9 Joo Seng Road #18-16 Singapore 360009 Mobile: 92979951
	Document No	
	Document Date	
	0	
	14/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	28/11/2016	SKK7793K	0	33410	:6TP/SKK7793K/14071:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W20J006242	2ZR1874783	60	Shashitharan	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	--------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	8	T90467-09050 CLIP	6.00	2.40		new 14.40 ✓
17	9	T53812-68060 FENDER SUB-ASSY, LH	1.00	968.60		X 968.60
18	0	T53510-68050 FRONT BONNET LOCK,	1.00	91.20		X 91.20
19	1	T53420-68030 L/FRT BONNET HINGE,	1.00	57.80		X 57.80
20	2	T53410-68030 R/FRT BONNET HINGE,	1.00	57.80		X 57.80
21	3	T53208-68020 F/BRACE LOCK SUPPORT,	1.00	91.20		X 91.20
22	4	T53292-68020 F/UPPER RADIATOR SEAL,	1.00	91.20		X 91.20
23	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	1457.50		Rx 1457.50
24	6	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		new 72.20 ✓
25	7	T81145-68100 UNIT, HEADLAMP	1.00	1239.50		an X 1239.50
26	8	T81185-68100 UNIT, HEADLAMP LH	1.00	1239.50		cm/? 1239.50 ✓
27	9	T88450-12280 A/C CONDENSER ASSY,	1.00	1526.80		wn X 1526.80
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						
3363						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 9,367.20	16,288.40
		Labour 6,841.20	GST 7.00% 1,140.19
		Materials 80.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 17,428.59

PLEASE TEAR ALONG PERFORATED LINE

3723417

TO SECURITY GUARD

3723417

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 14/07/2018
TIME 09:21

VEHICLE NO SKK7793K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Tan Jian Li 9 Joo Seng Road #18-16 Singapore 360009 Mobile: 92979951
	Document No	
	Document Date	
	0	
	05/10/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	28/11/2016	SKK7793K	14751	33410 :6TP/SKK7793K/14071:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W20J006242	2ZR1874783	60	Shashitharan	01/08/2018 11.10	05/10/2018 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.:GBG2565M ACC DATE:13/07/18 DATE-IN:01/08/18 DATE SURVEY:01/08/18 NO OF REPAIR DAYS:7 BY:TAUFIKH AUTHORIZED ON:01/08/18	*			50.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP	*			169.50
3	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR	18			169.50
4	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL	*			60.00
5	B	BP-LAB REPL ACC AFF PARTS AND PANEL	*			2034.00
6	B	STRAIGHTEN AND REALIGN ACC AFF AREA	*			1668.00
7	1	BP-RES RESRPAY ACC AFF AREA	1.00	581.20		581.20
8	2	T52119-68909 COVER, FR BUMPER	1.00	407.00		407.00
9	3	T53101-68010 GRILLE, RADIATOR	6.00	2.40		14.40
10	4	T90467-09050 CLIP	1.00	72.20		72.20
11	5	T90975-02086 EMBLEM, SYMBOL	1.00	958.10		958.10
12	6	T53301-68020 HOOD SUB ASSY	1.00	90.60		90.60
13	7	T52611-68030 ABSORBER FR BUMPER	1.00	1239.50		1239.50
		T81185-68100 UNIT, HEADLAMP LH				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	7,514.00
		Labour	3,363.00
		Materials	4,151.00
		Lubrication/Fluid	0.00
		Others	0.00
			GST 7.00%
			Less
			0.00
			Amount Due
			8,039.98

PLEASE TEAR ALONG PERFORATED LINE

3775809

TO SECURITY GUARD

3775809

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/10/2018
TIME 15:35

VEHICLE NO SKK7793K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jul 2018		16 Jul 2018 13:00 Edit Adj Rpt	S\$7,514.00 Edit Estimates	S\$7,514.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: TAN JIAN LI									
Vehicle Reg. No.: SKK7793K		Date of Loss: 13/07/2018 00:00 - :59 [19 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03469C02		Policy/Cover Note No.: DMCVSN3045851800							
Vehicle Reg. No. (Insured): GBG2565M		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/07/2018]									
Adj Asg. Remarks: EST \$17,428.59, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKK7793K (SNM18D03469C02)**
[GBG2565M]
TP
TAN JIAN LI
Jul 13 2018 12:00AM
[-]
Borneo Motors (S) Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/01/19 12:04	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	16/01/19 12:04	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
13	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
14	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
15	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
16	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
25	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
26	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
27	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
28	16/01/19 12:04	General View	Load JPG	<input checked="" type="checkbox"/>
29	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	16/01/19 12:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/07/18 12:00	REPAIR EST		Load PDF	
2	16/07/18 12:01	EMAIL FM BORNEO		Load PDF	
3	16/07/18 12:01	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18012839/T1SD3E2

Date: 17/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3045851800

Claimant Vehicle
No : SKK7793KInsured Vehicle
No : GBG2565M

Date of Loss: 13/07/2018

Nature of Claim: TP

Claim
No: SNM18D03469C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK7793K**

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1874783

Reg. Date: 28/11/2016 (Man. Year: 2016)

Chassis No: JTDGG20W20J006242

Colour: Maroon

Odometer: 19218 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,467.20	3,413.00	6,054.20	63.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,821.20	4,101.00	2,720.20	39.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,288.40	7,514.00	8,774.40	53.87
+ GST 7.00/7.00% (S\$)	1,140.19	525.98	614.21	53.87
Nett Amount (S\$)	17,428.59	8,039.98	9,388.61	53.87

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 01/08/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK7793K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*R/FRT BUMPER SUPPORT	Not Necessary	61.60 FS	*- FS
3	1		*L/FRT BUMPER SUPPORT	Not Necessary	61.60 FS	*- FS
4	1		*FRONT BUMPER COVER	Deformed	581.20 FS	*581.20 FS
5	1		*FRT BUMPER ABSORBER	Cracked	90.60 FS	*90.60 FS
6	1		*F/BPR REINFORCEMENT	Not Necessary	299.40 FS	*- FS
7	1		*GRILLE SUB-ASSY	Cracked	407.00 FS	*407.00 FS
8	1		*FRONT BONNET ASSY	Bent	958.10 FS	*958.10 FS
9	6		*CLIP	Necessary	14.40 FS	*14.40 FS
10	1		*FENDER SUB-ASSY, LH	Not Necessary	968.60 FS	*- FS
11	1		*FRONT BONNET LOCK	Not Necessary	91.20 FS	*- FS
12	1		*L/FRT BONNET HINGE	Not Necessary	57.80 FS	*- FS
13	1		*R/FRT BONNET HINGE	Not Necessary	57.80 FS	*- FS
14	1		*F/BRACE LOCK SUPPORT	Not Necessary	91.20 FS	*- FS
15	1		*F/UPPER RADIATOR SEAL	Not Necessary	91.20 FS	*- FS
16	1		*FRT RADIATOR SUPPORT	Repair	1,457.50 FS	*- FS
17	1		*TOYOTA SYMBOL EMBLEM	Necessary	72.20 FS	*72.20 FS
18	1		*UNIT, HEADLAMP	Not Necessary	1,239.50 FS	*- FS
19	1		*UNIT, HEADLAMP LH	Cracked	1,239.50 FS	*1,239.50 FS
20	1		*A/C CONDENSER ASSY	Not Necessary	1,526.80 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,467.20	3,413.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	169.50	169.50
2	R/I AIR PIPE, VACUUM AND REGAS	New	339.00	0.00
3	RESET ECU UPON COMPLETION OF REPAIR	New	169.50	169.50
4	SUPPLY SEALANT (NETT) 2 PANEL	New	120.00	60.00
5	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	4,068.00	2,034.00
6	RESPRAY ACC AFF AREA	New	1,875.20	1,668.00
7	SUPPLY REGN PLATE (PO#)	New	80.00	0.00
Gross Labour Cost (S\$)			6,821.20	4,101.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >