

ASS. REC. BY:

REF:

CS/EGT18012852 Mvds

n2

Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

16/7/18 @ 3:15pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 8909K

Insured:

SJT 9544P

at Workshop n/s:

FOCUS AUTO

Tel:

6886 9097

of

No.1, Kaki Bkt Ave 6 #02-48 / 50 Autobay

Policy No:

Claim No:

DSMPC1801335 / SL / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/07/2018

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

3:38pm @ 16/7/18

Person Contacted:

Mr. Wong

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 8909K - X

SJT 9544P - X

17/7/18 @ 3:10pm: Laura said vehicle has been surveyed by marius.

18/7/18

Email preli revised to Pei Li

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Eni

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLN8909Kat Workshop m/s Focus

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR-Seen: 2 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN8909K Yr Regt: 5, 17Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mercedes 3 c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 68328 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0515416Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.05/60216R: 70yo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TriangleFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/7/18 D.O.I. 17/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/7/18 Confirmed 2/s \$1900 with MR way. (Ref 2234.32, 5410)

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 2571 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

250

Report Format: TPLump Sum / I.B.I.: (\$ 1900/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18012852/Uvd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 16-07-2018	
Code : EGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJT 9544P	Veh. Inspected	SLN 8909K
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1801335/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/07/2018	Inspection Date	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1801335/SL/pl
Our Ref: CS/EGH18012852/Uvd3

Date: 18/7/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLN 8909K


We thank you for your instruction on 16/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/7/2018 at the premises of M/s FOCUS SUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,134.32
Revised Estimate Amount	: S\$2,780.72
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 16 July 2018 3:15 PM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SJT9544P / TP : SLN8909K/LKK / DOA : 08/07/2018 (DSMPC1801335)
Attachments: SJT9544P - SAS.pdf; SLN8909K - SAS.pdf; SLN8909K - PRS FORM.pdf; Re: RE: (DSMPC1801335) ACCIDENT INVOLVING SLN8909K & SJT9544P ON 08/07/2... (21.3 KB)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FOCUS AUTO PTE LTD**.

ADDRESS : NO 1 KAKI BUKIT AVE 6
#02-48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : LAURA / WONG @ 6886 9097

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247
peili.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 16.07.2018
Our Reference: DSMPC1801335/SL/pl
Your Reference: SLN 8909K

To: FOCUS AUTO PTE LTD

Sent via Fax ☐
or
Email focus.autopteltd@yahoo.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLN 8909K
Insured's Vehicle: SJT 9544P
Date Of Accident: 08.07.2018


We acknowledge receipt of your request for PRS on: 16.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 18 July 2018 5:18 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SJT9544P / TP : SLN8909K/LKK / DOA : 08/07/2018 (DSMPC1801335)
Attachments: SLN 8909K PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLN 8909K
Date of survey: 17/7/2018
Number of days :3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 16 July 2018 3:49 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJT9544P / TP : SLN8909K/LKK / DOA : 08/07/2018 (DSMPC1801335)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not In workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 16 July 2018 3:15 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : SJT9544P / TP : SLN8909K/LKK / DOA : 08/07/2018 (DSMPC1801335)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FOCUS AUTO PTE LTD**,

ADDRESS : NO 1 KAKI BUKIT AVE 6
#02-48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : LAURA / WONG @ 6886 9097

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247
peili.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

4843R

Vehicle Details

Vehicle No.:

SLN8909K

Vehicle to be Exported:

No

Intended De-registration Date:

10 Jul 2018

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 SEDAN 1.5 AT EU6

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

P520446085

Chassis No.:

JM6BN22A8H0154161

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$14,761.00

Original Registration Date:

22 May 2017

First Registration Date:

22 May 2017

Transfer Count:

1

Actual ARF Paid:

\$9,761.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 May 2027

PARF Rebate Amount:

\$7,320.00

Intended COE Rebate Details

COE Expiry Date:

21 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,101.00

COE Rebate Amount:

\$44,404.00

Total Rebate Amount:

\$51,724.00

The information contained herein is correct as at 10 Jul 2018

OK

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

not Alred
r/s #1900/2
3dy.
17/7/18
The plus. Attorney

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Suntec Tower Five
Singapore 038985
TEL: (65)6829 9199 (Ext: 170) FAX: (65) 6829 9247
ATTN: Motor Claim Department

Estimate No: EST0000654
Date: 16 Jul 2018
Policy No: 5101761698
Veh Reg No: SLN8909K
Make/Model: MAZDA 3 SEDAN 1.5 AT EU6
Chassis No: JM6BN22A8H0154164
Engine No: P520446085
Reg. Date: 22-05-2017

Your Ref No: SLN8909K
Claim Type: Third Party
Accident Date: 08-07-2018
TP Veh Reg No: SJT9544P

Estimate Repair Cost to Vehicle No :SLN8909K

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
MAZDA 3				
List Price				
1 Front Head Lamp LH	773.3000	1 PC	773.30	—
2 Front Fender LH	756.2000	1 PC	756.20	—
3 Front Fender Dust Cover LH	124.4000	1 PC	124.40	α
4 Front Fender Dust Cover Clipse LH	5.5000	8 PC	44.00	—
5 Front Head Lamp Clipse LH	5.5000	2 PC	11.00	α
6 Front Bumper	925.2000	1 PC	925.20	—
7 Front Bumper Side Retainer LH	39.7000	1 PC	39.70	—
8 Front Bumper Fog Lamp Cover LH	80.4000	1 PC	80.40	α
9 Front Bumper Fog Lamp LH	326.2000	1 PC	326.20	α
			3,080.40	
		Less 20%	616.08	2,464.32
Labour				
10 Panel Beating	850.0000	1 PC	850.00	300
11 Check Wiring	60.0000	1 PC	60.00	20
12 Rust Proofing	60.0000	1 PC	60.00	50
13 Spray Painting	700.0000	1 PC	700.00	400
			1,670.00	1,670.00
		Total		SS 4,134.32

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED THIRTY FOUR AND CENTS THIRTY TWO

2383.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

16/7/2018

For FOCUS AUTO PTE LTD

Focus Auto Pte

No 1 Kaki Bukit Ave 6

#02-50 Singapore 417883

AUTHORISED SIGNATURE




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18012852/Uvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 01-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 9544P	Veh. Inspected	SLN 8909K	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1801335/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	16/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0154161	Colour	BLUE	
Odometer	68329	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/07/2018	Inspection Date	17/07/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 8909K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT HEAD LAMP LH	CRACKED	773.30	773.30
1	FRONT FENDER LH	DENTED	756.20	334.00
1	FRONT FENDER DUST COVER LH	NOT NECESSARY	124.40	-
8	FRONT FENDER DUST COVER CLIPSE LH @\$5.50	NECESSARY	44.00	44.00
2	FRONT HEAD LAMP CLIPSE LH @\$5.50	NOT NECESSARY	11.00	-
1	FRONT BUMPER	DEEP CUT	925.20	826.00
1	FRONT BUMPER SIDE RETAINER LH	BENT	39.70	39.70
1	FRONT BUMPER FOG LAMP COVER LH	NOT NECESSARY	80.40	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	326.20	-
	LESS 20% DISCOUNT		-616.08	-403.40
			2,464.32	1,613.60
	LABOUR			
	PANEL BEATING.		850.00	300.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.		60.00	50.00
	SPRAY PAINTING.		700.00	400.00
			1,670.00	770.00
	GRAND TOTAL		4,134.32	2,383.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/EGI18012852/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.