

(08/11/13) wef

ASS. REC. BY: Marius

REF:

CS/TP/8012858/05bn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGP3763Uat Workshop m/s 3rd

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 23

IDAC Accident Report: _____ Consistent?: Yes or No

QA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 17A/17440

Vehicle: IN / OUT

Date: _____ Person Contacted: 13/12/2014Veh No: SGP3763U Yr Regn: 12, 06Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Toyota corolla AT c.c. 1598Colour: grey A/C: Insured / Std / NI / NASp. Reading: 240748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EC107138287Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 185/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MR / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/7/18 D.O.I. 18/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3yrs. Salu. nett \$560 Muc Max.2/5 \$4500* independent report

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

25/07/181) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 4,500.00 H/S

170

50

50

84

80

434

Ref. No : <u>CS/TP 18012858/Usb</u>	Res. Date: <u>19/7/18</u>	Date Received:
Veh. No : <u>SIP3763U</u>	SP:	WKSP: <u> </u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By: <u> </u>



DON'T FALL FOR HER ONLINE PURCHASE

CLICK TO FIND OUT MORE AT www.scamalert.sg



toyota corolla altis

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » Hanns Auto » Toyota Corolla Altis 1.6A (COE till 12/2021)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Commercial Vehicle

PAN PACIFIC
SERVICE YOU DESERVE.
PEOPLE YOU TRUST.

MORE THAN 1,000 FLEET UNIT
Daily, Weekly, Monthly & Yearly Fleet Available.

Toyota Corolla Altis 1.6A (COE till 12/2021)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details

Price	\$22,800	
Depreciation	\$6,650 /yr	?
Reg Date	22-Dec-2006 (3yrs 5mths 3days COE left)	
Manufactured	2006	?
Mileage	123,000 km (10.6k /yr)	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$890 /yr	?
Power	81.0 kW (108 bhp) View specs of the Toyota Corolla Altis (2000-2007)	
Curb Weight	1,115 kg	?
Features	-	
Accessories	-	
COE	\$25,636	?
OMV	\$15,355	?
ARF	\$16,891	?
Dereg Value	\$17,587 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	
Category	COE Car	
Availability	Available	



Location Ma

Seller Infor

Company

Address

Location

Office No

Contact Perso

Useful Servi

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Compare](#)



toyota corolla altis

Price Range ▼

Depreciation ▼

> 10 year(▼

Vehicle Type ▼

Home » Used Cars » Prime Motor & Leasing » Toyota Corolla Altis 1.6A (COE till 12/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Corolla Altis 1.6A (COE till 12/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING

[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF C

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL S

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price **\$23,500**

Depreciation \$6,890 /yr

Reg Date 15-Dec-2006
(3yrs 4mths 26days COE left)

Manufactured 2006

Mileage -

Transmission Auto

Engine Cap 1,598 cc

Road Tax \$890 /yr

Power 81.0 kW (108 bhp)
View specs of the Toyota Corolla Altis (2000-2007)

Curb Weight 1,115 kg

Features SRS Airbags, ABS, Reliable And Fuel Efficient 1.6L VVTI Engine, Climate Control Aircon, Multi Function Steering.

Accessories Leather Seats, Sports Rims, Audio System.

Description Elegant Toyota Altis, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

COE \$25,636

OMV \$15,498



Location Ma

Seller Infor

Company

Address

Car Tyres



Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5821A

Vehicle Details

Vehicle No.: SGP3763U

Vehicle to be Exported: No

Intended De-registration Date: 18 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2006

Engine No.: 3ZZ4623094

Chassis No.: MR053ZEC107138287

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$15,355.00

Original Registration Date: 14 Dec 2006

First Registration Date: 14 Dec 2006

Transfer Count: 1

Actual ARF Paid: \$16,891.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,636.00

COE Rebate Amount: \$17,440.00

Total Rebate Amount: \$17,440.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jul 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5821A
Vehicle Details	
Vehicle No.:	SGP3763U
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4623094
Chassis No.:	MR053ZEC107138287
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	14 Dec 2006
First Registration Date:	14 Dec 2006
Transfer Count:	1
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,636.00
COE Rebate Amount:	\$17,440.00
Total Rebate Amount:	\$17,440.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Jul 2018

OK

MSME180917ER / SMC Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 16/07/2018 17:13
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/07/2018 17:13
Date Of Accident 14/07/2018 15:45
Exact Location Of Accident JALAN BAHAR
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGP3763U
Insured/Policyholder
Name Of Registered Owner LAI BENG SAN
NRIC No S7515821A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-92233113
Alternative Phone No OFFICE-92233113

Vehicle Particulars

Manufacturer TOYOTA
Model ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number A29061834QMX
Cover Note Number

Driver

Name of Driver LAI BENG SAN
NRIC No S7515821A
Date Of Birth 02/06/1975
Occupation OUTDOOR
Date Of Driving Pass 15/05/1999
Driving Experience 19 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-92233113
Fax Number
Contact Number OFFICE-92233113
Email Address NOEMAIL

Address BLK 183B BOON LAY AVE #14-730
 Postcode 642183
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information
 Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : DIANA
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name JURONG WEST NPC
 Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180715/2070.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJB3067J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver JOVI YAP JUN HUI
 NRIC/Passport Number S9444773I
 Contact Number 90232506
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LAI BENG SAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGP3763U

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature

Date & Time: 16/7/18, 11:50pm


 Driver's Signature


(if driver is not the policyholder)

Date & Time: 16/7/18, 11:50pm

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:



Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 16/7/18, 11:55pm

GLANMG SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/7/18, 11:55pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180715/2070

1 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180715/2070

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/07/2018 15:55		Vide Report No.:		Station Diary No.: 90	
Informant's Particulars					
Name of Informant: LAI BENG SAN			Address: APT BLK 183B BOON LAY AVENUE #14-730 SINGAPORE 642183		
ID Type / ID No.: NRIC NO / S7515821A			Contact No.: Home/Office: Mobile: 92233113		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 43	Date of Birth: 02/06/1975	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: FIELD SERVICE ENGINEER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/07/2018 15:45	Type of Location: FILTER LANE
Location: Along Road 1 Traveling Toward Road 2 PAN ISLAND EXPRESSWAY JALAN BAHAR				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGP3763U	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Slightly Damaged	1
SJB3067J	Car	SUZUKI	SWIFT	White	Slightly Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



SINGAPORE POLICE FORCE



T/20180715/2070

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20180715/2070

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGP3763U	MSIG INSURANCE (SINGAPORE) PTE. LTD.	7VPF1763660	14/12/2017	13/12/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LAI BENG SAN	ID No.	S7515821A
Related Vehicle	SGP3763U (Car)	Contact No.	92233113
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	14/07/2018	Date Discharge	14/07/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 14/17/2018 at about 1545hrs, I was driving my car bearing plate number SGP3763U along PIE exiting Jalan Bahar at the filter lane. When I was about to turn into the main road Jalan Bahar, suddenly the car behind me bearing plate number SJB3067J collided onto the rear of my car. I went out of my car and discovered that the rear bumper is damaged and came off. There is camera inside my car however it did not capture anything. No police or ambulance was at scene.

On the same day at about 2100hrs, I felt a strain on my neck and went to Ng Teng Fong General Hospital where I received 04 days of MC from 14/07/2018 till 17/07/2018.



**SINGAPORE
POLICE FORCE**



T/20180715/2070

3 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180715/2070

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 DIANATASHYA INDRIANI BINTE ABDUL
GHANI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant

Date/Time:

15/07/2018 15:55

Classification Of Case:

Authentication Stamp

NP168



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Not paid
 N/S 4500
 6 day

SAP 37634

	Booflid	Bent/Buc	788.10	/
	Booflid '1.6' emblem	neu	42.50	/
	Booflid 'VVTI' emblem	neu	35.00	/
	Booflid 'console' emblem	neu	36.00	/
	Booflid 'ALTIS' emblem	neu	38.00	/
2pcs	Booflid reflectors @ 158.10	N/Sene	316.20	PC
	Booflid inner lock	twi	86.60	/
	Booflid weatherstrip	twi	152.10	/
2pcs	Booflid hinges @ 86.10	A	172.20	X
	Rear bumper	W	496.50	/
2pcs	Rear bumper side retainers @ 45.10	Bent	90.20	/
2	Rear bumper brackets @ 65.50	N/SDD	131.00	PC
	Rear end panel	Soddy	698.10	/
	Rear end panel top garnish	twi	126.00	/
2pcs	tailamps @ 289.60	N/Sene	579.20	PC
2pcs	tailamp apron panels @ 126.10	N/SBent	252.20	PC
8pcs	tailamp apron panel rivets @ 4.50	neu	36.00	/
	tailamp housing panel 1/5	W/Buc	408.10	/
	Rear floor panel	A	911.20	X
	Rear floor panel top board	Tom	128.10	/
			5523.30	3800.6
			(25%)	
	S. Net			
1set	Rear bumper reverse sensor	short	280.00	200
1set	Rear bumper clips	neu	50.00	/
	Rear end panel sealant	neu	50.00	/
	Rear licence plate	Bent	50.00	20
1set	Rear floor panel insulator	1/1	300.00	X



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

Sgp 37634

To check wiring	50.00	30
To Dismantle & replacing reverse sensor	80.00	50
To transfer boot lid components	80.00	60
To Dismantle & refix seat cushion upholstery	120.00	80
To Dismantle & refix rear exhaust	~1 100.00	✓
To spray rust proofing	100.00	60
labour for panel beating/cut/weld/straighten replacing parts	1200.00	1000
To putty & spray painting	1500.00	1200
TOTAL = 9483.30		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP18012858/Usbn2	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 01-08-2018	
ON BEHALF OF LAI BENG SAN		Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	SGP 3763U	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107138287	Colour	GREY
Odometer	240748	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/70 R14	MICHELIN	6 mm
L/H Front Tyre	185/70 R14	MICHELIN	6 mm
R/H Rear Tyre	185/70 R14	MICHELIN	6 mm
L/H Rear Tyre	185/70 R14	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/07/2018	Inspection Date	18/07/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 3763U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	BENT / BUCKLED	788.10	788.10
1	BOOTLID "1.6" EMBLEM	NECESSARY	42.50	42.50
1	BOOTLID "VVTI" EMBLEM	NECESSARY	35.00	35.00
1	BOOTLID "COROLLA" EMBLEM	NECESSARY	36.00	36.00
1	BOOTLID "ALTIS" EMBLEM	NECESSARY	38.00	38.00
2	BOOTLID REFLECTORS @\$158.10	N/S CRACKED	316.20	158.10
1	BOOTLID INNER LOCK	TWISTED	86.60	86.60
1	BOOTLID WEATHERSTRIP	TWISTED	152.10	152.10
2	BOOTLID HINGES @\$86.10	TO REPAIR SEE LABOUR	172.20	-
1	REAR BUMPER	DENTED	496.50	496.50
2	REAR BUMPER SIDE RETAINERS @\$45.10	BENT	90.20	90.20
2	REAR BUMPER BRACKETS @\$65.50	N/S DENTED	131.00	65.50
1	REAR END PANEL	BADLY DENTED	698.10	698.10
1	REAR END PANEL TOP GARNISH	TWISTED	126.00	126.00
2	TAILLAMPS @\$289.60	N/S CRACKED	579.20	289.60
2	TAILLAMP APRON PANELS @\$126.10	N/S BENT	252.20	126.10
8	TAILLAMP APRON PANEL RIVETS @\$4.50	NECESSARY	36.00	36.00
1	TAILLAMP HOUSING PANEL N/S	DENTED / BUCKLED	408.10	408.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	911.20	-
1	REAR FLOOR PANEL TOP BOARD	TORN	128.10	128.10
	LESS 25% DISCOUNT		-	-950.15
			5,523.30	2,850.45
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	20.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
			730.00	320.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00

Report Ref No. CS/TP18012858/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACING REVERSE SENSOR.	NOT NECESSARY	80.00	50.00
	TO TRANSFER BOOTLID COMPONENTS.		80.00	60.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	-
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID HINGES AND REAR FLOOR PANEL.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,230.00	2,480.00
GRAND TOTAL			9,483.30	5,650.45

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00
--	--	--	--	----------

Report Ref No. CS/TP18012858/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.