

Jas Tan | CC4 / Asm 12861, Kua3y | LKK: 57637

Surveyor:

1002

DOI:

12/1/18

Date / Time:

16/2/2018

Registered in Merimen:

Pre-assign / CCU / FTE

SLW 3785K



Insured Vehicle No.:

Name of Insured:

MD. FADILLILAH BIN DAUD

Insured Tel No.:

HP:

96302485

Excess Sec II :SS

D.O.A.:

10/2/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

58m00086

Policy No.:

P2072047

Make / Model:

7. WISH

Place of Accident:

YISHUN RING ROAD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLM9312E



INSRS:

WSP:

Tel:

Liability:

RMKS:

AH Lim

CAMEL



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

23-4-19

23-4-19

SLM9312E - X ; SLW 3785K - X

Called OI, no response

23-4-19

VIDEO FROM AH LIM DYEM.

OI REVERSING. TP STOPPED.

PEND LOD.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

23-4-19 JUY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice

X

LTA / GIA

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

18/1

Sent By:

Hmk (views only)

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

14-2-19

Confirm with:

MUI HONG

Email

Call

Final Liability:

%

100

(Assessed)

BOLA S/N No.:

NIL

Repair Cost:

GST

851,862.14

(3 days)

100

Loss of Rental (LOR):

S\$

300

(3 days)

100

Loss of Use (LOU):

S\$

X

(3 days)

X

Loss of Income (LOI):

S\$

X

(3 days)

X

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

X

Disbursement:

S\$

44.94

AUDAT FEE

(e.g. Tow/ Independent)

Legal Cost

S\$

X

Total:

S\$

2,209.08

Global Sum S\$:

FINAL PAYMENT

Date/Time:

2,209.08

Confirm with:

AH LIM MOTOR COMPANY

Email

Call

Payee 1:

S\$

2,209.08

Name 1:

AH LIM

Payee 2 (Strike if N.A.):

S\$

X

Name 2:

X

Payee 3 (Strike if N.A.):

S\$

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 12/6/19

REF: $ASm(A \times A)$

ASSIGNMENT

From _____ Date 17/09/2018

Estimated Cost: 0

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJm 9312E

at Workshop m/s Ah Lim Motor

of Blok 10 Ank Ind Park 2A #01-09

insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Vehicle _____

1 pm

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value	\$52K	
IDAC Accident Report		Consistent? Yes or No
GIA / PR Seen		Consistent? Yes or No
Est. Repairs	03 days	Res: Yes or No
Turn Sum	1-B-1	3 Val: Yes or No

CA / REV / REP / 24 HRS

Vehicle IN / OUT

Date	Person Contacted
------	------------------

Vols 11/12
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mit ^A Attrax 1193
 Colour: M. Silver A/C Insured / Std / Nil / NA
 Sp. Reading: 9200 T/Radio: Insured / Std / Nil / NA
 Eng/No:
 C/No: MMBSTA13A1HH 003935
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 165/55R15
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. 9 mm	R/Bal. 9 mm
L/Bal. 9 mm	L/Bal. 9 mm
D.O.A. 10/7/18	D.O.I. 17/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FR O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
18/7	File pass to Catherine

\$ 1,740.32

$$R (\$1,775.95/51\%)$$
Downloaded from <http://www.ascelibrary.org/> by []: Prelim. Report☐ : Final Report

Report Format

Lump Sum / L.B. 1/03

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp: (\$)

Interagency	\$
-------------	----

Tech Tips \$

Standard 19

Survey Fees

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7823Z

Vehicle Details

Vehicle No.: SLM9312E

Vehicle to be Exported: No

Intended De-registration Date: 11 Jul 2018

Vehicle Make: MITSUBISHI

Vehicle Model: ATTRAGE 1.2 CVT

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: 3A92UDP3745

Chassis No.: MMBSTA13AHH003935

Maximum Power Output: 57.0 kW (76 bhp)

Open Market Value: \$13,641.00

Original Registration Date: 18 Apr 2017

First Registration Date: 18 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Apr 2027

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 17 Apr 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,951.00

COE Rebate Amount: \$44,667.00

Total Rebate Amount: \$48,417.00

The information contained herein is correct as at 11 Jul 2018

OK

SURVEYOR COPY

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: 3 PARTY CLAIM
Assessment Number: AH000861
Version: AHLIM001/1
Date Calculated: 13/07/2018 09:59

Full Report - V1
Registration: SLM9312E
Printed: 13/07/2018 17:00

LKK ipm

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	3 PARTY CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MITSUBISHI
Model:	Attrage
Sub Model:	BASE MODEL
Model Sheet Number:	GAT 01
Registration:	SLM9312E
Registration Month:	April
Registration Year:	2017
VIN Number:	MMBSTA13AHH003935
Manufacture Year:	2016
Odometer:	Not Known
Colour:	
Engine Number:	3A92UDP3745
Fuel Level:	%

Model Specs

FROM 10/2015	FOG LAMPS
LED DAYT RUN LAMPS	1.2 LTR 59KW
CVT AUTOMATIC	TWO COAT METALLIC
PAINTING OFF VEHICLE	

*Not Authorised
 1. B. 1
 Resurvey B4 pain
 3 days*

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:

Severity of Impact:

Vehicle Status on

Inspection:

Date of Inspection: 13/07/2018

Brakes Pedal Travel:

Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

LKK Auto Consultants hereby notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000861



Version: AHLIM001/1

Date Calculated: 13/07/2018 09:59

Full Report - V1

Registration: SLM9312E

Printed: 13/07/2018 17:00



Addresses

Cost Summary

Total Labour	\$625.50
Total Paint/Material	\$139.97
Total Parts	\$2,750.80
Excess:	TBA
Grand Total Exc GST:	\$3,516.27
7 % GST:	\$246.14
Grand Total Inc GST:	\$3,762.41

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	9.00
NO NUMBER	RENEW FR NUMBER PLATE	1.0	4.50
514110 00)	R + R FRONT BUMPER	4.0	18.00
514121 10)	R + R FRONT BUMPER ATTACHED PARTS	5.0	22.50
NO NUMBER	RENEW FRONT BUMPER REINFORCEMENT	8.0	36.00
	PART IS WELDED AND SCREWED		
541070 00)	R + R L/DAYTIME RUNNING LAMP	1.0	4.50
541070 00)	R + R R/DAYTIME RUNNING LAMP	1.0	4.50
541010 00)	R + R LEFT HEADLAMP	1.0	4.50
422022 10)	RENEW R/FR WING	8.0	36.00
	INCLUDES: R/HEADLAMP ASSY, WHEELARCH-TRIM RIGHT R + R		
NO NUMBER	ADJUST HEADLAMPS	2.0	9.00
1003	REPAIR R/RADIATOR BRACKET	10.0*	45.00
1009	REPAIR FRONT PANEL CPL	20.0*	90.00
1118	REPAIR R/F WHEELHOUSE	20.0*	90.00

LABOUR COST

Total Work Units	83.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	8.3HRS	\$373.50
Paint Labour	5.6HRS	\$252.00
Total Labour	13.9HRS	\$625.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number Description	WU	Cost Price (\$)
--------------------------	----	-----------------

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000861

Version: AHLIM001/1

Date Calculated: 13/07/2018 09:59

Full Report - V1

Registration: SLM9312E

Printed: 13/07/2018 17:00

	- TWO COAT METALLIC		
	- PAINTING OFF VEHICLE		
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
1003	R/RADIATOR BRACKET SURFACE PAINT	4.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	40.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	56.0	
	Total Paintwork Labour	5.6HRS	\$252.00
MATERIAL COST - PAINT			
			Cost Price
	New Part Painting		\$19.61
	New Part Painting - Plastic K1R		\$69.86
	Surface-/Blend Paint		\$23.40
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$139.97
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$139.97

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	35.00* X
283	1	FRONT BUMPER	6400H293		0%	390.00* ✓
318	1	R/F UPP BUMPER BRKT	6400F222		0%	10.00* ✓
340	1	FRT BUMPER REINF	5256B727		0%	120.00* ✓
350	1	FRT BUMPER MNTG KIT	USE SINGLE PARTS		0%	24.00* ✓
411	1	LWR RADIATOR GRILLE	6402A268		0%	110.00* X
415	1	GRILLE	6402A300		0%	280.00* ✓
561	1	L/F HEADLAMP	8301C545		0%	300.00* X
562	1	R/F HEADLAMP	8301C546		0%	300.00* ✓
648	1	R/F FOG LAMP	8321A365		0%	220.00* X
651	1	L/DAYT RUNNING LAMP	SEE GUIDE NO. 0650		0%	80.00* X
652	1	R/DAYT RUNNING LAMP	SEE GUIDE NO. 0650		0%	80.00* X
742	1	R/F WING	5220H942		0%	250.00* X
790	10	R/F WING CLAMP KIT	MS100222		0%	20.00* X
842	1	R/F WHEELHOUSE COVER	5370B890		0%	75.00* X
1000	1	FRONT GRILLE CLPX10	Renew		0%	20.00* ✓
1000	1	H LAMP LOW BEAM LH	Renew		0%	10.00* X
1000	1	H LAMP LOW BEAM RH	Renew		0%	10.00* X
1000	1	H LAMP CLIPS X4	Renew		0%	8.00* X
1000	1	F FENDER LGO ECO RH	Renew		0%	0.00* X
1000	1	F FEN SIG OT CHRO RH	Renew		0%	50.00* X
f: OEM Parts						\$2,392.00
g: Original						\$358.80
h: Secondhand						\$2,750.80
p: Parallel						
Sub Total						\$2,750.80
Mark Up From Cost (15 %)						
Total Parts						

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM

Assessment Number: AH000861

Version: AHLIM001/1

Date Calculated: 13/07/2018 09:59

Full Report - V1

Registration: SLM9312E

Printed: 13/07/2018 17:00

x: Exchange

**THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**

Total Extras \$0.00

Final Calculation

Total Parts		\$2,750.80
Labour		
Total Panel/Mechanical	\$373.50	121
Total Paintwork	\$252.00	297
Total Labour		\$625.50
Total Paint/Material Costs		\$139.97
Grand Total Excludes GST		\$3,516.27
GST @ 7 %		\$246.14
Grand Total Includes GST		\$3,762.41

Assessment Notes

L&L Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

Claim Reference: 3 PARTY CLAIM
Assessment Number: AH000861
Version: AHLIM001/3
Date Calculated: 10/10/2018 09:52

Full Report - V1
Registration: SLM9312E
Printed: 13/10/2018 10:11

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	3 PARTY CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MITSUBISHI
Model:	Attrage
Sub Model:	BASE MODEL
Model Sheet Number:	GAT 01
Registration:	SLM9312E
Registration Month:	April
Registration Year:	2017
VIN Number:	MMBSTA13AHH003935
Manufacture Year:	2016
Odometer:	Not Known
Colour:	
Engine Number:	3A92UDP3745
Fuel Level:	%



Model Specs

FROM 10/2015	FOG LAMPS
LED DAYT RUN LAMPS	1.2 LTR 59KW
CVT AUTOMATIC	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	13/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

**Addresses****Cost Summary**

Total Labour	\$468.00
Total Paint/Material	\$113.82
Total Parts	\$1,138.50
Total of Additional Costs	\$20.00
Excess:	TBA
Grand Total Exc GST:	\$1,740.32
7 % GST:	\$121.82
Grand Total Inc GST:	\$1,862.14

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	9.00
514110 00	R + R FRONT BUMPER	7.0	31.50
514121 10)	R + R FRONT BUMPER ATTACHED PARTS	5.0	22.50
541070 00)	R + R L/DAYTIME RUNNING LAMP	1.0	4.50
541070 00)	R + R R/DAYTIME RUNNING LAMP	1.0	4.50
541010 00)	R + R LEFT HEADLAMP	1.0	4.50
541010 00)	R + R RIGHT HEADLAMP	1.0	4.50
NO NUMBER	ADJUST HEADLAMPS	2.0	9.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	8.0	36.00
0742	REPAIR R/F WING	10.0*	45.00

LABOUR COST

Total Work Units	38.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	3.8HRS	\$171.00
Paint Labour	6.6HRS	\$297.00
Total Labour	10.4HRS	\$468.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
283	FRONT BUMPER REPAIR PAINT PLASTIC	17.0	
742	R/F WING REPAIR PAINTING >50%	16.0	

LABOUR COST - PAINT

TIME(PAINT)	33.0	
Preparation Main Work Plastic	8.0	

Ah Lim Motor Company

Claim Reference: 3 PARTY CLAIM
 Assessment Number: AH000861
 Version: AHLIM001/3
 Date Calculated: 10/10/2018 09:52

Full Report - V1
 Registration: SLM9312E
 Printed: 13/10/2018 10:11

Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	66.0	
Total Paintwork Labour	6.6HRS	\$297.00
MATERIAL COST - PAINT		Cost Price
Repair Painting		\$15.01
Repair Painting Plastic		\$57.51
Material-Const Main Work Plastic		\$12.70
Total Excluding Pearlescent Uplift		\$113.82
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$113.82

PARTS

Price Valid: 01/06/2015					
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
283	1	FRONT BUMPER	6400H293		0% 390.00*
415	1	GRILLE	6402A300		0% 280.00*
562	1	R/F HEADLAMP	8301C546		0% 300.00*
1000	1	FRONT GRILLE CLPX10	Renew		0% 20.00*
f: OEM Parts		Sub Total			\$990.00
g: Original		Mark Up From Cost (15 %)			\$148.50
h: Secondhand		Total Parts			\$1,138.50
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
CHK WIRING SPECIALIST	0%	\$20.00
Total Extras		\$20.00

Final Calculation

Total Parts	\$1,138.50
Labour	
Total Panel/Mechanical	\$171.00
Total Paintwork	\$297.00
Total Labour	\$468.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$20.00
Total of Additional Costs	\$20.00
Total Paint/Material Costs	\$113.82
Grand Total Excludes GST	\$1,740.32
GST @ 7 %	\$121.82
Grand Total Includes GST	\$1,862.14

Assessment Notes



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
GST/M9-0009639-E RCB NO:06470300B

Avdatex

DRAFT

M/S : SEE CHOR NGAK
612 YISHUN ST 61
#08-193 NEE SOON CENTRAL MEADOWS
SINGAPORE 760612

Claim No: MC0913262
Ref No: MF0911358
Date: 22 Sep 2018
Policy No: PNPV2018-00003974
Veh Reg No: SLM9312E
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

ATTN:

Your Ref No: SLM9312E
Claim Type: Third Party
Accident Date: 10/07/2018

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLM9312E

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT GRILLE WITH CHROME MOULDING		1 PC	280.00	
2 FRONT GRILLE CLIPS		10 PC	20.00	
3 HEADLAMP (NOT HID)		1 PC	300.00	
4 FRONT BUMPER		1 PC	390.00	
			990.00	
	Add 15%		148.50	1,138.50
LABOUR				
5 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT BUMPER REINFORCEMENT.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL,WHEELHOUSE SIDE PANEL RH,FRT BONNET INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	171.00	
7 TO SPRAY FRONT BONNET,RADIATOR SUPPORT PANEL, WHEELHOUSE SIDE PANEL RH,FRONT BUMPER.		1 PC	410.82	
				601.82

Amount Before Excess	S\$ 1,740.32
Less Excess	S\$ 0.00
Amount Before GST	S\$ 1,740.32
Add GST @ 7%	121.82
Total Amount payable	S\$ 1,862.14

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED SIXTY TWO AND CENTS FOURTEEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 17/07/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0913262
Your Ref : SLW3785K
Date : 08/05/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SLM9312E and your Insured SLW3785K ON 10/07/2018 19:15 ALONG 624 YISHUN OSCP

We refer to the above matter.

Please assess through your Insured's (SLW3785K) report and our Client (SLM9312E) – SEE CHOR NGAK's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search

The above vehicle was surveyed by Kenneth from LKK as appointed by OP from AXA on 17/07/2018.

We would quantify our claim as below:-

Cost of Repair	: \$1,862.14
Rental	: \$300.00(3 Day X \$100) Surveyor recommend 3 days. We had rented for 4 days
Audatex Fee	: \$44.94
LTA Search	: \$2.00
=====	
Total	: \$2,209.08

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170


Kee Mui Hong

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7823Z

Vehicle Details

Vehicle No.: SLM9312E
Vehicle to be Exported: No
Intended De-registration Date: 11 Jul 2018
Vehicle Make: MITSUBISHI
Vehicle Model: ATTRAGE 1.2 CVT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 3A92UDP3745
Chassis No.: MMBSTA13AHH003935
Maximum Power Output: 57.0 kW (76 bhp)
Open Market Value: \$13,641.00
Original Registration Date: 18 Apr 2017
First Registration Date: 18 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Apr 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 17 Apr 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,951.00
COE Rebate Amount: \$44,667.00
Total Rebate Amount: \$48,417.00

The information contained herein is correct as at 11 Jul 2018

OK



YOUR EXECUTIVE CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2018-00003974

About this policy

Premium paid : S\$635.52 Coverage start date : 18/04/2018
(Inclusive of GST) Coverage end date : 17/04/2019
Who is insured to drive: : You and any Authorised Driver
Policy Type : EXECUTIVE

About you (As the policyholder)

Your name : See Chor Ngak Joshua
Address : 612 Yishun Street 61 #08-193 Nee Soon Central Meadows Singapore 760612
Email : blaze_see@yahoo.com
NRIC/FIN : S7427823Z Date of birth : 28/08/1974
Marital status : Married Gender : Male
Current no claims discount : 50% Mobile Number : 98220559
Years of driving experience : Three or more Certificate of merit : Yes

About your car

Car make and model : MITSUBISHI ATTRAGE 1.2
Year of first registration : 2017
Car plate number : SLM9312E
Issued on: : 17/03/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions
and exclusions of this policy.

Please immediately inform us at +65-6820-8888
or email us to contact.sg@fwd.com if any details in
this Car Insurance Summary need to be changed.

⏪ Re:MANDATE IA - SLM 9312E- AH LIM

Type

🔗 Question

Message

please proceed.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 189687188R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/7/2018

Survey Details:

Date of loss	10-Jul-18
Date of appointment	16-Jul-18
Date of survey	17-Jul-18
Location of survey	Ah Lim Motor Company

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLM9312E
Make and Model	MITSUBISHI ATTRAGE 1.2 CVT - 1193cc
Date of registration	18-Apr-17
Excess	
Market Value	\$ 52,000.00
Part Rebate	\$ 48,417.00
Nett Loss	\$ 3,583.00

Repair details:

Initial Estimate	3,516.27
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 1,138.50
Check items (estimate)	
Labour	\$ 601.82
Total	\$ 1,740.32
Lump Sum(if applicable)	\$ -

Number of days for repair	3 days
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

INSURED REVERSING IN A CARPARK

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	1,862.14	
Loss of rental	\$	300.00	3 DAYS
LTA search fees	\$	2.00	
Others	\$	44.94	AUDATEX FEE
Proposed Total	\$	2,209.08	



Service Request Details

Claim

S8M00O86

Reference

None

Loss Date

July 10, 2018

Request Date

July 16, 2018

Due Date

July 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

16/7/2018 @ 11:34am
Zila veh ng in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLM9312E

Make

TPVD MITSUBISHI

Model

ATTRAGE-1.2 CVT (A)

Service Address

...

Primary Contact/Insured

DAUD MOHAMMAD FADILLILAH BIN
BLK 308A ANG MO KIO AVE 1, #05-419, 561308, Singapore
96302485
MDFADILLILAH.CAG@GMAIL.COM

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

7/16/18 10:39 AM

FROM

TAN Jas

SUBJECT

DS

BODY

Hi, please proceed DS and obtain video footage for...





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

23 APRIL 2019

MOHAMMAD FADILLILAH BIN DAUD

BLK 308A ANG MO KIO AVE 1

#05-419

SINGAPORE 561308

Dear Sir/Madam,

OUR REF : CC4/ASM18012861/Kja3

YOUR REF : SLW 3785K

ACCIDENT INVOLVING SLW 3785K AND SLM 9312E ALONG YISHUN RING RD CAR PARK ON 10.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s AH LIM MOTOR COMPANY acting on behalf of the owner of SLM 9312E against your motor insurance policy.

Based on the accident report and video, your vehicle had hit Third Party stationary vehicle whilst reversing. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at joyirene@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Joy Irene

Case Handler

DID: 6841 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)


Authorisation to Act


I, SEE CHUR NGAR. (the third party claimant) of 612, YISHUN S161 #08-193 Nee Sun Central meadows S760612 (address), owner of SLM 9312E (Vehicle no) hereby authorise **Ah Lim Motor Company** (the workshop) to act for me in respect to my claim for repair costs and / or rental and /or/loss of use (Claim) for my vehicle No. SLM 9312E that was damaged pursuant to the accident which occurred on 10/07/2018 (date) along 624 YISHUN OPEN SPACE car park. (location) involving vehicle Nos SLW 3785K (the Accident)

I further authorise the workshop to settle the above mentioned claim in a manner that they deem fit and the workshop is further authorised to receive the payment further to settlement of my claim with payment cheque/s made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.

Dated this 11th day of July (month) 20 18 (year)


Signed by Third party claimant
Owner Veh No : SLM 9312E X

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 Ah Lim Autopoint Singapore 568047
Tel: 6392 2444 Fax: 6392 8170

Signed by the workshop

Personal data Protection Act 2012

I/ We acknowledge and consent to Ah Lim Motor Company collecting , using and disclosing and /or processing my/our personal data to Third Party service providers and/or Insurance company my / our personal data for the purpose of processing the claim and related insurance / claim matters.


Owner Signature X



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLW 3785K (Insd veh)	Model: MITSUBISHI ATTRAGE 1.2
	SLM 9312E (TP veh)	
Date of Accident/ Time:	10/07/2018	

Repair Estimate	: \$	3,831.96	
Final Repair Cost	: \$	1,862.14	
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$	300.00	3 days at \$ 100 per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	44.94 AUDATEX FEE	
	: \$		
Final Settlement Sum	: \$	2,209.08	

Payee Name: AH LIM MOTOR COMPANY

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes / No BOLA Scenario No: <u>NIL</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

AH LIM MOTOR COMPANY No. 10 Ang Mo Kio Industrial Park 2A 01-09 AMK Autopoint Singapore 568047 Tel: 6483 1744 Fax: 6483 8170	AH LIM MOTOR COMPANY No. 10 Ang Mo Kio Industrial Park 2A 01-09 AMK Autopoint Singapore 568047 Tel: 6483 1744 Fax: 6483 8170
--	--

Signature of workshop representative / Workshop stamp

Name of Representative: KEE Hui KongDate: 17/06/2019

KSC

Signature of AXA's surveyor/representative:

Name of AXA's surveyor/Representative:

Date: 17/6/19

Signature of Witness / Workshop stamp (if applicable)

Name of Witness: Mark Siew KongDate: 17/06/2019

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SEE CHOR NGAK
612 YISHUN ST 61
#08-193 NEE SOON CENTRAL MEADOWS
SINGAPORE 760612

ATTN:

Your Ref No: SLM9312E
Claim Type: Third Party
Accident Date: 10/07/2018

Claim No: MC0913262
NO: AL1900828
Date: 08 May 2019
Policy No: PNPV2018-00003974
Veh Reg No: SLM9312E
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

Tax Invoice-Final Repair Cost to Vehicle No :SLM9312E

Description	U/Price	Quantity	Cost <u>S\$</u>	Amount <u>S\$</u>
SPARE PARTS				
1 FRONT GRILLE WITH CHROME MOULDING		1 PC	280.00	
2 FRONT GRILLE CLIPS		10 PC	20.00	
3 HEADLAMP (NOT HID)		1 PC	300.00	
4 FRONT BUMPER		1 PC	390.00	
			990.00	
	Add 15%		148.50	1,138.50
LABOUR				
5 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT BUMPER REINFORCEMENT.TO KNOCK & REPAIR RADIATOR SUPPORT PANEL,WHEELHOUSE SIDE PANEL RH,FRT BONNET INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	171.00	
7 TO SPRAY FRONT BONNET,RADIATOR SUPPORT PANEL, WHEELHOUSE SIDE PANEL RH,FRONT BUMPER.		1 PC	410.82	
				601.82

Amount Before Excess	S\$ 1,740.32
Less Excess	S\$ 0.00
Amount Before GST	S\$ 1,740.32
Add GST @ 7%	121.82
Total Amount payable	S\$ 1,862.14

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED SIXTY TWO AND CENTS FOURTEEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 17/07/2018

E. & O. E.

For AH LIM MOTOR COMPANY

~~AH LIM MOTOR COMPANY~~

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AUTHORISED SIGNATURE

Ace Auto

18, Ubi Road 4 #02-05 Ubi Car Mall
Singapore 408616 Reg no : 53029719A

To: Ah Lim Motor Company
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint
Singapore 568047

Invoice No : A4148

Date 31/7/2018

Vehicle No : SJM3335C

Make / Model : Toyota Axio

Rent to : See Chor Ngak - SLM9312E

Account : Ah Lim Motor Company

Rental Ref : 4148

Duration : From :27/07/2018 16.06pm

To : 31/07/2018 17.05pm

Grand Total

No. of days	Rate	Total
4	\$ 100.00	\$ 400.00
		\$ 400.00

ACE AUTO



for Ace Auto

ACE Auto

18 Ubi Road 4, #02-07 Singapore 408616
Tel: 6483 6143 Fax: 6483 6170
Registration No. 53029719 A

Express \$ 1900 00

\$ 1500 *A

No. 4148

RENTAL AGREEMENT / INVOICE

Hirer's Name SEE CHOR NGAK		Date of Birth	Passport / Nric No.	Nationality
Address 612 Vishnu St 61		Occupation	Driving Licence No.	Date of Licence Obtained
Postal Code # 08-193		Contact No.	Mobile Phone No. 93720554	Own Vehicle No. SLN19312E
Driver Name		Date of Birth	Passport / Nric No.	Nationality Malay
Address		Occupation	Driving Licence No.	Date of Licence Obtained
Postal Code		Contact No.	Mobile Phone No.	

CHECK OUT

Date 2/27	Time 1606	Mileage 135935 KM	E 1/4 1/2 3/4 F
Date 31/7/18	Time 5.05pm	Mileage 13609 KM	E 1/4 1/2 3/4 F

Pay for every quarter tank petrol if the petrol is less than the check out amount.

CHECK IN

VEHICLE NO.	SJM 3335 C	MODEL	Toyota Axio 1.5 AT
-------------	------------	-------	--------------------

IMPORTANT NOTES:-

- This vehicle is restricted to SINGAPORE use only.
- BE WARNED: Hirer / Driver shall be fully responsible for all consequences including all outstanding summons and all costs incurred to & by the owner for any invalid entry in Malaysia.
- No refund will be given for vehicle that returns early.
- The hirer shall be liable to pay the first \$1000 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability is \$1500 any accident.
- Hirer shall pay all parking fines & traffic summons, incurred during the period of rental.
- Extension:- One day's advance notice is required otherwise No extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension:- Refer to prevailing rates.
- Please check water & engine oil daily as preventive maintenance.

	UNIT	RATE (\$)	TOTAL (\$)
RATE PER DAY	@		
RATE PER WEEK	@		
RATE PER MONTH	@		
GRAND TOTAL			
DEPOSIT			
EXTENSION ____ DAYS			
TOTAL PAYABLE AMOUNT			
DEPOSIT REFUNDABLE	S\$		
CHANGED OVER FROM VEH.			DATE



We have read and agree to the terms and conditions of the rental agreement above and as set out hereof.
We declare that all information given on this form is true and accurate.

Hirer's Signature

Driver Signature

for ACE Auto



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-107356
Date of Request: 13/07/2018

Your Ref No: Online Purchase

Ah Lim Motor Company
10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 13/07/2018
Enquiry By: Kee Mui Hong
TP Vehicle No.: SLW3785K
Accident Date: 10/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLW3785K	AXA Insurance Pte Ltd	09/02/2018-08/02/2020	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-107356
Date of Request: 13/07/2018

Your Ref No: Online Purchase

Ah Lim Motor Company
10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date 13/07/2018
Enquiry By Kee Mui Hong
TP Vehicle No. SLW3785K
Accident Date 10/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW 3785K (Insd veh)	Model:	MITSUBISHI ATTRAGE (A)
	SLM 9312E (TP veh)		
Date of Accident:	10/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,831.96	
Final Repair Cost	:	\$	1,862.14	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	300.00	3 days
LTA / GIA Search Fee	:	\$	2.00	

Others: Audat Fee	:	\$	44.94	
-------------------	---	----	-------	--

	:	\$		
Final Settlement Sum	:	\$	2,209.08	

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	AH LIM MOTOR COMPANY	:	\$ 2,209.08

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

03/07/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18012861/Kja3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Date : 03-07-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 3785K	Veh. Inspected	SLM 9312E	
Policy No.	P2072047	Coverage (\$)	0.00	
Claim No.	S8M00086	Excess (\$)	0.00	
Assign From		Assign Date	16/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MMBSTA13AHH003935	Colour	METALLIC SILVER	
Odometer	9200	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/55 R15	BRIDGESTONE	9 mm	
L/H Front Tyre	165/55 R15	BRIDGESTONE	9 mm	
R/H Rear Tyre	165/55 R15	BRIDGESTONE	9 mm	
L/H Rear Tyre	165/55 R15	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2018	Inspection Date	17/07/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9312E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT NUMBER PLATE (WCP) (CONSISTENT)	SERVICEABLE	✓ 35.00	-
1	FRONT BUMPER (WCP) (CONSISTENT)	BUCKLED	✓ 390.00	390.00
1	R/F UPP BUMPER BRKT (WCP) (CONSISTENT)	NOT NECESSARY	✓ 10.00	-
1	FRT BUMPER REINF (WCP) (CONSISTENT)	NOT NECESSARY	✓ 120.00	-
1	FRT BUMPER MNTG KIT (WCP) (CONSISTENT)	NOT NECESSARY	✓ 24.00	-
1	LWR RADIATOR GRILLE (WCP) (CONSISTENT)	SERVICEABLE	✓ 110.00	-
1	GRILLE (WCP) (CONSISTENT)	SCRATCHED	✓ 280.00	280.00
1	L/F HEADLAMP (WCP) (CONSISTENT)	SERVICEABLE	✓ 300.00	-
1	R/F HEADLAMP (WCP) (CONSISTENT)	MTG CRACKED	✓ 300.00	300.00
1	R/F FOG LAMP (WCP) (CONSISTENT)	SERVICEABLE	✓ 220.00	-
1	L/DAYT RUNNING LAMP (WCP) (CONSISTENT)	NO SUCH PARTS	✓ 80.00	-
1	R/DAYT RUNNING LAMP (WCP) (CONSISTENT)	NO SUCH PARTS	✓ 80.00	-
1	R/F WING (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 250.00	-
10	R/F WIND CLAMP KIT (WCP) (CONSISTENT)	NOT NECESSARY	✓ 20.00	-
1	R/F WHEELHOUSE PANEL (WCP) (CONSISTENT)	SERVICEABLE	✓ 75.00	-
1	FRONT GRILLE CLIPX10 (WCP) (CONSISTENT)	NECESSARY	✓ 20.00	20.00
1	H LAMP LOW BEAM LH (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 10.00	-
1	H LAMP HOW BEAM RH (WCP) (CONSISTENT)	NOT NECESSARY	✓ 10.00	-
4	H LAMP CLIPS (WCP) (CONSISTENT)	NOT NECESSARY	✓ 8.00	-
1	F FENDER LEO ECO RH (WCP) (CONSISTENT) (NPA)	NOT NECESSARY	✓ -	-
1	F FEN SIG OT CHRO RH (WCP) (CONSISTENT)	NOT NECESSARY	✓ 50.00	-
	COST PLUS 15%		358.80	148.50
			2,750.80	1,138.50
LABOUR				
	PANEL /MECHANICAL INCLUSIVE OF THE REPAIR OF R/F WING.		✓ 373.50	171.00
	PAINTWORK.		297.00	297.00
	CHK WIRING.(ADDITIONAL)		✓ 20.00	20.00

Report Ref No. CC4/ASM18012861/Kja3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINT/MATERIAL COSITS.		139.97	113.82
			830.47	601.82
GRAND TOTAL			3,581.27	1,740.32
RECOMMENDED COST OF REPAIRS				1,740.32

Report Ref No. CC4/ASM18012861/Kja3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	24 July 2018
 TP ESTIMATE - MAILED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2018
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2018
 SLW2785K insd glia.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 July 2018
 TP AH LM-SLM9312E email from workshop including SLM9312E to glia.mg	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	14 July 2018