

15/5/2016

CASE OWNER:

Plehed

IE

CC 4, Asm

180

12862, Kfa39

LKK:

IDAC:

57770

Surveyor:

KINNETH

DOI:

ASSIGNMENT

25/7/2018

Date / Time:

16/7/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PC85IE

Name of Insured:

ST Lee Transport Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10/7/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8M00N2C

Policy No.:

Make / Model:

Place of Accident:

AMK AVE 3 7 Hongkong

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLZ 260 L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

7/7/18
CPL

SLZ 260 L - X; PC85IE - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 27/7/2018

After call ltr to OI: 6/8/2018

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

16/7

OINP. sent out letter.

27/7/2018

Video upload in SMART CLAIM
Spoke to OI, OI mention he already lodge report on
Next day of accident, and admit he doing reversing and
collided to TP vehicle. told him we received a claim from
TP workshop.

3/8/2018

received OI GIA report / IA uploaded in SMART 6/8/2018
pass the to handler

LOD

RECEIVED 30 OCT 2018

After point photo

PRELIMINARY ADVICE

Date/Time:

26/7

Sent By:

Hui Yang (Vince).

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 4,100.00

(4 days)

Reduction: 57-33

%

Email

Call

FINAL SETTLEMENT

Date/Time:

24/10/2018

Confirm with

Mario

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

LH

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST)

S\$ 4,587.00

Loss of Rental (LOR):

S\$ 321.00

(3 days)

x 4100.00 + 7% GST

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

Legal Cost

S\$ -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

Total:

S\$ 4,910.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 4,910.00

Name 1:

Hui Yang Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC. BY:

REF:

ADA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

885k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

26/7 File pass to Catherine

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Veh No:

SL7 2802

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C.

14P8

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

2772

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7 1207721

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

25

mm

D.O.A.

10/7/18

D.O.I.

18/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

US\$4,100.00 (Net \$5,508.68 / 57.33 %)

Report Format :

Lump Sum / I.B.I: (\$