

(08/11/13)

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 296C Yr Regn: 31/12/2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe cc 1991Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 273660 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HET41UMCA 828929

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inor 6 / Jammed / Leaked / Burnt orBrakes: Inor 6 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Wettk

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 14/7/18 D.O.I. 16/7/18Survey held at (DHE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>U/S 42,200.00</u>
	<u>CRWD: 41,749.92 (44%)</u>
	<u>AXA</u>
	<u>42</u>

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

REPAIR ESTIMATE*

VEHICLE NO : SHC 296C

MAKE :

MODEL : HYUNDAI SONATA

DATE 16/7/2018

AXA-45

TS

1/30

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>✓ cr</i>			\$ 538.80 ✓
	Front Bumper Sponge <i>X^{sc}</i>			\$ 136.30
	Front Bumper Reinforcement <i>X^{sc}</i>			\$ 504.10
	Front Bumper Bracket Top (RH) <i>X^{sc}</i>			\$ 22.40
	Front Bumper Protector (RH) <i>X^{sc}</i>			\$ 29.20
	Headlamp (RH) <i>✓ grazed</i>			\$ 797.90 ✓
	Front Fender (RH) <i>✓</i>			\$ 593.00 ✓
	Front Fender Shield (RH) <i>X^{sc}</i>			\$ 86.00
	Front Wheel Rim (RH) <i>X^{sc}</i>			\$ 284.70
	Front Wheel Hub Cap (RH) <i>✓</i>			\$ 145.00 ✓
	<i>Front Bumper X^{sc}</i>			
	SUB TOTAL			\$ 3,137.40
	LESS 20%			\$ 627.48
	DISCOUNTED TOTAL			\$ 2,509.92
	Front Fender Advertisement Logo (RH) <i>✓</i>			\$ 100.00 Nett ✓
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>550</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	FRT Wheel Alignment			\$ 80.00 <i>X^{sc}</i>
	TOTAL LABOUR			\$ 1,340.00
	ESTIMATE TOTAL			\$ 3,949.92
<p><i>Kalua 16/7/18</i></p> <p><i>16/7/18 14:10 hrs</i></p> <p><i>2 days</i></p> <p><i>45</i></p> <p><i>After Repair p/He</i></p>				
<p>KK Auto Consultants hence notify the Reparer of the following:</p> <ul style="list-style-type: none"> To resurvey before after spray painting To display damaged parts during resurvey Parts prices are subject to confirmation Third party liability is on a "no prejudice" basis No illegal modifications allowed Supplies and items must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Reparer:</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Team: ARC Repair TP(CFSO)1 JOB CARD Sales Order: JC NO.: 305188076

OWNER CITYCAB PTE LTD 7010070 OWNER NO 383 SIN MING DRIVE ESS Singapore SINGAPORE 575717 65551188 (R) (P)	REGN NO SHC 296C MAKE HYUNDAI MODEL SONATA YR OF MANU 31.07.2012 CHASSIS CODE RMHET41VMCA828929	MILEAGE FUEL E 1/2 F DATE/TIME IN 14.07.2018 22:10 TARGET DATE COMPLETION DATE/TIME
--	--	---

UNIT CARD NO.

JOB DESCRIPTION

Accident Date: 14.07.2018
NATURE: 3P 14.07.18

S/NO LABOR CODE DESCRIPTION

RECEIVED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Checklist Slip	Exit Pass
No. SHC 296C LIMITS	Vehicle No.: SHC 296C
Service Advisor	Name of Service Advisor
Signature/Date	Date
Returned to Service Reception upon collection	To be kept by Security Guard

AXA-45

TS

1130

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) <i>X repair</i>			\$ 29.20
	Headlamp (RH) ✓			\$ 797.90
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) X			\$ 86.00
	Front Wheel Rim (RH) X			\$ 284.70
	Front Wheel Hub Cap (RH) ✓			\$ 145.00
	<i>Front Bumper X repair</i>			
	SUB TOTAL			\$ 3,137.40
	LESS 20%			\$ 627.48
	DISCOUNTED TOTAL			\$ 2,509.92
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>540</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	FRT Wheel Alignment			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 1,340.00
	ESTIMATE TOTAL			\$ 3,949.92
<p><i>Kalun 10/1/14</i></p> <p><i>16/7/18 1410 hr</i></p> <p><i>2 days</i></p> <p><i>45</i></p> <p><i>After Repair p.l.h</i></p>				
<p>Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To return to the original condition • To display damage - parts during survey • Parts prices are subject to confirmation • Third party survey on a "Without Prejudice" basis • No illegal or dangerous work is allowed • Supplier's warranty must be surveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer:</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Our Job Ref No : 305188076

Date : 17/07/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC 296C

Date of Accident : 14-Jul-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- SJH4893C

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$2,200.00

Final Lumpsum Repair cost \$2,200.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 17/7/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Final Amount Subject to Insurance Approval



**Re:<SEEK MANDATE> S8M00OJ4 ACCIDENT
INVOLVING VEHICLES SJH 4893C(OI) AND SHC
296C(TP) ON 14.07.18 TOTAL: \$2,880.37**

Type

Question

Message

Mandate approved

Reply

Our Ref : CC18070403/ SHC 296C /WT(st)

Your Ref :

Date : 23-Jul-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No. 196900089

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408549

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 726791

Yishun
501 Yishun Industrial Park A
Singapore 768732

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC 296C YOUR INSURED SJH4893C
AND OTHER ON 14.07.18**

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No : **SHC 296C** which was involved in the captioned accident with your insured vehicle.

The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SJH4893C** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 2,354.00
2	3.5 days Loss of Rental @ \$ 98.25 per day	\$ 343.88
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
Sub Total :		\$ 2,705.37

HIRER'S CLAIM

7	3.5 days Loss of Income @ \$ 80.00 per days	\$ 280.00
Total Claims :		\$ 2,985.37

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 6 pcs.
- b) LTA search slip/s of : **SJH4893C**
- c) GIA / Police report/s of : **SHC 296C**
- d) Letter of authority from owner / hirer / operator
 - (X) Photocopies of Accident Scene Photo/s () Certificate of Insurance
 - () Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

05 NOVEMBER 2018

LEE CHAI THIAM
BLOCK 9 TOH YI DRIVE
#11-323
SINGAPORE 590009

Dear Sir/Madam,

OUR REF : CC4/ASM18012866/K1ha3
YOUR REF : SJH 4893C
ACCIDENT INVOLVING SJH 4893C AND SHC 296C ALONG UPPER BUKIT TIMAH
ROAD ON 14.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD, acting on behalf of the owner of SHC 296C against your motor insurance policy.

Based on the accident report and accident scenario and pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONG

SONATA SHC296C , SJH4893C

ON 14-Jul-18 21:20

UPP BUKIT TIMAH RD TWDS CITY BEFORE OLD BUKIT TIMAH FIRE STATION

I / We

TAN KEE SENG

(Hirer) NRIC No.:

S0016948Z

and/or

TEH SOON HON

(Relief) NRIC No.:

S2506462C

Taxi Number

SHC296C

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

15-Jul-2018

Name of Hirer

TAN KEE SENG

Hirer NRIC

S0016948Z

Signature :



Address

194 KIM KEAT AVENUE #09-400
310194

Contact No.

96353954

Name of Relief

TEH SOON HON

Relief NRIC

S2506462C

Signature :



Address

249 KIM KEAT LINK #09-87
310249

Contact No.

93364557



redefining / insurance

CLAIM REF : S8M000J4
INSURED : LEE CHAI THIAM

DISCHARGE VOUCHER

We, **COMFORTDELGRO ENGINEERING PTE LTD** confirm that by letter of authorisation dated **15/07/2018**, we are authorised to and do hereby give this discharge for ourselves and on behalf of **CITYCAB PTE LTD** and the Hirer, **TAN KEE SENG** of vehicle no. **SHC 296C**.

Now we **COMFORTDELGRO ENGINEERING PTE LTD** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars **TWO THOUSAND EIGHT HUNDRED EIGHTY** only (**\$52,880.00**) in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no **SJH 4893C** arising out of an accident with **SHC 296C** on **14/07/2018**.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **SJH 4893C** arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **COMFORTDELGRO ENGINEERING PTE LTD** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **SJH 4893C**.

Dated this 14 day of November 2018

Signed by _____
(AUTHORISED SIGNATORY)

Company Stamp _____
COMFORTDELGRO ENGINEERING PTE LTD
38 LLOYD DRIVE
SINGAPORE 600033

Witness : _____
Name : _____
I/C No : _____
Address : _____
COMFORTDELGRO ENGINEERING PTE LTD
38 LLOYD DRIVE
SINGAPORE 600033

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

All provisions of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document.

Our Ref: CC18070403



Date: 18 July 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	14/07/2018 @ 21:20 hrs
ALONG	UPP BT TIMAH RD > CITY B4 OLD BUKIT TIMAH FIRE STN
INVOLVING	SJH4893C

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC0296C** (the "Taxi"). The Taxi was hired to **TAN KEE SENG IC NO S0016948Z** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$98.25** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SAC 296C

NG	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		FROM	TO								FROM	TO
17	149	0500	1000	10-07-18	Kee Seng	2709	50			292	0425	1530
17	120	1100	1600	10-07-18	M	2711	279			329	1555	0145
15	318	1610	0125	11-07-18	Dely	2711	537			258	0400	1430
18	333	0340	1520	12-07-18	M	2711	859			322	1535	0055
2	364	1500	0207	20-07-18	Dely	2721	84			325	0430	1510
8	336	0340	1345	13-07-18	M	2725	18			338	1600	0105
27	339	1530	0110	13-07-18	Dely	2728	44			325	0400	1500
2	405	0340	1540	14-07-18	M	2731	32			288	1530	0015
1	289	1610	004	14-07-18	Dely	2734	78			346	0340	1500
18	377	0450	2110		M	2736	60			182	1550	2200

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJH4893C	14 Jul 2018 / 21:20:00	Successful	A12	AXA INSURANCE PTE LTD

[Previous](#)[OK](#)

SAC 296 C

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJH 4893C (Insd veh)	Model:	HYUNDAI SONATA
	SHC 296C (TP veh)		
Date of Accident:	14/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	4,226.41
Final Repair Cost	:	\$	2,354.00
Loss of Token Sum	:	\$	175.00
Rental (if any)	:	\$	343.88
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,880.00

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____100_____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	\$ 2,880.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

20/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012866/K1ha3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA LOH

Date : 20-11-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 4893C	Veh. Inspected	SHC 296C
Policy No.	GA283123/1	Coverage (\$)	0.00
Claim No.	S8M000J4	Excess (\$)	0.00
Assign From		Assign Date	16/07/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHET41VMCA828929	Colour	YELLOW
Odometer	273660	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2018	Inspection Date	16/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 296C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER (CONSISTENT)	CRACKED	538.80	538.80
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	136.30	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	504.10	-
1	FRONT BUMPER BRACKET TOP (RH) (CONSISTENT)	SERVICEABLE	22.40	-
1	FRONT BUMPER PROTECTOR (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	29.20	-
1	HEADLAMP (RH) (CONSISTENT)	GRAZED	797.90	797.90
1	FRONT FENDER (RH) (CONSISTENT)	DENTED	593.00	593.00
1	FRONT FENDER SHIELD (RH) (CONSISTENT)	SERVICEABLE	86.00	-
1	FRONT WHEEL RIM (RH) (CONSISTENT)	SERVICEABLE	284.70	-
1	FRONT WHEEL HUB CAP (RH) (CONSISTENT)	CRACKED	145.00	145.00
1	FRONT BONNET (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-627.48	-414.94
			2,509.92	1,659.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT LOGO (RH) (CONSISTENT) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF FRONT BUMPER PROTECTOR (RH) AND FRONT BONNET .		560.00	400.00
	SPRAY PAINTING CHARGE.		600.00	540.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT .	NOT NECESSARY	80.00	-
			1,340.00	980.00
	GRAND TOTAL		3,949.92	2,739.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CC4/ASM18012866/K1ha3q2



Report Ref No. CC4/ASM18012866/K1ha3q2

A handwritten signature in black ink, appearing to be 'KALVIN'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'HO LEONG CHUAN'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.