

ASS. EPC. BY:

REF CS3/EG118012920/T124d3<sup>2</sup>

Special Instruction

Surveyor

Tau Hieh

ASSIGNMENT (Office)

From (Person)

Yee Pei Li

of

EG1

Date/Time

17/7/18 @ 9:13am

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G1BD4U

Insured:

SDR 333C

at Workshop n/s

Seng Hwee Motor

Tel:

6755 5205

of

Blk 1018, Yishun Ind. Park A #01-350

Policy No:

Claim No:

SDR 333C

Sum Insured:

Excess:

Make of Veh:

D.O.A

13/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time

9:21am @ 17/7/18

Person Contacted:

Mr. Kueh

Vehicle IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

G1BD4U-X

SDR 333C-X

After repair: 20/7/2018





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS3/EGI18012920/T1z4d3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 17-07-2018	
		Code : EGI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SDR 333C	Veh. Inspected	GBD 4U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	17/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	13/07/2018	Inspection Date	17/07/2018
Survey held at	SENG HWEE MOTOR BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 17 July 2018 9:13 AM  
**To:** admin-d@lkkauto.com  
**Cc:** ASSIGNMENTS@LKKAUTO.COM  
**Subject:** OI : SDR333C / TP : GBD4U/JPK / DOA : 13.07.2048  
**Attachments:** SDR333C - SAS.pdf; GBD4U - SAS.pdf; GBD4U - PRI NOTICE.pdf

Dear Catherine/Nivitha,

We have rejected to their PRS list, please assist to conduct this survey **ONG & SHAN LLC**,

ADDRESS : **SENG HWEE MOTOR**  
BLK 1018 YISHUN INDUSTRIAL PARK A  
#01-350  
SINGAPORE 768760

PERSON TO CONTACT : MR KUEH SENG HOE @ 6755 5205

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are our insured's and third party's SAS (note: reports not to be released to any Third Party). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**ONG & SHAN LLC**

ADVOCATES & SOLICITORS  
COMMISSIONERS FOR OATHS  
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:  
Lawyer : [ongshanllc@gmail.com](mailto:ongshanllc@gmail.com)  
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407  
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357  
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184  
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.3559.18  
Your Ref : Your Insured vehicle SDR 3333C  
Date : 16 July 2018

ERGO Insurance Pte. Ltd.

BY FAX ONLY 6829 9247

Dear Sirs

**NOTICE OF ACCIDENT  
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES GBD 4U & SDR 3333C ON  
13.07.2018 ALONG LOT ONE BASEMENT CAR PARK @ 1458 HRS**

We act for the owner who has appointed the under-mentioned workshop to repair their motor vehicle no. GBD 4U.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Seng Hwee Motor  
Address : Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760  
Contact person : Mr. Kueh  
Telephone no. : 6755 5205  
Fax no. : 6753 4407

We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

**ONG & SHAN LLC**

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

Date of Accident : 13/07/18  
Accident Time : 1458  
Accident Place : LOT ONE BASEMENT CAR PARK

Vehicle Reg. No. (A) : GBD 4u  
Vehicle Make \ Model : TOYOTA HIACE  
Insurance company : NTUC INCOME 080118 - 151218

Policy No : 509 719 3055  
Name & IC no. OWNER : THE AYE JYE 53341588L  
52A

Name & IC- no. DRIVER : THONG JI7 WU 37829328D.  
DATE OF BIRTH : 20/10/1978

Relationship bet. owner & Driver : Spouse \ Father \ Mother \ son \ daughter  
Others :

DRIVER'S Address : 134 SERANGOON NORTH AVE 1 #12-140  
Contact No. DRIVER : 9228 3393 (S550134)

Occupation : INDOOR \ OUTDOOR  
Fax no \ Email Address : ayejye33@gmail.com

Weather & Road Surface : CLEAR | RAINING | WET | DRY


Reporting type : Reporting Only \ Claim Other Party \ Claim Own Ins.  
T/P claim

### Other Party Driver's Particulars

(B)  
Vehicle Reg. No. : SDR 3333C  
Vehicle Make \ Model : PEUGEOT  
Name DRIVER :  
IC no. DRIVER :  
DRIVER'S contact & add : 81890922

Vehicle Reg. No. :  
Vehicle Make \ Model :  
Name DRIVER :  
IC no. DRIVER :  
DRIVER'S contact & add :

# SKETCH PLAN



A. GBD 4U

B. SDR 3333C

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 13/7/18 1458 HRS ~~FROM~~ TRAVELING STRAIGHT

TOWARD EXIT OF CARPARK VEHICLE B SDR 3333C

WHICH IS PARK BESIDE THE PILLAR, FAIL TO

CHECK CLEAR OF TRAFFIC BEFORE COMING OUT

OF THE PARKING LOT AND HIT VEHICLE A

GBD 4U.

FEELING GIDDY AND LEFT LEG ACHING.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

*[Handwritten Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time: 14-07-2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EG18012920/T1z4d3s2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 17-08-2018		
FIVESINGAPORE 038985		Code: EGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SDR 333C	Veh. Inspected	GBD 4U	
Policy No.		Coverage (\$)	0.00	
Claim No.	SDR 333C	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTFHT02P600051823	Colour	RED	
Odometer	435383 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	195 R15	MICHELIN	6 mm	
L/H Rear Tyre	195 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
5. General Information				
Accident Date	13/07/2018	Inspect Date / Time	17/07/2018 ( 03:30 PM )	
Survey held at	SENG HWEE MOTOR BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500- \$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/EG18012920/T1z4d3s2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.