

Your Ref : S8M00OM9

Date: 13<sup>th</sup> August 2018

Our Ref : CS/ASM18012926/Zvd3s2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GW 4398Y  
ACCIDENT ON 12/07/2018**

Instruction was received to inspect the vehicle Reg. No. GW 4398Y. The inspection was conducted on 18/07/2018 at the premises of M/s K.Kim Hin Automotive Pte Ltd, 160 Sin Ming Drive #02-20 Sin Ming Autocity Singapore 575722.

The following vehicle information was recorded:

Registration Number	: GW 4398Y
Make/Model	: Volkswagen
Year of Registration	: 2003
Body Colour	: Yellow
Chassis Number	: WV1ZZZ9KZ3R517652
Engine Capacity	: 1896 cc
Speedometer Reading	: 263439 km

The engine burnt. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	24,000.00
Less: LTA Reimbursement Value (RV)	(S\$	18,085.00)
Nett Liability	S\$	5,915.00

Vehicle Inspected By:



ROHAIZAL A. RAHIM (HAIZAL)  
Technical Investigator



K.K. LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MII(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.