

NATIONAL Assessment Centre Services [ver 1 Jan 2005]			
Date In: 17/07/2018 11:29	Job description	Date & Time Completed	Done by
Ref No: NA/INC18012933/K4	SAS e-filing		
Veh No: GBE 8273B	E-mail (within 8hrs, AIC 2hrs)		
D.O.A: 16/07/2018 15:30	i-Motor Claim Form	MT/1003350+001	17/7/18 13:30
OD TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
TP Insurer:	i-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: () Tel: () Fax: ()

TP Particulars:	Veh No: XE1124J	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: () Date: () Time: ()		
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks: () Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: ()

Date/Time	Actions

Claimant's Particulars:-	Invoice Preparation Checklist		Am't (\$)	Am't (\$)
			In Bill	Add Bill
Driver/Owner:	1) AR: Accident Reporting (\$30);			
Contact No:	2) DA: Damage Assessment (\$100); INC (\$80)			
Damaged Portion:	3) TF: Towing Fee \$40/\$45			
QC Checked by (Engr-In-Charge):	4) FT: Follow-Through Survey \$120			
Auditors' Comments:-	5) FT: Follow-Through Survey (Resurvey) \$30			
	For claiming against INC Only (wef 10 Jan 2005)			
Cat. 1:	6) TR: Re-inspection \$75			
Cat. 2 / 3:	7) N1: Idno DA + SMRT Survey \$160			
	8) NTUC Additional Services:-			
	OD*			
	*N5: Courtesy Car / Tpt Allowance \$5			
	*N6: Repair Co-ordination \$10			
	*N7: Post Repair Inspection \$25			
	*N8: DV / Collect Excess Coordination \$5			
	TP (N11): TP (Non INC) against INC \$20			
	9) N12: Idno Mobile 30			
	Invoice dated	Fee Charged		
	Invoice dated	Fee Charged		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2018 11:29
Date Of Accident	16/07/2018 15:30
Exact Location Of Accident	PIE TWDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8273B
Insured/Policyholder	
Name Of Registered Owner	TOADS HANDYMAN
Co Reg No	53339375B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90521385
Alternative Phone No	OFFICE-90521385

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE 3.0 SUPER GL DARK PRIME
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082050301-01
Cover Note Number	

Driver

Name of Driver	YEO POH HWA (YAO BAOHUA)
NRIC No	S7412993E
Date Of Birth	26/04/1974
Occupation	OUTDOOR
Date Of Driving Pass	21/10/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90521385
Fax Number	
Contact Number	OTHERS-90521385
EMail Address	NOEMAIL

Address	BLK 95 GEYLANG BAHRU 02-3134
Postcode	330095
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1124J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIA CHIT BENG (XIE ZHIMING)
NRIC/Passport Number	S7331003B
Contact Number	87178667
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - 6 BE 8273 B
B - XE 1124 J

PIE to TUAAS



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was driving along PIE towards TUAAS. When Vehicle B in front of me suddenly slowdown and stop. I was driving behind Vehicle B and I just hit on Vehicle B rear portion. The damage of my Vehicle A was in front portion and right side door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Amount Payable (From 06 Oct 2018 to 05 Apr 2019)

Amount Payable (From 06 Oct 2018 to 05 Oct 2019)

	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	91.00	-	91.00
Total Amount Payable :			116.00

This vehicle has a road tax Over Payment of \$56.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

Print

Reported on 17/7/2018

@ 1129 AM

ACCIDENT STATEMENT

ACCIDENT DATE: (16, 7, 2018) (DD/MM/YYYY), TIME: (15:30) (HH:MM)

LOCATION: PIE towards Tyas

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: GBE 8273B
b) INSURANCE COMPANY: _____
c) POLICY NUMBER: _____
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: _____
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: _____
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 9
c) ADDRESS: _____

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 90521385
c) ADDRESS: _____

*d) DATE OF BIRTH: (____/____/____) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS: _____

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: XE1124J MODEL: _____
b) DRIVER'S NAME: _____
c) NRIC/FIN/PASSPORT: _____ CONTACT: _____

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
e) DRIVER'S NAME: _____
f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

No of passengers
(including driver)
(1)

No of passengers
(including driver)

No of passengers
(including driver)

Vehicle Tow
In to
idac on
16/7/2018
Key given but
cannot start
but Automatic
starting.

Email =

Fax =

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S7412993E



Name
YEO POH HWA
(YAO BAOHUA)

Race
CHINESE

Date of Birth Sex
26-04-1974 M

Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7412993E**

Name
YEO POH HWA
(YAO BAOHUA)

Birth Date **26 Apr 1974**
 Issue Date **28 Mar 2003**




A0075236




S7412993E

Blood Group Date of issue
O+ 02-11-2001

Address
APT BLK 95 GEYLANG BAHRU
#02-3134
SINGAPORE 330095

LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 1 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE **21 Oct 1999**

MILEAGE 90521388

Licence No: S7412993E



Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident

16/07/2018 15:30

Vehicle No.(For Motor)

GBE8273B

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5082050301-01	TOADS HANDYMAN	53339375B	GCV	Comprehensive	GBE8273B	GBE8273B	06/10/2017	05/10/2018

Continue

▼ Policy Information

Policy No.	5082050301-01	Policyholder Name	TOADS HANDYMAN	Policyholder NRIC	53339375B
Address	BLK 28 #11-681 BENDEMEER ROAD BENDEMEER VILLE SINGAPORE 330028				
Product Name	COMMERCIAL VEHICLE INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	27/09/2017	Effective Date	06/10/2017 00:00	Expiry Date	05/10/2018 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess		OS Premium	0		
Outside Singapore OD Excess		Outside Singapore TP Excess			
Agent	THINK ONE AUTOMOBILE & TRA	Agent Tel.	65433303	GST Flag	Y
Co-Insurance Flag	No				
Open Policy Info					
Certificate Info					

▼ Policyholder Mailing Address

Address 1	BLK 28 #11-681	Address 2	BENDEMEER ROAD	Address 3	BENDEMEER VILLE
Address 4	SINGAPORE 330028	Address Type	Singapore address	Post Code	330028
Unit No.	11-681	Related Policy Number	5082050301-01		

▶ Insured Object: GBE8273B

▼ Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
----------	---------------------	------------------	--------------------	---------------------

Continue

Cancel

Claim Handling

Accident MT/1003350

Policy No.	5082050301-01	Vehicle No.	GBE8273B	GST Registration No.	
Policyholder Name	TOADS HANDYMAN			Policyholder NRIC	533:
Product Code	COMMERCIAL VEHICLE INSURAT	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

▼ Accident Details

Report Date	17/07/2018 13:20	Accident Report Within 24 hrs	Yes	Accident Type	Colli
Date of Accident	16/07/2018	Time of Accident hh:mm	15:30	Country of Accident	Sing
Reporting Centre		Orange Force		ICM No.	
Accident Location	PIE TWDS TUAS				

▼ Benefits

▼ Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	No
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 28 #11-681	Address 2	BENDEMEER ROAD	Address 3	BEN
Address 4	SINGAPORE 330028	Address Type	Singapore address	Post Code	3300
Unit No.	11-681	Related Policy Number	5082050301-01		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	YEO POH HWA (YAO BAOHUA)	Driver NRIC	S7412993E	Driver DOB	26/C
Register Date of Driver License	21/10/1994	Driver Age	44	Driving Experience	23
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 95	Address 2	GEYLANG BAHRU	Address 3	
Address 4		Address Type	Singapore address	Post Code	3300
Unit No.	#02-3134				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 OD-MD

New

Claim Type *	OD-MD	Insured Name	TOADS HANDYMAN	Insured NRIC	533:
Contact No.(Mobile)	94516574	Contact No.(Home)	NIL	Contact No.(Office)	
Email Address		OI Vehicle Number	GBE8273B	TP Vehicle Number	XE1
Claim Description	GBE8273B / XE1124J ON 16 Jul 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability *	Partially at Fault	GIA report	Rec
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	Date Received	17/K
Date Registered	17/07/2018 13:31	Claim Close Date		Total Loss but Repaired	
Report Taken By	KRISHNASAMY	Workshop Repairer		OD Excess Collected by Workshop	

☒ Print AK letter

Save Submit

Attachment

Accident No.

MT/1003350

Claim No.

001

Last Doc. Received

Yes

No

Upload Date

17/07/2018 13:30

Path *

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Choose File

No file chosen

Message Read

Category *

Confidential

Urgency *

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Descrip
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:30	NRIC/ Driving License	Normal	NRIC/ Driving Lice
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:26	SAS	Normal	SAS 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:26	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:26	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:26	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 17 Jul 2018 13:25	Photos	Normal	Photos 2018

Video List

Uploaded By/Date	Folder Date	File Name	Source
Display in New Window Scan and uploading			

VAN / LORRY (Frt)

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (✓)
(4)Not Committed (NC)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRA	✓	✓
1002	991887	Frt Number Plate Base	CRA	✓	✓
1004	991300	Frt Bumper	DIS	✓	✓
2001	991477	Frt Bumper Upper Clips	MEC	✓	6
2002	991387	Frt Bumper Lower Grille	CRA	✓	✓
2003	991449	Frt Bumper Side Cover		✓	✓
2004	991443	Frt Bumper Retainer	DIS	✓	2
1006	991325	Frt Bumper Bracket		✓	✓
1008	991433	Frt Bumper Reinforcement		✓	✓
2005	991466	Frt Bumper Signal Lamp		✓	✓
1017	995100	Frt LH Bumper Fog Lamp Cover		✓	✓
1018	991355	Frt RH Bumper Fog Lamp Cover		✓	✓
1019	995079	Frt LH Bumper Fog Lamp		✓	✓
1020	995080	Frt RH Bumper Fog Lamp		✓	✓
1021	991793	Frt Grille	BR	✓	✓
1022	991328	Frt Grille Emblem		✓	✓
2006	990247	Frt Grille Sticker		✓	✓
1023	991799	Frt Grille Chrome Moulding		✓	✓
2007	991891	Frt Fire Wall Panel BUC		✓	✓
2008	991874	Frt Lower Panel		✓	✓
2009	991328	Frt Panel Emblem		✓	✓
2010	990247	Frt Panel Sticker		✓	✓
2011	991893	Frt Panel Garnish		✓	✓
1024	991222	Frt Brace Panel	BT	✓	✓
2012	991527	Frt Corner Panel RH	BUC	✓	✓
2013	991532	Frt Corner Panel Signal Lamp		✓	✓
2014	995245	Frt Signal Lamp LH		✓	✓
2015	995246	Frt Signal Lamp RH		✓	✓
1029	995153	Frt LH Headlamp Assy	CRA	✓	✓
1030	991821	Frt RH Headlamp Assy	CRA	✓	✓
1031	995088	Frt LH Side Lamp		✓	✓
1032	995089	Frt RH Side Lamp		✓	✓
2016	992149	Frt Wiper Panel	BUC	✓	✓
2017	995043	Frt Wiper Nozzle		✓	✓
1120	992140	Frt Wiper Arm	BT	✓	2
1121	992142	Frt Wiper Blade	DIS	✓	2
2018	992145	Frt Wiper Link		✓	✓
2019	992148	Frt Wiper Motor		✓	✓
1122	995045	Wiper Panel Garnish	CUT	✓	✓
1114	992093	Frt Windscreen	CRA	✓	✓
1115	992097	Frt Windscreen Rubber Moulding	NEC	✓	✓
1117	992098	Frt Windscreen Sealant	NEC	✓	✓
2020	992114	Frt Windscreen Outer Pillar	BUC	✓	✓
2021	992113	Frt Windscreen Inner Pillar	BUC	✓	✓
1118	991019	ERP Bracket	NEC	✓	✓
1119	991020	ERP Unit		✓	✓
2022	991958	Frt Side Mirror (Big)		✓	✓
2023	991959	Frt Side Mirror (Small)		✓	✓
2024	991962	Frt Side Mirror (Round)		✓	✓
2025	995015	Frt Wing Mirror Stay		✓	✓
1025	992013	Frt Support Panel	BUC	✓	✓
1033	990248	Bonnet	BUC	✓	✓
1035	990287	Bonnet Lock	JM	✓	✓
1037	990273	Bonnet Hinge	BT	✓	2
1039	990305	Bonnet Rubber	BT	✓	✓
1042	990119	Air Con Condenser	BT	✓	✓
1043	990122	Air Con Fan Assy		✓	✓
1048	990149	Air Con Liquid Pipe		✓	✓
1049	995066	Air Con Receiver Drier		✓	✓
1052	995074	Radiator	DD	✓	✓
1053	992738	Radiator Cowling		✓	✓
1054	992742	Radiator Fan Assy		✓	✓
1056	992758	Radiator Hose Top	TN	✓	✓
1058	992741	Radiator Expansion Tank		✓	✓
2026	992596	Oil Cooler	DD	✓	✓
1079	994431	Power Steering Cooler Pipe		✓	✓
1059	990151	Air Duct		✓	✓
1060	990070	Air Cleaner Assy		✓	✓
1067	990219	Battery		✓	✓
1069	990223	Battery Bracket		✓	✓

Vehicle No: GBE 8273 B

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover		✓	✓
1086	990946	Engine Mounting		✓	✓
2027	991500	Frt Cabin Assy		✓	✓
2028	991501	Frt Cabin Mounting		✓	✓
2029	991502	Frt Cabin Rear Panel		✓	✓
1092	991520	Frt LH Chassis Member		✓	✓
1093	991520	Frt RH Chassis Member		✓	✓
1094	990728	Frt Vertical Cross Member		✓	✓
1095	991863	Frt Lower Cross Member		✓	✓
2030	990143	Air Con Evaporator Assy	DD	✓	✓
2031	990106	Air Con Blower	BR	✓	✓
1082	990427	Brake Master Pump Assy		✓	✓
1083	990403	Brake Booster Pump Assy		✓	✓
2032	990431	Brake Pedal		✓	✓
2033	990021	Accelerator Pedal		✓	✓
2034	990627	Clutch Pedal		✓	✓
1127	994483	Steering Wheel Airbag	BUS	✓	✓
1128	994485	Steering Wheel Airbag Sensor	NEC	✓	✓
1131	990029	Airbag Control Unit		✓	✓
1133	991922	Frt RH Seat Belt Assy	JM	✓	✓
1135	995182	Frt LH Seat Belt Assy	JM	✓	✓
1124	990753	Dashboard Assy	BR	✓	✓
1125	992282	Glove Box Cover		✓	✓
1126	992281	Glove Box Compartment		✓	✓
1096	995070	Frt LH Fender		✓	✓
1097	995072	Frt LH Fender Inner Panel		✓	✓
1100	991740	Frt LH Fender Inner Shield		✓	✓
1101	995179	Frt LH Mudflap		✓	✓
2035	994966	Frt LH Wheel Guard		✓	✓
1102	995170	Frt LH Wheel Rim		✓	✓
1104	995065	Frt LH Tyre		✓	✓
1105	995071	Frt RH Fender		✓	✓
1106	991739	Frt RH Fender Inner Panel		✓	✓
1109	991740	Frt RH Fender Inner Shield		✓	✓
1110	991884	Frt RH Mudflap		✓	✓
2036	994966	Frt RH Wheel Guard		✓	✓
1111	992087	Frt RH Wheel Rim		✓	✓
1113	995065	Frt RH Tyre		✓	✓
1255	995326	Frt LH Door		✓	✓
1256	995140	Frt LH Door Protector		✓	✓
1257	995104	Frt LH Door Hinge		✓	✓
1258	995142	Frt LH Door Wing Mirror		✓	✓
1262	995103	Frt LH Door Glass		✓	✓
1263	991595	Frt LH Door Glass Regulator		✓	✓
1264	991596	Frt LH Door Glass Regulator Motor		✓	✓
1265	991662	Frt RH Door Edge Protector	BT	✓	✓
1266	991636	Frt RH Door Lock		✓	✓
1272	991617	Frt RH Door Window Guide	DIS	✓	✓
1316	995327	Frt RH Door	BUC	✓	✓
1317	991654	Frt RH Door Outer Moulding	DIS	✓	✓
1318	991601	Frt RH Door Hinge	BT	✓	2
1319	991685	Frt RH Door Wing Mirror	BR	✓	✓
1323	991584	Frt RH Door Glass	BR	✓	✓
1324	991595	Frt RH Door Glass Regulator	BT	✓	✓
1325	991596	Frt RH Door Glass Regulator Motor		✓	✓
1326	991662	Frt RH Door Rubber	TN	✓	✓
1327	991636	Frt RH Door Outer Handle		✓	✓
1333	991617	Frt RH Door Inner Trim Board		✓	✓
2037	991644	Frt Door Frt Pillar RH	BUC	✓	✓
2038	991657	Frt Door Rear Pillar		✓	✓
2039	992072	Frt Wheel Arch Panel		✓	✓
2040	992069	Frt Wheel Arch Panel Garnish		✓	✓
2041	991996	Frt Step Panel		✓	✓
2042	994498	Frt Step Panel Top Garnish		✓	✓
2043	994495	Frt Step Panel Inner Garnish		✓	✓
1073	995053	Wiper Washer Tank		✓	✓
1136	990247	Sucker	NEC	✓	✓
		Bonnet Emblem	SCR	✓	✓
		Fire Wall Insulator	NEC	✓	✓
		Steering Column Coupling	BR	✓	✓

No of Items:

Assessor:

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

VAN / LORRY (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (✓)
(4) Not Consistent (NC)

Vehicle No:

GBE 8273 B

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		Roof Panel	BUC	/	
		" Lining	BT	/	
		Sun Visor	? 2		
		- FT W/S Green RH Pillar Inner DD	/		
		Garnish			
		- Rear View Mirror	?		
		- Passenger Air Bag	BUS	/	
		" " " " Sensor	NEC	/	
		- Instrument Cluster	?		
		- RH Air Can Duct	?		
		- Push Start Button	?		
		- Radio Set	?		
		- Steering Column Cover	D.S.	/	
		- Air Can Grille	?	4	
		- Dashboard/Cte Partition	?		
		- Interior Lighting Switch	?		
		- Gear Lever Pinial	?		
		- front Wire Harness	?		

No of Items: _____ Assessor: _____

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn Property () b) Road Work Object ()
- (Eg. signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other:
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
- when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: GBE8273B Yr Regn: 6 Apr 2016

Type: M.Car / M.Cycle / Bus (Van) / Lorry / Taxi / Prime Mover / M/RV

/ Truck / Trailer or

Make & Model: Toyota Hiace 3.0 C.C. 2982

Colour: Grey Transmission Type: Auto / Manual

Eng/No: Sp. Reading: No Display

C/No: KDH 201 0191605

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 - Power Trainers

R: 195 R15 - Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or As above

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>4</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>4</u> mm

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: 20 Vehicle in Idac: Yes / No

D.O.I. 17/7/2018 Time: 5.20 pm

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

Claim Handling

Task Transfer Exit

LOS SAL SUB

▼ Accident MT/1003350

Policy No.	5082050301-01	Vehicle No.	GBE8273B	GST Registration No.	
Policyholder Name	TOADS HANDYMAN			Policyholder NRIC	53339375B
Product Code	COMMERCIAL VEHICLE INSURAN	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No ▼
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

▼ Accident Details

Report Date	17/07/2018 13:20	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	16/07/2018	Time of Accident hh:mm	15:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	3572675
Accident Location	PIE TWDS TUAS				

▼ Benefits

▼ Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	18/07/2018 09:57:56 Emily Tan changed GST Status Verified from No to Yes		

▼ Policyholder Mailing Address

Address 1	BLK 28 #11-681	Address 2	BENDEMEER ROAD	Address 3	BENDEMEER VILLE
Address 4	SINGAPORE 330028	Address Type	Singapore address	Post Code	330028
Unit No.	11-681	Related Policy Number	5082050301-01		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	YEO POH HWA (YAO BAOHUA)	Driver NRIC	S7412993E	Driver DOB	26/04/1974
Register Date of Driver License	21/10/1994	Driver Age	44	Driving Experience	23
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 95	Address 2	GEYLANG BAHRU	Address 3	
Address 4		Address Type	Singapore address	Post Code	330095
Unit No.	#02-3134				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History	18/07/2018 11:33 s990621 Modify Orange Force(N-->Y) 18/07/2018 11:33 s990621 Modify ICM No(==>3572675)		

▼ Investigation

Claim 001 OD-MD

▼ Claim Case Officer Zuraimie Bin Mantau

Claim Type	OD-MD	Insured Name	TOADS HANDYMAN	Insured NRIC	53339375B
Contact No.(Mobile)	94516574	Contact No.(Home)	NIL	Contact No.(Office)	
Email Address		OI Vehicle Number	GBE8273B	TP Vehicle Number	XE1124J
Claim Description	GBE8273B / XE1124J ON 16 Jul 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Partially at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	17/07/2018 13:32	Claim Close Date		Date Received	17/07/2018 13:30
Report Taken By	KRISHNASAMY	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	
Modification History					

Special Claim Creation Approval

Approval

Reason

Remarks

damage assessment

Activity Handling

Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	HIACE	Engine Capacity	1.3
Date of Registration	06/04/2016	Classis No.	KDH2010191605		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☒ Yes ☐ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

Remark

NO OF REPAIR DAYS : 20 /1X FRT GRILLE CHROME MOULDING UNCONFIRM/1X FRT WINDSCREEN REPLACE/1X FRT WINDSCREEN OUTER PILLAR REPLACE/1X FRT WINDSCREEN IN REPLACE/1X BONNET LOCK REPLACE/1X BONNET RUBBER REPLACE/1X AIR CON LIQUID PIPE UNCONFIRM /1X STEERING WHEEL AIRBAG REPLACE/1X STEERING WHEEL AIRBAG REPLACE/1X DASHBOARD ASSY REPLACE/1X FRT RH DOOR EDGE PROTECTOR REPLACE/1X FRT DOOR LOCK UNCONFIRM /1X FRT RH DOOR WINDOW GUIDE REPLACE/1X FRT RH MOULDING REPLACE/1X FRT RH DOOR WING MIRROR REPLACE/1X FRT RH DOOR OUTER HANDLE UNCONFIRM/1X FRT RH DOOR INNER TRIM BOARD UNCONFIRM/1X FRT DOOR REPLACE/1X STICKER REPLACE/1X FIRE WALL INSULATOR REPLACE/1X STEERING COLUMN COUPLING REPLACE/1X REAR VIEW MIRROR UNCONFIRM/1X PASSENGER AIR BAG RE PASSENGER AIR BAG SENSOR REPLACE/1X INSTRUMENT CLUSTER UNCONFIRM/1X RH AIR CON DUCT UNCONFIRM/PUSH STRAT BUTTON UNCONFIRM/1X STEERING COLUMN CO

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root					
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	6	Replace
ACTUATOR	5	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm
ADVERTISEMENT STICKER	6	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm
	7	2550	FIREWALL PANEL	1	Replace
	8	454008	WIPER PANEL	1	Replace
	9	45400301	WIPER BLADE (FRONT LEFT)	1	Replace
	10	45400302	WIPER BLADE (FRONT RIGHT)	1	Replace
	11	45400501	WIPER LINK (FRONT)	1	Unconfirm
	12	451020	WINDSCREEN SEALANT	1	Replace
	13	41300101	SUPPORT PANEL (FRONT)	1	Replace
	14	14902201	BONNET HINGE (LEFT)	1	Replace
	15	16003201	BUMPER GRILLE (FRONT)	1	Replace
	16	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
	17	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
	18	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Unconfirm
	19	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm
	20	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm
	21	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm
	22	27100101	GRILLE (FRONT)	1	Replace
	23	15600101	BRACE PANEL (FRONT)	1	Replace
	24	21300102	CORNER PANEL (FRONT RIGHT)	1	Replace
	25	27700101	HEAD LAMP (LEFT)	1	Replace
	26	27700102	HEAD LAMP (RIGHT)	1	Replace
	27	45400101	WIPER ARM (FRONT LEFT)	1	Replace
	28	45400102	WIPER ARM (FRONT RIGHT)	1	Replace
	29	45400601	WIPER MOTOR (FRONT)	1	Unconfirm
	30	454009	WIPER PANEL GARNISH	1	Replace
	31	45101403	WINDSCREEN MOULDING (RIGHT)	1	Replace
	32	245001	ERP BRACKET	1	Replace
	33	245002	ERP UNIT	1	Unconfirm
	34	149001	BONNET	1	Replace
	35	112023	AIR CON CONDENSER	1	Replace
	36	112060	AIR CON FAN	1	Unconfirm
	37	344001	RADIATOR	1	Replace

38	344005	RADIATOR COWLING	1	Unconfirm
39	344008	RADIATOR FAN	1	Unconfirm
40	323001	OIL COOLER	1	Replace
41	338007	POWER STEERING COOLER PIPE	1	Unconfirm
42	14902202	BONNET HINGE (RIGHT)	1	Replace
43	34402802	RADIATOR HOSE (TOP)	1	Replace
44	112053	AIR CON EVAPORATOR	1	Replace
45	112003	AIR CON BLOWER	1	Replace
46	15701602	BRAKE MASTER PUMP (FRONT RIGHT)	1	Unconfirm
47	103002	ACCELERATOR PEDAL	1	Unconfirm
48	106007	AIR BAG CONTROL UNIT	1	Unconfirm
49	36300101	SEAT BELT (FRONT LEFT)	1	Replace
50	270002	GLOVE BOX COVER	1	Unconfirm
51	23303001	DOOR HINGE (BOTTOM) (FRONT LEFT)	1	Replace
52	23303002	DOOR HINGE (BOTTOM) (FRONT RIGHT)	1	Replace
53	23306102	DOOR RUBBER (FRONT RIGHT)	1	Replace
54	356009	ROOF PANEL	1	Replace
55	356006	ROOF LINING	1	Replace
56	4110	SUN VISOR	2	Unconfirm
57	345001	RADIO	1	Unconfirm
58	112068	AIR CON GRILLE	4	Unconfirm
59	268012	GEAR LEVER	1	Unconfirm
60	455001	WIRE HARNESS	1	Unconfirm
61	15700501	BRAKE BOOSTER PUMP (FRONT)	1	Unconfirm
62	15701902	BRAKE PEDAL (FRONT RIGHT)	1	Unconfirm
63	36300102	SEAT BELT (FRONT RIGHT)	1	Replace
64	270003	GLOVE COMPARTMENT	1	Unconfirm
65	23300202	DOOR (FRONT RIGHT)	1	Replace
66	23302002	DOOR GLASS (FRONT RIGHT)	1	Replace
67	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	1	Replace
68	23302502	DOOR GLASS REGULATOR MOTOR (FRONT RIGHT)	1	Unconfirm
69	149016	BONNET EMBLEM	1	Replace
70	45100902	WINDSCREEN INNER PILLAR (FRONT RIGHT)	1	Replace

Save

Submit

Claim Handling

[Task Transfer](#)
[Exit](#)
[Accident MT/1003350](#)
[LOS](#)
[SAL](#)
[SUB](#)

Policy No.	5082050301-01	Vehicle No.	GBE8273B	GST Registration No.	
Policyholder Name	TOADS HANDYMAN			Policyholder NRIC	53339375B
Product Code	COMMERCIAL VEHICLE INSURAF	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

[Accident Details](#)

Report Date	17/07/2018 13:20	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	16/07/2018	Time of Accident hh:mm	15:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	3572675
Accident Location	PJE TWDS TUAS				

[Benefits](#)
[Excess](#)

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

[GST Registered Information](#)

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	18/07/2018 09:57:56 Emily Tan changed GST Status Verified from No to Yes		

[Policyholder Mailing Address](#)

Address 1	BLK 28 #11-681	Address 2	BENDEMEER ROAD	Address 3	BENDEMEER VILLE
Address 4	SINGAPORE 330028	Address Type	Singapore address	Post Code	330028
Unit No.	11-681	Related Policy Number	5082050301-01		

[OI Driver Info](#)

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	YEO POH HWA (YAO BAOHUA)	Driver NRIC	S7412993E	Driver DOB	26/04/1974
Register Date of Driver License	21/10/1994	Driver Age	44	Driving Experience	23
Contact No.(Mobile)	90521385	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 95	Address 2	GEYLANG BAHRU	Address 3	
Address 4		Address Type	Singapore address	Post Code	330095
Unit No.	#02-3134				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

[Declaration](#)

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History	18/07/2018 11:33 s990621 Modify Orange Force(N-->Y) 18/07/2018 11:33 s990621 Modify ICM No(-->3572675)		

[Investigation](#)
[Claim 001 OD-MD](#)
[Claim Case Officer Zuraimee Bin Mantau](#)

Claim Type	OD-MD	Insured Name	TOADS HANDYMAN	Insured NRIC	53339375B
Contact No.(Mobile)	94516574	Contact No.(Home)	NIL	Contact No.(Office)	
Email Address		OI Vehicle Number	GBE8273B	TP Vehicle Number	XE1124J
Claim Description	GBE8273B / XE1124J ON 16 Jul 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Partially at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	17/07/2018 13:32	Claim Close Date		Date Received	18/07/2018
Report Taken By	KRISHNASAMY	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

[Modification History](#)
[Special Claim Creation Approval](#)

Approval Reason

Remarks

damage assessment Activity Handling Attachment

▼

Accident No.	MT/1003350	Claim No.	001			
Last Doc. Received	☒ Yes ☐ No	Upload Date	18/07/2018 13:48			
Path *		Category *	Confidential	Urgency *		
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Choose File	No file chosen	Clear	Please Select ▼	NO ▼	Normal ▼	
Message Read		Clear	Please Select ▼	NO ▼	Normal ▼	

▼ Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:48	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:47	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:46	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:45	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:43	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:42	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:41	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:41	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:41	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:41	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:40	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:39	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 18 Jul 2018 13:38	Photos	Normal	Photos 2018-7-18
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:30	NRIC/ Driving License	Normal	NRIC/ Driving License 2018
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:26	SAS	Normal	SAS 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:26	Photos	Normal	Photos 2018-7-17



Video List

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:26	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:26	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o n 17 Jul 2018 13:25	Photos	Normal	Photos 2018-7-17

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)
51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: _____ Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: modern auto

Collection Date: 24/7/18 Time: 1650 with Keys: Yes / No

Tow Truck No: YM F654C Tow Man: Michael ong NRIC: S7727585A

Signature: [Signature]

97544909

For office use

Attended by: KOSKINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Zuraimie Bin Mantau <zuraimie.mantau@income.com.sg>
Sent: Tuesday, 24 July 2018 11:37 AM
To: Modern Automotive (admin@modernautomotive.com.sg)
Cc: LKK Paya Ubi
Subject: Vehicle GBE8273B, OD Claim No: MT/1003350-001, DOA: 16/07/2018

Dear Modern Automotive

OD Excess \$600 applies.

Vehicle is currently at NAC Paya Ubi.

Please arrange to tow away the vehicle and update Mr Sam at 94516574 on the repair status.

Strictly no further supplementary is allowed. A **survey before repair** is required.

Please forward the invoice and DV within 7 working days to us once repairs has been done and survey. Update the 'Repair Status' when repairs are done.

XX

Our Ref: MT/CA/OD/051/1003350-001/ZBM

24 Jul 2018

MODERN AUTOMOTIVE PTE LTD

BLK 3023A #01-61 UBI ROAD 1

SINGAPORE 408717

Dear Sir

CLAIM NUMBER: MT/1003350-001

REPAIR OF VEHICLE NUMBER: GBE8273B

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 24 Jul 2018

Make: TOYOTA

Model: HIACE

Estimated Repair Days: 21

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimie Bin Mantau at 64307891 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

Thank you

Zuraimee Bin Mantau
Senior Executive, Motor Insurance
T +65 6430 7891
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.