15/5/2010

INS. CASE OWNER: | CC 3 UR ~~/AIG~~1801 2939, F1 j163 | LKK: IDAC:

ASSIGNMENT

Surveyor: Edwin DOI: 16/7/18 Date / Time : 16/7/18

Registered in Merimen: 17/7/18

Pre-assign / CCU / FTE

Insured Vehicle No. : SLG 1505A		Claim No. :	
Name of Insured : UR		Policy No. :	
Insured Tel No. :	HP:	Make / Model :	
Excess Sec II :S$	D.O.A : 15/7/18	Place of Accident :	
Is driver the owner? (YES / NO)	Nature of Accident :		

If **NO**, Driver Name / Age :

Driver Tel No. : (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % **Final ? Yes / No**

GH 8097B → → →

INSRS: cove WSP: Tel : Liability : ly. RMKS:	INSRS: WSP: Tel : Liability : RMKS:	INSRS: WSP: Tel : Liability : RMKS:	INSRS: WSP: Tel : Liability : RMKS:

Date/ Time		
	GH8097B - NR/AIG1800[illegible]/UR DTM: 30/1/18.	
	SLG1505A - X	

STAGE	**DATE / PIC**
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	**Handler**	**Typist**
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$ (days)	Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$	(days)	
Loss of Use (LOU):	S$	($ x days)	
Loss of Income (LOI):	S$	($ x days)	
LOR only ☐	LOU only ☐ LOR + LOU ☐	LOR + LO ☐ **[Tick only one]**	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH 8097B Yr Regn: 11 Ly / 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Sonata c.c 1991

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 571769 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHETK1WMDA835239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size; F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	15/7/13	D.O.I.	16/7/13

Survey held at CDRE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ATG c/s

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
___S + RS, ___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING
member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408849
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305188184

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO.: SH 8097B	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 16.07.2018 08:25
YR OF MANU. 11.07.2013	TARGET DATE
CHASSIS CODE KMHET41VMDA835339	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 15.07.2018
NATURE: 3P 15.07.18

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

No.: SH 8097B JU AIG LKK

f Service Advisor

Signature/Date

eturned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 8097B

Name of Service Advisor

Date

To be kept by Security Guard