

AXA - CP/P

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305188433
 REGN NO : SH 7644D
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 03.10.2017
 DATE/TIME IN : 16.07.2018 09:35
 ACCIDENT DATE : 16.07.2018

1445

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0592-G FRT DOOR RH 1 1,227.00 25.00 920.25

0002 28-01-0103-0003-A Frt Door COMFORTDELGRO RH 1 75.00 ~~250~~ 75.00

SUB-TOTAL : 995.25

JOB NATURE

0000 L PANEL BEATING

~~300.00~~ 200

0001 23-502 SPRAYPAINT ON AFFECTED AREA

~~300.00~~ 200

SUB-TOTAL : 600.00

TOTAL : 1,595.25

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalin 16/7/18
 16/7/18 16:15 hrs.
 2 Dgs
 PIR
 Beton Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: