

Surveys

XGQ

REF: MID

ASSIGNMENT

(-2023)

From: Date: 26062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 320R
at Workshop m/s Complete Vms
of 19 Defu Lane 8

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 9757 2433 - Veerasamy.

(Policy Condition)

2pm
8333 2118 (Damen)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No


Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT



Veh No: XE320R Yr Regn: 25 Jan 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan CWB45 c.c 13074

Colour: yellow A/C: Insured / Std / NI / NA

Sp.Reading: 467170 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / S/Rim / STD A/Rim or

Tyre Size: F: 295/60R 22.5

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CHENG SHAN

Front

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6666/6666mm

L/Bal. 6666/6666mm

D.O.I. 26-06-18

2pm

w/s

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



967170

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
32 JALAN KELULUT
SINGAPORE 809049

Attention : THE OWNER

Contact : 64819588 83518839

Estimate : ES006380

Date : 26/06/2018

Vehicle Num. : XE320R

Make/Model : NISSAN CWB45CLPHNB-2008

Chassis/Eng# : CWB4CLP00098/GE13334373B

Accident Date : 21/06/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO SUPPLY AND INSTALL U-MAD 100K (TMA'S) TRUCK MOUNTED
ATTENUATOR (PASSED NCHRP 350 TEST LEVEL 3) C/W
HYDRAULIC LIFT UP

59,800.00

Labour Total S\$:

59,800.00

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Guo Q: ang - 8288 0282

26/6/18

~~ump~~ repair part by part

SingDollars : Fifty-Nine Thousand Eight Hundred Only

Total S\$: 59,800.00

After repair photos.

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun