

RESTRICTED

## HQ TPT COMMAND

AFPN 1616, KRANJI CAMP 3, 151 CHO A CHU KANG WAY, BLK 822, #01-04, SINGAPORE 688248

Tel: 63074511 Fax: 63074520

### **FAX TRANSMISSION**

<b>FROM</b> <b>SENDER:</b>  CPT Merlin Koh  HQ TPT  TPT SAFETY BRANCH	<b>TO</b> <b>RECIEVER:</b>  Ms Chew Hsiao Tong  LKK Auto Consultants Pte Ltd  Blk 51, Ubi Ave 1, #01/02-25  Paya Ubi Industrial Park  S(408933)
<b>DATE:</b> 24/7/18	<b>NO. OF PAGES INCLUDING THIS</b> <b>PAGE:</b> 04
<b>SUBJECT:</b> Driver Statement & Traffic Police Report for MIO 21799	

Remarks:


Nil

### **WARNING**

This transmission is strictly restricted and is intended solely for the addressee. If you are not the addressee, you must not read, copy, distribute or take any action in reliance thereon. Any communication of any information in this fax to any unauthorised person is an offence under the Official Secret Act (Cap 213). Please notify us immediately if you receive this in error or if this transmission is incomplete.

1  
RESTRICTED

**SINGAPORE ARMED FORCES**  
**STATEMENT OF DRIVER/WITNESS**

STATEMENT OF	SON JING XIAN			ALIASES	
NRIC NO	S9624541P	AGE	21	MALE/FEMALE	MALE
EMPLOYMENT	NSF	DRIVING LICENCE NO	SAF/TPT/A/01587/12	NATIONALITY	SINGAPOREAN
DIALECT		LANGUAGE SPOKEN	ENGLISH	TEL NO	97856968
ADDRESS	BIF 419 HOUGIANG AVE 8 #03-942				
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY		RANK	TIME	DATE	SIGN
<p>I, S9624541P, LCP SON JING XIAN is writing a statement regarding a BFOV (MID 21799) grazing against a construction vehicle, ON 210618. On 210618, I was doing convoy training, going to gedong training area. At BKE going KJE, <del>going</del> entering the link between BKE and KJE there is a long construction vehicle taking the left lane, just after a left turn. After turning the left turn, I saw the <sup>long</sup> vehicle park just after the left and started to brake. I started looking at my right mirror to start changing lane. I let a few vehicle go and inched out when the traffic is clear. While changing lane I heard a <u>scree</u> <u>grazing</u> sound and started to check both my mirrors and saw that my vehicle is not in contact with any vehicle. After I reached my destination, I <del>at</del> check for any damage and saw scratches at the B11 compartment. When I did my BOC <sup>check the convoy</sup> I saw there is minor scratches at the B11 compartment. I did not report <sup>the</sup> damages as I was afraid of my mileage and my license. I was also unsure the damages that I cause. This is all I have to say.</p>					
DATE	260618		SIGNATURE OF DRIVER/ WITNESS		

SAF 1201/01

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.  
Statements of witness must be signed by the witness.





# **SINGAPORE POLICE FORCE**



F/20180628/2061

1 of 2

## **POLICE REPORT (NP299)**

Report No. F/20180628/2061

Police Station Of Origin  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE 757633  
Tel No: 1800-5549999

Date/Time Report Made 28/06/2018 12:10		Vide Report No.		Station Diary No. 48	
Name Of Informant SOH JING XIANG		Address APT BLK 419 HOUGANG AVENUE 8 #03-942 SINGAPORE 530419			
ID Type / ID No. NRIC NO / S9624541F		Contact No. Home/Office Mobile 97856968			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation NSF		Sex Male	Age 21	Date of Birth 13/07/1996	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 21/06/2018 11:10		Location Of Incident KRANJI EXPRESSWAY SINGAPORE On Gali Batu flyover			

### **Brief details.**

On the above mentioned date, time and location, I was driving SAF military vehicle bearing license plate number: MID21799 (6TON) from Sembawang Camp to Sungei Gedong Camp as part of Convoy Movement training for Charlie GTC. I was part of a 6 vehicle convoy and my vehicle was the 2nd vehicle of the convoy. I had no vehicle commander with me at that point of time. There were no passengers with me during the accident.

Signature Of Officer Recording The Report: F / Sgt 2 LIM AI LING, IVY	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 28/06/2018 12:10
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Sgt 2 VIJAYAN NAIR RAMADHASAN Contact No.:	Classification Of Case:

Authentication Stamp





**SINGAPORE  
POLICE FORCE**

POLICE REPORT (NP299)

CONTINUATION OF REPORT



F/20180628/2061

2 of 2

Report No. F/20180628/2061

While I was driving along Gali Batu flyover, I was travelling on lane 2 of the expressway and a civilian trailer (V2) bearing license plate number: XE320R, was parked stationary on the left road shoulder as there was construction works going on. I noticed V2 was outside of the left road shoulder and was obstructing the 2nd lane which I was on. There was also no cones or warning signs to inform drivers of the road works going on. When I was nearing V2, I slowed down and checked my side mirrors. Subsequently I signaled right to avoid V2. After I signaled right, vehicles gave way to allow me to move into lane 1. As I passed V2, I heard a grazing sound on the left of my vehicle but I did not stop my vehicle at that point of time to ascertain the damage as I checked my side mirrors but did not see any visible damages nor was my vehicle near to V2.

After the video from IVC was reviewed, it was shown that my vehicle had indeed come into contact with V2. However, during the time of the accident, there was heavy traffic and my convoy was broken up. The convoy operating MID21756 (6TON) did not see the incident occur. When I reached Sungei Gedong Camp, I made a check on the left side of my vehicle. That was when I saw that there were scratches. I am not very certain if the scratches were due to the accident. I was informed that there was a tear on the spare tyre netting, scratches on the BII compartment box and LHR wheel hub and rim was also grazed.

I am lodging this report for GIA action.

Signature Of Officer Recording The Report: F / Sgt 2 LIM AI LING, IVY	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/08/2018 12:10
Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Sgt 2 VIJAYAN NAIR RAMADHASAN Contact No.:	Classification Of Case:
Authentication Stamp	

