

Surveyor

Meriv

REF: ASM (AXA)

ASSIGNMENT

From:

Date:

18/07/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLD 1629S

at Workshop m/s

1st Auto works

of

23 Kaki Bukit Ave 11 #04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Renault

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

7812

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

47A 50046

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 1629S

Yr Regn:

6 / 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

OPEL meriva

C.C

1364

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

46733

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WOLSH9EM3A4038079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/7/18

D.O.I.

18/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

74/5 11m. rep 8800

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)