

(55020)

INS. CASE OWNER:

Jas

CCU ASM
AXA1801

2968, F2ub3/

LKK:
IDAC

Surveyor:

Fatin

DOI:

ASSIGNMENT

12/3/18

Date / Time:

A/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 8895m - virtual

Claim No.:

S8M000Lm/5802

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : \$

D.O.A.:

14/3/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 711X

INSRS:
WSP:
Tel:
Liability:
RMKS:CPGE
WINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(\$

(days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$250.00

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

108/11/13

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 711X Yr Regn: 24/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Huan Lu South C.C. 1.8LColour: Yellow A/C: Insured / Std / Nil / NASp. Reading: 230512 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHET41ABA 81517X

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD Alloy or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wan Ula

Front

Rear

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 14/2/12 D.O.I. 17/2/12Survey held at CHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s B/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

	<u>U/S 25 (Red # 1679.36 / 87%)</u>	<u>AXA</u>
		<u>4</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

AXA

POA: 14.07.18

REPAIR ESTIMATE*

VEHICLE NO: SHC 711X

MAKE: HYUNDAI

MODEL: SONATA

Date: 16.07.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Door - LH <i>x repair</i>			\$ 1,294.70
1	Rear Door Protector - LH <i>x repair</i>			\$ 54.50
SUB TOTAL				\$ 1,349.20
LESS 20%				269.84
DISCOUNTED TOTAL				\$ 1,079.36
1	Rear Door Tel Sticker <i>me</i>			\$ 10.00
				Nett
				\$ 10.00
Labour Charge				
Panel Beating				\$ 250.00 ¹⁰⁰
Spray Painting Charge				\$ 250.00 ²⁰⁰
Transfer of Door				\$ 180.00 ^{??}
Wiring Charge				\$ 80.00 ^{??}
Tuff Kote				\$ 80.00 ^{??}
TOTAL LABOUR				\$ 840.00
ESTIMATE TOTAL				\$ 1,929.36

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before after spray painting
- To display damaged vehicle during resurvey
- Parts problem is not a direct cost

- This estimate is not a 'Guarantee' but a 'Provisional' estimate
- No warranty is given on the estimate
- Surveys only need to be surveyed and is subject to the approval from insurance Company

Acknowledged by Repaired

Signature:

Date:

Kalin 10/11/14

17/7/18 1120L

2/8/18

4/8

After Repair photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

AXA

REPAIR ESTIMATE*

VEHICLE NO : SHC 711X

MAKE : HYUNDAI

MODEL : SONATA

Date : 16.07.2018

POA : 14.07.18

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Door - LH <i>x repair</i>			\$ 1,294.70
1	Rear Door Protector - LH <i>x repair</i>			\$ 54.50
SUB TOTAL				\$ 1,349.20
LESS 20%				269.84
DISCOUNTED TOTAL				\$ 1,079.36
1	Rear Door Tel Sticker			\$ 10.00
				Nett
				\$ 10.00
Labour Charge				
Panel Beating				\$ 250.00
Spray Painting Charge				\$ 250.00
Transfer of Door				\$ 180.00
Wiring Charge				\$ 80.00
Tuff Kote				\$ 80.00
TOTAL LABOUR				\$ 840.00
ESTIMATE TOTAL				\$ 1,929.36

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve telephone access during
- To display damaged goods during security
- Parts prices are subject to change without notice
- Third party liability is not covered by this estimate
- No legal proceedings can be brought against LKK Auto Consultants
- Supplementary work may be required and is subject to final inspection and approval by the insurance company

Kalin 10/11/14

17/7/18 1120h

2/8/18

4/5

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305188147

Date : 18. Jul. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHC 711X

Date of Accident: 14. Jul. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA SLX8895M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$250.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LKK

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : KALVIN

Date : 18/7/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Final Amount Subject to Insurance Approval

<< Service Request Details

Claim

S8M00OLM

Reference

None 

Loss Date

July 14, 2018

Request Date

July 17, 2018

Due Date

July 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*Kalvin
'Virtual'*

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SHC711X

Make

TPVD HYUNDAI

Model

SONATA

• Service Address

Primary Contact/Insured

SEE CHERN LIANG LEONEL
BLK 315A YISHUN AVENUE 9, #13-216, 761315, Singapore

JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

virtual acc CDGE Please do not finalise repair

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

7/17/18 10:30 AM

FROM

TAN Jas

SUBJECT

non reporting

BODY

hi, insured not yet report. we will be sending the...



SEE CHERN LIANG LEONEL

Address

BLK 315A YISHUN AVENUE 9, #13-216, 761315,
Singapore

Home Phone

63380083 (primary)

Work Phone

Cell Phone

(primary)

Email

JEUNESSE@VIRTUALINVEST.BIZ

Close



Service Request Details

Claim

S8M00OLM

Reference

CC4/ASM18012968/K1ub3 

Loss Date

14 July 2018

Report Date

16 Jul 2018 3:49:00 PM

Request Date

17 July 2018

Due Date

17 July 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More ▾

Vehicle Information

Make
TPVD HYUNDAI

Model
SONATA

Service Address

...

Primary Contact/Insured

SEE CHERN LIANG LEONEL
BLK 315A YISHUN AVENUE 9, #13-216, 761315, Singapore

JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions
virtual acc CDGE Please do not finalise repair

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE	<div>?</div>
SENT	5/7/19 11:37 AM
FROM	LKK AUTO CONSULTANTS PTE LTD (TP)
SUBJECT	RE: Re:nr
BODY	Hi Jas, as spoken, We await your further instructi...

https://vp.smartclaims.axa.com.sg/claim-portal/html/index-vendor-service-requests.html#/service-requests/?serviceRequestNumber=58012

TYPE 

SENT 6/5/19 9:44 AM

FROM LOW Garnet

SUBJECT 2nd reminder

BODY Hi, Please follow up. Thank you



TYPE 

SENT 21/2/19 10:59 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Re:nr

BODY Hi Jas, we have uploaded a copy of video from thir...



TYPE 

SENT 24/1/19 4:33 PM

FROM TAN Jas

SUBJECT Re:nr

BODY Hi, please update the video footage. thanks.



SENT 15/1/19 10:33 AM

FROM TAN Jas

SUBJECT Re:nr

BODY Please update on the footage. thanks.



TYPE ?

SENT 10/12/18 11:21 AM

FROM TAN Jas

SUBJECT nr

BODY Hi, please obtain video footage from TP. insured i...



TYPE ?

SENT 27/7/18 3:10 PM

FROM TAN Jas

SUBJECT NR

BODY hi insured has not report the accident. In the asp...



TYPE ?

FROM IAN Jas

SUBJECT photos

BODY hi, please upload inspection photos.



TYPE 

SENT 17/7/18 10:30 AM

FROM TAN Jas

SUBJECT non reporting

BODY hi, insured not yet report. we will be sending the...



Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 27 August 2019 9:21 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 58012, vehicle number SHC711X

<input type="checkbox"/>	**VIRTUAL ACCOUNT**	CHT	5/7/2019 11:25:53 AM
<input type="checkbox"/>	Called Jas Tan. She had sent NR reminder to Ol. Wait for her instruction	CHT	5/7/2019 11:26:11 AM
<input type="checkbox"/>	Message Hi, kindly advise if Ol had reported and whether we can proceed DS. Thank you. Hsiao Tong - 26 Aug 2019	CHT	26/8/2019 11:31:58 AM
<input type="checkbox"/>	8/26/19 2:00 PM TAN Jas-----hi, we have repudiated liab. please inform TP and close your file. thanks .	LSP	27/8/2019 9:08:09 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 26 August 2019 2:03 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 58012, vehicle number SHC711X

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue
1, #02-25 | S(408933)

-----Original Message-----

From: jas.tan@axa.com.sg <jas.tan@axa.com.sg>
Sent: Monday, 26 August, 2019 2:01 PM
To: admin-d@lkkauto.com
Subject: New message for service request 58012, vehicle number SHC711X

AXA Insurance has sent you a message for claim number S8M000LM.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 27 August 2019 4:55 PM
To: 'williamtan@cdge.com.sg'; 'catherinekoh@cdge.com.sg'
Subject: Your Ref: CC18070401/ SHC 711X/ WT(st) *Our Ref: CC4/ASM18012968/K1pb3
[ACCIDENT INVOLVING SLX 8895M(AXA) & SHC 711X ON 14/07/2018]

Your Ref: **CC18070401/ SHC 711X/ WT(st)**
Our Ref: CC4/ASM18012968/K1pb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLX 8895M(AXA) & SHC 711X ON 14/07/2018

We refer to the above matter.

Please be informed that our principal M/s AXA Insurance Pte Ltd had repudiated the claims in view of our insured has breach of policy terms and conditions.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref : CC18070401/ SHC 711X /WT(st)

Your Ref :

Date : 23-Jul-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 8280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 19800898W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
363 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 608286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC 711X YOUR INSURED SLX8895M
AND OTHER ON 14.07.18**

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No : **SHC 711X** which was involved in the captioned accident with your insured vehicle.

The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SLX8895M** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	267.50
2	5 days Loss of Rental @ \$ 109.14 per day	\$	545.70
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing Fees	\$	-
Sub Total :		\$	820.69

HIRER'S CLAIM

7	5 days Loss of Income @ \$ 80.00 per days	\$	400.00
Total Claims :		\$	1,220.69

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 4 pcs.
b) LTA search slip/s of : **SLX8895M**
c) GIA / Police report/s of : **SHC 711X**
d) Letter of authority from owner / hirer / operator

- (X) Photocopies of Accident Scene Photo/s () Certificate of Insurance
() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax : 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Our Ref: CC18070401



Date: 19 July 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 14/07/2018 @ 13:30 hrs
ALONG SERANGOON NORTH AVE 1 BLK 153 OPEN
CARPARK
INVOLVING SLX8895M

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC0711X** (the "Taxi"). The Taxi was hired to **ZHUO SHAORONG IC NO S8230339A** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$109.14** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

$\times 112.545$

[illegible]

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONG

SONATA SHC711X , SLX8895M

ON 14-Jul-18 13:30

SERANGOON NORTH AVE 1 BLK 153 OPEN CARPARK

I / We

ZHUO SHAORONG

(Hirer) NRIC No.: S8230339A

and/or

ZHUO SHAORONG

(Relief) NRIC No.: S8230339A

Taxi Number

SHC711X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

15-Jul-2018

Name of Hirer

ZHUO SHAORONG

Hirer NRIC

S8230339A

Signature :



Address

680 WOODLAND AVENUE 6 #02-760
730680

Contact No.

97106111

Name of Relief

ZHUO SHAORONG

Relief NRIC

S8230339A

Signature :



Address

680 WOODLANDS AVE 6 #02-760
730680

Contact No.

97106111

Enquire Vehicle Insurer *

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLX8895M	14 Jul 2018 / 13:30:00	Successful	A12	AXA INSURANCE PTE LTD

[Previous](#)[OK](#)

SUC711X

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012968/K1pb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS		Date : 03-09-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLX 8895M	Veh. Inspected	SHC 711X
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00OLM	Excess (\$)	0.00
Assign From		Assign Date	17/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMB815174	Colour	YELLOW
Odometer	230512	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/07/2018	Inspection Date	17/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 711X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR-LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,294.70	-
1	REAR DOOR PROTECTOR -LH (CONSISTENT)	TO REPAIR SEE LABOUR	54.50	-
	LESS 20% DISCOUNT		-269.84	-
			1,079.36	-
	<u>SPECIAL NETT ITEMS</u>			
1	REARDOOR TEL STICKER (SN) (CONSISTENT)	NECESSARY	10.00	10.00
			10.00	10.00
	<u>LABOUR</u>			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR DOOR -LH AND REAR DOOR PROTECTOR -LH.		250.00	100.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	TRANSFER OF DOOR.	NOT NECESSARY	180.00	-
	WIRING CHARGE.	NOT NECESSARY	80.00	-
	TUFF KOTE.	NOT NECESSARY	80.00	-
			840.00	300.00
	GRAND TOTAL		1,929.36	310.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			250.00

Report Ref No. CC4/ASM18012968/K1pb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim

50M4000L4M

Reference

CCM/ASM18012946/K146342

Loss Date

14 July 2018

Report Date

16 Jul 2018 3:49:00 PM

Request Date

17 July 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

94C711X

Make

TPVD HYUNDAI

Model

SONATA

Service Address

...

Primary Contact/Insured

SEE CHERN LIANG LEONEL
BLK 315A YISHUN AVENUE 9, #13-216, 761315, Singapore
JEUNESE@VIRTUALINVEST.BIZ

Claim Handler

TAN Jai
6568804844
jai.tan@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

virtual acc CDGE Please do not finalise repair

Messages

Invoices

History





Documents

Assessment

Metrics

Notes

Document Type	Document SubType																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
---------------	------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKKAdjustment1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 Email to TP of 270819.pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	27 August 2019
 SHC711X dos 14718 - TP VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	21 February 2019
 Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 July 2018
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 July 2018
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 July 2018
 TP ESTIMATE- MAINE D.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2018
 TP CDGE-PRI RECEIVED WORKSHOP GIA & EST.mpg	Letters and Correspondence	Workshop	DHAKAL Raghu	16 July 2018