

ASS. REC. BY:

REF

CS/MSG18012974/G-103⁵²

Special Instruction:

Surveyor
Menimen

From (Person):

Glu Henry
Vimma la

ASSIGNMENT (Office)

of

MSG

Date/Time:

17/7/18 @ 2:05pm

Estimated Cost:

Bill to:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

98531969

To Inspect Vehicle No:

SJN 8820E

Insured:

at Workshop m/s

Vertex Automobile

Tel:

9489 7901 / 6742 9368

of

No. 3, Ubi Rd 4

Policy No:

27454618DMA

Claim No:

564528

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

(Client's Record)

11/07/2018

CA / ☒ REV / REP. / REV 24 HRS

18/07/2018

H.O.D. Endorsement:

Date/Time:

2:19pm @ 17/7/18

Person Contacted:

Chris

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

19/7

SJN 8820E - X

Revert via menimen

25/7

Approval on US \$2200 including Supp & check item

25/7 @ 9:06am

email to chris all in \$2200 inclusive supplementary and check item

25/7 @

email to chris authorize accordingly

(08/1/13) waf
ASS. REC. BY:

REF: MSIG

34621

ASSIGNMENT

From: Date: 18/7/18

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SIN 8820E
at Workshop m/s: Vertex Automobile
of No. 3 ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh: Chris
674293868

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$7000 7200

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SIN 8820E Yr Regn: 03 Mar 2009

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: chery A1 1.3 C.C. 1297

Colour: orange A/C: Insured / Std / NI / NA

Sp. Reading: 47413 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LUV0B12B08D 167534

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / ☒ Rim or

Tyre Size: F: 185/ 60 R14

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 18-07-18

Survey held at w/s 2:30pm

Des. of Damages: ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/7 limit \$3500. wait for chris call back
offer \$3000 to chris.

2200/- (AU in) (Red: 688260 175%)

[Signature]
8/8/2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 8/8 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format : OD

Lump Sum / I.B.I. (\$) 2200/-

150
10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18012974/Gtd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 17-07-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJN 8820E
Policy No.	27454618DMA	Coverage (\$)	0.00
Claim No.	564528	Excess (\$)	500.00
Assign From	MERIMEN (VIMMALA)	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/07/2018	Inspection Date	
Survey held at	VERTEX AUTOMOBILE PL 3 UBI ROAD 4 SINGAPORE 408608		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2018		17 Jul 2018 14:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: WANG YONG KANG , ID: S2643462I, Tel: +6591682153	
Vehicle Reg. No.: SJN8820E	Date of Loss: 11/07/2018 10:00 - :59 [112 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 564528	Policy/Cover Note No.: 27454618DMA (Comprehensive) Coverage: 03/03/2018 - 02/03/2019
	Excess: S\$500.00
Repairer: Vertex Automobile Pte Ltd (HQ) No 3, Ubi Road 4, 408608 Ubi - Tel: 94897901	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/07/2018]	
Driver/Custodian: ZHANG JINGMEI (47 / Female), NRIC: S7175134A, Tel: +6591682153	
Adj Asg. Remarks: To survey by end of today. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert and arrange for survey by today. We received the estimate repair bill via fax yesterday at 10.56am but staff who collect the fax yesterday put together with the mails today. Surveyor, please check the market value and rebates if the vehicle is economical to repair. Manufacturing year :2008. Please call Chris from Vertex Automobile at 67429368 to arrange for the survey appointment and also inform the repairer to file an addendum to change from reporting only to own damage claim.	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SJN8820E (564528)**

OD

Jul 11 2018 10:00AM

[WANG YONG KANG]

Vertex Automobile Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 25/07/2018 08:45 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2200.00) - SJN8820E - Claim Handler: Vimmala D/O Raja Singam

Approved:2200.00:lumpsum repair at \$2.2k including supp parts and check items and before \$500 excess.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 25 July 2018 9:06 AM
To: 'sa1@vertex.sg'
Subject: RE: SJN 8820E / OD / MSIG

Dear Chris,

As instructed by our client, please proceed to repair the insured vehicle **SJN 8820E (Excess \$500/-). ALL IN AT \$2200 INCLUSIVE SUPPLEMENTARY& CHECK ITEMS.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Monday, 23 July 2018 4:21 PM
To: 'sa1@vertex.sg' <sa1@vertex.sg>
Subject: RE: SJN 8820E / OD / MSIG

Dear Chris,

I've check with MSIG office, Please check if owner is willing to top up the different.

Eg. MSIG will pay \$2,200 and the owner will top up the balance \$1000/- + excess \$500/-.

Please check with owner and get back to us.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SJN8820E (564528)**

OD

Jul 11 2018 10:00AM

[WANG YONG KANG]

Vertex Automobile Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 23/07/2018 14:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Revoked - SJN8820E - Claim Handler: Vimmala D/O Raja Singam

Revoked: We are unable to justify lumpsum repair at \$3,200.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SJN8820E (564528)**

OD

Jul 11 2018 10:00AM

[WANG YONG KANG]

Vertex Automobile Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/07/2018 16:38 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$2200.00) - SJN8820E - Claim Handler: Vimmala D/O Raja Singam

Approved:2200.00:lumpsum repair including check items and supp parts and before excess.

Sai@vertex.sg

DOCUMENTS SUMMARY

There are no documents.

PCV Accident Report

(For Reporting only)



☐ Braddell ☐ Sin Ming ☐ Sg. Kadut ☐ Pandan ☐ Loyang ☒ Ubi

2

Section A - To Be Completed By Driver Who Is Involved in The Accident

Date & Time of Accident: Date: 11/7/18 10:00pm Time: 1000
 Date & Time of Reporting: Date: 12/7/18 1420 Time: 1420
 Place of Accident: Bukit Batok East Ave 6
 Vehicle Reg. No.: JN8820E Make / Model: A5 A1 cherry
 Purpose of Use at Time of Accident: Goods transportation (private usage) / Others:
 Name: ZHANG JING MEI NRIC / FIN No. 87175134A
 Address: Bukit Batok Street 21 Block 201 #04-156
 Postcode: 650201 Date Of Birth: 28/01/1971
 Home: 65651552 Handphone: 91682153
 Email: kelly197128@live.com Gender: Male / Female
 Occupation: Management / Sales / Retiree / Housewife / Technical / Education / Others:
 Type of Claims: Third Party / Own Damage / Reporting Only
 Driver Status: Owner / Non-owner Years of Driving Experience: 8
 Licence Pass Date: 30/08/2008

If you are not the owner, the owner's name & tel: WANG YONG KANG
 Owner's Address: Bukit Batok Street 21 Block 201 #04-156
 Relationship with Owner: SPOUSE Owner's NRIC / Company Reg. No: S26434021

Vehicle Towed In? Yes / No My Insurance Company: MSI G
 Police Reported? Yes / No Police Report Reference No.:
 Company's Vehicle? Yes / No Insurance Policy No.:
 Do you have witness? Yes / No Type of Policy: Comprehensive / Third Party Fire & Theft / Third Party Only

(If Yes, Witness Name & Contact No.: 2 WANG XI LIN ANNIE

Weather Condition: Clear / Cloudy / Light Rains / Heavy Rains
 Road Condition: Dry / Wet Was anyone injured in the accident? Yes / No
 Other vehicle or property damage? Yes / No Was Notice of Intended Prosecution given? Yes / No

Describe How Accident Happened: Please use **SKETCH PLAN** for accident description & sketch of accident scene

Third Party's Details (Use Annex 2 for Chain Collision as attachment)

Vehicle Make / Model: Honda Civic Vehicle Reg. No: EN7899U
 Name of Driver: TAN WEI LONG NRIC No: S9047395F
 Insurance Company: Tokyo Marine Handphone: 91262699

Driver's Declaration: I declare that the information given in this report are true and correct and I undertake to assume full responsibilities for all consequences should any part given above be untrue.


Signature:

[Signature]

Date:

12.07.2018

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car is going straight. Car B turning right. Both car collides. Traffic light turning red, we were unable to stop and hit the car which is going right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	34621
Vehicle Details	
Vehicle No.:	SJN8820E
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	CHERY
Vehicle Model:	A1 1.3 MT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Gold
Manufacturing Year:	2008
Engine No.:	SQR473FFF8E01817
Chassis No.:	LVVDB12B08D167534
Maximum Power Output:	61.0 kW (81 bhp)
Open Market Value:	\$6,591.00
Original Registration Date:	03 Mar 2009
First Registration Date:	03 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$6,591.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2019
PARF Rebate Amount:	\$3,295.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,460.00
COE Rebate Amount:	\$274.00
Total Rebate Amount:	\$3,569.00

The information contained herein is correct as at 19 Jul 2018

OK

▶ Chery A1 Used Vehicle List (2 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
Chery A1 1.3M	\$18,800	\$6,770 /yr	11-Nov-2010	1,297 cc	-	Classic Credit Pte Ltd	Available

A1 Is Available With A 1.3 Litre Engine. Only \$1,880 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate In Town. Flexible Loan / High Trade In Are Available. Package With Unrival...

Office No. - 68412076 / 68481203 / 68410680 / 68417082 / 68414849

Ram - 87505747 | Roland - 97479331 | Mr Chen - 90044461

Chery A1 1.3M	\$7,800	\$7,240 /yr	23-Feb-2009	1,297 cc	101,000 km	Esprit Motor Trading	Available
---------------	---------	-------------	-------------	----------	------------	----------------------	-----------

Office No. - 64568623

Francis Goh - 96608623

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand: carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.

Vertex Automobile Pte Ltd

3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
GST:200605693R RCB NO:200605693R

QUOTATION

M/S : ZHANG JINGMEI

BLK 201 BUKIT BATOK STREET 21 #04-156
SINGAPORE 650201

NO: WQT0600416

DATE: 14 Jul 2018

A/C CODE: Z0024

YOUR REF: SJN8820E

VEH REG NO: SJN8820E

MAKE/MODEL: CHERY A1 1.3MT

ATTN: MS. MALA H/P: 62257402

DEL. MODE: LOCAL

SALESMAN: TAN TECK KHENG

PAGE:1

Description	Quantity	Unit Price	%	Amount
		SS		SS
BUMPER FRT EX-STOCK / PIS	1 PC	480.00 ✓		480.00
FOG LAMP - FR LH EX-STOCK / PIS.	1 PC	175.00 ✓		175.00
HEAD LAMP -FR LH EX-STOCK / CAA NN	1 PCS	475.00 X		475.00
HEAD LAMP -FR RH EX-STOCK / PR.	1 PCS	475.00 ✓		475.00
BUMPER REINF FRT EX-STOCK / BT.	1 PC	290.00 ✓		290.00
BUMPER REINF SPONGE FRT EX-STOCK X CAA NN	1 PC	80.00		80.00
WATER TANK SUPPORT PANEL NOT-STOCK X BT NN	1 PCS	125.00		125.00
RAD GRILLE UPPER NOT-STOCK X BT NN	1 PC	20.00		20.00
FENDER LH EX-STOCK / P. par X	1 PC	300.00		300.00 X
FENDER SHIELD FRT LH EX-STOCK X BT NN	1 PCS	40.00		40.00
BONNET FRT EX-STOCK X CAA NN	1 PC	1,330.00		1,330.00
BONNET LOCK-LWR EX-STOCK X BT NN	1 PCS	10.00		10.00
RADIATOR NOT-STOCK X NN	1 PCS	265.00		265.00 ?
CONDENSER EX-STOCK X BT NN	1 PCS	470.00		470.00
RAD FAN EX-STOCK X NN	1 PCS	380.00		380.00 ?
H/LAMP BKT LH NOT-STOCK X BT NN	1 PCS	95.00		95.00
AIR FILTER BOX EX-STOCK X CAA NN	1 PC	95.00		95.00
DRYER EX-STOCK X REC.	1 PCS	95.00		95.00
RAD SUPPORT PANEL LH NOT-STOCK X BT NN	1 PCS	55.00		55.00
BUMPER SPOILER NOT-STOCK X BT NN	1 UNIT	300.00		300.00
CLIP- BUMPER SPOILER / not X NN REC.	20 UNIT ✓	1.20 ✓		24.00
CLIP-FENDER SHIELD X NN REC.	6 UNIT	0.60		3.60
NUMBER PLATE X CAA	1 UNIT	80.00		80.00
COOLANT- IL X NN	1 UNIT	55.00		55.00
AIR-CON GAS X X NN	1 UNIT	65.00		65.00
LABOUR TO CHECK WIRING,LIGHTING SYSTEM FOR PROPER FUNCTION	1 UNIT	120.00		120.00
LABOUR TO DISMANTLE AND REPLACE ABOVE DAMAGE PARTS TO NEW	1 UNIT	480.00		480.00

NN 4837.6

60

NN

Vertex Automobile Pte Ltd

3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
GST:200605693R RCB NO:200605693R

QUOTATION

M/S: ZHANG JINGMEI

NO: WQT0600416
DATE: 14 Jul 2018

PAGE:2

Description	Quantity	Unit Price	%	Amount
		SS		SS
LABOUR TO PANEL BEATING & RE-ALIGN,KNOCK OUT DENTS,STRAIGHTEN & RE-ALIGN ALL AFFECTED PARTS	480 1 UNIT	750.00	720	750.00
LABOUR TO SPRAY PAINTING FRONT BUMPER,FRONT LHS FENDER,LHS MIRROR COVER,FRONT AND REAR LHS DOOR ASSY & FRONT INNER BODY AFFECTED AREAS	350 1 UNIT	1,950.00	1750	1,950.00

Total S\$ 9,082.60
Add GST @ 7% 635.78
Grand Total S\$ 9,718.38

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SEVEN HUNDRED EIGHTEEN AND CENTS THIRTY EIGHT ONLY

CHERY A1-LVVDB12B08D167534

ZHANG JINGMEI

For Vertex Automobile Pte Ltd

AUTHORISED SIGNATURE

CONFIRMED & ACCEPTED BY

5 Days.
part by part.
before paint photos.
Excess \$500
Not Authorised.
Guo Qiang - 82880282
18/7/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vertex Automobile Pte Ltd

GST:200605693R RCB NO:200605693R
3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

TAX INVOICE NO:

WS0650655

Owner's Information		Service Advisor :	Job Card No :
A/C: M0056		CHISTOPHER DASS	JB112539
MSIG INSURANCE		ANTHONIDAS	
(SINGAPORE) PTE LTD	Registration No. :	Make/Model :	Date of Invoice :
4 SHENTON WAY #21-01 SGX	SJN8820E	CHERY A1 1.3MT	31/07/2018
CENTRE 2 SINGAPORE 068807	Mileage (km):	Next Mileage(km):	Next Service Date
	47413		Date In : Time In :
			13/07/2018 9:02 AM
	Chassis No. :	Engine No. :	Promised Date/Time :
	LVVDB12B08D167534	SQR473FFF8E01817	20/07/2018 5:00:00 PM

Service Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
CLIP - PLASTIC	20 PCS	1.20	24.00 ✓
HEAD LAMP ASSY-FR LH	1 PCS	475.00	475.00 ✓
SCREW SEAT - PLASTIC (1A7) / ABC.	4 PCS	0.60	2.40 ✓
BUMPER FRT	1 UNIT	480.00	480.00 ✓
F/LAMP LH	1 UNIT	175.00	175.00 ✓
BUMPER REINF FRT	1 UNIT	290.00	290.00 ✓
LABOUR TO CHECK WIRING. LIGHTING SYSTEM FOR PROPER FUNCTION	1 UNIT	60.00	60.00 ✓
LABOUR TO DISMANTLE AND REPLACE ABOVE DAMAGE PARTS TO NEW	1 UNIT	180.00	180.00 ✓
LABOUR TO PANEL BEATING & RE-ALIGN,KNOCK OUT DENTS,STRAIGHTEN & RE-ALIGN ALL AFFECTED PARTS	1 UNIT	240.00	240.00 ✓
LABOUR TO SPARY PAINTING FRONT BUMPER	1 UNIT	273.60	273.60 ✓
EXCESS FEE	1 UNIT	-500.00	-500.00 ✓

Vertex Automobile Pte Ltd

GST:200605693R RCB NO:200605693R
3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281

TAX INVOICE NO:

WS0650655

TOTAL	SS 1,700.00
ADD GST @ 7%	119.00
GRAND TOTAL	<u>SS 1,819.00</u>

SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED NINETEEN ONLY

Remark: 1.)ACCIDENT REPAIR.-OWN DAMAGE CLAIM.

Customer's Signature/Co. Stamp

E. & O. E.

Service Advisor's Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2018		17 Jul 2018 14:05 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS	[Created by insurer]
Insured: WANG YONG KANG , ID: S2643462I, Tel: +6591682153	
Vehicle Reg. No.: SJN8820E	Date of Loss: 11/07/2018 10:00 - :59 [112 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 564528	Policy/Cover Note No.: 27454618DMA (Comprehensive) Coverage: 03/03/2018 - 02/03/2019
	Excess: S\$500.00
Repairer: Vertex Automobile Pte Ltd (HQ) No 3, Ubi Road 4, 408608 Ubi - Tel: 94897901	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/08/2018]	
Driver/Custodian: ZHANG JINGMEI (47 / Female) , NRIC: S7175134A, Tel: +6591682153	
Adj Asg. Remarks:	To survey by end of today. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert and arrange for survey by today. We received the estimate repair bill via fax yesterday at 10.56am but staff who collect the fax yesterday put together with the mails today. Surveyor, please check the market value and rebates if the vehicle is economical to repair. Manufacturing year :2008. Please call Chris from Vertex Automobile at 67429368 to arrange for the survey appointment and also inform the repairer to file an addendum to change from reporting only to own damage claim.

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
- MSIG_SG (25/07/2018): Alert - Adj Mandate Approved (S\$2200.00) - SJN8820E - Claim Handler: Vimmala D/O... - MSIG_SG (23/07/2018): Alert - Adj Mandate Revoked - SJN8820E - Claim Handler: Vimmala D/O Raja Singam - MSIG_SG (19/07/2018): Alert - Adj Mandate Approved (S\$2200.00) - SJN8820E - Claim Handler: Vimmala D/O...	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

Claim Documents

***SJN8820E (564528)**
OD
Jul 11 2018 10:00AM
[WANG YONG KANG]
Vertex Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 14:48	Adjuster Immediate Advice	 Load HTM	☐
2	20/07/18 13:16	Adjuster Immediate Advice	 Load HTM	☐
3	25/07/18 08:37	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 14:56	General View	 Load JPG ☒	☒
2	19/07/18 14:56	General View	 Load JPG ☒	☒
3	19/07/18 14:56	General View	 Load JPG ☒	☒
4	19/07/18 14:56	General View	 Load JPG ☒	☒
5	19/07/18 14:56	General View	 Load JPG ☒	☒
6	19/07/18 14:56	General View	 Load JPG ☒	☒
7	19/07/18 14:56	General View	 Load JPG ☒	☒
8	19/07/18 14:56	General View	 Load JPG ☒	☒
9	19/07/18 14:56	General View	 Load JPG ☒	☒
10	19/07/18 14:56	General View	 Load JPG ☒	☒
11	19/07/18 14:56	General View	 Load JPG ☒	☒
12	19/07/18 14:56	General View	 Load JPG ☒	☒
13	19/07/18 14:56	General View	 Load JPG ☒	☒
14	19/07/18 14:56	General View	 Load JPG ☒	☒
15	19/07/18 14:56	General View	 Load JPG ☒	☒
16	19/07/18 14:56	General View	 Load JPG ☒	☒
17	19/07/18 14:56	General View	 Load JPG ☒	☒
18	19/07/18 14:56	General View	 Load JPG ☒	☒
19	19/07/18 14:56	General View	 Load JPG ☒	☒
20	19/07/18 14:56	General View	 Load JPG ☒	☒
21	19/07/18 14:56	General View	 Load JPG ☒	☒
22	19/07/18 14:56	General View	 Load JPG ☒	☒
23	19/07/18 14:56	General View	 Load JPG ☒	☒
24	19/07/18 14:56	General View	 Load JPG ☒	☒
25	19/07/18 14:56	General View	 Load JPG ☒	☒
26	19/07/18 14:56	General View	 Load JPG ☒	☒
27	19/07/18 14:56	General View	 Load JPG ☒	☒
28	19/07/18 14:56	General View	 Load JPG ☒	☒
29	19/07/18 14:56	General View	 Load JPG ☒	☒
30	19/07/18 14:56	General View	 Load JPG ☒	☒
31	19/07/18 14:56	General View	 Load JPG ☒	☒
32	19/07/18 14:56	General View	 Load JPG ☒	☒

Assessment Reports				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	19/07/18 14:56	General View	 Load JPG	☒
34	19/07/18 14:56	General View	 Load JPG	☒
35	19/07/18 14:56	General View	 Load JPG	☒
36	19/07/18 14:56	General View	 Load JPG	☒
37	19/07/18 14:56	General View	 Load JPG	☒
38	19/07/18 14:56	General View	 Load JPG	☒
39	19/07/18 14:56	General View	 Load JPG	☒
40	19/07/18 14:56	General View	 Load JPG	☒
41	19/07/18 14:56	General View	 Load JPG	☒
42	19/07/18 14:56	General View	 Load JPG	☒
43	19/07/18 14:56	General View	 Load JPG	☒
44	19/07/18 14:56	General View	 Load JPG	☒
45	19/07/18 14:56	General View	 Load JPG	☒
46	19/07/18 14:56	General View	 Load JPG	☒
47	19/07/18 14:56	General View	 Load JPG	☒
48	19/07/18 14:56	General View	 Load JPG	☒
49	19/07/18 14:56	General View	 Load JPG	☒
50	08/08/18 09:24	Photo After Spray	 Load JPG	☒
51	08/08/18 09:24	Photo After Spray	 Load JPG	☒
52	08/08/18 09:24	Photo After Spray	 Load JPG	☒
53	08/08/18 09:24	Photo After Spray	 Load JPG	☒
54	08/08/18 09:24	Photo After Spray	 Load JPG	☒
55	08/08/18 09:24	Photo After Spray	 Load JPG	☒
56	08/08/18 09:24	Photo After Spray	 Load JPG	☒
57	08/08/18 09:24	Photo After Spray	 Load JPG	☒
58	08/08/18 09:24	Photo After Spray	 Load JPG	☒
59	08/08/18 09:24	Photo After Spray	 Load JPG	☒
60	08/08/18 09:24	Photo After Spray	 Load JPG	☒
61	08/08/18 09:24	Photo After Spray	 Load JPG	☒
62	08/08/18 09:24	Photo After Spray	 Load JPG	☒
63	08/08/18 09:24	Photo After Spray	 Load JPG	☒
64	08/08/18 09:24	Photo After Spray	 Load JPG	☒
65	08/08/18 09:24	Photo After Spray	 Load JPG	☒
66	08/08/18 09:24	Photo After Spray	 Load JPG	☒
67	08/08/18 09:24	Photo After Spray	 Load JPG	☒
68	08/08/18 09:24	Photo After Spray	 Load JPG	☒
69	08/08/18 09:24	Photo After Spray	 Load JPG	☒
70	08/08/18 09:24	Photo After Spray	 Load JPG	☒
71	08/08/18 09:24	Photo After Spray	 Load JPG	☒
72	08/08/18 09:24	Photo After Spray	 Load JPG	☒
73	08/08/18 09:24	Photo After Spray	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/07/18 14:02	Email approval from Jason to outsource for survey	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 14:52	ESTIMATE	 Load PDF	
2	13/08/18 14:05	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

				View	View in Browser ▼
Assessment Reports				1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print
1	12/07/18 18:15	Accident Statement	1	Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print
1	12/07/18 18:15	Accident Photo	1	Load JPG	✓
2	12/07/18 18:15	Accident Photo	1	Load JPG	✓
3	12/07/18 18:15	Accident Photo	1	Load JPG	✓
4	12/07/18 18:15	Accident Photo	1	Load JPG	✓
5	12/07/18 18:15	Accident Photo	1	Load JPG	✓
6	12/07/18 18:15	Accident Photo	1	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print
1	12/07/18 18:02	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18012974/GTD3S2

Date: 13/08/2018

REFERENCE

Insured/Claimant:	WANG YONG KANG	Policy No:	27454618DMA	
Date of Loss:	11/07/2018	Nature of Claim:	OD	Claim No: 564528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN8820E		
Make & Model:	CHERY A1, 1.3 (M)	Engine No:	SQR473FFF8E01817
Reg. Date:	03/03/2009 (Man. Year: 2008)	Chassis No:	LVVDB12B08D167534
Colour:	Orange	Odometer:	47413 km
Engine Capacity:	1297 cc		
Market Value/New Car Price:	S\$7,200.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R14	Rear Tyre Size:	185/60R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,785.00	1,446.40	4,338.60	75.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	753.60	2,546.40	77.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,085.00	2,200.00	6,885.00	75.78
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	8,585.00	1,700.00	6,885.00	80.20
+ GST 7.00/7.00% (S\$)	600.95	119.00	481.95	80.20
Nett Amount (S\$)	9,185.95	1,819.00	7,366.95	80.20

INSPECTION

Date of Assignment:	17/07/2018		
Date Inspected:	18/07/2018	Inspected At:	Vertex Automobile Pte Ltd (HQ) No 3, Ubi Road 4 Singapore 408608
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2018)
Parts:	143	CHERY A1 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN8820E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT	Distorted	480.00 F	*480.00 F
2	1		*FOG LAMP - FR LH	Distorted	175.00 F	*175.00 F
3	1		*HEAD LAMP - FR LH	Not Necessary	475.00 F	*- F
4	1		*HEAD LAMP - FR RH	Broken	475.00 F	*475.00 F
5	1		*BUMPER REINF FRT	Bent	290.00 F	*290.00 F
6	1		*BUMPER REINF SPONGE FRT	Not Necessary	80.00 F	*- F
7	1		*WATER TANK SUPPORT PANEL	Not Necessary	125.00 F	*- F
8	1		*RAD GRILLE UPPER	Not Necessary	20.00 F	*- F
9	1		*FENDER LH	Repair	300.00 F	*- F
10	1		*FENDER SHIELD FRT LH	Not Necessary	40.00 F	*- F
11	1		*BONNET FRT	Not Necessary	1,330.00 F	*- F
12	1		*BONNET LOCK - LWR	Not Necessary	10.00 F	*- F
13	1		*RADIATOR	Not Necessary	265.00 F	*- F
14	1		*CONDENSER	Not Necessary	470.00 F	*- F
15	1		*RAD FAN	Not Necessary	380.00 F	*- F
16	1		*H/LAMP BKT LH	Not Necessary	95.00 F	*- F
17	1		*AIR FILTER BOX	Not Necessary	95.00 F	*- F
18	1		*DRYER	Not Necessary	95.00 F	*- F
19	1		*RAD SUPPORT PANEL LH	Not Necessary	55.00 F	*- F
20	1		*UNIT BUMPER SPOILER	Not Necessary	300.00 F	*- F
21	20		*UNIT CLIP - BUMPER SPOILER	Necessary	24.00 F	*24.00 F
22	6		*UNIT CLIP - FENDER SHIELD	Not Necessary	3.60 F	*- F
23	1		*UNIT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
24	1		*UNIT COOLANT - 1L	Not Necessary	55.00 FS	*- FS
25	1		*UNIT AIR-CON GAS	Not Necessary	65.00 FS	*- FS
26	4		*SCREW SEAT - PLASTIC	Necessary	2.40 F	*2.40 F

F=Franchise part, S=SpcNett.

Total Parts (S\$)	5,785.00	1,446.40
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CHECK WIRING, LIGHTING SYSTEM FOR PROPER FUNCTION.	New	120.00	60.00
2	LABOUR TO DISMANTLE AND REPLACE ABOVE DAMAGE PARTS TO NEW.	New	480.00	180.00
3	LABOUR TO PANEL BEATING & RE-ALIGN, KNOCK OUT DENTS, STRAIGHTEN & RE-ALIGN ALL AFFECTED PARTS.	New	750.00	240.00
4	LABOUR TO SPRAY PAINTING FRONT BUMPER, FRONT LHS FENDER, LHS MIRROR COVER, FRONT AND REAR LHS DOOR ASSY & FRONT INNER BODY AFFECTED AREAS.	New	1,950.00	273.60
Gross Labour Cost (S\$)			3,300.00	753.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >