

ASS. REC. BY:

REF: CS/AGI18012975/ Ksd3n2

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Julie Mangubat

of

AGI

Date/Time:

17/07/18 @ 1:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN3103Y

Insured:

SJV 5293D

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Blk 7, Sin Ming Ind. Est # 01-76

Policy No:

Claim No:

C10001776 / JM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:00pm @ 17/7/18

Person Contacted:

Kenny

Vehicle IN / OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	YN3103Y - CS/CTI17022320/Tlgbe2 DOA: 09/11/2017
	SJV 5293D - CS3/AGI18006758/G24be2 DOA: 11/04/18
	(\$1,707.75 Red - 55%)

ASS. REC. BY:

REF:

AG21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

YN 31034

Yr Regn: _____

09.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Isuzu NPR

c.c

2999

Colour: _____

Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

262626

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

JAANPR 8514 B 7100040

C/No: _____

NPR8514

Gen. Cond: _____

Good / Fair / Poor / Burnt

Steering: _____

In order / Jammed / Leaked / Burnt or

Brake: _____

In order / Jammed / Leaked / Burnt or

Modl: _____

Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

FOUR 16

R: _____

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kendy

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

22

mm

L/Bal. _____

9

mm

L/Bal. _____

22

mm

D.O.A. _____

14/7/18

D.O.I. _____

23/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/7

File pass to Catherine

RECEIVED 27 JUL 2010

Date/Time, File Pass to?

27/07/18

1) _____

Date/Time, File Return to?

2) _____



Prell. Report



Final Report

Days Of Repair: _____

3

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

Add Fee: _____



Site Insp (\$ _____)



Interview (\$ _____)



Tech Invs (\$ _____)



Weekend (\$ _____)

S + RS, SI

Faktor

Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

1,400.00 H/S

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI18012975/Ksd3	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 17-07-2018 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 5293D	Veh. Inspected	YN 3103Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001776/JM	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/07/2018	Inspection Date	23/07/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Tuesday, 17 July 2018 1:52 PM
To: sur@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Subject: FW: ATTACHED YN3103Y REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRE SURVEY | Claim ref: C10001776/JM
Attachments: SKM_284e18071713200.pdf

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.

Thank you,
-julie

From: kennychan@alanutd.com <kennychan@alanutd.com>
Sent: Tuesday, 17 July, 2018 1:28 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: ATTACHED YN3103Y REPAIR ESTIMATE ,GIA REPORT FOR REQUEST JOINT EXPERT SURVEYOR LIST TO CONDUCT PRE SURVEY

Dear Motor Claims Dept. / Colin

Attached our client vehicle YN3103Y repair estimate , GIA report to request joint expert surveyor list for us to choose surveyor to conduct pre repair survey ,claiming your insured vehicle SJV5293D accident on 14-07-2018 , meant time kindly check the liability for confirm direct settle thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company
 Cert No. 1982D1763M
 Owner ID Type: Company
 Owner Name: ALLINTON ENGINEERING & TRADING PTE LTD
 Registered Address: 331 JALAN BESAR ALLINTON SINGAPORE 208983
 Mailing Address:
 Birth Date: -

Vehicle Particulars

Vehicle No. YN3103Y
 Previous Vehicle No.: -
 Effective Date of Ownership: 03 Sep 2012
 Original Regn Date: 03 Sep 2012
 Registration Date: 03 Sep 2012
 Year of Manufacture: 2011
 Vehicle Type: Goods (Open) Lorry (Wooden Body)
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3:
 Vehicle Make: ISUZU
 Vehicle Model: NPR85UH5AK
 Primary Colour: Blue
 Secondary Colour:
 Passenger Capacity: 2
 Chassis No. JAANPR85HB7100040
 Engine No.: 4JJ1100086
 Engine Capacity/Power Rating: 2999 cc / -
 Maximum Power Output: -
 Propellant: Diesel
 Max Unladen Weight: 2480 kg
 Maximum Laden Weight: 6700 kg
 Open Market Value: \$35,342.00
 PARF Eligibility: No
 PARF Eligibility Expiry Date:
 Minimum PARF Benefit:
 No. of Transfers: 0
 IU Label No.: 1510786502
 COE No.: 2012090105000152C
 COE Expiry Date: 02 Sep 2022
 COE Category: C - Goods Vehicle & Bus
 COE Registration Category: C - Goods Vehicle & Bus
 Quota Premium (QP) / Prevailing Quota: \$57,001.00 / -

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 17:44
Date Of Accident	14/07/2018 14:15
Exact Location Of Accident	EDGE DALE PLAINS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3103Y
Insured/Policyholder	
Name Of Registered Owner	ALLINTON ENGINEERING & TRADING PTE LTD
Co Reg No	198201763M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62960679

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR85UH5A-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1537791702
Cover Note Number	

Driver

Name of Driver	CHAN KAWN KIM
NRIC No	S1289706E
Date Of Birth	11/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	26/12/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97606128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 126B EDGEDALE PLAINS #07-356
Postcode	822126
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV5293D
Vehicle Make/Model/Colour	KIA CERATO FORTE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAVID CHEW
NRIC/Passport Number	S7411920D
Contact Number	93929163
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHAN KAWN KIM
Approximate Age	60

Injuries Sustain

Injured person in which vehicle?

YN3103Y

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 126B EDGEDALE PALINS #07-256

Postcode

822126

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

16 JUL 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

16 JUL 2018


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S6927273H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 14-7-2018 AT ABOUT 2.15 P.M I WAS DRIVING ALONG
EDGEHILL PLAINS ON MY LEFT LANE, VEHICLE SV 5293D
FROM BEHIND COLLIDED ONTO THE REAR OF MY VEHICLE
AND THE IMPACT CAUSE MY DRIVING WHEEL HIT AT
MY THROAT AND CAUSE MY THROAT PAIN NEED TO CONSULT
DOCTOR. WE EXCHANGE PARTICULAR FOR INSURANCE CLAIM

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

16 JUL 2018

GIA/IMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

16 JUL 2018

Reporting Centre Personnel's Signature

Name:

Jenny Lim
NRIC/FIN No.: S6927273H



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200208384E

MZ300/C

R SN

AN0044A

Cov. Type: C

PLM 268326

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.

DMCVSN1537791702

Engine No : 4JJ1100066

ChaN: JAANPR85HB7100040

1. Index Mark and Registration
Number of Vehicle

YN3103Y

AutoSafe

2. Name of Policy Holder

M/S ALLINTON ENGINEERING & TRADING PTE LTD

3. Effective date of the Commencement of
Insurance for the purposes of the Regulations,
Ordinance or Enactment

03 September 2017 Excess Sect I S\$800.00

EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance

02 September 2018

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:

26 SEP 2017

BY: CP-8776 UOB 376394

(1) Use in connection with the Policyholder's business.

(2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

(3) Use for social, domestic or pleasure purposes.

The Policy does not cover.

(1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05818

Date : 17-Jul-2018

PAGE : 1

Vehicle Insured : SJV5293D
Accident Date : 14-Jul-2018

Our Ref : 218123 (AUTO & GEN) / CHAN

ALLINTON ENGRG. & TRADING PTE LTD
331 JALAN BESAR RTW HOUSE
Singapore 208983

*Not Authorized
11 Sep @?
Resurvey After Repair*

ESTIMATED COST OF REPAIR FOR ISUZU NPR85UH5AK YN3103Y

2 pcs Taillamp	<i>CLSCM</i> @ S\$155.00	310.00	<i>CL</i>
2 pcs Taillamp bracket	<i>OLSCM</i> @ S\$ 97.20	194.40	<i>CL</i>
1 pc Rear no.plate lamp		<i>CLM</i> 87.40	<i>CL</i>
1 pc Rear no.plate bracket		<i>B1</i> 105.70	<i>CL</i>
		697.50	
	Less 10% :	69.75	

1 pc Rear bumper (metal)		<i>B1</i> 627.75	
2 pcs Rear bumper support bracket	@ S\$120.00	<i>B1</i> 450.00	sn <i>CL</i>
1 pc Rear end wooden plan		<i>B1</i> 240.00	sn <i>CL</i>
1 pc Rear wooden plan step bar		<i>B1</i> 400.00	sn <i>X</i>
2 pcs Taillamp wooden plan support	@ S\$ 30.00	<i>CLM</i> 100.00	sn <i>CL</i>
1 pc Rear no.plate		<i>B1</i> 60.00	sn <i>CL</i>
		<i>B1</i> 30.00	sn <i>CL</i>
		200.00	<i>200.00</i>

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *250*

To lift up tail wooden floor plan
for remove & renew rear end wooden
plan

600.00 *200*

Total : S\$ 3,107.75

Singapore Dollars Three Thousand One Hundred
and Seven and Cents Seventy Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18012975/Ksd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 01-08-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 5293D	Veh. Inspected	YN 3103Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001776/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	17/07/2018

2. Vehicle Particulars & Condition

Make & Model	ISUZU NPR	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JAANPR85HB7100040	Colour	BLUE
Odometer	262626	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	700 R16	KENDA	9 mm
L/H Front Tyre	700 R16	KENDA	9 mm
R/H Rear Tyre	700 R16 (D)	KENDA	2/2 mm
L/H Rear Tyre	700 R16 (D)	KENDA	2/2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2018	Inspection Date	23/07/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 3103Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	TAILLAMP @\$155.00	O/S CRACKED	310.00	155.00
2	TAILLAMP BRACKET @\$97.20	O/S CRACKED	194.40	97.20
1	REAR NO.PLATE LAMP	CRACKED	87.40	87.40
1	REAR NO.PLATE BRACKET	BENT	105.70	105.70
	LESS 10% DISCOUNT		-69.75	-44.53
			627.75	400.77
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER (METAL) (SN)	BENT	450.00	450.00
2	REAR BUMPER SUPPORT BRACKET @\$120.00 (SN)	BENT	240.00	240.00
1	REAR END WOODEN PLAN (SN)	SERVICEABLE	400.00	-
1	REAR WOODEN PLAN STEP BAR (SN)	CRACKED	100.00	100.00
2	TAILLAMP WOODEN PLAN SUPPORT @\$30.00 (SN)	O/S CRACKED	60.00	30.00
1	REAR NO.PLATE (SN)	BENT	30.00	20.00
			1,280.00	840.00
<u>LABOUR</u>				
	TO PUTTY AND SPRAY REPLACED PARTS.		200.00	120.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		400.00	250.00
	TO LIFT UP TAIL WOODEN FLOOR PLAN FOR REMOVE &RENEW REAR END WOODEN PLAN.		600.00	200.00
			1,200.00	570.00
GRAND TOTAL			3,107.75	1,810.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/AGI18012975/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.