



Your Ref: 4247931639SG003

Date: 07th August 2018

Our Ref: CS1/AIG18012992/Lqbs2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16

Chartis Building

Singapore 079120

(The Motor Claims Department)

Attn : Saliha

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SKG 6276P

INSURED VEHICLE: SJV 6017D

ACCIDENT DATE: 19/09/2016

We thank you for your instruction on 17/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKG 6276P from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SKG 6276P and SJV 6017D.
- c) Colour damaged vehicle photographs of SKG 6276P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKG 6276P
Make & Model	: Mercedes Benz C180 Blueefficiency
Year of Registration	: 2012
Chassis Number	: WDD2040312A760369

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.