



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18005671/Gtd3s2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 19-07-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7324A	Veh. Inspected	SLQ 6510Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801338/NSW	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31248445	Colour	SILVER	
Odometer	059192	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	6 mm	
L/H Front Tyre	215/60R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2018	Inspection Date	29/03/2018	
Survey held at	25 DEFU LANE 9			
Repairer	ALLSWELL MOTOR TRADERS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		