

ASS. REC-BY:

REF: CS/FCI 18013058/Uvd3n2 Special Instruction:

Surveyor:

Manus

ASSIGNMENT (Office)

CWS

From (Person):

Sithum

of

FCI

Date/Time: 17/7/18 @ 6:06pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 4898A

Insured:

SHA 82417

at Workshop m/s

Ethoz Group

Tel:

6654 7617

of

22 Kampines St. 92

Policy No:

Claim No:

D18004451 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

9:56am @ 18/7/18

Person Contacted:

Mr. Ng

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 4898A - CS/FCI 17006821/R/vh3p2

DOA: 29/3/2017

SHA 82417-X.

19/7/18

Email preli revised to FCI

(08/11/13) wef

ASS. REC: BY: Morins

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 4898Aat Workshop m/s Ephre

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 52

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

274 32425

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC 4898A Yr Regn: 12 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: NISSAN NV350 c.c. 2488Colour: Red A/C: Insured / Std / NI / NASp. Reading: 89/17 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC2E2620005381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or OHTSUFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/5/18 D.O.I. 18/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/7/18/5 # 1300 confirmed with AH (ag. (Red 4592.32, 789))

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 23- typistReport Format : CWSLump Sum / I.B.I: (\$ 13002)Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

140

50

50

30

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013058/Uvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8241T	Veh. Inspected	GBE 4898A
Policy No.		Coverage (\$)	0.00
Claim No.	D18004451MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	18/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/05/2018	Inspection Date	18/07/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004451MFSH

Our ref: CS/FCI18013058/Uvd3

DATE: 17/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 4898A


We thank for your instruction on 17/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 18/7/2018 at the premises of M/s ETHOZ GROUP LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,892.32
Revised Estimate Amount	: S\$1,948.25
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-06-2018	Our Ref No. D18004451MFSH
Accident Date	30-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8241T	Third Party Vehicle. GBE4898A
Survey Location	22 TAMPINES STREET 92	
Contact Person.	NG BOON KAI	
Contact No.	66547617/ 0	Fax No. 66547648
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241081)



PRI Documents



Close



PRI Header Details

Claim No	D18004451MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ETHOZ GR
Workshop Name	ETHOZ GROUP LTD (Contact Person : NG BOON KAI)	Survey Location & Contact Details	22 TAMPINES STREET 92 Mobile: 0 , Phone: 66547617 , Fax: 66547648 EmailId: BOONKAI.NG@ETHOZGROUP.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8241T	TP Vehicle No	GBE4898A
PRI Recieved Date	17-07-2018 01:22:03 PM	Surveyor Appointed Date	17-07-2018 06:05:17 PM	Surveyor Accept Date	18-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 19 July 2018 2:09 PM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004451MFSH/1, GBE 4898A
Attachments: GBE 4898A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBE 4898A
Date of survey: 18/7/2018
Number of days :3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 18 July 2018 9:58 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004451MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 July 2018 6:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004451MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly
From \$938 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING
 (CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)
 With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

 Browse by Category

 Sort by Date Posted 20 results/page

7 vehicles

Nissan NV350

[Advanced Search](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Nissan NV350

Any

Any

2015

Any

Any

Any

Available

Nissan NV350 2.5M

\$50,800

\$7,800 /yr

20-Jan-2015

2,488 cc

-

Van

Available

Fuel Type: Diesel

Free 8 Times Servicing And First Year Insurance! Very Well Maintained By Previous Owner. Cheapest In The Market. Accident Free. Call Us Now To Arrange For A Viewing.

Ezy-1 Pte Ltd

Posted: 16-Jul-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Nissan NV350 2.5A

\$53,800

\$7,710 /yr

10-Jul-2015

2,488 cc

71,000 km

Van

Available

Fuel Type: Diesel

Low Mileage, 1 Owner Only, Look As Good As New, High Loan/High Trade In Available, Call Now For Appointment!

ABWIN (1994) Pte Ltd

Posted: 15-Jul-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Nissan NV350 2.5M

\$50,500

\$7,450 /yr

28-Apr-2015

2,488 cc

106,345 km

Van

Available

Fuel Type: Diesel

Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Think One Automobile & Trading

Posted: 10-Jul-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Nissan NV350 2.5A

\$55,800

\$7,840 /yr

28-Aug-2015

2,488 cc

63,125 km

Van

Available

Fuel Type: Diesel

Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Think One Automobile & Trading

Posted: 04-Jul-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but Unsure of its Condition?

Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle

Nissan NV350 2.5A

\$66,900

\$9,750 /yr

28-May-2015

2,488 cc

63,627 km

Bus

Available

Fuel Type: Diesel

10 Seaters Excursion Bus In Excellent Condition. Well Maintained And Regularly Serviced. Call Now For Viewing Appointment!

Posted: 28-Jun-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Nissan NV350 2.5A

\$53,800

\$7,950 /yr

23-Apr-2015

2,488 cc

46,000 km

Van

Available

Fuel Type: Diesel

Automatic Transmission, We Provide Doorstep Viewing, 5 Door Unit, Nissan NV350 Van! Highest Trade In Value For Your Current Vehicle! Cargo Van! Full Accessories Ideal For All 3A Licence Holders! No Gl...

Posted: 12-Jun-2018

Tags: 2015 Nissan NV350, Nissan NV350, Nissan, NV350, Used Nissan

Compare

Nissan NV350 2.5A

\$53,800

\$7,770 /yr

20-Jun-2015

2,488 cc

-

Van

Available

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 4531H

Vehicle Details

Vehicle No.: GBE4898A

Vehicle to be Exported: No

Intended De-registration Date: 18 Jul 2018

Vehicle Make: NISSAN

Vehicle Model: NV350 PANEL VAN 2.5 5MT 5DR EURO V

Primary Colour: White

Manufacturing Year: 2015

Engine No.: YD25384088A

Chassis No.: JN1MC2E26Z0005381

Maximum Power Output: -

Open Market Value: \$22,481.00

Original Registration Date: 14 Dec 2015

First Registration Date: 14 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$1,125.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$43,809.00

COE Rebate Amount: \$32,425.00

Total Rebate Amount: \$32,425.00

The information contained herein is correct as at 18 Jul 2018

OK

4/5 @ 1300

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Ng Boon Kai
CLAIM DEPARTMENT
DID : 6654_7617
FAX :

Date : 17/07/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000151

Accident Date : 30/05/2018

Vehicle No : GBE-4898-A

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	FRONT BUMPER	514.70	7.5 641.00
10	FRONT BUMPER CLIPS	30.00	2.5 55.00
1	FRONT BUMPER SIDE RETAINER RH		1.1 155.60 X
1	FRONT BUMPER SIDE RETAINER LH	147.00	1.1 155.60
1	FRONT HEADLAMP LH		1.1 473.00 X
1	FRONT FOG LAMP LH		1.1 313.50 X
1	FRONT FOG LAMP GARNISH LH		7.5 145.20
1	FRONT DOOR LH		1.1 1,189.60 X
1	A-PILLAR LH		1.1 950.60 X

4P = 1342.50 - 10% = 1208.25

SM = 10

L = 720

1948.25 - 20% = 1558.60

Date : 17/07/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000151

Accident Date : 30/05/2018

Vehicle No : GBE-4898-A

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT STEP GARNISH LH	345.70	
	Sub Total	4424.80	
	Discount 10% On Parts	(442.48)	
	<u>Special Nett Item</u>		
1	LTA DOOR STICKER	20.00	
	Sub Total	20.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	800.00	
	LABOUR TO SPRAY PAINT AFFECTED AREAS	900.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	

7-1048.20
102
943.38
1663.38
1330.

Date : 17/07/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000151

Accident Date : 30/05/2018

Vehicle No : GBE-4898-A

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RUST PROOF AFFECTED AREA	1 1 80.00	X
	TO CONDUCT ALL WHEEL ALIGNMENT	1 1 80.00	X
	Sub Total	1890.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5,892.32

Remarks:

not allowed

SUB TOTAL

GST 7.0 % 412.46

TOTAL 6,304.78

Surveyor's name:

mercus nkh

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

Take photo of damage 3 days.
Tel: 62563561
18/7/18 @ 10.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013058/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8241T	Veh. Inspected	GBE 4898A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004451MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	17/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1MC2E26Z0005381	Colour	RED	
Odometer	89117	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	OHTSU	6 mm	
L/H Front Tyre	195 R15	OHTSU	6 mm	
R/H Rear Tyre	195 R15	OHTSU	6 mm	
L/H Rear Tyre	195 R15	OHTSU	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2018	Inspection Date	18/07/2018	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4898A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (N)	DISTORTED	641.00	514.70
10	FRONT BUMPER CLIPS (N)	NECESSARY	55.00	30.00
1	FRONT BUMPER SIDE RETAINER RH (N)	NOT NECESSARY	155.60	-
1	FRONT BUMPER SIDE RETAINER LH (N)	CRACKED	155.60	147.00
1	FRONT HEADLAMP LH (N)	NOT NECESSARY	473.00	-
1	FRONT FOG LAMP LH (N)	NOT NECESSARY	313.50	-
1	FRONT FOG LAMP GARNISH LH (N)	TORN	145.20	145.20
1	FRONT DOOR LH (N)	TO REPAIR SEE LABOUR	1,189.60	-
1	A-PILLAR LH (N)	TO REPAIR SEE LABOUR	950.60	-
1	FRONT STEP GARNISH LH (N)	TWISTED	345.70	211.30
	LESS 10% DISCOUNT		-442.48	-104.82
			3,982.32	943.38
SPECIAL NETT ITEMS				
1	LTA DOOR STICKER (SN)	NECESSARY	20.00	20.00
			20.00	20.00
LABOUR				
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND A-PILLAR LH.		800.00	300.00
	LABOUR TO SPRAY PAINT AFFECTEDAREAS.		900.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	20.00
	TO RUST PROOF AFFECTED AREA.	NOT NECESSARY	80.00	-
	TO CONDUCT ALL WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	-		-	-
	-		-	-
	-		-	-
			1,890.00	720.00
GRAND TOTAL			5,892.32	1,683.38

Report Ref No. CS/FCI18013058/Uvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00
---	--	--	----------

Report Ref No. CS/FCI18013058/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.