

22/03/2002

ASS. REC. BY:

REF: CS/MSG18013069/Ktd3et Special Instruction:

Survivor:

Menmen Kenneth  
Muhd Ashik

ASSIGNMENT (Office)

From (Person): of MSG

Date/Time: 18/7/18 @ 10:40am

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBL 9271M

Insured: SGS 9119A

at Workshop m/s GA Motor

Tel: 64539903 ✓

of Blk 32, Sin Ming Drive #01-331

Policy No: A28910231 QMX

Claim No: 564097

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/07/2018

CA / REV / REP. / REV 24 HRS

cup?

H.O.D. Endorsement:

Date/Time: 12:08pm @ 18/7/18

Person Contacted:

Mr. Tan

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBL 9271M - X

SGS 9119A - X.

23/7

Report via menmen

lump sum \$32007 (red: 27k; 46%)

ASS. REC. BY:

REF: MSG/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ GA \_\_\_\_\_  
of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBL 9271m Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Scooter

Make: Yamaha Tigor 15.5 15.5

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 12584 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MLES 3810000 36614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80R14

R: 130/70R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm Rear

L/Bal. mm R/Bal. 6 mm

D.O.A. 1.1/7/18 L/Bal. mm

D.O.I. 18/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear &amp; N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/7 File pass to Catherine

RECEIVED 13 NOV 2018

Date/Time, File Pass to?



: Prell. Report

1) 13/11/18 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I. (\$) 3200

150

10

160

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2018		18 Jul 2018 10:04 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEW KAI HWEE, ID: S1351574C, Tel: +6591871752, Email: NOEMAIL		
Main Claimant:	PAS AUTO PTE LTD, Co. Reg. No.: 201512120M		
Vehicle Reg. No.:	FBL9271M	Date of Loss:	11/07/2018 15:00 - :59 [13 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 564097	Policy/Cover Note No.:	A28910231QMX (TP, Fire & Theft) Coverage: 10/03/2018 - 09/03/2019
Vehicle Reg. No. (Insured):	SGS9119A	Policy No. (Claimant):	
		Excess:	
Repairer:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/07/2018]		
Driver/Custodian (Insured):	LEW KAI HWEE (58 / Male), NRIC: S1351574C, Tel: +6591871752		
Adj Asg. Remarks:	Liability: 100%. TP agree with SJE - Assign Kenneth Kong of LKK Auto Consultants Pte Ltd.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 23 Jul 2018

**Preliminary Advice**

Insured Vehicle No	: SGS9119A	Accident Date	: 11/07/2018
TP Vehicle No	: FBL9271M	Assignment Date	: 18/07/2018
Make	: YAMAHA TRICITY	Est. Duration of Repair	: 5.00
Date of Inspection	: 18/07/2018		
Inspection At	: GA MOTOR (HQ) BLK 32 SIN MING DRIVE, #01-331 SINGAPORE 575706		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear , n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,961.00
Revised Amount	:S\$	3,366.00
Check Items (Estimated)	:S\$	1,120.00
Total	:S\$	4,486.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013069/Ktd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 18-07-2018

Code : MSG



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 9119A	Veh. Inspected	FBL 9271M
Policy No.	A28910231QMX	Coverage (\$)	0.00
Claim No.	564097	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	18/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	11/07/2018	Inspection Date	18/07/2018
Survey held at	GA MOTOR BLK 32 SIN MING DRIVE #01-331 SINGAPORE 575706		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Denise Tay (LKKAuto)

---

**From:** GA MOTOR <gamotor@gmail.com>  
**Sent:** Tuesday, 13 November 2018 10:33 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** Re: fbl 9271m

Hi, denise  
We accept the offer of Lump sum repair \$3200.00 and the Loss of use 5 days  
Thanks

On Tue, Nov 13, 2018 at 10:10 AM Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)> wrote:

Dear Mrs Tan,

I check with Kenneth , offer at lump sum \$3200/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** GA MOTOR <[gamotor@gmail.com](mailto:gamotor@gmail.com)>  
**Sent:** Monday, 12 November 2018 2:34 PM  
**To:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Subject:** Re: fbl 9271m

Hi, Denise

attached the estimated list which Kenneth have take the photo

on the Question mark items on 20 july 2018

the lump sum amount should be \$3250

thanks

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/07/2018 17:45
Date Of Accident	11/07/2018 15:15
Exact Location Of Accident	BLK 32 SIN MING DRIVE #01-325
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL9271M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PAS AUTO PTE LTD
Co Reg No	201512120M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64523938

### Vehicle Particulars

Manufacturer	YAMAHA
Model	TRICITY
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5091101277-01
Cover Note Number	

### Driver

Name of Driver	FONG SOON YONG
NRIC No	G6632956P
Date Of Birth	15/04/1989
Occupation	INDOOR
Date Of Driving Pass	25/02/2012
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83322344
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 32 SIN MING DRIVE
	#01-325
Postcode	575706
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS9119A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91871752
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



PAS AUTO PTE LTD  
Blk 32, Sin Ming Drive  
#01-325 Singapore 575706  
Tel: 6452 3938 Fax: 6452 7936

*[Signature]*

*[Signature]*


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Our company motorbike was parked in front office.

A vehicle reverse hit our company vehicle (Bike).

\* Our one of our company vehicle video capture the whole incident happen.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



**PAS AUTO PTE LTD**

Blk 32, Sin Ming Drive

#01-325 Singapore 575706

Tel: 6452 3938 Fax: 6452 7938

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Signature: [Signature]



盛 摩 哆  
GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL:64539903,64539904 FAX:64539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.  
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



DATE: 12-07-2018

TO:

MSIG Insurance (Singapore) Pte. Ltd  
4 Shenton way #21-01 SGX Centre 2  
Singapore 068807

Tel: 68277888

Fax 62257402

Attn: Mr. Ashik

Attn: Motor Claim Dept.

Dear Sir,

Re: Accident involving SGS9119A & FBL9271M at Blk 32 Sin Ming Drive on 11-07-2018

We wish to make a claim on the accident motorcycle FBL9271M which met an accident  
With the above said vehicle insured under your insurance Co.

The motorcycle is now in GA Motor Blk 32 Sin Ming Drive #01-331 Singapore 575706.

Please send a surveyor to the accident motorcycle to conduct a pre-repair inspection  
Of our client's motorcycle.

Thank you,

Your faithfully,



GA MOTOR  
Tan Sin Huat



# GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL: 64539903, 64539904 FAX: 64539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.  
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 12-07-2018

Estimated repair list for the accident motorcycle Yamaha Tricity 155 Vehicle No. FBL9271M

1 pc	Mirror	CU	\$80.00	✓
1 pc	Handle bar	BH	\$120.00	✓
1 set	Handle balancer	CU / Rd	\$40.00	✓
1 pc	IU unit	Sh cr	\$156.00	✓
1 pc	Brake lever (L)	BH	\$90.00	✓
1 pc	Signal light (L)	CUA	\$125.00	✓
1 pc	Head light	CU	\$450.00	✓
1 pc	Windshield	CU	\$110.00	✓
1 pc	Front mudguard (L)	R	\$250.00	X
1 pc	Front fork inner tube (L)	Ry	\$240.00	✓
1 set	Fork oil seal & fork oil	new	\$60.00	✓ 501m
1 pc	Side fairing (L)	Respray	\$380.00	✓ 1501m
1 pc	Left side plastic cover	CU	\$160.00	✓
1 pc	Bottom cover (L)	CU	\$230.00	✓
1 pc	Side stand	Ry	\$170.00	✓
1 pc	Main stand	R	\$290.00	X
1 pc	Belting cover	CU	\$260.00	✓
1 pc	Air Box	CU	\$350.00	✓
1 pc	Rear box	CU Rd	\$800.00	✓ 2501m
1 pc	Rear carrier	BH	\$300.00	✓
1 pc	Damper (right)	Ry	\$220.00	✓
1 pc	Exhaust pipe	Rd	\$700.00	✓
	Towing		\$30.00	✓ 251
	Labour		\$350.00	✓ 2001

106

Total : \$5961.00

Not Authorized  
L/Ly &?  
Respray After Painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





# GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL: 64539903, 64539904 FAX: 64539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.  
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 12-07-2018

Estimated repair list for the accident motorcycle Yamaha Tricity 155 Vehicle No. FBL9271M

1 pc	Mirror	Ln	\$80.00	✓
1 pc	Handle bar		\$120.00	? X
1 set	Handle balancer	Ln 1nd	\$40.00	✓
1 pc	IU unit	Sh cr	\$156.00	✓
1 pc	Brake lever (L)	Rn	\$90.00	✓
1 pc	Signal light (L)	CR	\$125.00	✓
1 pc	Head light	Ln	\$450.00	✓
1 pc	Windshield	Ln	\$110.00	✓
1 pc	Front mudguard (L)	n	\$250.00	X
1 pc	Front fork inner tube (L)		\$240.00	? Y
1 set	Fork oil seal & fork oil		\$60.00	? X
1 pc	Side fairing (L)	Repair	\$380.00	1500n
1 pc	Left side plastic cover	Ln	\$160.00	✓
1 pc	Bottom cover (L)	Ln	\$230.00	✓
1 pc	Side stand	Dr	\$170.00	✓
1 pc	Main stand	n	\$290.00	X ✓
1 pc	Belting cover	Ln	\$260.00	✓
1 pc	Air Box	Ln	\$350.00	✓
1 pc	Rear box	100 Cr Rd	\$800.00	2500n
1 pc	Rear carrier	Rn	\$300.00	✓
1 pc	Damper (right)	Pr	\$220.00	✓
1 pc	Exhaust pipe		\$700.00	? X
	Towing		\$30.00	25h
	Labour		\$350.00	200l

Total : \$5961.00

Not Authorized  
L/Lm &?  
Repair After Paint

*[Signature]*  
23/7/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_



## ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2018		18 Jul 2018 10:04 <a href="#">Edit Adj Rpt</a>	<b>S\$3,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LEW KAI HWEE, ID: S1351574C, Tel: +6591871752, Email: NOEMAIL								
Main Claimant:	PAS AUTO PTE LTD, Co. Reg. No.: 201512120M								
Vehicle Reg. No.:	FBL9271M	Date of Loss:	11/07/2018 15:00 - :59 [13 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564097	Policy/Cover Note No.:	A28910231QMX (TP, Fire & Theft) Coverage: 10/03/2018 - 09/03/2019						
Vehicle Reg. No. (Insured):	SGS9119A	Policy No. (Claimant):							
		Excess:							
Repairer:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 17/08/2018]								
Driver/Custodian (Insured):	LEW KAI HWEE (58 / Male), NRIC: S1351574C, Tel: +6591871752								
Adj Asg. Remarks:	Liability: 100%. TP agree with SJE - Assign Kenneth Kong of LKK Auto Consultants Pte Ltd.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBL9271M (564097)  
[SGS9119A]  
TP  
PAS AUTO PTE LTD  
Jul 11 2018 3:00PM  
[LEW KAI HWEE]  
Ga Motor

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	17/07/18 14:12	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> From: SC - Reg. No: SGS9119A, Claimant: LEW KAI HWEE	 Load HTM	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	23/07/18 09:46	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	13/11/18 10:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	13/11/18 10:54	<b>General View</b>	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/11/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/07/18 14:12	<b>TP E-FILE REPORT</b> From: SC - Reg. No: SGS9119A, Claimant: LEW KAI HWEE	Load PDF	
2	17/07/18 14:21	<b>PRI notice</b>	Load PDF	
3	17/07/18 15:10	<b>TP agree SJE - assign LKK</b>	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013069/KTD3E2

Date: 21/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28910231QMX

Claimant Vehicle No : FBL9271M

Insured Vehicle No : SGS9119A

Date of Loss: 11/07/2018

Nature of Claim: TP

Claim No: 564097

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBL9271M

Make &amp; Model: YAMAHA TRICITY, 125cc MW125

Engine No: G3H3E056614

Reg. Date: 15/05/2017 (Man. Year: 2017)

Chassis No: MLESG381000056614

Colour: Blue

Odometer: 12594 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 90/80 R14

Rear Tyre Size: 130/70 R13

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,581.00	3,850.90	1,730.10	31.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	380.00	225.00	155.00	40.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,961.00	4,075.90	1,885.10	31.62
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	5,961.00	3,200.00	2,761.00	46.32

## INSPECTION

Date of Assignment: 18/07/2018

Date Inspected: 18/07/2018 Inspected At:

Ga Motor (HQ)  
Blk 32 Sin Ming Drive, #01-331  
Singapore 575706

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Nov 2018)	
<b>Parts:</b>	N/A	YAMAHA TRICITY 125cc MW125 (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL9271M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR	Cut	80.00 F	*80.00 FL
2	1		*HANDLE BAR	Bent	120.00 F	*120.00 FL
3	1		*SET HANDLE BALANCER	Cut / Dented	40.00 F	*40.00 FL
4	1		*IU UNIT	Shorted	156.00 F	*156.00 FL
5	1		*BRAKE LEVER (L)	Bent	90.00 F	*90.00 FL
6	1		*SIGNAL LIGHT (L)	Cracked	125.00 F	*125.00 FL
7	1		*HEAD LIGHT	Cut	450.00 F	*450.00 FL
8	1		*WINDSHIELD	Cut	110.00 F	*110.00 FL
9	1		*FRONT FORK INNER TUBE (L)	Bent	240.00 F	*240.00 FL
10	1		*SET FORK OIL SEAL & FORK OIL (50%)	Necessary	60.00 FS	*30.00 FS
11	1		*SIDE FAIRING (L)	Respray	380.00 FS	*150.00 FS
12	1		*LEFT SIDE PLASTIC COVER	Cut	160.00 F	*160.00 FL
13	1		*BOTTOM COVER (L)	Cut	230.00 F	*230.00 FL
14	1		*SIDE STAND	Distorted	170.00 F	*170.00 FL
15	1		*MAIN STAND	Repair	290.00 F	*- FL
16	1		*BELTING COVER	Cut	260.00 F	*260.00 FL
17	1		*AIR BOX	Cut	350.00 F	*350.00 FL
18	1		*REAR BOX (LOCAL REPAIR)	Dented	800.00 FS	*250.00 FS
19	1		*REAR CARRIER	Bent	300.00 F	*300.00 FL
20	1		*DAMPER (RIGHT)	Punctured	220.00 F	*220.00 FL
21	1		*EXHAUST PIPE	Dented	700.00 F	*700.00 FL
22	1		*FRONT MUDGUARD (L)	Repair	250.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,581.00</b>	<b>4,231.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>380.10</b>
<b>Total Parts (\$\$)</b>	<b>5,581.00</b>	<b>3,850.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	30.00	25.00
2	LABOUR	New	350.00	200.00
Gross Labour Cost (\$\$)			<b>380.00</b>	<b>225.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >