

ASS. REC. BY:

REF

CS3/FWD/8013080/Gz4d3e2

Special instruction:

Surveyor
• meinen

Guo Qiang
Jesey Toh

ASSIGNMENT (Office)

From (Person):

of FWD

Date/Time: 18/7/18 @ 10.20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 9860E

Insured:

SBG 7646 F

at Workshop m/s

Sunday Plus Auto

Tel:

6451 4933

of

Blk 4003, Amk Ind. Park 1 Ave 10 # 01-116/118

Policy No:

Claim No:

1201800609027

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14107118

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11.29am @ 18/7/18

Person Contacted:

Mrs. Yeo

Vehicle IN/OUT

Date/Time

Action/Instruction

(x) Estimate

SGG 9860E-X

8BG 7646 E-X

08/11/18
GUYANA

PRS
XPR

REF: RWD

245J ✓
(-2021)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Sunday Plus Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$18K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGG9860E Yr Regn: 26 May 2006

Type: ☒ M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 145138 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EC107/20341

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Air / or

Tyre Size: F: 225/70R14

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 18-07-18

Survey held at W/S 12:30pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>
<u>9/7/18</u>	<u>Submit PRS Report.</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS. _____ SI

Photos _____

Others _____

TOTAL

80

80

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Wednesday, 18 July 2018 10:20 AM
To: sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Our ref: LCH.jp/AMK05-80641.18 Your ref: SBG 7646 E (1201800009027) - Accident involving SGG 9860 E / SBG 7646 E (FWD) on 14/7/18 along the junction of Ang Mo Kio Ave 3 / Ang Mo Kio Industrial Park 2 - Pre-repair survey ("PRS") of SGG 9860 E
Attachments: 80641 (our ltr dd 17718 enc client's report).pdf; 80641 (our ltr dd 17718 - PRS).pdf

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is TP GIA report.

Please create the case in Merimen.

Thank you.

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Motor Claims SG - SG Common
Sent: Wednesday, 18 July, 2018 9:03 AM
To: 'Cheonghoh Law'
Cc: Motor Claims SG - SG Common
Subject: RE: Our ref: LCH.jp/AMK05-80641.18 Your ref: SBG 7646 E (1201800009027) - Accident involving SGG 9860 E / SBG 7646 E (FWD) on 14/7/18 along the junction of Ang Mo Kio Ave 3 / Ang Mo Kio Industrial Park 2 - Pre-repair survey ("PRS") of SGG 9860 E

WITHOUT PREJUDICE

Dear Jennifer,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SGG9860E. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Tuesday, 17 July, 2018 6:11 PM

To: Motor Claims SG - SG Common

Subject: Re: Our ref: LCH.jp/AMK05-80641.18 Your ref: SBG 7646 E (PNPV2018-00007920) - Accident involving SGG 9860 E / SBG 7646 E (FWD) on 14/7/18 along the junction of Ang Mo Kio Ave 3 / Ang Mo Kio Industrial Park 2 - Pre-repair survey ("PRS") of SGG 9860 E

URGENT

Dear Sirs

Kindly see attached our letter dated 17 July 2018 for your attention.

Thank you.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 17 Jul 2018, at 13:00, motorclaims.sg@fwd.com wrote:

WITHOUT PREJUDICE

Dear Jennifer,

We refer to your letter dated 17 July 2018 of the PRI Notice of your client's vehicle SGG9860E.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards
Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

<image001.png>

<image002.jpg>

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Tuesday, 17 July, 2018 12:17 PM
To: Motor Claims SG - SG Common
Subject: Re: Our ref: LCH.jp/AMK05-80641.18 Your ref: SBG 7646 E - Accident involving SGG 9860 E /

URGENT

Dear Sirs

Kindly see attached our letter dated 17 July 2018 - Notice of Accident and enclosing a copy of our client's report for your attention.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Cheonghoh

Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.jp/AMK05-80641.18
Your Ref: SBG 7646 E

17 July 2018

URGENT

FWD Singapore Pte Ltd
6 Temasek Boulevard
Suntec Tower 4 #18-01
Singapore 408868
Attn: Josey Loh

BY EMAIL ONLY
Fax No: 67275799

Dear Sirs

ACCIDENT INVOLVING VEHICLES NO SGG 9860 E AND SBG 7646 E ON 14 JULY 2018 AT/ALONG JUNCTION OF ANG MO KIO AVENUE 3 / ANG MO KIO INDUSTRIAL PARK 2 -

We refer to the above matter and to your e-mail of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows :-

- (1) Lee Kok Weng
- (2) Patrick Ng Kong Beng
- (3) Ang Guea Kiang
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly liaise with our client's repairer workshop for arrangement of the pre-repair survey ("PRS") of our client's vehicle no. SGG 9860 E as follows :-

Sunday Plus Auto Computerised Service Centre Pte Ltd
Blk 4003 Ang Mo Kio Industrial Park 1 Ave 10 #01-116/118
Singapore 569624

Contact : Mrs Yeo (tel: 64514933 / 64514261

Yours faithfully



Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (SGG 9860 E)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD18013080/Gz4d3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 18-07-2018	
			Code : FWD	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SBG 7646E		Veh. Inspected	SGG 9860E
Policy No.			Coverage (\$)	0.00
Claim No.	1201800009027		Excess (\$)	0.00
Assign From	JOSEY LOH		Assign Date	18/07/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/07/2018		Inspection Date	18/07/2018
Survey held at	SUNDAY PLUS AUTO COMPUTERISED SERVICE CENTRE PTE LTD BLK 4003 ANG MO KIO IND. PARK 1 #01-118 AVE 10, SINGAPORE 569624			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 17:28
Date Of Accident	14/07/2018 17:00
Exact Location Of Accident	ALONG ANG MO KIO AVE 3 JUNCTION OF AMK IND PK 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG9860E
Insured/Policyholder	
Name Of Registered Owner	TOK CHOON BOON
NRIC No	S7732195J
Email Address	BLOCK615@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91771454
Alternative Phone No	OFFICE-91771454

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10668227
Cover Note Number	

Driver

Name of Driver	GOH KUI KHENG ESTHER
NRIC No	S7900284D
Date Of Birth	10/01/1979
Occupation	INDOOR
Date Of Driving Pass	30/06/2000
Driving Experience	18 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97873570
Fax Number	
Contact Number	
EEmail Address	GOH_ESTHER@YAHOO.COM.SG

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TOK CHOON BOON GENDER: : MALE
Passenger 2	NAME: : TOK EN ZHI ADELA GENDER: : FEMALE
Passenger 3	NAME: : TOK ZHAN XU JULIUS GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 14 JULY 2018 @ 5.10PM, I STOPPED MY VEHICLE SGG9860E AT THE T- JUNCTION AT ANG MO KIO INDUSTRIAL PARK 2 & ANG MO KIO AVE 3. WHEN THE TRAFFIC LIGHT TURNED AMBER. SUDDENLY I FELT A STRONG IMPACT FROM THE REAR. A VEHICLE SBG7646E HAS CRASHED IN TO MY VEHICLE CAUSING SERIOUS DAMAGE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBG7646E
Vehicle Make/Model/Colour	TOYOTA/ STARLET XL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WU YOUHONG EDWIN
NRIC/Passport Number	S8804144E

Contact Number	81394322
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2

Date of accident: 14/7/2018 Time: 5:10 pm Location: T-junction (Ang Mo Kio Ave 3 & Ang Mo Kio Industrial Park 2)
 My Vehicle A: SG9 9310E Vehicle B: SG 7646E Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14 July 2018 @ 5:10pm, I stopped my vehicle SG9 9310E at the T-junction at Ang Mo Kio Industrial Park 2 & Ang Mo Kio Ave 3 when the traffic light turned amber. Suddenly, I felt a strong impact from the rear. A vehicle SG 7646E has crashed into my vehicle causing serious damage.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Qinley pwsawo

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's signature

Date & Time:

Driver's signature

(if driver is not the policyholder)

Reporting Centre Personnel's signature

Name:

Email Attachment Pg. 1

Elizabeth Lee

From: Esther Goh <goh_esther@yahoo.com.sg>
Sent: Tuesday, 17 July 2018 9:33 AM
To: group@ajaxmars.com
Subject: Fwd: GIA Report - SGG9860E
Attachments: GIA Report - SGG9860E.PDF; Untitled attachment 00096.html

Hi

Can you change the time of accident to 5pm? Same date of 14 July 2018.

Please edit the report to reflect under Details of Own Vehicle section - email address of Registered Owner: block615@yahoo.com
Mobile phone no. of Registered Owner: +65 9177 1454

Please send the updated report so that I can forward to workshop

Thanks
Esther

Begin forwarded message:

From: "Ben" <ben@ajaxmars.com>
Date: 16 July 2018 at 5:37:49 PM SGT
To: <goh_esther@yahoo.com.sg>
Subject: GIA Report - SGG9860E

Dear Sir/Madam,

Please find attached file, the GIA Accident Report for your perusal.

Kindly ignore, If you find the statement, 'Your NCD will be affected due to late reporting' found on the right top corner of the report.

The date and time of your call to Mobile Accident Response Service (MARS) will be taken as the time you reported your accident to the insurer which is within 24 hours from the time of accident as required under the Motor Claims Framework (MCF).

If you require any further clarification on the matter, please do not hesitate to contact us at 6333 2222.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2195J

Vehicle Details

Vehicle No.:	SGG9860E
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Gold
Manufacturing Year:	2006
Engine No.:	3ZZ4567243
Chassis No.:	MR053ZEC107120341
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	26 May 2006
First Registration Date:	26 May 2006
Transfer Count:	1
Actual ARF Paid:	\$17,545.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$12,987.00
Total Rebate Amount:	\$12,987.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Wu Youhong Edwin , ID: S8804144E									
Main Claimant: TOK CHOON BOON , ID: S7732195J									
Vehicle Reg. No.: SGG9860E		Date of Loss: 14/07/2018 17:00 - :59 [145 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201800009027		Policy/Cover Note No.: PNPV2018-00007920 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): SBG7646E		Policy No. (Claimant):							
		Excess:							
Repairer: Sunday Plus Auto Computerised Services Centre Pte Ltd (HQ) BLK 4003 ANG MO KIO INDUSTRIAL PARK 1 AVE 10, #01-116/118, 569624 Ang Mo Kio - Tel: 64514933/64514261									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGG9860E (1201800009027)

[SBG7646E]






































TP
















TOK CHOON BOON

Jul 14 2018 5:00PM

[Wu Youhong Edwin]

Sunday Plus Auto Computerised Services Centre Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/07/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/07/18 16:33	Insured GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18013080/GZ4D3E2

Date: 20/07/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00007920
 Claimant Vehicle No: SGG9860E Insured Vehicle No: SBG7646E
 Date of Loss: 14/07/2018 Nature of Claim: TP Claim No: 1201800009027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG9860E
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4567243
 Reg. Date: 26/05/2006 (Man. Year: 2006) Chassis No: MR053ZEC107120341
 Colour: Gold Odometer: 145138 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R14 Rear Tyre Size: 275/70 R14
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/07/2018
 Date Inspected: 18/07/2018 Inspected At: Sunday Plus Auto Computerised Services
 Centre Pte Ltd (HQ)
 BLK 4003 ANG MO KIO INDUSTRIAL
 PARK 1 AVE 10, #01-116/118
 Singapore 569624
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGG9860E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >