

(55021)

INS. CASE OWNER:

CC 4/EQ1801

3081

LKK:

IDAC:

Surveyor:

KAMATH

DOI:

ASSIGNMENT

20/05/18

Date / Time

18/7/18

Registered in Meriteri:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 8258T

Name of Insured:

FELLY MAMU

Insured Tel No.:

HP: 8518 518

Excess Sec II :\$5

D.O.A.:

11/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

PMPM 213-004278

BMW

WOODLAND CHTOM

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SDX 6172X

INSRS:
WSP:
Tel:
Liability:
RMKS:

LH HUAT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

18/7/18

VIC

08/08/18

21/08/18

5:30PM

6/10/18

08/11/18

20/03/2020

SDX 6172X -X

SLB 8258T -X

- TP VIDEO IN. V DRIVE / OIL / OIL OIL

- WI LK YAW. OI GYM WORK LKUB.

- SHOWS TO OI CONFIRMED & ACCIDENT

DAMAGE. INFORMATION FULL OF TP CLAIM.

OI UNDERSTOOD THE WHO NOT AT FAULT.

HE IS ALSO WORKING A TP CLAIM.

NO OFFER FOR. HE WILL FORWARDED

COPY OF HIS VIDEO BY WHISTLER.

- BE AFTER LKUBAT @ 80% FOUND

- OFFER TO SUNDAY GYM, ACCIDENT ON

CHURCH

- OI PHOTOS & VIDEO IN.

- V DRIVE / OIL / OIL OIL

- PINKUBAT.

- ORIGINAL TP LOP IN.

- GROUND FOR OFFER TO TP

- TP ACCEPTED OFFER.

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 29/08/2018 Sent By: LB

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PLP

SS

644.25

(2 days)

Reduction:

23

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/03/2020

Confirm with:

JENNY

Email

Call

Final Liability:

%

80

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28. Ass. Lia:

Repair Cost (w/GR)

SS

689.25

- \$501.18

Loss of Rental (LOR):

SS

400.00

(4 days)

x \$100

= \$400.00

Loss of Use (LOU):

SS

-

(5 x days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

1,091.35

Global Sum SS:

870.00

FINAL PAYMENT

Date/Time:

20/03/2020

Confirm with:

JENNY

Email

Call

Payee 1:

SS

870.00

Name 1:

LH HUAT

(LHUB KEB)

MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

-

COPY SENT

23/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4400.00

06
26/5/20
EW

ASS. REC. BY:

REF:

EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDX 6173X Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra cc 1591

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading 23488 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM140841CMTU 45989

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/7/18

Survey held at 28/8/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8 File pass to Catherine

P/P \$644.75

CRAB: \$199.20 (23%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18013081/hb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 18-07-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 8258T	Veh. Inspected	SDX 6173T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/07/2018	Inspection Date		
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118013081/Khb3

Date: 29.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SDX6173X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.08.2018 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	843.45
Revised Estimate Amount	: S\$	615.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019812
Zuraimi Bin Ali

Page 1 of 1
Your ref TP-SLB 8258T EQ
Job No. 69652
Our ref 18.07.17
Payment
Date 18/7/2018

Attn

Vehicle No SDX 5173X
Vehicle Model Hyundai Elantra
Accident on 11/7/2018

*Not Withdraw
Resurvey B4 paint
2 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts					
1.00	Pc	Front bumper	195.00		195.00 ✓
1.00	Pc	Front bumper side retainer RH	8.00		8.00 X
Total amount of parts supplied - S\$203.00					
1.00		15% of parts supplied	30.45		30.45
Labour & Misc					
1.00		To check wheel alignment	60.00		60.00 X
1.00		To remove and renew above parts	300.00		300.00 200
1.00		To spray paint	250.00		250.00 220

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和快速修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Nivitha (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 18 July 2018 11:35 AM
To: 'assignments'
Cc: Admin A
Subject: DM18HO01755/JT: Third Party Claim - Your Ref: SLB 8258T / Our Ref: SDX 6173X (Date of Accident: 11 Jul 2018)
Attachments: SDX 6173X.pdf; SAS2437444.PDF

11.44 am @ 18/7/18
person @ jenny
vehicle not in

Dear all,

Please arrange to attend the PRS.

We can agree on liability at 80% down on OI.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Wednesday, July 18, 2018 10:18 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: Third Party Claim - Your Ref: SLB 8258T / Our Ref: SDX 6173X (Date of Accident: 11 Jul 2018)

Dear Sir

We refer to the above matter.

Please can you arrange for survey of our client's vehicle no. SDX 6173X?

Please advise officer-in-charge and confirm whether liability is in our client's favour?

Supporting documents are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim

For: AI HUAT (MENG KEE) MOTOR PTE LTD
60 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Report Remarks Entry - CC4/EQI18013081/Kwb3

Remarks

Remarks

Add

Remarks 1	By	On
☐ SDX 6173T ; SLB 8258T	LSP	18/7/2018 4:16:33 PM
☐ EST :\$843.45 --- SUR :KSC ---WKSP : LAI HUAT (MENG KEE) MOTOR PTE LTD	LSP	29/8/2018 4:05:54 PM
☐ FILE PASS TO VIC	LSP	19/7/2018 9:44:41 AM
☐ PENDING SURVEY	LSP	19/7/2018 9:44:46 AM
☐ 010818 EMAIL: Dear Sir We refer to the above matter. Please find below the link for the video footage: https://www.dropbox.com/s/ri0x894nv4t6fdj/FNKP8117.MP4?dl=0 Please can you confirm whether liability is in our client's favour? Thank you. Kind regards. Jenny Lim for LAI HUAT (MENG KEE) MOTOR PTE LTD 160 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autocity Singapore 575722 Tel: 64538110 Fax: 64596267	VAS	1/8/2018 1:04:47 PM
☐ ***TP VIDEO FOOTAGE IN. SAVED IN V DRIVE / VIC / SDX 6173T	VAS	1/8/2018 1:05:05 PM
☐ 010818 EMAIL: Without Prejudice Dear Jenny, Received with thanks. We will get back to you for an update in due course.	VAS	1/8/2018 1:07:57 PM
☐ Dear all, Please arrange to attend the PRS. We can agree on liability at 80% down on OI. Regards, Janet Tan Senior Executive Claims EQ Insurance Company Limited	LSP	30/8/2018 9:07:18 AM
☐ ESTIMATE & SURVEYOR ASSGNMENT PAPER PASS TO HANDLER	LSP	30/8/2018 8:46:11 PM
☐ 210818@5:50PM Spoke to OI Mr Keng Wong at 85182518. OI confirmed accident details. Informed him of TP claim. OI insisted he was not at fault. He got video footage and he already forwarded to his reporting centre. Send letter to OI to notify TP claim and NCD issues.-Vic	VAS	31/8/2018 2:48:46 PM
☐ (80%BNIL)	VAS	31/8/2018 2:48:53 PM
☐ ***OI VIDEO IN, V DRIVE / VIC / SLB 8258T	VAS	31/8/2018 3:07:15 PM
☐ ***PENDING COR FINALIZATION	VAS	31/8/2018 3:07:30 PM
☐ 310818 EMAIL: Hi Vic, I am claiming against the other for damages and repair. As I had been busy with my work and travelling overseas, I had not probably appointed a garage to evaluate for me. I will get my garage to make contact with you shortly on the matter. Regards. Keng Wong H/P: (+65) 85182518	VAS	31/8/2018 3:07:53 PM
☐ REC'D TP SIGNED LOD***PASS TO VIC	STU	6/5/2019 11:02:54

			AM
☐	060619 File transferred to Vivian to handle.-Vic	VAS	6/6/2019 3:34:40 PM
☐	***TO SEND OFFER	VAS	6/6/2019 3:35:47 PM



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 06/04/2020

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLB 8258T (Insd Veh)	Your Ref. No. : DM18HO01755/JT
	SDX 6173X (TP Veh)	Our Ref. No. : CC4/EQ118013081/Kha3q2
Date of Accident	11/7/2018	

Liability	80%	
Final Repair Cost	: \$ 689.35	
Loss of Use	: \$	days
Rental (If any)	: \$ 400.00	4 days
Others:	: \$ 2.00	
	: \$	
	1,091.35	
Final Settlement Sum	: \$ 870.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	LAI HUAT (MENG KEE) MOTOR PTE LTD	: \$ 870.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18013081/Kha3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 06-04-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 8258T	Veh. Inspected	SDX 6173X	
Policy No.	DMPPHQ17-004378	Coverage (\$)	0.00	
Claim No.	DM18HO01755/JT	Excess (\$)	0.00	
Assign From	JANET	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMHU459891	Colour	METALLIC RED	
Odometer	23488	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	8 mm	
L/H Front Tyre	205/55 R16	KUMHO	8 mm	
R/H Rear Tyre	205/55 R16	KUMHO	8 mm	
L/H Rear Tyre	205/55 R16	KUMHO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/07/2018	Inspection Date	28/08/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 6173X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	BROKEN / CUT	195.00	195.00
1	FRONT BUMPER SIDE RETAINER RH (WCP)	SERVICEABLE	8.00	-
	COST PLUS 15%		30.45	29.25
			233.45	224.25
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	TO REMOVE AND RENEW ABOVE PARTS.		300.00	200.00
	TO SPRAY PAINT.		250.00	220.00
			610.00	420.00
	GRAND TOTAL		843.45	644.25
RECOMMENDED COST OF REPAIRS				644.25

Report Ref No. CC4/EQ118013081/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.