

ASS. REC. BY:

REF

CS/SMO18013086/Tlqd3

n2

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person): Guel Teo

of

SMO

Date/Time: 18/7/18 @ 1:50pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 1882D

Insured:

XD 1222 P

at Workshop in/s:

HKL Lim Team

Tel:

6275 6656

of BIK 1008# 01-24 Bkt Meruh Lane 3

Policy No:

Claim No:

CMTD1802859 / NSW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/07/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:43pm @ 18/7/18

Person Contacted:

Mr. James

Vehicle

☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBG 1882D - NBA / INC 18012097 / Y

DOA: 02/07/18

XD 1222P - NBA / INC 18012097 / Y

DOA: 02/07/2018

13/7/18 @ 2:35pm - revised to Shawn Ng by email.

Tanpin

REF:

Atta Somp

ASSIGNMENT

31/8/2011

From:

Date:

1-1-2018

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

914K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBG 1882D

Yr Regn:

2011 Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW K1600 GTL

CC

1649

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp Reading

69949

T/Radio:

Insured / Std / NI / NA

Eng/No:

WB106020052215552

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size:

F:

120 / 70 R17

R:

190 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

detzler

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

18/7/18 01200

Survey held at

HK2

Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/1/19

Confirm with Mr. Keay → 4/54 3400, 6 days  
(Cred # 39850, 42/1)

RECEIVED 31 JAN 2019

Date/Time: File Pass to?

☐

: Preli. Report

31/1/19

☐

: Final Report

Date/Time: File Return to?

3)

Days Of Repair:

6

Resurvey No. of Trip:

Report Format:

Lump Sum / I.P. (\$) 3400

Add Fee:

☐

Site Insp (\$) 0

☐

Interview (\$) 0

☐

Tech. Insp (\$) 0

☐

Weekend (\$) 0

Survey Fee:

Transportation:

1 3 - PS or

2 Photo

3 Email

TOTAL

450



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18013086/T1qd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 18-07-2018



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1222P	Veh. Inspected	FBG 1882D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802859/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	18/07/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	02/07/2018	Inspection Date	18/07/2018
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802859/NSW

Date: 23<sup>th</sup> July 2018

Our Ref: CS/SMO18013086/T1qd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. FBG 1882D.**


We thank you for the instruction on 18/07/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/07/2018 at the premises of M/s HKL LIM TEAM and have the following to report:-

Workshop Estimate Amount	: S\$ <u>43,250.00</u>
Revised Estimate Amount	: S\$ <u>17,439.00</u>
"Check" Items Amount	: S\$ <u>1,044.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s & n/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 12 days.

We have NOT authorized repair.

Yours faithfully

Taufikh  
Automobile Assessor

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 18 July 2018 1:50 PM  
**To:** HKL Lim Team Motorsport (hklteam@gmail.com); admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James  
**Subject:** CMTD1802859/NSW - SUV(LKK/7)/ XD1222P & FBG1882D ACC on 02/07/2018  
**Attachments:** FBG1882D 6.jpg; FBG1882D 5.jpg; FBG1882D 1.jpg; FBG1882D 2.jpg; FBG1882D 3.jpg; FBG1882D 4.jpg

Our Claim Reference: CMTD1802859/NSW

Your Reference: FBG1882D

Hi James,

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

-----  
Aside to LKK AUTO/ Catherine,

Please make arrangement to conduct the survey for FBG1882D today.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** HKL Lim Team Motorsport [mailto:hklteam@gmail.com]  
**Sent:** Tuesday, July 17, 2018 12:59 PM  
**To:** Claims - Motor Survey  
**Subject:** FBG1882D / XD1222P on 02/07/2018 ARRANGE SURVEYOR

Hi to whom it may concern,

Do arrange surveyor for this case.

--

Thank You.

Best Regards

**James Lim ( Keong )**

Tel:+65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722  
Tel:+65 6275-6656, 6275-6566 Fax: 6272-9291

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 23 July 2018 3:35 PM  
**To:** 'Teo, Grace'; assignments; 'Shawn.Ngo@sompo.com.sg'  
**Cc:** 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1802859/NSW - SUV(LKK/7)/ XD1222P & FBG1882D ACC on 02/07/2018  
**Attachments:** CSSMO18013086T1qd3.pdf

Dear Shawn,

Enclosed herewith preliminary advice of FBG 1882D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 18 July 2018 2:46 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Ngo, Sau Wei Shawn' <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1802859/NSW - SUV(LKK/7)/ XD1222P & FBG1882D ACC on 02/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Wednesday, 18 July 2018 1:50 PM  
**To:** HKL Lim Team Motorsport ([hklteam@gmail.com](mailto:hklteam@gmail.com)) <[hklteam@gmail.com](mailto:hklteam@gmail.com)>; [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** CMTD1802859/NSW - SUV(LKK/7)/ XD1222P & FBG1882D ACC on 02/07/2018

Our Claim Reference: CMTD1802859/NSW

Your Reference: FBG1882D

Hi James,

Please be informed that we have appointed LKK AUTO to conduct the survey.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	0822G
<b>Vehicle Details</b>	
Vehicle No.:	FBG1882D
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	K1600GTL
Primary Colour:	Gold
Manufacturing Year:	2011
Engine No.:	166EA29118590
Chassis No.:	WB1060200BZZ15552
Maximum Power Output:	-
Open Market Value:	\$35,393.00
Original Registration Date:	31 Aug 2011
First Registration Date:	25 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$5,309.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Apr 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,924.00
COE Rebate Amount:	\$723.00
<b>Total Rebate Amount:</b>	<b>\$723.00</b>

The information contained herein is correct as at 20 Jul 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/07/2018 18:31
Date Of Accident	02/07/2018 17:40
Exact Location Of Accident	JURONG ROAD EXIT TO BUKIT BATOK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG1882D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG CHEE CHANG
NRIC No	S1540822G
Email Address	AIYOYO2010@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81230013
Alternative Phone No	OTHERS-81230013

### Vehicle Particulars

Manufacturer	BMW
Model	K1600GTL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5053863812-06
Cover Note Number	

### Driver

Name of Driver	ONG CHEE CHANG
NRIC No	S1540822G
Date Of Birth	21/05/1962
Occupation	INDOOR
Date Of Driving Pass	02/08/1993
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81230013
Fax Number	
Contact Number	OTHERS-81230013
EEmail Address	AIYOYO2010@YAHOO.COM

Address	BLK 124 PENDING ROAD #02-02
Postcode	670124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1222P
Vehicle Make/Model/Colour	TRAILER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PURA SINGH S/O CHAWDRY SINGH
NRIC/Passport Number	S1635341H
Contact Number	91021413
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF INJURED PERSON 1

Name	ONG CHEE CHANG
------	----------------

Approximate Age

Injuries Sustain

SLIGHT INJURY

Injured person in which vehicle?

FBG1882D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SCENE 1  
WHITE VAN, MYSELF & LARRY WERE AT THE  
JUNCTION SUP ROAD TOWARDS 3rd AVE BT BAYVIEW ROAD  
WHITE VAN MOVE OFF.

SCENE 2  
TRAILER MOVE TO EXTREME RIGHT EDGE OF EXIT  
MY BIKE (2ND) AFTER WHITE VAN MOVE-OFF WAS  
AT THE EXTREME LEFT EDGE OF THE EXIT TOWARDS  
BT BAYVIEW ROAD.  
WHEN TRAFFIC CLEAR, I MOVE OFF, SUDDENLY  
FROM NOWHERE THE TRAILER KNOCK ME OVER  
AT THE EDGE OF ROAD RESULTING IN THE INCIDENT.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

83 Acc 18712  
15286

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Birmingham's Signposts

Number

NISC/EIN No.



# HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722  
Email: support@hklimmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291  
Website: www.hklimmotorsport.com.sg

FBG1882D

- 1 FRONT FENDER
- 2 FRONT WHEEL RIM
- 3 FRONT WHEEL SHALF
- 4 FRONT BRAKE DISC LH
- 5 FRONT BRAKE PAD LH
- 6 SIDE MIRROR LH
- 7 HANDLEBAR
- 8 LOWER COWLING FRONT
- 9 LOWER COWLING REAR
- 10 SIDE PANEL CHROME LH
- 11 SIDE BOX INNER 2PCS
- 12 SIDE BOX OUTER 2PCS
- 13 SIDE BOX CHROME PANEL 2PCS
- 14 EXHAUST PIPE LH
- 15 EXHAUST GASKET 3PCS
- 16 FUEL PUMP
- 17 IGNITION COIL
- 18 ALARM SYSTEM
- 19 FOG LIGHT
- 20 FOG LIGHT BRACKET
- 21 CYLINDER HEAD
- 22 OVERHAUL GASKET
- 23 OVERHAUL GASKET SEAL
- 24 CRANKSHALF LH CASE + GASKET
- 25 CRANKSHALF LH CASE SCREWS 3PCS
- 26 CRANKCASE
- 27 TOWING
- 28 LABOUR

TOTAL

\$450.00 X an  
\$2,800.00 X n n  
\$380.00 cut  
\$980.00 R an  
\$180.00 X n n  
\$580.00 cut  
\$850.00 X h n  
\$550.00 X n n  
\$380.00 dl  
\$350.00 cut  
\$1,500.00 cut  
\$1,300.00 cut  
\$240.00 cut  
\$1,800.00 X n n  
\$45.00 X n n  
\$1,800.00 X n n  
\$2,280.00 X n n  
\$950.00 X n n  
\$450.00 cut  
\$120.00 b to  
\$7,800.00 X n n  
\$1,200.00 rect X n n  
\$250.00 rect X n n  
\$250.00 cut  
\$15.00 dl  
\$12,600.00 R n  
\$150.00 ✓  
\$3,000.00 1200300  
\$43,250.00

Paint - 4625  
10% - 3838.50  
SN - 150  
Labour - 300  
4288.50  
4383400  
6 days

Tanjim 97455149  
WP 18/7/18 @ 1700

\* Re survey new parts  
Su @ 11kamb.com  
12 days  
23/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



# BIKEBULANCE

90, Yuan Ching Road #03-38 S(618646)  
Tel: 6425-5333 96880928  
Email: bikebulance@yahoo.com  
MOTORCYCLE / SCOOTER Haulage Company

- ☐ DELIVERY ORDER  
☒ CASH SALE  
☐ INVOICE

NO : 16152

RE : GTL 1600

DATE : 2/7/18

CH/1: BG1882D

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1		Tony Batale-	\$	\$ \$150
2		tree	\$	\$
3			\$	\$
4			\$	\$
5			\$	\$
Total				\$ 150

50% of quoted Price or min \$20 (which ever is higher) is liable for cancellation of booking (Not For Contract Basis)

注意: 本公司對所拖的電單車, 在拖運中如有任何損壞, 一概由車主自行負責

E & OE

NOTE: Vehicle is hauled at owner's risk. The Company accepts no responsibility for damages or other misdemeanor to your vehicle whilst being towed

YM 2E ☐ YM3C ☐ GY 2E ☐ GBB 2K ☐ GZ 2320T ☐ GBB4376E ☐ Other ☐

Issued By

Customer's Signature & Chop

bulance Is The Solution To Your Motorcycle / Scooter Conveying Needs (Local & West Malaysia)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18013086/T1qd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 01-02-2019



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1222P	Veh. Inspected	FBG 1882D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802859/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	18/07/2018

### 2. Vehicle Particulars & Condition

Make & Model	BMW K1600 GTL	c.c	1649
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WB1060200BZZ15552	Colour	SILVER
Odometer	69949	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	METZELER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55 R17	METZELER	5 mm
L/H Rear Tyre			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/07/2018	Inspection Date	18/07/2018
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 1882D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	NOT NECESSARY	450.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	2,800.00	-
1	FRONT WHEEL SHALF	CUT	380.00	380.00
1	FRONT BRAKE DISC LH	NOT NECESSARY	980.00	-
1	FRONT BRAKE PAD LH	NOT NECESSARY	180.00	-
1	SIDE MIRROR LH	CUT	580.00	580.00
1	HANDLEBAR	NOT NECESSARY	850.00	-
1	LOWER COWLING FRONT	NOT NECESSARY	550.00	-
1	LOWER COWLING REAR	DEFORMED	380.00	380.00
1	SIDE PANEL CHROME LH	CRACKED	350.00	350.00
2	SIDE BOX INNER	CUT	1,500.00	1,500.00
2	SIDE BOX OUTER	NOT NECESSARY	1,300.00	-
2	SIDE BOX CHROME PANEL	CUT	240.00	240.00
1	EXHAUST PIPE LH	NOT NECESSARY	1,800.00	-
3	EXHAUST GASKET	NOT NECESSARY	45.00	-
1	FUEL PUMP	NOT NECESSARY	1,800.00	-
1	IGNITION COIL	NOT NECESSARY	2,280.00	-
1	ALARM SYSTEM	NOT NECESSARY	950.00	-
1	FOG LIGHT	CRACKED	450.00	450.00
1	FOG LIGHT BRACKET	BENT	120.00	120.00
1	CYLINDER HEAD	NOT NECESSARY	7,800.00	-
1	OVERHAUL GASKET	NOT NECESSARY	1,200.00	-
1	OVERHAUL GASKET SEAL	NOT NECESSARY	250.00	-
1	CRANKSHALF LH CASE + GASKET	CRACKED	250.00	250.00
3	CRANKSHALF LH CASE SCREWS	DENTED	15.00	15.00
1	CRANKCASE	TO REPAIR SEE LABOUR	12,600.00	-
	LESS 10% DISCOUNT		-	-426.50
			40,100.00	3,838.50
<b><u>LABOUR</u></b>				
	TOWING.		150.00	150.00
	LABOUR.INCLUSIVE OF THE REPAIR OF CRANKCASE.		3,000.00	300.00
			3,150.00	450.00

Report Ref No. CS/SMO18013086/T1qd3n2



GRAND TOTAL		43,250.00	4,288.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,400.00

Report Ref No. CS/SMO18013086/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.