

SS. REC. BY:

REF: CS/MSG18013113/Gtd3n2 Special Instruction:

Survivor  
Menmen

GHO Qdnd

## ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSG

Date/Time: 19/7/18 @ 9.22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 48012

Insured:

SKK 8839G

at Workshop m/s

Chew Qoon Motor

Tel:

6484 1626

of

Bik 10, AMK Ind. park 2A #01-15/16

Policy No:

27684567 QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time:

9:30am @ 19/7/18

Person Contacted:

Sam

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJG 48012 - CV/DBS08028965/FKq

DOA: -

SKK 8839G - X

23/7

Revert via menmen.

lump sum \$11007 Cred: 1346.50; 440/10)

Xarl.

REF: MS16

71628

C-2023)

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

chew Goon Motor

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$27K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIG480R

Yr Regn:

01 Jul 2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AX10

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

231565

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NZE 1416087802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 55 R 15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19-07-18

Survey held at

WKS

4:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 29 NOV 2018

*[Signature]*  
28/11/2018

Date/Time, File Pass to?

28/11/2018



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

150

Transportation:

10

\$ + RS. SI

Photos

Others

TOTAL

160

Report Format :

TP

Lump Sum / I.B.I. (\$)

1700+



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18013113/Gtd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 19-07-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKK 8839G	Veh. Inspected	SJG 4801Z	
Policy No.	27684567QMY	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	19/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	16/07/2018	Inspection Date	19/07/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 23 Jul 2018

**Preliminary Advice**

Insured Vehicle No	: SKK8839G	Accident Date	: 16/07/2018
TP Vehicle No	: SJG4801Z	Assignment Date	: 19/07/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 3.00
Date of Inspection	: 19/07/2018		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,046.50
Revised Amount	:S\$	2,466.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,466.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018		19 Jul 2018 09:22 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SION KEE HO FON SING, ID: S2206230A		
Main Claimant:	NG KOK CHIN, ID: S1807162B		
Vehicle Reg. No.:	SJG4801Z	Date of Loss:	16/07/2018 00:00 - :59 [120 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27684567QMY (Comprehensive) Coverage: 14/05/2018 - 13/05/2019
Vehicle Reg. No. (Insured):	SKK8839G	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/07/2018]		
Adj Asg. Remarks:	OI not reported SJE agree - LKK Contact : Sam at 6848 1626		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAUTO)

---

**From:** Chew Goon Motor(ad3) <ad3@chewgoonmotor.com.sg>  
**Sent:** Tuesday, 27 November 2018 4:36 PM  
**To:** Denise Tay (LKKAUTO)  
**Cc:** chewgoon@singnet.com.sg  
**Subject:** RE: SJG 4801Z / TP / MSIG / DOA: 16/07/2018

Dear Denise,

Confirm L/S amount \$1700 and 3 working days.

Thanks & Regards,  
Grace

Chew Goon Motor  
Blk 10, Ang Mo Kio Ind Park 2A,  
Ave 5 #01-15, 16 & 17,  
Ang Mo Kio Autopoint  
Singapore 568047  
Tel : 6484 1626  
Fax : 6484 0465

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 30 October 2018 2:32 PM  
**To:** Chew Goon Motor(ad3)  
**Cc:** chewgoon@singnet.com.sg  
**Subject:** RE: SJG 4801Z / TP / MSIG / DOA: 16/07/2018

Dear Grace,

Please consider at lump sum \$1700, headlamp remains as \$640

Any confirmation

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 16 October 2018 10:47 AM  
**To:** 'Chew Goon Motor(ad3)' <ad3@chewgoonmotor.com.sg>  
**Cc:** 'chewgoon@singnet.com.sg' <chewgoon@singnet.com.sg>  
**Subject:** RE: SJG 4801Z / TP / MSIG / DOA: 16/07/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/07/2018 13:54
Date Of Accident	16/07/2018 16:15
Exact Location Of Accident	CAIRNHILL MANSIONS CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG4801Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG KOK CHIN
NRIC No	S1807162B
Email Address	KCNG854@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97961779
Alternative Phone No	OFFICE-97961779

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO 1.5X A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101035380
Cover Note Number	

### Driver

Name of Driver	NG KOK CHIN
NRIC No	S1807162B
Date Of Birth	09/08/1967
Occupation	OUTDOOR
Date Of Driving Pass	06/09/1988
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97961779
Fax Number	
Contact Number	OFFICE-97961779
EEmail Address	KCNG854@YAHOO.COM

Address	BLK 319 SERANGOON AVE 2 #08-366
Postcode	550319
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 16 JULY 2018 ABOUT 1615HRS, I GO TO CAIRNHILL MANSIONS CAR PARK TO PICK UP PASSENGER, THE CAR IN FRONT OF ME REVERSE INTO THE CAR PARK AND KNOCK ONTO MY CAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK8839G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN



A - SJ648018  
B - SKK 88396

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16 Jul about 4:15pm, I go to Cairnhill Mansions car park to pick up passengers. The car in front of me reverse into the car park and knock onto my car.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1807162B



Name: NG KOK CHIN  
 黄国勤  
 Race: CHINESE  
 Date of Birth: 09-08-1967 Sex: M  
 Country of Birth: SINGAPORE

S1807162B

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S1807162B  
 Name: NG KOK CHIN  
 Birth Date: 09 Aug 1967  
 Issue Date: 13 Apr 2004

001194414C

0469535



NRIC No. S1807162B



Blood Group: O+ Date of Issue: 13-08-1992


APT. BLK 319 SERANGOON AVENUE 2 #08-366  
 SINGAPORE 550319  
 NRIC No: S1807162B Date: 12-11-2006 No: 5594001

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	06 Sep 1988

NP 428A

Licence No: S1807162B



## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number :** 5101035380

**Cover :** Comprehensive

- |   |                 |
|---|-----------------|
| 1. Index mark and Registration Number of Vehicle  | : SJG4801Z      |
| Chassis Number  | : NZE1416087802 |
| 2. Name of Policyholder   | : NG KOK CHIN   |
| 3. Effective Date of Insurance  | : 04 Jun 2018   |
| 4. Expiry Date of Insurance   | : 03 Jun 2019   |
| 5. Persons or Classes of Persons entitled to drive#   |                 |
| (a) The Policyholder.   |                 |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.   |                 |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                 |
| 6. Limitations as to Use#   |                 |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.  |                 |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's or Hirer's business.  |                 |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$2,000
WINDSCREEN EXCESS	: S\$100
INSURE WITH COE	: YES
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : GRABCAR PTE. LTD. (00000601726)  
Date of Issue : 28 May 2018 13:11 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7162B

### Vehicle Details

Vehicle No.: SJG4801Z  
Vehicle to be Exported: No  
Intended De-registration Date: 17 Jul 2018  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA AXIO 1.5X A  
Primary Colour: Grey  
Manufacturing Year: 2008  
Engine No.: 1NZD107973  
Chassis No.: NZE1416087802  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$12,471.00  
Original Registration Date: 01 Jul 2008  
First Registration Date: 01 Jul 2008  
Transfer Count: 1  
Actual ARF Paid: \$12,471.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 Jun 2023  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$19,107.00  
COE Rebate Amount: \$18,926.00  
**Total Rebate Amount: \$18,926.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jul 2018

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7162B
Vehicle Details	
Vehicle No.:	SJG4801Z
Vehicle to be Exported:	No
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZD107973
Chassis No.:	NZE1416087802
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,471.00
Original Registration Date:	01 Jul 2008
First Registration Date:	01 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$12,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,107.00
COE Rebate Amount:	\$18,894.00
<b>Total Rebate Amount:</b>	<b>\$18,894.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Jul 2018

OK

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Policy No.

18.07.2018

Accident Date : 16.07.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Axio" Reg. No. SJG4801Z Claiming Against Your Insured Veh. No. SKK8839G			
1pc	Front Bumper / BR	3.80	425.8 510.00 P
10pcs	Front Bumper Clips / MC		38.00 /
1pc	Front Bumper Reinforcement X NN		360.00 X
1pc	Front Bumper Corner Retainer RH / CC.		45 62.00 /
1pc	Front Bumper Sponge R / CFA		83.00 /
1pc	Grille / BR		340.7 396.00 P
1pc	Grille Emblem / MC		66 90.00
1pc	Brace Panel / BT		117.00 /
1pc	Headlamp Assy RH / BR.		640 906.00 P
			2,562.00
	Less 25%		640.50
		1755.5	1,921.50
1pc	Front Number Plate / CFA	25% 1316.63	40 45.00 SN
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		20 30.00
	Labour Charge - Panel Beating, Repairing Of Bonnet, Support Panel and Parts Replacement		300 450.00
	To Respray Affected Areas		450 600.00
		Total :	3,046.50
	3 Days. Unpsum Repair. After repair photos. Gmo Qiang - 82880282 19/8 7/18.		2126.63 20%: 1700



## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013113/GTD3N2

Date: 03/12/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27684567QMY
Claimant Vehicle No :	SJG4801Z	Insured Vehicle No :	SKK8839G
Date of Loss:	16/07/2018	Nature of Claim:	TP
		Claim No:	564810

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJG4801Z	Engine No:	1NZD107973
Make & Model:	TOYOTA COROLLA, 1.5 X AXIO (A)	Chassis No:	NZE1416087802
Reg. Date:	01/07/2008 (Man. Year: 2008)	Odometer:	231565 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,966.50	1,356.62	609.88	31.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	770.00	310.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,046.50</b>	<b>2,126.62</b>	<b>919.88</b>	<b>30.19</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,700.00</b>		
<b>(\$\$)</b>	<b>3,046.50</b>	<b>1,700.00</b>	<b>1,346.50</b>	<b>44.20</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>213.26</b>	<b>119.00</b>	<b>94.26</b>	<b>44.20</b>
<b>Nett Amount (\$\$)</b>	<b>3,259.76</b>	<b>1,819.00</b>	<b>1,440.76</b>	<b>44.20</b>

## INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 19/07/2018 Inspected At:

Chew Goon Motor (AMK)  
Blk 10 Ang Mo Kio Industrial Park 2A,  
#01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our



*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2018)
<b>Parts:</b> 143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJG4801Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	510.00 FL	*425.80 FL
2	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	360.00 FL	*- FL
4	1		*FRONT BUMPER CORNER RETAINER RH	Deformed	62.00 FL	*45.00 FL
5	1		*FRONT BUMPER SPONGE	Cracked	83.00 FL	*83.00 FL
6	1		*GRILLE	Broken	396.00 FL	*340.70 FL
7	1		*GRILLE EMBLEM	Necessary	90.00 FL	*66.00 FL
8	1		*BRACE PANEL	Bent	117.00 FL	*117.00 FL
9	1		*HEADLAMP ASSY RH	Broken	906.00 FL	*640.00 FL
10	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,607.00</b>	<b>1,795.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>640.50</b>	<b>438.88</b>
<b>Total Parts (S\$)</b>	<b>1,966.50</b>	<b>1,356.62</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT FRONT ELECTRICAL CHECK,LOCKING SYSTEM,ADJUST,FOCUS HEADLAMP ETC	New	30.00	20.00
2	LABOUR CHARGE-PANEL BEATING,REPAIRING OF BONNET,SUPPORT PANEL AND PARTS REPLACEMENT	New	450.00	300.00
3	TO RESPRAY AFFECTED AREAS	New	600.00	450.00
Gross Labour Cost (S\$)			1,080.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >