

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
SOMPO INSURANCE SINGAPORE PL Re				: CS/SMO18013120/T1vd3s2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date :	12-09-2018		
			Code:	SMO		
1. Policy Particulars :- THIRD PARTY CLAIM						
Ir	nsured Veh.	XD 2658J	Veh. Ir	nspected	FBJ 3478J	
P	Policy No.		Covera	age (\$)	0.00	
С	Claim No.	CMTD1803052/AGC	Exces	s (\$)	0.00	
A	Assign From	GRACE TEO	Assign	n Date	19/07/2018	
2. Vehicle Particulars & Condition						
N	/lake & Model	HONDA CB400	c.c		399	
E	Ingine No.	HIDDEN	Year o	f Reg.	2014	
C	Chassis No.	JH2NC4299BK300604	Colou	r	WHITE	
C	Odometer	-	Steerii	ng	IN ORDER	
В	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
G	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
R	R/H Front Tyre	120/60R17	BRIDGI	ESTONE	5 mm	
L	_/H Front Tyre				mm	
R	R/H Rear Tyre	170/50R17	BRIDGI	ESTONE	5 mm	
L	./H Rear Tyre				mm	
4.	Description of Damages					
T	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
A	Accident Date	10/07/2018	Inspec	tion Date	20/07/2018	
s	Survey held at	t BIKE PRODUCTION PTE LTD				
		610 SERANGOON ROAD SINGAPORE 218216				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
E	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					