



Surveys: Kelvin

## ASSIGNMENT

Veh No: SHC 57 69K Yr Regn: Aug 1 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Taxi~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai ZK0 C.O. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 540791 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: K 468414M E 9 057728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim of

N/S	O/S

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm R/Bal. 7 mm

L/Bal.  $\times$  mm L/Bal.  $\times$  mm

D.O.A. 17/7/68 D.O.I. 18/7/68

Survey held at CHE (Loyang)

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision,

Date / Time	Action / Instruction
	A24
	- PIP £70.00 (Rediff 1,038.44 / 11%)

☐: Prell. Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ Interview (\$)

Lump Sum / I.B.I: (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

Photos

Others

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18013131/K1fb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 19-07-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 2848H	Veh. Inspected	SHC 3769K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	17/07/2018	Inspection Date	18/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

[e-Services \(/content/policehubhome/homepage.html\)](#)[Log in ↗](#)

# Status of Driving Licence

## Qualified Driving Licence

<b>Qualified Driving Licence Number</b>	S6885618C
<b>Status of Qualified Driving Licence</b>	Valid
<b>Class(es) of Qualified Driving Licence</b>	3
<b>Expiry Date</b>	Valid for life unless revoked,suspended or disqualified

## Provisional Driving Licence

You are not a valid Provisional Driving Licence Holder.

[HOME \(https://www.police.gov.sg/\)](https://www.police.gov.sg/)  
[ABOUT US \(https://www.police.gov.sg/about-us\)](https://www.police.gov.sg/about-us)  
[SGSECURE \(https://www.police.gov.sg/sgsecure\)](https://www.police.gov.sg/sgsecure)  
[I-WITNESS \(https://www.police.gov.sg/iwitness\)](https://www.police.gov.sg/iwitness)  
[COMMUNITY PROGRAMMES \(https://www.police.gov.sg/community-programme\)](https://www.police.gov.sg/community-programme)  
[RESOURCES \(https://www.police.gov.sg/resources\)](https://www.police.gov.sg/resources)  
[NEWS & PUBLICATIONS \(https://www.police.gov.sg/news-and-publications\)](https://www.police.gov.sg/news-and-publications)  
[JOIN US \(https://www.police.gov.sg/join-us\)](https://www.police.gov.sg/join-us)  
[FAQS \(https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx\)](https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx)  
[CONTACT US \(https://www.police.gov.sg/content/contact-us\)](https://www.police.gov.sg/content/contact-us)  
[E-FEEDBACK \(/content/policehubfeedback/efeedback.html\)](/content/policehubfeedback/efeedback.html)  
[SITEMAP \(https://www.police.gov.sg/sitemap\)](https://www.police.gov.sg/sitemap)

[Privacy Statement \(https://www.police.gov.sg/content/privacy-statement\)](https://www.police.gov.sg/content/privacy-statement) | [Terms of Use \(https://www.police.gov.sg/content/terms-of-use\)](https://www.police.gov.sg/content/terms-of-use) .  
© 2018 Singapore Police Force. A Member of The Home Team (<https://www.mha.gov.sg>).

COMFORTDELGRO  
ENGINEERING

ComfortDelGro Engineering Pte Ltd

309 Bras Basah Road Singapore 179701  
Mainline - 65 65814280 Facsimile - 65 6580 9722  
Workshops  
29 Layard Drive Singapore 508988 24 Tanjong Lorong Singapore 756156  
283 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791  
41 Pandan Road Singapore 605256 501 Yishun Industrial Park A Singapore 768700  
210 Upper Road Singapore 969693


Member of COMFORTDELGRO

Date/Time: 17.07.2018 17:03 Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO: 305188974

MEMBER NO. 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)	REGN NO: SHC3769K	MILEAGE
	MAKE: HYUNDAI	FUEL E 1/2 F
	MODEL I-40	DATE/TIME IN 17.07.2018 14:50
	YR OF MANU 14.08.2014	TARGET DATE
	CHASSIS CODE KMHLB41UMEU057738	COMPLETION DATE/TIME

Accident Date: 17.07.2018  
NATURE: 3P 17.07.18  
JOB DESCRIPTION:

NO	LABOR CODE	DESCRIPTION
		

TO BE PASSED OUT BY:		CUSTOMER'S SIGNATURE	
SERVICE ADVISOR			
Document Slip	Exit Pass		
SHC3769K	LIMITS	Vehicle No:	SHC3769K
Service Advisor	Signature/Date	Name of Service Advisor	Date
To be kept by Security Guard			

Highway - 45  
LKR - Kalvin

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305188974  
REGN NO : SHC3769K  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 14.08.2014  
DATE/TIME IN : 17.07.2018 14:50  
ACCIDENT DATE : 17.07.2018

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0578-G	FRT BUMPER	1	562.30 20.00 449.84
0002	04-01-0103-0582-G	RADIATOR GRILLE	1	417.00 20.00 333.60
0003	FNPS	NO PLATE(S)w/Trim Cover	1 N	55.00 55.00

SUB-TOTAL : 838.44

## JOB NATURE

0000 L	PANEL BEATING	280.00	60
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	180

SUB-TOTAL : 480.00

TOTAL : 1,318.44

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

Link Any Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Kahr 10/1/14  
18/7/18 1005L  
20/7/18  
L/s  
After Repair

Our Job Ref No : 305188974

Date : 20/07/18

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No : SHC3769K

Date of Accident : 17-Jul-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG ASIA --- SLK2848H

2. The finalized amount shall be:

(a) Spare Parts after List discount NIL

(b) Labour Charges \$280.00

**Total for Part-By-Part Repair Cost \$280.00**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 23/7/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305188974  
REGN NO : SHC3769K  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 14.08.2014  
DATE/TIME IN : 17.07.2018 14:50  
ACCIDENT DATE : 17.07.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

SUB-TOTAL : 0.00

## JOB NATURE

0000 L PANEL BEATING 100.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 180.00

SUB-TOTAL : 280.00

TOTAL : 280.00

  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE : AUTHORIZED : YES / NO



## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Highway - 45  
LKK - Ka

L/s: 4220 00//

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO  
REGN NO  
MILEAGE  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 14.08.2014  
DATE/TIME IN : 17.07.2018 14:50  
ACCIDENT DATE : 17.07.2018

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0578-G	FRT BUMPER	1	562.30 20.00 449.84
0002	04-01-0103-0582-G	RADIATOR GRILLE	1	417.00 20.00 333.60
0003	FNPS	NO PLATE(S)w/Trim Cover	1 N	55.00 55.00

SUB-TOTAL : 838.44

## JOB NATURE

0000 L	PANEL BEATING	280.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00

SUB-TOTAL : 480.00

TOTAL : 1,318.44

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Kaka 10/11/14  
18/7/18 1005L  
2018  
L/s  
After Repair

LKK Auto Consultants hence notify the Repairer of the following :

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be allowed
- Supplemental work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Monday, 3 September 2018 5:18 PM  
**To:** 'Cecilia Lee Peng Geok'  
**Subject:** RE: offer; Our Ref: CC3/AIG18013131/K1fb3; Your Ref: T0718/SHC3769K/CL(st)  
**Attachments:** DV SHC 3769K.pdf  
**Importance:** High

### Without Prejudice

Our Ref: CC3/AIG18013131/K1fb3  
Your Ref: T0718/SHC3769K/CL(st)

Dear Cecilia,

Thank you for your acceptance.

Please duly sign the **DV** enclosed and return for payment processing.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Poh Kin (LKKAUTO)

---

**From:** Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>  
**Sent:** Thursday, 30 August 2018 3:56 PM  
**To:** Poh Kin (LKKAUTO)  
**Subject:** Re: offer; Our Ref: CC3/AIG18013131/K1fb3; Your Ref: T0718/SHC3769K/CL(st)

**Categories:** clear

Without Prejudice

Dear Sir/Madam

Strictly without admission of any liability and solely for quick amicable settlement, we confirm settlement at **\$640.00** for property damage only. Please note that the contents of this document apply to vehicle damages only. It is condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Please forward Discharge Voucher for execution and your cheque made payable to : COMFORTDELGRO ENGINEERING PTE LTD

Thank you.

Best Regards  
Cecilia Lee  
Claims Department | ComfortDelGro Engineering Pte Ltd  
Off: 6214 8354 | Fax: 6214 1843

---

**From:** Poh Kin (LKKAUTO) <pohkin@lkkauto.com>  
**Sent:** Thursday, 30 August 2018 3:01 PM  
**To:** Cecilia Lee Peng Geok  
**Subject:** offer; Our Ref: CC3/AIG18013131/K1fb3; Your Ref: T0718/SHC3769K/CL(st)

### Without Prejudice

Our Ref: CC3/AIG18013131/K1fb3  
Your Ref: T0718/SHC3769K/CL(st)

Dear Cecilia,

We refer to the above matter and your letter of demand dated 27<sup>th</sup> July 2018.

Towards an amicable settlement, we offer settlement at global sum of **\$640.00(all in):**

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 30 August 2018 3:02 PM  
**To:** 'Cecilia Lee Peng Geok'  
**Subject:** offer; Our Ref: CC3/AIG18013131/K1fb3; Your Ref: T0718/SHC3769K/CL(st)  
**Importance:** High

### Without Prejudice

Our Ref: CC3/AIG18013131/K1fb3  
Your Ref: T0718/SHC3769K/CL(st)

Dear Cecilia,

We refer to the above matter and your letter of demand dated 27<sup>th</sup> July 2018.

Towards an amicable settlement, we offer settlement at global sum of **\$640.00(all in)**:

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Our Ref : T 0718 / SHC3769K /CL(st)  
Your Ref:  
Date : 27-Jul-18

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**CHARTIS Building**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**Attn : Motor Claims Department WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC3769K YOUR INSURED SLK2848H**  
**AND OTHER ON 17.07.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHC3769K** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SLK2848H** we are submitting these claim for your consideration on behalf of the claimants.

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 299.60
2	3 days Loss of Rental @ \$ 119.28 per day	\$ 357.84
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
<b>Sub Total :</b>		<b>\$ 664.93</b>

#### HIRER'S CLAIM

7	3 days Loss of Income @ \$ 80.00 per days	\$ 240.00
<b>Total Claims :</b>		<b>\$ 904.93</b>

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 7 pcs.
- b) LTA search slip/s of : SLK2848H
- c) GIA / Police report/s of : SHC3769K
- d) Letter of authority from owner / hirer / operator
  - ( X ) Photograph/s of Accident Scene ( ) Certificate of Insurance
  - ( ) Witness statement/s ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

CDGE Taxi Claims Dept

59 Loyang Drive 4th Floor

Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506428K

Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

**Ubi**  
329 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758158

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

**Yishun**  
501 Yishun Industrial Park A  
Singapore 768732





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG18013131/K1fb3**

21<sup>st</sup> August 2018

**CHEN YOKE KEE**

Block 15 Marsiling Lane,  
#13-165,  
Singapore 730015.

Attn: Madam Low Choi Maie

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING SLK 2848H AND SHC 3769K ALONG  
LORONG 30 GEYLANG ROADSIDE PARALLEL PARKING ROAD ON 17.07.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the video footage and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong  
*Case Handler*

DID: 6841 2132

FAX: 6741 4108

Email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHC3769K , SLK2848H  
ALONG GEYLANG LOR 30

ON 17-Jul-18 13:15

I / We CHEW CHONG YEOW (Z... (Hirer) NRIC No.: S7441250E

and/or (Relief) NRIC No.:

Taxi Number SHC3769K

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date 17-Jul-2018

Name of Hirer CHEW CHONG YEOW (ZHOU ZONGYAO)  
Hirer NRIC S7441250E

Signature :



Address 122 MCNAIR ROAD #04-49  
320122

Contact No. 81254777



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 640.00 (Global Sum) for vehicle no. SHC 3769K that was damaged pursuant to the accident which occurred on 17/07/2018 (date) along GEYLANG LORONG 30 (location) involving vehicle no/s SLK 2848H.

This is pursuant to the inspection conducted on 18/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHC 3769K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 3769K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ (day) of 3 SEP 2018 (month) 20 (year)



Signed by appointed surveyor

CLAIMS DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
205 BRADDELL ROAD  
SINGAPORE 579701

Signed by "the workshop" (with chop).

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Please forward your cheque made payable to:-  
COMFORTDELGRO ENGINEERING PTE LTD

GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 1

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHC3769K

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
14.08.2014

CHASSIS CODE  
KMHLE41UMEU057738

INV. NO/DATE  
91385531 24.07.2018

JOB NO.  
305188974

ODOMETER READING

DATE/TIME IN  
17.07.2018 14:50

Description : 3P 17.07.18

S/No Part No.

Qty Unit Price %Disc Net

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0001 L PANEL BEATING 100.00 100.00

0002 23-502 SPRAYPAINT ON AFFECTED AREA 180.00 180.00

SUB-TOTAL : 280.00

Items total 280.00

Add GST @ 7.000 % 19.60

Invoice amount 299.60

1. WHEN TAKING ALL REASONABLE PRECAUTIONS AGAINST THE THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
2. CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY OR NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FROM THE PERIOD OF DEFAULT.
4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91385531	299.60	

## TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 2

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY CHARTIS BUILD  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHC3769K

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
14.08.2014

CHASSIS CODE  
KMHLB41UMEU057738

INV. NO/DATE  
91385531 24.07.2018

JOB NO.  
305188974

ODOMETER READING

DATE/TIME IN  
17.07.2018 14:50

Issued by : CHEWBEELING 24.07.2018 11:44:48  
Repair type : CLSO/57/57  
Payment Type/Term: /Credit 30 days

1. WHILE TAKING ALL REASONABLE PRECAUTIONS AGAINST THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS RISK.  
2. CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLE WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.  
3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (IE AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.  
4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91385531	299.60	

Our Ref: CT18070491

Date: 24 July 2018



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON                      17/07/2018    @   13:15 hrs  
ALONG                              GEYLANG LOR 30  
INVOLVING                      SLK2848H

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3769K** (the "Taxi"). The Taxi was hired to **CHEW CHONG YEOW (ZHOU ZONGYAO) IC NO S7441250E** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$119.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

3769K

[illegible]

**Enquire Vehicle Insurer**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLK2848H	17 Jul 2018 / 13:15:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous      OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018 <a href="#">Edit Reg</a>		18 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$280.00</b> <a href="#">Edit Estimates</a>	<b>S\$280.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Chen Yoke Kee</b> , ID: S2705212F								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHC3769K</b>	Date of Loss:	17/07/2018 13:00 - :59 [47 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3120467511SG</b>	Policy/Cover Note No.:	2100497060 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLK2848H</b>	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 30/07/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHC3769K (3120467511SG)  
 [SLK2848H]  
 TP  
 COMFORT TRANSPORTATION PTE LTD  
 Jul 17 2018 1:00PM  
 [Chen Yoke Kee]  
 ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	21/08/18 15:41	TP Video Footage SHC 3769K												1	Load MP4					
Letters/Correspondences															1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
2	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
3	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
4	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
11	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
12	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
15	19/07/18 17:10	General View												1	Load JPG	<input checked="" type="checkbox"/>				
16	19/07/18 17:19	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
17	19/07/18 17:19	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
18	19/07/18 17:19	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>				
Documentation															1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	19/07/18 17:44	TP ESTIMATE- MARKED												1	Load PDF					
2	19/07/18 17:44	TP GIA REPORT												1	Load PDF					
3	23/08/18 15:56	LETTER TO OI												1	Load PDF					
4	07/09/18 11:37	WORKSHOP INVOICE												1	Load PDF					
5	07/09/18 11:37	AUTHORISATION TO ACT FORM												1	Load PDF					
6	07/09/18 11:37	Release Voucher												1	Load PDF					
7	07/09/18 11:37	RENTAL RECEIPT												1	Load PDF					
8	07/09/18 11:37	LTA SEARCH												1	Load PDF					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	20/07/18 09:18	OI GIA REPORT												1	Load PDF					



## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK2848H (Insd veh)	Model:	HYUNDAI I40 1.7 D (A)
	SHC3769K (TP veh)		
Date of Accident:	17/07/2018		

Global Sum Settlement	:	[ X ]	Yes	[ ]	No
Repair Estimate	:	\$	1,410.73		
Final Repair Cost	:	\$	640.00		
Loss of Use	:	\$	2.00 days at \$50.00 per day		
Rental (if any)	:	\$	2 days		
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$	640.00		
Is Third Party Workshop GIA Registered? [ X ] YES [ ] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____(%)					
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: <del>Yes</del> / No BOLA Scenario No: _____					
NIL					
BOLA Liability: ____100____(%) Assessed Liability (*):_____(%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 640.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

07 Sep  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18013131/K1FB3Q2

Date: 07/09/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100497060

Claimant Vehicle No: SHC3769K

Insured Vehicle No: SLK2848H

Date of Loss: 17/07/2018

Nature of Claim:

TP

Claim No: 3120467511SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC3769K

Make &amp; Model: HYUNDAI I40, 1.7 D (A)

Reg. Date: 14/08/2014 (Man. Year: 2014)

Colour: Blue

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: D4FDEU450952

Chassis No: KMHLB41UMEU057738

Odometer: 540791 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Campeon 7 mm

Rear Left Side:

Campeon 7 mm

Front Right Side: Campeon 7 mm

Rear Right Side:

Campeon 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	838.44	0.00	838.44	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	280.00	200.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,318.44</b>	<b>280.00</b>	<b>1,038.44</b>	<b>78.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>92.29</b>	<b>19.60</b>	<b>72.69</b>	<b>78.76</b>
<b>Nett Amount (S\$)</b>	<b>1,410.73</b>	<b>299.60</b>	<b>1,111.13</b>	<b>78.76</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$119.28/day) (S\$)</b>		238.56		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>645.65</b>		
<b>Global Sum Settlement (S\$)</b>		<b>640.00</b>		

### INSPECTION

Date of Assignment: 18/07/2018

Date Inspected: 18/07/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	562.30 FL	*- FL
2	1		*RADIATOR GRILLE	Serviceable	417.00 FL	*- FL
3	1		*NO PLATE (S) W/TIME COVER	Serviceable	55.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>1,034.30</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>0.00</b>
					<b>Total Parts (S\$)</b>	<b>0.00</b>

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	280.00	100.00
2	SPRAYPAINT ON AFFECTED AREA	New	200.00	180.00
Gross Labour Cost (\$\$)			<b>480.00</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >