

Aigba - 45  
LKK - Kalvin

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305188974  
REGN NO : SHC3769K  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 14.08.2014  
DATE/TIME IN : 17.07.2018 14:50  
ACCIDENT DATE : 17.07.2018

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                         |     |        |       |        |          |
|------------------------|-------------------------|-----|--------|-------|--------|----------|
| 0001 04-01-0103-0578-G | FRT BUMPER              | 1   | 562.30 | 20.00 | 449.84 | X Repair |
| 0002 04-01-0103-0582-G | RADIATOR GRILLE         | 1   | 417.00 | 20.00 | 333.60 | X        |
| 0003 FNPS              | NO PLATE(S)w/Trim Cover | 1 N | 55.00  |       | 55.00  | X        |

SUB-TOTAL : 838.44

## JOB NATURE

|             |                             |  |  |  |  |        |
|-------------|-----------------------------|--|--|--|--|--------|
| 0000 L      | PANEL BEATING               |  |  |  |  | 280.00 |
| 0001 23-502 | SPRAYPAINT ON AFFECTED AREA |  |  |  |  | 200.00 |

SUB-TOTAL : 480.00

TOTAL : 1,318.44

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin LKK  
18/7/18 10:54  
2018  
L/s  
After Repair