

REF: CS3 / MS618003331 / THB-1⁰² Special Instruction:

b 560

ASSIGNMENT (Office)
From (Person): Mund Ashik of MSG Date/Time: 17072018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: SJH 8391M Insured: ET 919K

at Workshop m/s V-Tech Auto Tel:

of 1 Sam Lee St #06-04

Policy No: B28998172Qmf Claim No: 550338

Sum Insured: Excess:

Make of Veh: D.O.A. 20072018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

Date/Time: 28072018 1053am Person Contacted: Ms. Chong Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	<u>SJH 8391M - x</u>	
	<u>ET 919K - NA / INC09003761 / r</u>	<u>Don 180709</u>
	<u>Diamond: 2/8/2018</u>	
	<u>→ 16/3/2018</u>	
	<u>lump sum \$ 7950 (Red: 10550, 570%) 9 days.</u>	

2/8 - File pass to typist

RECEIVED 02 JUL 2018

mv: 13,000+ LTA: 8240 NV: 4760

Ref: *mpk*

REF: *ml*

MSIG

ASSIGNMENT

2018 July
2008 July

From: _____ Date: 28/2/2018

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To: Inspect Vehicle No: *SI* *201X*

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

(DAC Accident Report) Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: _____ days Res. Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time Action / Instruction

an: *83G 8391M* *2008 July*

Type: *6* Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Mazda 3* *1598*

Colour: *Black* A/C Insured / Std / Nil / NA

Sp. Reading: *124132* T. Radio: Insured / Std / Nil / NA

Eng. No: _____

G.No: *JMLBK106280413447*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Mod: *Nil* / S/S rim / STD A/Rim or

Tyre Size: *F: 205/55R16*

R: *205/55R16*

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *blanket*

Front

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A: _____ D.O.I: *28/2/18 @ 11am*

Survey held at: *V-Tech Soun Lee*

Des. of Damages: *Fr / Rear / D/S / N/S / U/C / Rooftop or*

o/s, n/s, u/c
The U/C / Chassis frame / Body Structure affected due to collision

* Repair Estimate : S\$ 15 - 16 K.

* 12 days

RECEIVED 16 MAY 2018

Date/Time File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time File Return to?

Days Of Repair: *12*

Resurvey No. of Trip: *3*

Survey Fee

Transportation

S. & P. 2008

Other

Other

Add Fee:

☐ S. & P. 2008
☐ S. & P. 2008
☐ S. & P. 2008
☐ S. & P. 2008

S. & P. 2008

S. & P. 2008

S. & P. 2008

S. & P. 2008

Report Format

PRS

Lump Sum: I.B. 10

120

50

10

(180)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018		26 Feb 2018 15:54 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ARUL CHANDRAN, ID: S1785083J		
Main Claimant:	V-TECH AUTO SERVICE, Co. Reg. No.: 52949633W		
Vehicle Reg. No.:	SJG8391M	Date of Loss:	20/02/2018 07:00 - :59 [115 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 550338	Policy/Cover Note No.:	B28998172QMY (Comprehensive) Coverage: 28/07/2017 - 27/07/2018
Vehicle Reg. No. (Insured):	ET919K	Policy No. (Claimant):	
		Excess:	
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/07/2018]		
Driver/Custodian (Insured):	ARUL CHANDRAN ANTOINETTE HELENE NEE GAMMA (), NRIC: S2028358J, Tel: +6590306950		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

- MSIG_SG (17/07/2018): Report Send Back Alerts - SJG8391M (TP)

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Vehicle & Owner Information (Vehicle No. ET919K As At 20 Feb 2018 / 07:40:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: VT

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1785083J

Owner Name: ARUL CHANDRAN

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 255

Registered Street Name: ARCADIA ROAD

Registered Unit No.: # 08 - 26

Registered Building Name:-

Registered Postal Code: 289850

Current Vehicle Details

Vehicle No.: ET919K

Make Description/Model: CITROEN / C5 1.6I E-HDI EGS

Insurance Company Name:MSIG INSURANCE (SINGAPORE) PTE LTD



V-TECH AUTO SERVICE

No.1 Soon Lee St #06-04/05/06/07 Pioneer Centre Singapore 627605
Tel: 62646211, 62646222 Fax: 62646233 Email: vtech.autoservice@gmail.com
Reg. 52949633W, GST Reg No. M90364098A 24 HRS TOWING SERVICES
Website: http://vtechauto.com.sg

Tax Invoice

Date	Invoice
23-Mar-2018	2018-783

Bill To
MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581

Ship To
SJG 8391 M M/3

Rep	Terms	Due Date
CTF	Cash-GST	23-Mar-2018

Item	Description	Qty	Rate	Amount
Insurance Clai...	The repair has agreed to undertake the repair under a Lump Sum Basis. We Have further adjusted the amount to a Lump Sum Repair contract of:	1	18,500.00	18,500.00T

Subtotal	\$18,500.00
GST (7.0%)	\$1,295.00
Total	\$19,795.00

Payment Must Be Made Within 30 days. A 1.5% Per Month Late
Payment Interest Will Be Levied For All Overdue Invoices.
This is computer generated document.
No signature is required.

Payments/Credits	\$0.00
Balance Due	\$19,795.00

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 02-18053/AY

Billing Name & Address

V-Tech Auto Service

c/o No.1 Soon Lee Street

#06-04/05/06/07 Pioneer Centre

Singapore 627605

Date 23 Mar 2018

Vehicle No : SJG 8391 M

Model : Mazda 3

Item	Descriptions	Amount S\$
1	Date of inspection : <u>28 Feb 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>249</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1374.00</u>
	SDLS : ONE THOUSAND THREE HUNDRED AND SEVENTY-FOUR ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 02-18053/AY / 2018
Date of Report : 23 Mar 2018

V-Tech Auto Service
c/o No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre
Singapore 627605

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 20 Feb 2018

As per your instruction dated 28 Feb 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJG 8391 M. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJG 8391 M
Model : Mazda 3
Year / Capacity : 2008/1598
Chassis No : JM6BK106280413447
Engine No : Z6691339
Mileage : 124132
Colour : Black

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 205/55 R16	Hankook	6.00	mm	Sport
REAR	O/S	: 205/55 R16	Hankook	6.00	mm	Sport
FRONT	N/S	: 205/55 R16	Hankook	6.00	mm	Sport
REAR	N/S	: 205/55 R16	Hankook	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the o/s and n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : V-Tech Auto Service
No.1 Soon Lee Street
#06-04/05/06/07 Pioneer Centre
Singapore 627605

5. Estimated normal period of repair : 12 working days to complete.
6. Enclosed number of photograph : 249 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJG 8391 M
Report No: TP/ 02-18053/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front bumper	Damage	\$ 860.00	\$ 860.00 XNC
2	Front bumper side retainers	Necessary	\$ 52.60	\$ 52.60 XNN
2	Front fenders	Damage	\$ 589.80	\$ 589.80 BUC
2	Front fender inner shields	N/S Damage	\$ 237.00	\$ 118.50 D.S
1	Front n/s shocker absorber	Damage	\$ 281.33	\$ 281.30 BT
1	Front n/s lower arm	Damage	\$ 516.70	\$ 516.70 BT
1	Front n/s knuckle arm	Damage	\$ 349.45	\$ 349.45 D.S
1	Front n/s knuckle arm bearing	Necessary	\$ 249.83	\$ 249.83 NEP
1	Front stabilizer bar	Damage	\$ 287.13	\$ 287.13 XNN
1	Front n/s stabilizer bar link	Damage	\$ 69.80	\$ 69.80 BT
1	Front power steering rack	Damage	\$ 1609.20	\$ 1609.20 OST
1	Front power steering rack cross member	Damage	\$ 1408.80	\$ 1408.80 XNN
1	Front o/s door	Damage	\$ 894.70	\$ 894.70 DD
1	Front o/s door lock	Damage	\$ 313.06	\$ 313.06 XNN
1	Front o/s door rubber	Necessary	\$ 47.85	\$ 47.85 BT
1	Front o/s door protector	Damage	\$ 68.60	\$ 68.60 CUT
1	Front o/s door regulator	Damage	\$ 419.10	\$ 419.10 XNN
1	Front o/s door regulator support	Damage	\$ 214.82	\$ 214.82 XNN
1	Front o/s door regulator motor	Damage	\$ 250.09	\$ 250.09 XNN
2	Rocker panel side skirts	Damage	\$ 1562.44	\$ 1259 1562.44 CRA
1	Rear o/s door	Damage	\$ 669.50	\$ 669.50 DD
1	Rear o/s door lock	Damage	\$ 272.90	\$ 272.90 XNN
1	Rear o/s door protector	Damage	\$ 65.80	\$ 65.80 CUT
1	Rear o/s door regulator	Damage	\$ 312.51	\$ 312.51 XNN
1	Rear door regulator motor	Damage	\$ 236.25	\$ 236.25 XNN
1	Rear door regulator support	Damage	\$ 207.64	\$ 207.64 XNN
1	Rear o/s door rubber	Damage	\$ 109.50	\$ 109.50 DD
			\$ 12156.40	\$ 12037.87
	Discount 20.0%		\$ 2431.28	\$ 2407.57
			\$ 9725.12	\$ 9630.30
<u>Special Nett Items</u>				
1	Front bumper lower spoiler (original)	Damage	\$ 1055.67	\$ 1055.67 XNC
2	Front fender inner shield clips (1 set)	Damage	\$ 70.00	\$ 70.00 NEC
1	Front n/s tyre (Deprecation)	Damage	\$ 300.00	\$ 180.00 150
1	Front n/s sport rim	Damage	\$ 450.00	\$ 450.00 CUT
1	Gear box	Damage	\$ 12000.00	\$ 6000.00 XNN
1	Rear o/s tyre (Deprecation)	Damage	\$ 300.00	\$ 180.00 XNN
1	Rear o/s sport rim	Damage	\$ 450.00	\$ 450.00 XNN
			\$ 14625.67	\$ 8385.67
Spare Parts Total			\$ 24350.79	\$ 18015.97

Vehicle No: **SJG 8391 M**
Report No: **TP/ 02-18053/AY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 24350.79	\$ 18015.97
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 ³⁰
2	To remove and refit front undercarriage.	\$ 450.00	\$ 300.00 ²⁵⁰
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 100.00	\$ 60.00 ⁸
4	To remove and refit gearbox from the engine.	\$ 600.00	\$ 450.00 ²⁰⁰
5	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 200.00	\$ 120.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2000.00	\$ 1540.00 ^{1,000}
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2800.00	\$ 2420.00 ¹⁴⁰⁰
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 200.00	\$ 150.00 ¹⁰⁰
Total		\$ 30750.79	\$ 23095.97

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 18500.00

9 days

SDLS: EIGHTEEN THOUSAND FIVE HUNDRED ONLY


Qualified Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

9633W

Vehicle Details

Vehicle No.:

SJG8391M

Vehicle to be Exported:

No

Intended De-registration Date:

01 Mar 2018

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 SP

Primary Colour:

Black

Manufacturing Year:

2008

Engine No.:

Z6691339

Chassis No.:

JM6BK106280413447

Maximum Power Output:

79.0 kW (105 bhp)

Open Market Value:

\$15,308.00

Original Registration Date:

17 Jul 2008

First Registration Date:

17 Jul 2008

Transfer Count:

1

Actual ARF Paid:

\$15,308.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 Jul 2018

PARF Rebate Amount:

\$7,654.00

Intended COE Rebate Details

COE Expiry Date:

16 Jul 2018

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

D.O.A - 20/2/2018
Bal = 5 mthsM.V. - \$13,000
- Rebate \$ 8,240
Repair margin \$4,760

QP Paid:	\$15,701.00
COE Rebate Amount:	\$586.00
Total Rebate Amount:	\$8,240.00

The information contained herein is correct as at 01 Mar 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

AdWords Can Help You
Reach The Right Customers.

mazda 3

Price Range

Depreciation

2008

Vehicle Type

Home » Used Cars » 1 Walker Automobile » Mazda 3 1.6A SP

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



Mazda 3 1.6A SP

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price **\$11,998**

Depreciation -

Reg Date 26-Aug-2008
(5mths 24days COE left)

Manufactured 2008

Mileage 99,287 km (10.4k /yr)

Transmission Auto

Engine Cap 1,598 cc

Road Tax \$742 /yr

Power 79.0 kW (105 bhp)
View specs of the Mazda 3 Sedan (2004-2009)

Curb Weight 1,235 kg

Features 1.6L 4 Cylinders DOHC 16 Valves Engine, 4 Speed Automatic Transmission With Tiptronic, Knockdown Rear Seats, Immobilizer Remote Key, SRS Airbags, ABS.

Accessories Sports Rims, Leather Seats, Factory Fitted Audio System With Steering Controls, Retractable Side Mirrors, Reverse Sensors, Digital Aircon Controls.

Description Stock Condition With Genuine Mileage With Service Records. Ideal For Short Terms Usage Or Future COE Renewal! Cheaper Than Rental Car! All Our Cars Selling At The Most Reasonable Price And With A Peace Of Mind! STA/VICOM Are Welcome. Thank You

COE \$13,289

OMV \$14,962

ARF \$14,962

Dereg Value \$8,125 as of today (change)

No. of Owners 2



Seller Informat

Company

Address

Location

Office No

Contact Person(s)

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/02/2018 14:25
Date Of Accident 20/02/2018 07:40
Exact Location Of Accident AYER RAJAH EXPRESSWAY & TUAS AVE 2 ROUNDABOUT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJG8391M
Insured/Policyholder
Name Of Registered Owner V-TECH AUTO SERVICE
Co Reg No 52949633W
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-94884990
Vehicle Particulars
Manufacturer MAZDA
Model 3
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 5091277865
Cover Note Number
Driver
Name of Driver TOH KAI WEI
NRIC No S9629178G
Date Of Birth 21/08/1996
Occupation INDOOR
Date Of Driving Pass 16/06/2015
Driving Experience 2 YEARS AND 8 MONTHS
Gender FEMALE
Mobile Number +65-94884990
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 648B JURONG WEST ST 61 #08-322
 Postcode 642648
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured RELATIVE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - ROUNDABOUT
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ET919K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category
 Name of Driver ANTOINETTE HELENE ARUL
 NRIC/Passport Number S2028358J
 Contact Number 90306950
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TOH KAI WEI
 Approximate Age 21

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SLIGHT

SJG8391M

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any intentional misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Advisory Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me relating to delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim, (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) My Personal Information may/also be disclosed by any of the Insurers, and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) My personal information will also be collected and used to compile a database for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) The information so collected under (d) above may be shared / disclosed to:
 - (i) to all insurers and/or any other third parties that assist me in settling, litigating, controlling or managing fraud;
 - (ii) regulatory, law enforcement and government agencies established or reported for the purpose mentioned;
 - (iii) in complying with the pertinent regulatory requirements and/or orders.


Insured Signature:
Date: 23/1/18 1:10pm

Insurer Signature:
(Insurer is not the policyholder)
Date & Time: 23/1/18 1:26pm

Reported by (Not a Party to the Accident)
Name:
Date & Time:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Road was clear, hence exited from exit ① using the most outer lane.
 Nearing to exit ②, car ET9RK was trying to exit ^{from the inner lane} and barged into my car.

DECLARATION

I declare that the facts stated above are true and correct.

Signature of Driver

[Signature]
 Date: 23/07/18 1:37pm

[Signature]
 Date: 23/07/18 1:37pm

[Signature]
 Date: 23/07/18 1:37pm



**SINGAPORE
POLICE FORCE**



T/20180220/2141

1 of 3

Report No. T/20180220/2141

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649618
Tel No: 1800-2689999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/02/2018 17:53		Vice Report No.:	Station Diary No.: 159
Informant's Particulars			
Name of Informant: TOH KAI WEI		Address: APT BLK 648B JURONG WEST STREET 61 #08-322 SINGAPORE 642648	
ID Type / ID No.: NRIC NO / S9629178G		Contact No.: Home/Office:	Mobile: 94884990
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 21	Date of Birth: 21/08/1996	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: LAB ASSOCIATE		Driving Licence Information: Class: 3A	Date of Expiry:

General Information of the Accident:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/02/2018 07:40	Type of Location: Roundabout
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH EXPRESSWAY TUAS AVENUE 2 ROUNDAABOUT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
ET919K	Car				Slightly Damaged	1
SJG6391M	Car	MAZDA	3		Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180220/2141

2 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180220/2141

CONTINUATION OF REPORT

Driver		ID No.	
Name	ANTOINETTE HELENE ARUL	ID No.	S2028358J
Related Vehicle		Contact No.	
ET919K (Car)		90306950	
Hospital/Clinic		Class of Driving Licence & Expiry Date	
NIL		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver		ID No.	
Name	TOH KAI WEI	ID No.	S9029178G
Related Vehicle		Contact No.	
S.JG8391M (Car)		94884990	
Hospital/Clinic		Class of Driving Licence & Expiry Date	
NG TENG FONG GENERAL HOSPITAL		Class: 3A Date of Expiry: NIL	
Date Treatment	20/02/2018	Date Discharge	20/02/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 20/02/18 at about 0740hrs, I was driving my Uncle's car, S.JG8391M, along AYE. I was occupying Lane 2 of the 2-lane road and intended to exit the roundabout towards Tuas Avenue 2. When the oncoming vehicles on my right were cleared and it was safe to pass, I then exited the lane and drove on using the same lane. I did not manage to reach the other side when suddenly, there was a loud bang coming from my right side of my car.

One car, ET919K, had collided onto the right driver's side and I was unaware where she came from. The impact also caused my car to hit the nearby kerb causing damages on the left side of the car. I then managed to brake fully and resumed control of my car about four car lengths away from the original accident location. I got out of my car and spoke to the driver to assess the damages and exchange particulars. No one was injured at that time.

At about 1030hrs, I feel uncomfortable and decided to visit Ng Teng Fong General Hospital. I was given three days of medical leave for my neck and shoulder pains.



SINGAPORE
POLICE FORCE



T/20180220/2141

3 of 3

Report No. T/20180220/2141

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474886 stating the report number as reference.

Signature Of Officer Recording The Report J / Sr Staff Sgt SHARIFA BINTE IBRAHIM	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 20/02/2018 17:53
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP188	

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048560
 Tel (65) 6724 0010 Fax (65) 6724 0030
 Operating hours: Monday to Friday, 09:00 - 17:00
 UEN: S65000286 / GST Reg. No.: M430017715

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No : SJG8391M
 Name (as shown on NRIC) : V-TECH AUTO SERVICE NRIC/FIN/Passport No : 52949633W
 [* Vehicle Driver / Vehicle Owner] (*) Please delete as appropriate
 Address : 1 SOON LEE ST #05-04/05 PIONEER CENTRE Singapore (627605)
 Contact (Tel) : 94884990 Mobile No. : _____
 Email Address : _____
 Date of Accident : 20-02-2018 Time of Accident : 07:35
 Place of Accident : AYER RAJAH EXPRESSWAY & TUAS AVENUE 2 ROUNDABOUT
 Insurance Company : NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I WOULD LIKE TO ADD POLICE REPORT

Policyholder / Driver's Signature

Date: 23/02/18



Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No: _____

Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2018		26 Feb 2018 15:54 Edit Adj Rpt	S\$7,950.00 Edit Estimates	S\$7,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ARUL CHANDRAN , ID: S1785083J								
Main Claimant:	V-TECH AUTO SERVICE , Co. Reg. No.: 52949633W								
Vehicle Reg. No.:	SJG8391M	Date of Loss:	20/02/2018 07:00 - :59 [115 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550338	Policy/Cover Note No.:	B28998172QMY (Comprehensive) Coverage: 28/07/2017 - 27/07/2018						
Vehicle Reg. No. (Insured):	ET919K	Policy No. (Claimant):							
		Excess:							
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/07/2018]								
Driver/Custodian (Insured):	ARUL CHANDRAN ANTOINETTE HELENE NEE GAMMA (), NRIC: S2028358J, Tel: +6590306950								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (17/07/2018): Report Send Back Alerts - SJG8391M (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJG8391M (550338)**
[ET919K]

TP

















































V-TECH AUTO SERVICE


Feb 20 2018 7:00AM





































[ARUL CHANDRAN]

V-Tech Auto Service

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	26/02/18 11:27	Accident Statement Addm. #1 From:SC - Reg. No: ET919K, Claimant: ARUL CHANDRAN					1	Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
4	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
6	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
7	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
8	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
9	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
10	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
11	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
12	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
13	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
14	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
15	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
16	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
17	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
18	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
19	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
20	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
21	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
22	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
23	07/05/18 10:57	General View					1	Load JPG	<input checked="" type="checkbox"/>	
24	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
25	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
26	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
27	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
28	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
29	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
30	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
31	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
32	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	
33	16/05/18 09:51	General View					1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
65	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
66	16/05/18 09:51	General View	 Load JPG	<input checked="" type="checkbox"/>
67	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	16/05/18 09:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	16/05/18 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
148	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
149	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
150	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
151	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
152	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
153	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
154	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
155	16/05/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/18 11:27	SJG8391M E-FILE & POLICE REPORT From: SC - Reg. No: ET919K, Claimant: ARUL CHANDRAN	 Load PDF	
2	26/02/18 11:31	PRI from Jusequity Law	 Load PDF	
3	26/02/18 15:56	Survey Disagree on SJE - appoint LKK	 Load PDF	
4	24/04/18 09:31	LTA & FINAL REPAIR BILL	 Load PDF	
5	24/04/18 09:31	SURVEY REPORT	 Load PDF	
6	24/04/18 09:40	SURVEY PHOTOS	 Load PDF	
7	24/04/18 09:41	SURVEY PHOTOS	 Load PDF	
8	24/04/18 09:41	SURVEY PHOTOS	 Load PDF	
9	24/04/18 09:46	SURVEY PHOTOS	 Load PDF	
10	24/04/18 09:46	SURVEY PHOTOS	 Load PDF	
11	20/06/18 11:26	PARF & COE rebate	 Load PDF	
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/18 16:20	PRS Invoice	 Load PDF	
2	03/08/18 16:24	PHOTO	 Load PDF	
3	03/08/18 16:24	PHOTO2	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18003881/T1TBE2-1

Date: 06/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28998172QMY

Claimant Vehicle No : SJG8391M

Insured Vehicle No : ET919K

Date of Loss: 20/02/2018

Nature of Claim: TP

Claim No: 550338

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG8391M

Make & Model: MAZDA 3, 1.6 SP (A)

Engine No: Z6691339

Reg. Date: 17/07/2008 (Man. Year: 2008)

Chassis No: JM6BK106280413447

Colour: Black

Odometer: 124132 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,350.79	6,819.62	17,531.17	71.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	3,160.00	3,240.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,750.79	9,979.62	20,771.17	67.55
Approved Total (Overridden) (S\$)		7,950.00		
(S\$)	30,750.79	7,950.00	22,800.79	74.15
+ GST 7.00/7.00% (S\$)	2,152.56	556.50	1,596.06	74.15
Nett Amount (S\$)	32,903.35	8,506.50	24,396.85	74.15

INSPECTION

Date of Assignment: 26/02/2018

Date Inspected: 28/02/2018 Inspected At:

V-Tech Auto Service (HQ)
No.1 Soon Lee Street, #06-04 Pioneer
Center
Singapore 627605

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$13,000.00(EST)-LTA REIMBURSEMENT VALUE: \$8,240.00=NETT VALUE: \$4,760.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2018)
Parts:	143	MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG8391M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (DAMAGED)	Not Consistent With The Impact	860.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	52.60 FL	*- FL
3	2		*FRONT FENDERS	Buckled	589.80 FL	*589.80 FL
4	1		*FRONT FENDER INNER SHIELDS	N/S Distorted	237.00 FL	*118.50 FL
5	1		*FRONT N/S SHOCKER ABSORBER	Bent	281.33 FL	*281.30 FL
6	1		*FRONT N/S LOWER ARM	Bent	516.70 FL	*516.70 FL
7	1		*FRONT N/S KNUCKLE ARM	Distorted	349.45 FL	*349.45 FL
8	1		*FRONT N/S KNUCKLE ARM BEARING	Necessary	249.83 FL	*249.83 FL
9	1		*FRONT STABILIZER BAR	Not Necessary	287.13 FL	*- FL
10	1		*FRONT N/S STABILIZER BAR LINK	Bent	69.80 FL	*69.80 FL
11	1		*FRONT POWER STEERING RACK	Bent	1,609.20 FL	*1,609.20 FL
12	1		*FRONT POWER STEERING RACK CROSS MEMBER	Not Necessary	1,408.80 FL	*- FL
13	1		*FRONT O/S DOOR	Dented	894.70 FL	*894.70 FL
14	1		*FRONT O/S DOOR LOCK	Not Necessary	313.06 FL	*- FL
15	1		*FRONT O/S DOOR RUBBER	Bent	47.85 FL	*47.85 FL
16	1		*FRONT O/S DOOR PROTECTOR	Cut	68.60 FL	*68.60 FL
17	1		*FRONT O/S DOOR REGULATOR	Not Necessary	419.10 FL	*- FL
18	1		*FRONT O/S DOOR REGULATOR SUPPORT	Not Necessary	214.82 FL	*- FL
19	1		*FRONT O/S DOOR REGULATOR MOTOR	Not Necessary	250.09 FL	*- FL
20	2		*ROCKER PANEL SIDE SKIRTS	Cracked	1,562.44 FL	*1,259.00 FL
21	1		*REAR O/S DOOR	Dented	669.50 FL	*669.50 FL
22	1		*REAR O/S DOOR LOCK	Not Necessary	272.90 FL	*- FL
23	1		*REAR O/S DOOR PROTECTOR	Cut	65.80 FL	*65.80 FL
24	1		*REAR O/S DOOR REGULATOR	Not Necessary	312.51 FL	*- FL
25	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	236.25 FL	*- FL
26	1		*REAR DOOR REGULATOR SUPPORT	Not Necessary	207.64 FL	*- FL
27	1		*REAR O/S DOOR RUBBER	Dented	109.50 FL	*109.50 FL
28	1		*FRONT BUMPER LOWER SPOILER (ORIGINAL) (DAMAGED)	Not Consistent With The Impact	1,055.67 FS	*- FS
29	2		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	70.00 FS	*50.00 FS
30	1		*FRONT N/S TYRE (DEPRECIATION)	Cut	300.00 FS	*150.00 FS
31	1		*FRONT N/S SPORT RIM	Cut	450.00 FS	*300.00 FS
32	1		*GEAR BOX (LOCAL REPAIR)	Damaged	12,000.00 FS	*800.00 FS
33	1		*REAR O/S TYRE	Not Necessary	300.00 FS	*- FS
34	1		*REAR O/S SPORT RIM	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 26,782.07 8,199.53

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)						2,431.28
						1,379.91
Total Parts (S\$)						24,350.79
						6,819.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS	New	50.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	450.00	250.00
3	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT	New	100.00	60.00
4	TO REMOVE AND REFIT GEARBOX FROM THE ENGINE	New	600.00	200.00
5	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS	New	200.00	120.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	2,800.00	1,400.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	200.00	100.00
8	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	2,000.00	1,000.00
Gross Labour Cost (S\$)			6,400.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >